

ASS. REC. BY:

REF:

09/26217014311 / Ggbsm

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): Tan Wei Yin of EQZ Date/Time: 25072017 1022am

Estimated Cost: Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFK 41726 Insured: GX 7251L

at Workshop m/s 154 Tick Hai Tel: 6842 9089

of Blk 1 Kaki Bukit Ave 6 #01-20

Policy No: Claim No: DM17H00642/JT

Sum Insured: Excess:

Make of Veh: D.O.A. 21072017
(Client's Record)

CA / REV / REP. / REV 24 HRS (Wp)

H.O.D. Endorsement:

Date/Time: 25072017 1055am Person Contacted: Connie Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SFK 41726 - X
	GX 7251L - X

AC S. REC. BY: Xhd.

REF: 6Q.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Tick Hai

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$19K.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SFK41726 Yr Regn: 17 Nov 2007

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda odyssey c.c. 2254 2354

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 174632 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMRB18508 C201858

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 25-07-17

Survey held at w/s 3:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
08/12	Finalised, \$3200 with Boss (Red & 626736, 66/1.)

Date/Time, File Pass to? ☐ : Preli. Report

11/12 train ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee: 160

Transportation: _____

_____ \$ + RS. _____ \$

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Report Format : Tr

Lump Sum / I.B.I. (\$ 3200)

Reference No.: 6/20170431/696
Policy Type: OD / TP / TP RES / TL / EVA

Policy Type: OD / ~~TP~~ / TP RES / TL / EVA

Typist

Admin (GFC): Case handler to make sure all information created by the assignment team are **ACCURATE**.

Y-Date	N-Date
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	

C Excess

N	Des.of Damages
---	----------------

C Re-inspection Cases to Finalize within 5 Days

Check By:

Case Handler

Date _____

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CS/EQI17014311/Gqb	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 25-07-2017	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GX 7251L	Veh. Inspected	SFK 4172G
Policy No.		Coverage (\$)	0.00
Claim No.	DM17HO01642/JT	Excess (\$)	0.00
Assign From	TAN WEI YIN	Assign Date	25/07/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	21/07/2017	Inspection Date	25/07/2017
Survey held at	159 TICK HAI MOTOR BLK C KAKI BUKIT AVE 6 #01-20/22/54 & #02-59 SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Catherine Chong (LKK Auto)

From: Tan Wei Yin <weiyin.tan@eqinsurance.com.sg>
Sent: Tuesday, 25 July, 2017 10:22 AM
To: Admin A; assignments@lkkauto.com
Cc: Janet Tan
Subject: Our ref: DM17HO01642/JT, Your ref: TBA, Acc on 21/7/17 involving GX7251L & SFK4172G
Attachments: 25072017101815-0001.pdf; SAS2246140.PDF

Dear Sirs,

Please proceed to survey TP vehicle on a without prejudice basis.

We enclosed the following documents for your reference:

- Our insured GIA report
- PRI Request

Thank you

Regards,

Tan Wei Yin
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9882 | tel 65 6223 9433 ext.882 | fax 65 6223 4190
www.eqinsurance.com.sg



A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all

From: Aridas & Associates [mailto:aridasv@singnet.com.sg]
Sent: Tuesday, July 25, 2017 10:06 AM
To: Tan Wei Yin <weiyin.tan@eqinsurance.com.sg>
Subject: FW: Our ref: DM17HO01642/JT, Your ref: AA.21393.17.159-PRS

Hi Ms Wei Yin

Kindly acknowledge receipt of this email.

Thank you.

Yours faithfully

Mr Vincent Kee
M/s Aridas & Associates

From: Aridas & Associates [mailto:aridasv@singnet.com.sg]
Sent: Tuesday, 25 July 2017 9:33 AM
To: 'Janet Tan'
Subject: RE: Our ref: DM17HO01642/JT, Your ref: AA.21393.17.159-PRS

ATTENTION : MS JANET TAN (SENIOR EXECUTIVE)

Dear Sirs

We refer to your fax of 24 July, 2017.

We wish to inform you that our client wishes to appoint your surveyor from **M/s LKK Auto Consultants Pte. Ltd.**, to do the pre-repair survey as a single joint expert.

Thank you.

Yours faithfully

Mr Vincent Kee
M/s Aridas & Associates
Telephone No. : 6337 6359
Fax No. : 6338 2713
Email : aridasv@singnet.com.sg

From: Janet Tan [mailto:janet.tan@eginsurance.com.sg]
Sent: Monday, 24 July 2017 4:57 PM
To: Aridas & Associates
Subject: Our ref: DM17HO01642/JT, Your ref: AA.21393.17.159-PRS

Without Prejudice
Save as to Cost

Dear Sir,

We refer to your fax of 24 July 2017.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd	4) Priority Services

L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	Tel: 62934822 Fax: 62963283 Contact Person: Hui Lian
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Ricky Teng	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328 Contact Person: Edna Lee	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.


Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqnsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

ARIDAS & ASSOCIATES

NOTARY PUBLIC
ADVOCATES & SOLICITORS
COMMISSIONER FOR OATHS

Dm17/1642

NO. 75 BUKIT TIMAH ROAD, #05-18
BOON SIEW BUILDING
SINGAPORE 229833
TEL : 6 337 6359 (3 LINES) FAX : 6 338 2713
E-mail : aridasv@singnet.com.sg

VYILINGAM ARIDAS
LLB (Hons) Lond. M.A.
Barrister, (Lincoln's Inn)

Service of Court Documents
By Fax
Is Not Acceptable

Our Ref : AA.21393.17.159

Your Ref : Please advise

LKF

24 July 2017

M/s EQ Insurance

BY FAX : 6224 3903

Dear Sirs

**ACCIDENT INVOLVING MOTOR VEHICLES NOS. SFK 4172G AND GX 7251L
ALONG UBI AVENUE 1 ON 21.07.2017**

We are instructed by Lim Yen Ching to notify you of a road traffic accident on 21.07.2017 at about 12.10 p.m. along Ubi Avenue 1 involving our client's vehicle registration number **SFK 4172G** and vehicle registration number **GX 7251L** driven by you at the material time. Copies of the Singapore Accident Statement filed and LTA search particulars are enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damage vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Our client's motor vehicle **GX 7251L** can be inspected at M/s 159 Tick Hai Motor, Blk 1 Kaki Bukit Avenue 6, #01-20 Autobay @ Kaki Bukit, Singapore 417883. Please contact **Ms Connie** at office number : **6842 9089**.

Yours faithfully

enc

cc

M/s J-Force Delivery Solutions LLP
Block 521 Hougang Avenue 6
#08-43
Singapore 530521



Text size - -

Enquire Vehicle & Owner Information (Vehicle No. GX7251L As At 21 Jul 2017 / 12:10:01)
Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: 21393.159

Current Owner Details

Owner ID Type: Limited Liability Partnership
Owner ID: Y13LL0479K
Owner Name: J-FORCE DELIVERY SOLUTIONS LLP
Registered Address Type: HDB / HUOC
Registered Block/House No.: 521
Registered Street Name: HOUGANG AVENUE 6
Registered Unit No.: # 08 - 43
Registered Building Name: -
Registered Postal Code: 530521

Current Vehicle Details

Vehicle No.: GX7251L
Make Description/Model: MITSUBISHI / L300 HR M
Insurance Company Name: EQ INSURANCE COMPANY LTD



Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)
Last updated on 16 Jul 2017 at 12:47 AM

24-07-17;10:49

MANC17096223 / Auto N Cars Services Pte Ltd - HQ
ENTRY DATE & TIME: 21/07/2017 15:08

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 21/07/2017 15:08
Date Of Accident 21/07/2017 12:10
Exact Location Of Accident UBI AVE 1
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SFK4172G
Insured/Policyholder
Name Of Registered Owner LIM YEN CHING (LIN YANJING)
NRIC No S7523686G
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-96704211
Alternative Phone No OFFICE-96704211
Vehicle Particulars
Manufacturer HONDA
Model ODYSSEY 2.4 A
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number DMPCSN3008141705
Cover Note Number
Driver
Name of Driver SIM SEE HWEE
NRIC No S7423353H
Date Of Birth 19/07/1974
Occupation INDOOR
Date Of Driving Pass 25/04/2003
Driving Experience 14 YEARS AND 2 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-97847475
Fax Number
Contact Number
Email Address NOEMAIL

24-07-17;10:49

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of Intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GX7251L

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

RHAIME BIN ABD RAHMAN

NRIC/Passport Number

S7135904B

Contact Number

85565656

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report accurately the details of the accident to speed up the claims process.
 2. This form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The use and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of this report being made available aforesaid.
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively, the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



24-07-17:10:49


Sketch Plan #2 Pg. 1


Describe Circumstances of the Accident


I was driving along Ubi Avenue 1. Suddenly, Vehicle B which is exiting from Paya Ubi Industrial Park, hit onto the rear right hand portion of my vehicle.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

 21/07/2017, 1.15pm
Driver's Signature (if driver is not the policyholder) / Date & Time

 21/07/2017
Witnessed by Reporting Centre Personnel

Insurance Co.	China Taiping		
Vehicle NO.	SEK4172G	Date Of Accident	21, 7, 17
<input type="checkbox"/> Reporting Only <input type="checkbox"/> Own Damage Claim <input checked="" type="checkbox"/> Third Party Claim			

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 3686G

Vehicle Details

Vehicle No.: SFK4172G

Vehicle to be Exported: No

Intended De-registration Date: 26 Jul 2017

Vehicle Make: HONDA

Vehicle Model: ODYSSEY 2.4 A

Primary Colour: Black

Manufacturing Year: 2007

Engine No.: K24A65001854

Chassis No.: JHMRB18508C201858

Maximum Power Output: 118.0 kW (158 bhp)

Open Market Value: \$27,089.00

Original Registration Date: 17 Nov 2007

First Registration Date: 17 Nov 2007

Transfer Count: 1

Actual ARF Paid: \$29,798.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 16 Nov 2017

PARF Rebate Amount: \$14,899.00

Intended COE Rebate Details

COE Expiry Date: 16 Nov 2017

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$18,001.00

COE Rebate Amount: \$554.00

Total Rebate Amount: \$15,453.00

The information contained herein is correct as at 26 Jul 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Last updated on 16 Jul 2017 at 12:47 AM

159 TICK HAI MOTOR
1 KAKI BUKIT AVE 6 #01-20 SINGAPORE 417883
TEL: 6842 9089 FAX: 6841 2869
REG NO : 53033608A

Vehicle Number: SFK4172G

S/N.	Item Description	Amount (\$)
1	Rear Bumper <i>- cut</i>	\$ 808.39
2	Rear Bumper Side Retainer (RH) <i>- AEL</i>	\$ 31.57
3	Taillamp (RH) <i>- NIS</i>	\$ 748.22
4	Rear Fender (RH) <i>- BUC</i>	\$ 991.65
5	Rear Boot <i>X repair</i>	\$ 1,096.04
6	Rear Boot Lamp (RH) <i>X NN</i>	\$ 641.85
7	Air Con Blower <i>- CPA</i>	\$ 1,201.57
Total :		\$ 5,519.29
Less 10% :		\$ 551.93
Amount :		\$ 4,967.36

764.4
365.2
899.3
X
X
1120.4

3180.87
20%: 2544.7

S/N	Special Nett Item	Amount (\$)
1	Reverse Sensor x 2 pcs <i>- DM</i>	\$ 130.00
3	Windscreen Sealant <i>X NN</i>	\$ 80.00
Amount :		\$ 210.00

65
X

Labour	Amount (\$)
To check rear electrical wiring system	\$ 80.00
To transfer rear boot component parts to new rear boot	\$ 150.00
To transfer rear fender windscreen to new fender	\$ 150.00
To remove, replace, and reinstall rear reverse sensors	\$ 80.00
To apply anti-rusting coating on new and affected areas	\$ 200.00
To remove & reinstall rear interior trims, garnishes etc for necessary repair	\$ 180.00
To remove & reinstall air con blower, and refill air con gas	\$ 150.00
Labour to remove, cut, change & panel beating	\$ 1,900.00
To putty and respray affected areas	\$ 1,400.00
the Repairer of the following:	
• To resurvey before/after spray painting	
• To display damaged part(s) during resurvey	
• Parts prices are subject to confirmation	
• Third party survey is on a "Without Prejudice" basis	
• No illegal modification(s) is allowed	
Labour Total :	\$ 4,290.00
Total (Parts & Labour)	\$ 9,467.36

30
X NN
60
40
60
60
40
600
500
1390
3999.7

20%: 3200
5 days

Acknowledged by Repairer

Signature:

Date:

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CS/EQI17014311/Gqbs2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 18-12-2017



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GX 7251L	Veh. Inspected	SFK 4172G
Policy No.		Coverage (\$)	0.00
Claim No.	DM17HO01642/JT	Excess (\$)	0.00
Assign From	TAN WEI YIN	Assign Date	25/07/2017

2. Vehicle Particulars & Condition

Make & Model	HONDA ODYSSEY	c.c	2354
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JHMRB18508C201858	Colour	BLACK
Odometer	174632	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55R17	MICHELIN	6 mm
L/H Front Tyre	215/55R17	MICHELIN	6 mm
R/H Rear Tyre	215/55R17	MICHELIN	6 mm
L/H Rear Tyre	215/55R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	21/07/2017	Inspection Date	25/07/2017
Survey held at	159 TICK HAI MOTOR BLK C KAKI BUKIT AVE 6 #01-20/22/54 & #02-59 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFK 4172G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	CUT	808.39	764.40
1	REAR BUMPER SIDE RETAINER (RH)	NECESSARY	31.57	31.57
1	TAILLAMP (RH)	DISTORTED	748.22	365.20
1	REAR FENDER (RH)	BUCKLED	991.65	899.30
1	REAR BOX	TO REPAIR SEE LABOUR	1,096.04	-
1	REAR BOOT LAMP (RH)	NOT NECESSARY	641.85	-
1	AIR CON BLOWER	CRACKED	1,201.57	1,120.40
	LESS 10% DISCOUNT		-551.93	-
	LESS 20% DISCOUNT		-	-636.17
			4,967.36	2,544.70
	<u>SPECIAL NETT ITEMS</u>			
2	REVERSE SENSOR (SN)	DAMAGED	130.00	65.00
1	WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
			210.00	65.00
	<u>LABOUR</u>			
	TO CHECK REAR ELECTRICAL WIRING SYSTEM.	NOT NECESSARY	80.00	30.00
	TO TRANSFER REAR BOOT COMPARTMENT PARTS TO NEW REAR BOOT.		150.00	-
	TO TRANSFER REAR FENDER WINDSCREEN TO NEW FENDER.		150.00	60.00
	TO REMOVE, REPLACE, AND REINSTALL REAR REVERSE SENSORS.		80.00	40.00
	TO APPLY ANTI-RUSTING COATING ON NEW AND AFFECTED AREAS.		200.00	60.00
	TO REMOVE & REINSTALL REAR INTERIOR TRIM, GARNISHES ETC FOR NECESSARY REPAIR.		180.00	60.00
	TO REMOVE & REINSTALL AIR CON BLOWER, AND REFILL AIR CON GAS.		150.00	40.00
	LABOUR TO REMOVE, CUT, CHANGE & PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BOX.		1,900.00	600.00
	PUTTY AND RESPRAY AFFECTED AREAS.		1,400.00	500.00
			4,290.00	1,390.00
GRAND TOTAL			9,467.36	3,999.70



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,200.00
---	--	--	----------

Report Ref No. CS/EQ117014311/Gqbs2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.