

ISS. REC BY:

REF:

C/AXA17014549/Emb

Special Instruction:

SURVAYOR:

ASSIGNMENT (Office)

From (Person): ^{James or} ~~Michelle Lee~~ of AKA Date/Time: 27072017

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PZ 56M Insured: XD 1907Y

at Workshop m/s Crown Asia Tel:

of 44 Sungai Kadut Ave

Policy No: P1670742 Claim No: C0445131

Sum Insured: Excess:

Make of Veh: D.O.A. 19072017
(Client's Record)

CA / REV / REP. / REV 24 HRS w/pi 02082017 @ 10am
Judyden 64670956 H.O.D. Endorsement:

Date/Time: 27072017 4:24pm Person Contacted: Rochelle Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	PZ 56M - X
	XD 1907Y - X
	Confirm \$ 2940.00 , 2 days
	Red: 8350, 60%.

Surveiur **RICHARD**
Melman

REF: AXA

ASSIGNMENT

From: _____ Date: 02082017
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: P2 56m
 at Workshop m/s: Crown Asia
 of: 44 Sungai Kadut Ave
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: P2 56m Yr Regn: 10 / 10
 Type: M.Car / M.Cycle Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: SCANIA C.C. 11205
 Colour: WHITE A/C: Insured / Std / NI / NA
 Sp. Reading: 499319 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: Y92K4X20001865918
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil S/Rim / STD A/Rim or _____

(Policy Condition) 10um
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Tyre Size: F: 295/80 R 22.5
 R: " " 2 x 2
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or CDN

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS Wp1
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6+6 mm L/Bal. 6+6 mm
 D.O.A. _____ D.O.I. 2/8/17 10.37
 Survey held at CROWN ASIA
 Des. of Damages: Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
RECEIVED 23 JUL 2018	
	 23/7/2018

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) Report
 Date/Time, File Return to?
 2) _____
 Report Format : TP
 Lump Sum / I.B.I: (\$ 2940.00)

Days Of Repair: 2
 Resurvey No. of Trip: 1
 Add Fee: Site Insp (\$ _____)
 Interview (\$ _____)
 Tech. Invs (\$ _____)
 Weekend (\$ _____)
 Survey Fee: 250
 Transportation: _____
 Photos _____
 Others _____
 TOTAL _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/AXA17014549/Srb

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 27-07-2017



Code : AXA2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 1907Y	Veh. Inspected	PZ 56M
Policy No.	P1670742	Coverage (\$)	0.00
Claim No.	C0445131	Excess (\$)	0.00
Assign From	MERIMEN (CYNTHIA LOH)	Assign Date	27/07/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/07/2017	Inspection Date	
Survey held at	CROWN ASIA BUS BUILDER PTE LTD NO. 44 SUNGEI KADUT STREET 1 SINGAPORE 729349		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

...CLAIM SUBFOLDER...(New Assignment)

Non-Reporting

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jul 2017		27 Jul 2017 15:45 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	HONG HUAT TRANSPORT PTE LTD, Co. Reg. No.: 197802590C								
Main Claimant:	B & A TRAVEL PTE LTD								
Vehicle Reg. No.:	PZ56M	Date of Loss:	19/07/2017 15:00 - :59						
Claim Type:	TP / C0445131	Policy/Cover Note No.:	P1670742 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	XD1907Y	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Crown Asia Bus Builder Pte Ltd (sungei Kadut) (HQ) 44 Sungei Kadut Ave, 729667 Sungei Kadut - Tel:								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Cynthia Loh - 68804843]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/08/2017]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
● AXA_SG (27/07/2017): WP / New TP Assignment - C0445131/P1670742									
ALL ASSOCIATED TASKS				View All	Search Tasks	Create New Task	Complete		
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/07/2017 14:37
Date Of Accident	19/07/2017 15:45
Exact Location Of Accident	WOODLANDS AVE 12 TOWARDS SLE(BKE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PZ56M
Insured/Policyholder	
Name Of Registered Owner	B & A TRAVEL PTE LTD
Co Reg No	200608499C
Email Address	BNATRAVEL899@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-67537634

Vehicle Particulars

Manufacturer	SCANIA
Model	BUS
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5079185706-01
Cover Note Number	

Driver

Name of Driver	TAN KOCK TEE
NRIC No	S1493155D
Date Of Birth	18/09/1961
Occupation	OUTDOOR
Date Of Driving Pass	03/08/1995
Driving Experience	21 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94597138
Fax Number	
Contact Number	
EEmail Address	BNATRAVEL899@GMAIL.COM

Address	BLK 629 YISHUN STREET 61 #12-13
Postcode	760629
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD1907Y
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan #2 Pg. 1

Describe Circumstances of the Accident

while the traffic light turn green, I continue to drive turn to SLE, out of sudden A trailer had hit my vehicle front left side. (side mirror).

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





CROWN ASIA BUS BUILDER PTE LTD

44 SUNGEI KADUT AVE, SINGAPORE 729667
Tel : +65 6467 0956 Fax : +65 6469 4319
Email : crownasia@hotmail.sg
Company Reg No: 201023449R

24/7/2017

To : AXA Insurance Singapore Pte Ltd

BY ENAIL ONLY
(motor.survey@axa.com.sg)

Attn : Motor claims dept

Dear Sirs ,

We are instructed by M/s B & A Travel Pte Ltd to notify you of a road traffic accident on 19/7/2017 at about 1545 hrs along Woodlands Avenue 12 involving our customer's vehicle , PZ 56 M and your insured's vehicle XD 1907 Y A copy of the Singapore Accident Statement report is enclosed.

As a result of the accident , our customer's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a per-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline , we shall proceed to repair the vehicle without further reference to you.

Please contact our Miss Rochelle at h/p 83036523 or Ah Wee h/p 97228998 for survey.

Yours faithfully



PRI
RICHARD / LKIC
2/8 10.30 AM.
91740253
68411972



CROWN ASIA BUS BUILDER PTE LTD

44 SUNGEI KADUT AVE, SINGAPORE 729667
 Tel : +65 6467 0956 Fax : +65 6469 4319
 Email : crownasin@hotmail.sg
 Company Reg No: 201023449R

AXA Insurance Singapore Pte Ltd
 c/o LKK Auto consultants Pte Ltd

BY FAX ONLY
 (62564315)

Dear Sirs ,

THIRD PARTY CLAIM :- REPAIR ESTIMATE FOR PZ 56 M
TRAFFIC ACCIDENT ON 19/7/2017 INVOLVING PZ 56 M AND XD 1907 Y ALONG
WOODLANDS AVENUE 12.

We append below the repair estimate for PZ 56 M.

Parts required :-


1 pc	Front left electrical wing mirror assy.	\$2900.00	CRA
	Less 10% trade discount	\$ 290.00	
	Total parts costs	\$2610.00	

Labour charges :-

To remove damaged front left electrical wing mirror and refit new including checking of its wiring system.	\$ 180.00	120
To putty and spray painting on front left wing mirror Casing assy.	\$ 450.00	210
Total repair cost	<u>\$3290.00</u>	3240

Note :- This estimate is based on visible damage only. Should any hidden parts and/or labour charges required during works in progress , insurer and/or their surveyor will be notified accordingly.

CROWN ASIA BUS BUILDER PTE LTD



 David Liang (h/p 96662662)
 Claims Consultant

**CROWN ASIA BUS BUILDER PTE. LTD.** (UEN:201023449R)

44 Sungei Kadut Avenue Singapore 729667

Tel: (65) 6469 3319, Fax: (65) 6902 6758

GST ID No : 201023449R

TAX INVOICENo. : **I-18030140**

B & A TRAVEL PTE LTD

629 YISHUN STREET 61

#12-13

SINGAPORE 760629

Your Ref. : PZ56M

Our D/O No. :

Terms : C.O.D.

Date : 26-03-2018

Page : 1 of 1

TEL :

FAX :

Item	Tax Code	Description	Qty	UOM	U/ Price	Disc.	Total
					S\$		S\$
1.	SR	FRONT LEFT ELECTRICAL WING MIRROR	1.00		2,900.00		2,900.00
2.	SR	LESS 10% TRADE DISCOUNT	1.00		-290.00		-290.00
3.	SR	LABOUR CHARGE TO REMOVE DAMAGED FRONT LEFT WING MIRROR AND REFIT NEW INCLUDING CHECKING OF WIRING SYSTEM	1.00		120.00		120.00
4.	SR	TO POLY PUTTY AND SPRAY PAINTING ON FRONT LEFT MIRROR CASING Traffic accident on 19/07/2017 involving PZ56M AND XS1907Y ALONG WOODLANDS AVENUE 12	1.00		210.00		210.00

VEHICLE NO: PZ56M

DATE OF ACCIDENT : 19/07/2017

Being the final repair bill for vehicle no PZ56M

SINGAPORE DOLLAR THREE THOUSAND ONE HUNDRED FORTY FIVE
AND CENTS EIGHTY ONLYSub Total (Excluding GST) **2,940.00**GST payable @ 7% on 2,940.00 **205.80**

Remarks:

Total (Inclusive of GST) **3,145.80**

Notes :

- All cheques should be crossed and made payable to
CROWN ASIA BUS BUILDER PTE. LTD.
- Goods sold are neither returnable nor refundable. Otherwise
a cancellation fee of 20% on purchase price will be imposed.

GST Summary

SR @ 7 %

Amount(S\$)

2,940.00

Tax(S\$)

205.80



Authorised Signature

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI VNI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jul 2017		27 Jul 2017 15:45 Edit Adj Rpt	S\$2,940.00 Edit Estimates	S\$2,940.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	HONG HUAT TRANSPORT PTE LTD, Co. Reg. No.: 197802590C								
Main Claimant:	B & A TRAVEL PTE LTD								
Vehicle Reg. No.:	PZ56M	Date of Loss:	19/07/2017 15:00 - :59 [80 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0445131	Policy/Cover Note No.:	P1670742 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	XD1907Y	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Crown Asia Bus Builder Pte Ltd (sungei Kadut) (HQ) 44 Sungei Kadut Ave, 729667 Sungei Kadut - Tel:								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Chen Xinyou - 6880 4269]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 07/08/2017]								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
<ul style="list-style-type: none"> AXA_SG (12/07/2018): Re: WP / New TP Assignment - C0445131/P1670742 AXA_SG (31/07/2017): C0445131/P1670742 -- AGENT & INSURED DISPUTED, PLEASE OBTAIN TP CCTV & U... AXA_SG (31/07/2017): TP settlement - C0445131/P1670742 AXA_SG (27/07/2017): WP / New TP Assignment - C0445131/P1670742 									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***PZ56M (C0445131)**
[XD1907Y]
TP
B & A TRAVEL PTE LTD
Jul 19 2017 3:00PM
[HONG HUAT TRANSPORT PTE LTD]
Crown Asia Bus Builder Pte Ltd (sungei Kadut)

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser ▾	
										3 per page ▾ <input checked="" type="checkbox"/>	
Photos/Images											
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	23/07/18 15:57	Reinspection Photo							Load PDF		
2	23/07/18 15:57	General View							Load PDF		
										1 per page ▾ <input checked="" type="checkbox"/>	
Documentation											
No	Finalized On	AXA Insurance Pte Ltd (HQ)						Thumbnail	Print		
1	24/07/17 16:13	EMAIL_ABS							Load PDF		
2	24/07/17 16:13	CO_CLAIMANT_ABS							Load PDF		
3	24/07/17 16:23	CO-CLAIMANT THIRD PARTY_ABS							Load PDF		
4	25/07/17 08:58	Certificate of Insurance							Load PDF		
5	25/07/17 08:58	Certificate Schedule							Load PDF		
6	25/07/17 10:49	EMAIL TO WORKSHOP_ABS							Load PDF		
7	26/07/17 16:40	REMINDER TO TP W/S							Load TIF		
8	31/07/17 09:49	E-filed GIA report - insd							Load PDF		
9	31/07/17 09:49	E-filed GIA report - TP							Load PDF		
10	31/07/17 10:02	Emailed to LKK							Load TIF		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	27/07/18 12:01	WORKSHOP INVOICE							Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AXA17014549/CRBS2

Date: 27/07/2018

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1670742
Claimant Vehicle No :	PZ56M	Insured Vehicle No :	XD1907Y
Date of Loss:	19/07/2017	Nature of Claim:	TP
		Claim No:	C0445131

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PZ56M	Engine No:	6425141
Make & Model:	SCANIA KIB4X2, 11.7 D (M)	Chassis No:	YS2K4X20001865918
Reg. Date:	29/10/2010 (Man. Year: 2009)	Odometer:	499319 km
Colour:	White		
Engine Capacity:	11705 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5(D)
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6/6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,610.00	2,610.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	630.00	330.00	300.00	47.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,240.00	2,940.00	300.00	9.26
+ GST 7.00/7.00% (S\$)	226.80	205.80	21.00	9.26
Nett Amount (S\$)	3,466.80	3,145.80	321.00	9.26

INSPECTION

Date of Assignment:	27/07/2017	
Date Inspected:	02/08/2017	Inspected At: Crown Asia Bus Builder Pte Ltd (sungei Kadut) (HQ) 44 Sungei Kadut Ave Singapore 729667
Estimated Period of Repair:	2.0 days	

Adjuster: Sebastian Yeang Wai Keen

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 27 Jul 2018)	
Parts:	N/A	SCANIA KIB4X2 11.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PZ56M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT LEFT ELECTRICAL WING MIRROR ASSY (CONSISTENT)	Cracked	2,900.00 FL	*2,900.00 FL	
						F=Franchise part, L=ListItemDisc.	
					Sub Total (S\$)	2,900.00	2,900.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	290.00	290.00
					Total Parts (S\$)	2,610.00	2,610.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE DAMAGED FRONT LEFT ELECTRICAL WING MIRROR AND REFIT NEW INCLUDING CHECKING OF ITS WIRING SYSTEM.	New	180.00	120.00
2	TO PUTTY AND SPRAY PAINTING ON FRONT LEFT WING MIRROR CASING ASSY.	New	450.00	210.00
Gross Labour Cost (S\$)			630.00	330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >