

ASS. REC. BY:

REF:

08 / CTU17015065 / Hbez

Special Instruction:

Survivor: Taufiq mauliden **ASSIGNMENT (Office)**

From (Person):

Joel Guh

of

CTU

Date/Time:

03082017 4:45pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJP 8210E

Insured:

SJN 5935C

at Workshop m/s

Mova

Tel:

62723892

of

Blk 1008 Bukit Merah Lane 3 #01-04

Policy No:

DmPCSN 1607151701

Claim No:

SHM17004476C02/5

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28072017

CA / REV / REP. / REV 24 HRS 1wp

14/8/2017 10amOwner Waiting

H.O.D. Endorsement:

Date/Time:

03082017 5:28pm

Person Contacted:

Avril
(Karen)Vehicle IN / OUT

Date/Time

Action/Instruction () EstimateSJP 8210E - CCG / AXA 13008527 / UMB33DA: 030413SJN 5935C - X8/8/17According to Annie vehicle did not sent in for repair.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17015065/T1tb	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 03-08-2017	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJN 5935C	Veh. Inspected	SJP 8210E
Policy No.	DMPCSN1607151701	Coverage (\$)	0.00
Claim No.	SNM17D04478C02/5	Excess (\$)	0.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	03/08/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/07/2017	Inspection Date	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Aug 2017		03 Aug 2017 16:45 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CHEN YUNJIE, ID: S2721689G		
Main Claimant:	LOW AIK LIM, ID: S1790005F		
Vehicle Reg. No.:	SJP8210E	Date of Loss:	28/07/2017 07:00 - :59
Claim Type:	TP / SNM17D04478C02/5	Policy/Cover Note No.:	DMPCSN1607151701 (Comprehensive)
Vehicle Reg. No. (Insured):	SJN5935C	Policy No. (Claimant):	5065047239-03
		Excess:	S\$0.00
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) No. 22 Jalan Kilang, #03-01, Mova Building, 159419 Bukit Merah - Tel: 62723892/64763333		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/08/2017]		
Driver/Custodian (Insured):	CHEN YUNJIE (49 / Male), NRIC: S2721689G		
Adj Asg. Remarks:	ESTIMATES AS ATTACHED. SELECTED AS SJE FOR WP PRS. KINDLY PROVIDE US WITH YOUR RECOMMENDATION		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/07/2017 11:36
Date Of Accident	28/07/2017 07:00
Exact Location Of Accident	NORTH BUONA VISTA ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJP8210E
Insured/Policyholder	
Name Of Registered Owner	LOW AIK LIM
NRIC No	S1790005F
Email Address	LOWAIKLIM@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96801830
Alternative Phone No	OTHERS-96801830

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY 2.4L AT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5065047239-03
Cover Note Number	

Driver

Name of Driver	LOW AIK LIM
NRIC No	S1790005F
Date Of Birth	02/02/1967
Occupation	INDOOR
Date Of Driving Pass	06/10/1993
Driving Experience	23 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96801830
Fax Number	
Contact Number	OTHERS-96801830
Email Address	LOWAIKLIM@GMAIL.COM

Address	7D PALM DRIVE
Postcode	456481
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN: ATTENDED BY SITI

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJN5935C
Vehicle Make/Model/Colour	TOYOTA COROLLA ALTIS
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name
Phone Number
Email Address

SKETCH PLAN

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4
Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@singnet.com.sg




Policyholder's Signature / Date & Time

28 JUL 2017

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan #2 Pg. 1

Describe Circumstances of the Accident

At 7.00am on 28 July 2017, I was taking my usual route of sending my daughter to school at Dover Road. After exiting from the AYE (towards Tuas) at the 4th exit, I was on the extreme right lane. After passing the main traffic light at North Brown Vista Road (still on the extreme right lane of the 4/5 lane road), vehicle STN 5935 C (Toyota Corolla Altis) cut into my lane all a sudden right into my path. I braked heavily (my children and wife were in my car) unfortunately, his sudden entry into my path resulted in the left side of my car damaged, my left front bumper, the left light lamp and scratches on the front (left) of my car including now resistance to the left front door of my vehicle. The driver Mr Chen Yunjie (S2721689G) was apologetic and surrendered his IC for me to note his particulars. Thankfully my children and wife were safe.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

28 JUL 2017

Driver's Signature (if driver is not the policyholder) / Date & Time

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

Witnessed by Reporting Centre Personnel

Estimate

01/08/2017

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1
 Veh # :- SJP8210E
 Veh Model :- HONDA ODYSSEY
 Estimate# :- CK416170
 Claim # :-
 ACC. Date :- 28/07/17
 Terms :- C.O.D Days
 Remarks :-

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel : (65) 6476 3333
 Fax : (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel : (65) 6272 3892
 Fax : (65) 6270 8314

Co. Reg. 198904033G
 GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	FRONT HEADLAMP LH	1	958.00	<i>cut</i> 958.00
2.	FRONT HEADLAMP LOWER BRACKET LH	1	68.00	<i>re</i> 68.00
3.	FRONT BUMPER	1	785.00	<i>de</i> 785.00
4.	FRONT BUMPER RETAINER LH	1	38.00	<i>re</i> 38.00
5.	FRONT FOGLAMP COVER LH	1	35.00	<i>nn x</i> 35.00
6.	FRONT BUMPER UNDERCOVER	1	245.30	<i>?</i> 245.30
7.	FRONT BUMPER CLIPS	10	3.90	<i>re</i> 39.00
8.	FRONT FENDER LH	1	682.00	<i>bt</i> 682.00
9.	FRONT FENDER COWLING LH	1	158.60	<i>?</i> 158.60
10.	FRONT FENDER COWLING CLIPS	10	3.90	<i>re</i> 39.00
11.	FRONT HEADLAMP PANEL LH - REPAIR	1		
12.	FRONT FENDER LH - REPAIR	1		
	LIST TOTAL S\$			3,047.90
	20% DISCOUNT S\$			-609.58
				2,438.32
SPECIAL NET ITEMS :				
1.	FRONT BUMPER SENSOR	1	250.00	<i>?</i> ²⁰⁰ 250.00
	SPECIAL NET TOTAL S\$			250.00
LABOUR :				
	TO REPAIR FRONT HEADLAMP PANEL LH AND FRONT FENDER LH. TO REMOVE AND REPLACE ALL ACCIDENT DAMAGED PARTS AND REALIGN ALL AFFECTED AREA			<i>450.</i> 550.00
	TO SPRAY PAINT ON ACCIDENT AFFECTED AREA			800.00
	TO INSPECT FRONT LIGHTING AND WATER LEAKAGE TEST			<i>20.</i> 50.00
	TO REMOVE AND REFIX FRONT SENSORS AND CHECK WIRING			<i>30.</i> 60.00
	TO RUST PROOF AFFECTED AREA			<i>30.</i> 60.00
	TO CHECK WHEEL ALIGNMENT			<i>?</i> 80.00
	LABOUR TOTAL S\$			1,600.00

Estimate

01/08/2017

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 128930
Veh # :- SJP8210E
Veh Model :- HONDA ODYSSEY
Estimate# :- CK416170
Claim # :-
ACC. Date :- 28/07/17
Terms :- C.O.D Days
Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 4,288.32

GST @ 7 % 300.18

AMOUNT DUE S\$ 4,588.50

Signature

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanfika 97495749
'WP'
sur@lkkauto.com
4-5 days
Lumpsum
Resurvey After repair.
14/8/17.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Aug 2017		03 Aug 2017 16:45 Edit Adj Rpt	S\$3,117.20 Edit Estimates	S\$3,117.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	CHEN YUNJIE , ID: S2721689G			
Main Claimant:	LOW AIK LIM , ID: S1790005F			
Vehicle Reg. No.:	SJP8210E	Date of Loss:	28/07/2017 07:00 - :59 [99 Months and 27 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM17D04478C02/5	Policy/Cover Note No.:	DMPCSN1607151701 (Comprehensive)	
Vehicle Reg. No. (Insured):	SJN5935C	Policy No. (Claimant):	5065047239-03	
		Excess:	S\$0.00	
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3, 159722 Bukit Merah - Tel: 62723892/64763333			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]			
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 15/08/2017]			
Driver/Custodian (Insured):	CHEN YUNJIE (49 / Male), NRIC: S2721689G			
Adj Asg. Remarks:	ESTIMATES AS ATTACHED. SELECTED AS SJE FOR WP PRS. KINDLY PROVIDE US WITH YOUR RECOMMENDATION			

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SJP8210E (SNM17D04478C02/5)
[SJN5935C]
TP
LOW AIK LIM
Jul 28 2017 7:00AM
[CHEN YUNJIE]
Mova Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View <input type="button" value="View in Browser"/>	
Assessment Reports									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)			Thumbnail			Print		
1	28/07/17 11:51	Accident Statement				Load HTM				
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)			Thumbnail			Print		
1	28/07/17 11:45	Accident Photo [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>		
2	28/07/17 11:45	Accident Photo [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>		
3	28/07/17 11:45	Accident Photo [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>		
4	28/07/17 11:45	Accident Photo [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>		
5	28/07/17 11:45	Accident Photo [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>		
6	28/07/17 11:45	Accident Photo [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>		
7	28/07/17 11:45	Accident Photo [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>		
8	28/07/17 11:45	Accident Photo [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>		
9	28/07/17 11:45	Accident Photo [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail			Print		
1	08/08/18 11:50	General View				Load JPG		<input checked="" type="checkbox"/>		
2	08/08/18 11:50	General View				Load JPG		<input checked="" type="checkbox"/>		
3	08/08/18 11:50	General View				Load JPG		<input checked="" type="checkbox"/>		
4	08/08/18 11:50	General View				Load JPG		<input checked="" type="checkbox"/>		
5	08/08/18 11:50	General View				Load JPG		<input checked="" type="checkbox"/>		
6	08/08/18 11:50	General View				Load JPG		<input checked="" type="checkbox"/>		
7	08/08/18 11:50	General View				Load JPG		<input checked="" type="checkbox"/>		
8	08/08/18 11:50	General View				Load JPG		<input checked="" type="checkbox"/>		
9	08/08/18 11:50	General View				Load JPG		<input checked="" type="checkbox"/>		
10	08/08/18 11:50	General View				Load JPG		<input checked="" type="checkbox"/>		
11	08/08/18 11:50	General View				Load JPG		<input checked="" type="checkbox"/>		
12	08/08/18 11:50	General View				Load JPG		<input checked="" type="checkbox"/>		
13	08/08/18 11:50	General View				Load JPG		<input checked="" type="checkbox"/>		
14	08/08/18 11:50	General View				Load JPG		<input checked="" type="checkbox"/>		
15	08/08/18 11:50	General View				Load JPG		<input checked="" type="checkbox"/>		
16	08/08/18 11:50	General View				Load JPG		<input checked="" type="checkbox"/>		
17	08/08/18 11:50	General View				Load JPG		<input checked="" type="checkbox"/>		
18	08/08/18 11:50	General View				Load JPG		<input checked="" type="checkbox"/>		
19	08/08/18 11:50	General View				Load JPG		<input checked="" type="checkbox"/>		
20	08/08/18 11:50	General View				Load JPG		<input checked="" type="checkbox"/>		
21	08/08/18 11:50	General View				Load JPG		<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
22	08/08/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
23	08/08/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
24	08/08/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
25	08/08/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
26	08/08/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
27	08/08/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/08/17 16:46	OI GIA REPORT	Load PDF	
2	03/08/17 16:46	ASSIGNMENT	Load PDF	
3	03/08/17 16:46	ESTIMATES	Load PDF	

No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	28/07/17 11:51	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	28/07/17 11:51	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	28/07/17 11:51	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	28/07/17 11:45	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	28/07/17 11:45	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	28/07/17 11:45	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	28/07/17 11:45	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	28/07/17 11:45	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	28/07/17 11:45	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	28/07/17 11:45	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	28/07/17 11:45	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	28/07/17 11:45	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	28/07/17 11:51	Sketch Plan	Load TIF	
2	28/07/17 11:51	Sketch Plan #2	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17015065/T1TBE2

Date: 30/08/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN1607151701
 Claimant Vehicle No: SJP8210E Insured Vehicle No: SJN5935C
 Date of Loss: 28/07/2017 Nature of Claim: TP Claim No: SNM17D04478C02/5

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJP8210E**
 Make & Model: HONDA ODYSSEY, 2.4 (A) Engine No: HIDDEN
 Reg. Date: 01/04/2009 (Man. Year: 2009) Chassis No: JHMRB38309C200694
 Colour: Maroon Odometer: 258670 km
 Engine Capacity: 2354 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: LEAO 6 mm Rear Left Side: LEAO 6 mm
 Front Right Side: LEAO 6 mm Rear Right Side: LEAO 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,688.32	2,087.20	601.12	22.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	1,030.00	570.00	35.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,288.32	3,117.20	1,171.12	27.31
+ GST 7.00/7.00% (S\$)	300.18	218.20	81.98	27.31
Nett Amount (S\$)	4,588.50	3,335.40	1,253.10	27.31

INSPECTION

Date of Assignment: 03/08/2017
 Date Inspected: 14/08/2017 Inspected At: Mova Automotive Pte Ltd (Bukit Merah)
 Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3
 Singapore 159722
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$653.12 NETT)

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Aug 2018)	
Parts: M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for SJP8210E)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH	Cut	958.00 FL	*958.00 FL
2	1		*FRONT HEADLAMP LOWER BRACKET LH	Necessary	68.00 FL	*68.00 FL
3	1		*FRONT BUMPER	Deformed	785.00 FL	*785.00 FL
4	1		*FRONT BUMPER RETAINER LH	Necessary	38.00 FL	*38.00 FL
5	1		*FRONT FOGLAMP COVER LH	Not Necessary	35.00 FL	*- FL
6	1		*FRONT BUMPER UNDERCOVER	* Check	245.30 FL	*- FL
7	10		*FRONT BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
8	1		*FRONT FENDER LH	Bent	682.00 FL	*682.00 FL
9	1		*FRONT FENDER COWLING LH	* Check	158.60 FL	*- FL
10	10		*FRONT FENDER COWLING CLIPS	Necessary	39.00 FL	*39.00 FL
11	1		*FRONT HEADLAMP PANEL LH (NPA)	Repair	0.00 FL	*- FL
12	1		*FRONT FENDER LH (NPA)	Repair	0.00 FL	*- FL
13	1		*FRONT BUMPER SENSOR	* Check	250.00 FS	*- FS
Sub Total (S\$)					3,297.90	2,609.00
- List Item Discount on L Items 20.00/20.00% (S\$)					609.58	521.80
Total Parts (S\$)					2,688.32	2,087.20

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR FRONT HEADLAMP PANEL LH AND FRONT FENDER LH. TO REMOVE AND REPLACE ALL ACCIDENT DAMAGED PARTS AND REALIGN ALL AFFECTED AREA	New	550.00	450.00
2	TO SPRAY PAINT ON ACCIDENT AFFECTED AREA	New	800.00	500.00
3	TO INSPECT FRONT LIGHTING AND WATER LEAKAGE TEST	New	50.00	20.00
4	TO REMOVE AND REFIX FRONT SENSORS AND CHECK WIRING	New	60.00	30.00
5	TO RUST PROOF AFFECTED AREA	New	60.00	30.00
6	TO CHECK WHEEL ALIGNMENT (* Check)	New	80.00	0.00
Gross Labour Cost (\$\$)			1,600.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >