

Surveyor

REF:

CS3/AIG17011797/US62-1

Special Instruction:

R\$3600f

From (Person): Bennie Tan of AVG Date/Time: 4/8/2017

Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant: OwnerSurveyor: MC-LoyWorkshop: BlugelOD/T² Re-inspection: (Evaluation)To Inspect Vehicle No: SBK 8635JInsured: GY918TXat Workshop m/s Blugel AutomotiveTel: 67452088of 1 Kaki Bukit Ave 6 #01-28Policy No: 2100228439-06000Claim No: 08747907THSG

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. 8/6/2017

H.O.D. Enforcement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT

Date/Time: _____ Confirmed with _____ Final Fig _____ days (Red S _____ / _____ %; Original 5 days)Date/Time: 6/12/18 Submit Final Fig 452900, 4 days (Red S 700/-, 19 %; Original 5 days)

Date/Time	Action/Instruction
	SBK 8635J - CS3 / AIG17011797 / TH62
	GY 918TX - IS / INC 19014788 / No
	DLA: 08062017
	SEA: 07072017
18/07/2018	Received email from Irene Lim. owner already sold the vehicle. request Paper Survey
23/07/2018	Bennie request LTA transfer documents and Sales Agreement from Irene Lim
26/09/2018	Confirmed with Irene Lim, she still can't get the document request from Bennie Tan
27/11/2018	Received email from Bennie Tan change to Paper Survey



Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 8 DEC 2018

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date:

14/14/

1) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____

ASS. REC. BY:

PLS

REF

RS/AG/17011797/JH322

Special Instruction

Surveyor

Richard

ASSIGNMENT (Office)

From (Person):

Chia Lee Yung

of

AZU

Date/Time

19/6/2017 11:12am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SRK 8635J

Insured:

679187K

at Workshop m/s

Burrell Automotive

Tel:

61452088

of

1021 Duff Ave 6 #01-28

Policy No:

240228429-6000

Claim No:

0874 790774561

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

8/6/2017

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Sally

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SRK 8635J ^

679187K ^

Survey: 19/6/2017; dismantle: 19/6/2017; after repair: 22/6/2017

Surveyor RICHARD REP:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
QD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: SGK 8635 J Yr Reg: 2007 07/04
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HYUNDAI SONATA cc 1998
 Colour: WHITE AC Insured / Std / Nil / NA
 Sp Reading: 45285 T-Race: Insured / Std / Nil / NA

Eng No:

C/Nr: KMHCU41R6A268570

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60/16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. 08/06 02:25 D.O.I. 19/6 11:30AM

Survey held at: BLUNELL

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time File Pass to:

21/6-19/14

Date/Time File Return to:

2:

Report Format: PRS

Lump Sum / L.B.I: (\$

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

180

20

200

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

TOTAL

Nivitha (LKK Auto)

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Tuesday, 27 November 2018 5:30 PM
To: Tan, Bennie-WZ (Bennie-WZ.Tan@aig.com)
Cc: assignments; SUR
Subject: RE: YOUR REF : 08747907745G-003 *LKK REF: CS3/AIG17011797/ b-1
Attachments: 23112018121300.pdf

Hi Bennie,

Contents noted.

By copy to Assign Team

EYNA.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>
Sent: Tuesday, 27 November 2018 4:56 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: YOUR REF : 08747907745G-003

Hi LKK

Reference to Igene's email below.

Kindly proceed with paper re-inspection.

Best Regards

Bennie Tan

AIG

Senior Complex Claims Examiner

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1718 | Fax +(65) 6835 7416

Bennie-WZ.Tan@aig.com | www.aig.com.sg

From: Igene Lim [mailto:igene.lim@mneduco.com.sg]
Sent: Friday, November 23, 2018 12:15 PM
To: Tan, Bennie-WZ
Cc: Hsiao Tong (LKKAUTO); SUR
Subject: RE: YOUR REF : 0874790774SG-003

WITHOUT PREJUDICE

Our Ref : MN.IG.B1.1711684

Hi Bennie,

Our client has informed us that he had misplaced the documents which you have requested for. That is why it's taking us so long to respond to your request.

Please conduct a paper survey based on our survey report submitted and perhaps with a copy of the Enquire Transfer Fee (copy attached) and let us have your offer for our client's consideration.

With thanks & regards,

Igene

M NEDUMARAN & CO
Advocates & Solicitors
Commissioner for Oaths

Branch Office :
No. 11 Sin Ming Road
#B2-09 (Unit 2), Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : igene.lim@mneduco.com.sg

IMPORTANT NOTE: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) **6509-8480** if you have received this message in error. Thank you.

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>
Sent: Monday, 23 July 2018 5:44 PM
To: Igene Lim <igene.lim@mneduco.com.sg>
Cc: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: YOUR REF : 0874790774SG-003

WITHOUT PREJUDICE
(Save As To Cost)

Hi Igene

We refer to your email below.

Kindly forward us a copy of the LTA transfer documents and Sale Agreement documents for our further consideration as we have requested for re-inspection on your client's vehicle on 04/08/2017.

Best Regards

Bennie Tan
AIG
Senior Complex Claims Examiner
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1718 | Fax +(65) 6835 7416

Bennie-WZ.Tan@aig.com | www.aig.com.sg

This email should not construed as an admission of liability on the part of whomsoever is concerned.

From: Igene Lim [<mailto:igene.lim@mneduco.com.sg>]
Sent: Wednesday, July 18, 2018 10:27 AM
To: Tan, Bennie-WZ
Cc: Hsiao Tong (LKKAUTO); SUR
Subject: YOUR REF : 0874790774SG-003

WITHOUT PREJUDICE

Our Ref : MN.IG.B1.1711684

Hi Bennie,

We refer to your request to conduct a re-inspection on our client's vehicle.

We regret to inform that we are unable to accede to your request as our client had sold his vehicle.

Attached is a copy of the LTA Search conducted on motor vehicle SBK 8635J.

You may wish to instruct your surveyor to conduct a paper re-survey on our client's vehicle.

Alternatively, please let us have your offer (in lieu of re-inspection) for our client's consideration.

With thanks & regards,
Igene Lim
M NEDUMARAN & CO
Advocates & Solicitors
Commissioner for Oaths

Branch Office :

No. 11 Sin Ming Road
#B2-09 (Unit 2), Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : igene.lim@mneduco.com.sg

IMPORTANT NOTE: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509-8480 if you have received this message in error. Thank you.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Enquire Transfer Fee**Vehicle Details**

Vehicle No. : SBK8635J
 Vehicle Type : P10 - Passenger Motor Car
 Vehicle Attachment 1 : No Attachment
 Vehicle Scheme : Normal
 Vehicle Make : HYUNDAI
 Vehicle Model : NFSONATA 2.0
 Chassis No. : KMHEU41BR6A268590
 Propellant : Petrol
 Engine No. : G4KA6386215
 Engine Capacity : 1998 cc
 Maximum Power Output: 106.3 kW (142 bhp)
 Maximum Laden Weight: 2030 kg
 Unladen Weight: 1552 kg
 Year Of Manufacture: 2006
 Original Registration Date: 07 Apr 2007
 Lifespan Expiry Date : -
 COE Category : B - Car (1601cc & above)
 PQP Paid : \$50,347.00
 COE Expiry Date : 31 Mar 2027
 Road Tax Expiry Date : 06 Oct 2017
 Inspection Due Date : 06 Apr 2018
 Intended Transfer Date : 09 Jun 2017
 CO2 Emission: -

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use [Enquire Road Tax Payable](#) for fee(s) payable.
 Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.
Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	11.00	-	11.00
Total Amount Payable :			11.00
You may print this page for reference.			11.00

OK Print

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
 Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.
 Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution
 Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
 Last updated on 28 May 2017 at 12:58 AM

Catherine Chong (LKK Auto)

TP - Ree

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Friday, 4 August, 2017 2:18 PM
To: Tan, Bennie-WZ (Bennie-WZ.Tan@aig.com)
Cc: assignments; SUR; CS A Team
Subject: FW: Our Ref: 0874790774SG-003; RI for SBK8635J
Attachments: PRI photos.pdf; 0874790774SG_2.pdf; 0874790774SG_1.pdf

Importance: High

Hi Bennie,

Thank you for your email.

By copy to Team Assign,

Kindly assist. CS3/AIG17011797/Jh3e2

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Bennie-WZ [mailto:Bennie-WZ.Tan@aig.com]
Sent: Friday, 4 August, 2017 2:11 PM
To: CS A Team <cs-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Our Ref: 0874790774SG-003; RI for SBK8635J
Importance: High

Hi LKK

Referring to above mentioned.

Kindly assist to conduct a reinspection on TP vehicle (SBK8635J) as soon as possible.

Attached is TP documents & PRI photos. Please get back to me upon completion.

Best Regards

Bennie Tan

AIG

Senior Complex Claims Examiner

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1718 | Fax +(65) 6835 7416

Bennie-WZ.Tan@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Catherine Chong (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 18 July, 2018 12:09 PM
To: 'assignments'
Subject: FW: YOUR REF : 0874790774SG-003
Attachments: 18072018101946.pdf

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Igene Lim [mailto:igene.lim@mneduco.com.sg]
Sent: Wednesday, 18 July 2018 10:27 AM
To: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: YOUR REF : 0874790774SG-003

WITHOUT PREJUDICE

Our Ref : MN.IG.B1.1711684

Hi Bennie,

We refer to your request to conduct a re-inspection on our client's vehicle.

We regret to inform that we are unable to accede to your request as our client had sold his vehicle.

Attached is a copy of the LTA Search conducted on motor vehicle SBK 8635J.

You may wish to instruct your surveyor to conduct a paper re-survey on our client's vehicle.

Alternatively, please let us have your offer (in lieu of re-inspection) for our client's consideration.

With thanks & regards,

Igene Lim

M NEDUMARAN & CO

Advocates & Solicitors

Commissioner for Oaths

Branch Office :

No. 11 Sin Ming Road

#B2-09 (Unit 2), Thomson V Two

Singapore 575629

Tel : 6509-8480 / 6509-8481

Fax : 6509-8482

Email : lgene.lim@mneduco.com.sg

IMPORTANT NOTE: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509-8480 if you have received this message in error. Thank you.

Front Portion

NAC	ENG	Item	CON	ACC
1001	99131	Fit Number Plate	BR	✓
1002	991317	Fit Number Plate Base	BR	✓
1003	991389	Fit Number Plate Grommet	BR	✓
1004	991309	Fit Bumper	BR	✓
1005	992341	Fit Bumper Clips	NU	✓
1006	991325	Fit Bumper Brackets		
1007	991402	Fit Bumper Side Retainer		
1008	991433	Fit Bumper Reinforcement		
1009	991315	Fit Bumper-Beam		
1010	991458	Fit Bumper Springs	BR	✓
1011	991427	Fit Bumper Protector		
1012	991420	Fit Bumper Pad		
1013	991363	Fit Bumper Grille		
1014	991321	Fit Bumper Moulding		
1015	991407	Fit Bumper Lower Spoiler		
1016	991438	Fit Bumper Sensor		
1017	991100	Fit LH Bumper Fog Lamp Cover		
1018	991355	Fit RH Bumper Fog Lamp Cover		
1019	991079	Fit LH Bumper Fog Lamp	OR	✓
1020	991080	Fit RH Bumper Fog Lamp	OR	✓
1021	991193	Fit Grille	BR	✓
1022	991328	Fit Grille Emblem	SCA	✓
1023	991799	Fit Grille Chrome Moulding	SCA	✓
1024	991222	Fit Apron Panel		
1025	992013	Fit Support Panel		
1026	992025	Fit Support Panel Top Garnish Cover	BR	✓
1027	992416	Horn		
1028	991277	Fit Brake Panel		
1029	991553	Fit LH Headlamp Assy	OR	✓
1030	991821	Fit RH Headlamp Assy	OR	✓
1031	991038	Fit LH Side Lamp		
1032	991039	Fit RH Side Lamp		
1033	990348	Bonnet	DT	✓
1034	991328	Bonnet Grille Moulding	DT	✓
1035	990287	Bonnet Lock		
1036	990385	Bonnet Insulator		
1037	990273	Bonnet Hinge		
1038	990261	Bonnet Damper		
1039	990305	Bonnet Rubber		
1040	990252	Bonnet Cable		
1041	990311	Bonnet Strand		
1042	990119	Air Con Condenser		
1043	990122	Air Con Fan Assy		
1044	990134	Air Con Suction Pipe (Low Pressure)		
1045	990118	Air Con Suction Hose		
1046	990133	Air Con Discharge Pipe (High Pressure)		
1047	990114	Air Con Discharge Hose		
1048	990149	Air Con Liquid Pipe		
1049	990065	Air Con Receiver Drier		
1050	990111	Air Con Compressor Assy		
1051	990204	Air Con Belt		
1052	990074	Radiator		
1053	992738	Radiator Cowling		
1054	992742	Radiator Fan Assy		
1055	992745	Radiator Fan Clutch		
1056	992758	Radiator Hose Top		
1057	992757	Radiator Hose Bottom		
1058	992741	Radiator Expansion Tank		
1059	990151	Air Duct		
1060	990070	Air Cleaner Assy		
1061	990050	Air Cleaner Hose		
1062	990089	Air Cleaner Resistor		
1063	991713	Fit Exhaust Manifold Cover		
1064	991054	Fit Exhaust Manifold Sensor (Oxygen)		
1065	991714	Fit Exhaust Manifold Pipe		
1066	990219	Battery		
1067	990224	Battery Cover		
1068	990223	Battery Bracket		
1069	990229	Battery Tray		

Rev A/C (Rev 1)

4/16

Author:

RICHARD

23/6

Vol 1: Rev 1 SOR 8635 J

NAC	ENG	Item	CON	ACC
1071	992325	Plate Sm		
1072	994311	Wiper Switch		
1073	993353	Wiper Washer Tank		
1074	992352	Wiper Washer Tank Motor		
1075	990159	Alternator Assy		
1076	990160	Alternator Belt		
1077	991883	Power Steering Pump		
1078	992659	Power Steering Belt		
1079	994431	Power Steering Cooler Pipe		
1080	990592	Power Steering Hose		
1081	990010	ABS Pump Control Unit		
1082	990427	Brake Master Pump Assy		
1083	990403	Brake Booster Pump Assy		
1084	991003	Engine Top Cover		
1085	991011	Engine Under Cover		
1086	992946	Engine Mounting		
1087	990949	Engine Mounting Fit		
1088	992950	Engine Mounting LH		
1089	990952	Engine Mounting RH		
1090	990951	Engine Mounting Rein		
1091	992234	Gear Box Mounting		
1092	991510	Fit LH Chassis Member		
1093	991520	Fit RH Chassis Member		
1094	990728	Fit Vertical Cross Member		
1095	991863	Fit Lower Cross Member		
1096	990070	Fit LH Fender	DT	R
1097	990072	Fit LH Fender Inner Panel		
1098	991347	Fit LH Fender Lamp		
1099	991348	Fit LH Fender Protector		
1100	991740	Fit LH Fender Inner Shield		
1101	992119	Fit LH Mudflap		
1102	992170	Fit LH Wheel Rim		
1103	994025	Fit LH Rim Cover		
1104	990065	Fit LH Tyre		
1105	990071	Fit RH Fender		
1106	991739	Fit RH Fender Inner Panel		
1107	991744	Fit RH Fender Lamp		
1108	991743	Fit RH Fender Protector		
1109	991740	Fit RH Fender Inner Shield		
1110	991834	Fit RH Mudflap		
1111	992087	Fit RH Wheel Rim		
1112	994025	Fit RH Rim Cover		
1113	990065	Fit RH Tyre		
1114	992051	Fit Windscreen Glass		
1115	992117	Fit Windscreen Rubber		
1116	992108	Fit Windscreen Moulding		
1117	992093	Fit Windscreen Sealant		
1118	991015	ERP Bracket		
1119	991023	ERP Link		
1120	992143	Fit Wiper Arm		
1121	992142	Fit Wiper Blade		
1122	992045	Wiper Panel Grommet		
1123	991125	Fit Wall Panel		
1124	990723	Dashboard Assy		
1125	992282	Glove Box Cover		
1126	992287	Glove Box Compartment		
1127	994433	Steering Wheel Airbag		
1128	994435	Steering Wheel Airbag Sensor		
1129	990745	Dashboard Airbag		
1130	990750	Dashboard Airbag Sensor		
1131	990020	Airbag Control Unit		
1132	990854	Fit Driver Seat		
1133	991921	Fit RH Seat Belt Assy		
1134	991809	Fit Passenger Seat		
1135	991812	Fit LH Seat Belt Assy		
1136	990247	Sticker		

2/16/2017

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607195R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17011797/JH3E2
Date: 28/06/2017

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100228429-06000
Claimant Vehicle No :	SBK8635J	Insured Vehicle No :	GY9187X
Date of Loss:	08/06/2017	Nature of Claim:	TP
		Claim No:	0874790774SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBK8635J	Engine No:	G4KA5386215
Make & Model:	HYUNDAI SONATA, 2.0 (A)	Chassis No:	KMHCU41BR6A268590
Reg. Date:	07/04/2007 (Man. Year: 2006)	Odometer:	45285 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60/16	Rear Tyre Size:	215/60/16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	19/06/2017	
Date Inspected:	19/06/2017 Inspected At:	Bluwel Automotive Service Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 (UNIT B) #01-28 Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: Richard Harjanto

Manager: Ashley Chong Chin Yan

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Broken	0.00 F	*.F
2	1		*FRT NUMBER PLATE GARNISH	Broken	0.00 F	*.F
3	1		*FRT BUMPER	Broken	0.00 F	*.F
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*.F
5	1		*FRT BUMPER SPONGE	Broken	0.00 F	*.F
6	1		*FRT LH BUMPER FOG LAMP	Broken	0.00 F	*.F
7	1		*FRT RH BUMPER FOG LAMP	Broken	0.00 F	*.F
8	1		*FRT GRILLE	Broken	0.00 F	*.F
9	1		*FRT GRILLE EMBLEM	Scratched	0.00 F	*.F
10	1		*FRT GRILLE CHROME MOULDING	Scratched	0.00 F	*.F
11	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Broken	0.00 F	*.F
12	1		*FRT LH HEADLAMP ASSY	Broken	0.00 F	*.F
13	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*.F
14	1		*BONNET	Dented	0.00 F	*.F
15	1		*BONNET MOULDING	Dented	0.00 F	*.F
16	1		*FRT LH FENDER	Repair	0.00 F	*.F

F=Franchise part

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

Enquire Vehicle & Owner Information (Vehicle No. SBK8635J As At 01 Dec 2017 / 12:00:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: MN.IG.B1.1711684

Current Owner Details

Owner ID Type: Business

Owner ID: 48044900K

Owner Name: SWEE WATT MOTOR TRADING

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 61

Registered Street Name: UBI AVENUE 2

Registered Unit No.: # 02 - 10

Registered Building Name: AUTOMOBILE MEGAMART

Registered Postal Code: 408898

Current Vehicle Details

Vehicle No.: SBK8635J

Make Description/Model: HYUNDAI / NFSONATA 2.0

Insurance Company Name: NTUC INCOME INS CO-OP LTD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/06/2017 11:03
Date Of Accident	08/06/2017 02:25
Exact Location Of Accident	BEDOK RESERVOIR ROAD CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBK8635J
Insured/Policyholder	
Name Of Registered Owner	ANG THAI WAH
NRIC No	S0829204C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98991852
Alternative Phone No	OFFICE-98991852
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	SONATA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5089505765
Cover Note Number	
Driver	
Name of Driver	ANG KIM KEONG
NRIC No	S8012094Z
Date Of Birth	25/04/1980
Occupation	INDOOR
Date Of Driving Pass	10/02/2017
Driving Experience	0 YEAR AND 3 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98991852
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured RELATIVE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident UNKNOWN - REFER TO SKETCH
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 Have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GY9187X
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver
 NRIC/Passport Number
 Contact Number 98261331
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report accurately the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of the report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if requested.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in the accident shall be collectively referred to as the "Insurers"), the Insurers' law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of enveloped/postal packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



reversed



NICIAO B
CCTV

YOUTUBE

Sketch Plan #2

Describe Circumstances of the Accident

On 8/6/11 at about 2:23 am I, the policyholder of BIK 740 Bedouk Reservoir Road. I was in the car waiting for a lot to park my car. Suddenly car B which was behind of my car, made a reverse and hit the front part of my car (A)

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Insurance Co.

Vehicle NO.



Reporting C/P



Own Damage Claim



Third Party Claim

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/06/2017 12:57
Date Of Accident	08/06/2017 02:40
Exact Location Of Accident	BLK 739 BEDOK RESERVOIR ROAD CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GY9187X
Insured/Policyholder	
Name Of Registered Owner	LEONG GUAN FOOD TRADING PTE LTD
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-81303102
Vehicle Particulars	
Manufacturer	TOYOTA
Model	DYNA
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100228429-06000

Cover Note Number

Driver

Name of Driver	LIU RUNDONG
Passport No/Fin	G2708137T
Address	7 WOODLANDS DRIVE 72 #04-35

General Information of the Accident

Type Of Accident	UNKNOWN - REFER TO SKETCH PLAN
Weather Conditions	CLEAR

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
Number of Passengers (Including Driver)	1

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SBK8635J

Vehicle Make/Model/Colour

Name of Driver

Insurance Company Name

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - (i) I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in the [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in the accident shall be collectively referred to as the "Insurers"), the Insurers' law firm/firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firm/firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firm/firms), which may be sited outside of Singapore, for one or more of the above Purposes.


 Policyholder's Signature / Date & Time

慶源食品貿易私人有限公司
Leong Guan Food Trading Pte. Ltd
 7 Woodlands Link, Singapore 738722
 Tel: 67541531 / 67541532
 Fax: 67541531 / 67541532
 Driver's Signature (If driver is not the policyholder) / Date & Time


 Witnessed by Reporting Centre Personnel

Sketch Plan



Vehicle A: 6Y9187X

Vehicle B: SBK8635J

Sketch Plan Pg. 2

Describe Circumstances of the Accident


on the stated date & time. I was parking & I am doing delivery to stalls. When I came back, I am putting on trolley back into my vehicle. I notices there was no vehicle behind my vehicle. When I reversing my vehicle suddenly vehicle B (SBK8635J) just park behind me & caused me into accident & knocked onto his vehicle. No one was injured in this incident.

Declaration

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

隆源食品貿易私人有限公司
Leong Guan Food Trading Pte. Ltd.
7 Wuxiang Road, Singapore 718722
Tel: 67 416121 Fax: 67561511
Assessor: 67561486-67561512
Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel



HOTLINE TEL: (65) 6419 3338
FAX: (65) 6419 3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 182)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1967
ROAD TRANSPORT ACT, 1967 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1968 (MALAYSIA)

W2.307

COMMERCIAL AUTOPLAN (TPO)

CERTIFICATE NO. 2100225429-06000

OWN DAMAGE EXCESS: NA
WINDSCREEN EXCESS: NA

SUM INSURED: NA
INSURING WITH COMPANIES: NA
GV9167X

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

Leong Guan Food Trading Pte Ltd

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

24 Sep 2016

4) DATE OF EXPIRY OF INSURANCE

23 Sep 2017

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*

Any person who is driving on the insured's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf made driving the Motor Vehicle.

6) LIMITATION AS TO USE*

- 1) Use in connection with the Insured's business.
 - 2) Use for the carriage of passengers (other than for hire or reward) in connection with the Insured's business.
 - 3) Use for social, domestic or pleasure purposes.
- The Policy does not cover:
- a) Use for hire or reward or for racing, speed-making, rally, or speed testing.
 - b) Use while driving a trailer except the towing of any one disabled mechanically propelled vehicle.

APPROVED REPORTING CENTRES / ARE AUTHORIZED REPORTING (FOR CLAIMS-RELATED MATTERS):

1. Carstar/Depot Group - 200 Selegie Rd (Tel: 63637114) 2. Straits - 30 DUNE DRIVE (Tel: 63637777)
3. One Body & Parts (Subsidiary of C&C) - 229 Pandan Gardens (Tel: 63634621)
4. Han Pook Sing Motor - 61 Delfi Lane 12 (Tel: 67479600) 5. Li Hui Hing Motor - 21 Sri Ming Ave (Tel: 64351110)
6. Motor Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723900) 7. Progressive Automotive - 3022A Looi Rd 1 (Tel: 67418238)
8. S&W Motor - 1 Kall Road Ave 8 SRS D (Tel: 67475106)

LOSS OF USE: Not Included

* NAMED DRIVER: NA

HIRE PURCHASE COMPANY: NA
EMPLOYER'S LOAN

*Uninsured rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 182) and Section 85 of the Road Transport Act, 1967 (Malaysia). ARE NOT to be included under these headings.

I / We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 182) and Part IV of the Road Transport Act, 1967 (Malaysia).

Issued in Singapore 26 Aug 2016

AIG Asia Pacific Insurance Pte. Ltd.

500713-000
ANIMA & ASSOCIATES
AIG BUILDING
78 SHENTON WAY #07-16
SINGAPORE 079120
ANSP - NONLIFE

[Signature]

AUTHORIZED REPRESENTATIVE

ORIGINAL

IMP/10

Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Text size + -

Enquire Transfer Fee**Vehicle Details**

Vehicle No.: SBK8635J
 Vehicle Type: P10 - Passenger Motor Car
 Vehicle Attachment 1: No Attachment
 Vehicle Scheme: Normal
 Vehicle Make: HYUNDAI
 Vehicle Model: NISSANATA 2.0
 Chassis No.: KMHEU41BR6A268590
 Propellant: Petrol
 Engine No.: G4KA6386215
 Engine Capacity: 1998 cc
 Maximum Power Output: 106.3 kW (142 bhp)
 Maximum Laden Weight: 2030 kg
 Unladen Weight: 1552 kg
 Year Of Manufacture: 2006
 Original Registration Date: 07 Apr 2007
 Lifespan Expiry Date: -
 COE Category: B - Car (1601cc & above)
 POP Paid: \$50,347.00
 COE Expiry Date: 31 Mar 2027
 Road Tax Expiry Date: 06 Oct 2017
 Inspection Due Date: 06 Apr 2018
 Intended Transfer Date: 09 Jun 2017
 CO2 Emission: -

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use [Enquire Road Tax Payable](#) for fee(s) payable.
 Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	11.00	-	11.00
Total Amount Payable:			11.00

You may print this page for reference.

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
 Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.
 Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution
 Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
 Last updated on 28 May 2017 at 12:58 AM

THE SCHEDULE

Private Car Insurance Policy

This Policy sets out the terms of a contract between NTUC Income Insurance Co-operative Limited (INCOME) and you (the Policyholder named in the schedule to this Policy).
The statements, information and declaration provided by you at the time of proposal shall form the basis of this contract.
We (INCOME) will provide the insurance set out in this Policy in respect of events occurring during the Period of Insurance shown in the Schedule and any further period for which we may accept a renewal premium.

The provision of this insurance is subject to:

1. any Endorsement specified as operative in the Schedule
2. the Conditions and General Exclusions of this Policy, and
3. the payment of the premium specified in the Schedule.

This Policy, the Schedule and the Certificate of Insurance are to be read together as one document.
GST Reg No. M4-0003030-B

Policy Number	: 5089505765	
The Policyholder	: ANG THAI WAH BLK 122 #02-1027 BEDOK RESERVOIR ROAD EUNOS SPRING SINGAPORE 470122	
Period of Insurance	: 04 Apr 2017 To 06 Apr 2018	
Sum Insured	: Market Value of Insured Vehicle at Time of Loss	
Premium (inclusive GST)	: S\$1,567.85	
Interest Insured		
Cover Type	: drive CLASSIC	
Primary Driver	: ANG THAI WAH	
Named Driver (1)	: N/A	
Named Driver (2)	: N/A	
Make/Model	: HYUNDAI/SONATA(NEW)	Capacity : 2000cc
Registration Number	: SBK8635J	Registration Date : 07 Apr 2007
Chassis Number	: KMHEU418R6A268590	Off-peak Car : No
Repair at Owner's Preferred Workshop	: No	Insure with COE : Yes
Excess (Section 1)	: S\$600	NCD Entitlement : 0%
Excess (Section 2)	: N/A	NCD Protection : No
Windscreen Excess	: S\$100	
Additional Excess	: N/A	
Unnamed Driver Excess	: Please refer to Terms and Conditions	
Hire Purchase Company	: SWEE WATT CREDIT PTE LTD	
Optional Cover		
Transport Allowance	: No	
Excess Waiver	: No	

Memo A : N/A

Endorsement Operative : N/A

Agency	: LQ INSURANCE AGENCY PTE LTD (00000613125)
Date of Issue	: 04 Apr 2017 14:05 hrs


DUTY OF DISCLOSURE

We would remind you that you must disclose to us, fully and faithfully, the facts you know or ought to know, otherwise you may not receive any benefit from your Policy.

Signed in Singapore by order of the Board of Directors



Chief Executive



PHOTOCOPY

MC-COY

APPRAISER PTE LTD

No 1 Kaki Bukit Avenue 6 #01 - 28 AutoBay @ Kaki Bukit Singapore 417883 Tel: 6748 6653 Fax: 6747 1017
Registration No: 200723212D

Billing Name & Address

Ang Thai Wah
c/o No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

Invoice No 17029-06/AY

Date 20 Jul 2017

Vehicle No : SBK 8635 J

Model : Hyundai Sonata

Item	Descriptions	Amount S\$
1	Date of inspection : <u>19 Jun 2017</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Develop photographs - Storage of digital photographs - Submission of photographs <u>82</u> copies	
3	Transportation Charges	
4	2nd Inspection	
	Total	<u>\$ 542.00</u>
	SDLS : FIVE HUNDRED AND FORTY-TWO ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Mc-Coy Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O. E

MC-COY

APPRAISER PTE LTD

No 1 Kaki Bukit Avenue 6 #01 - 28 AutoBay @ Kaki Bukit Singapore 417883 Tel: 6748 6633 Fax: 6747 1017
Registration No.: 200723352D

Report Reference : TP / 17029-06/AY / 2017
Date of Report : 20 Jul 2017

Ang Thai Wah
c/o No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 8 Jun 2017

Workshop Address : Bluwel Automotive Service Pte Ltd
No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

As per your instruction dated 19 Jun 2017 with regard to the above matter. We have carried out a physical inspection on the said vehicle SBK 8635 J. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No	: SBK 8635 J	Engine No	: G4KA6386215
Model	: Hyundai Sonata	Mileage	: 45285
Year / Capacity	: 2007/1998	Colour	: White
Chassis No	: KMHEU41BR6A268590		

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT O/S	: 215/60 R16	Yokohama	7.00	mm	Sport
REAR O/S	: 215/60 R16	Yokohama	7.00	mm	Sport
FRONT N/S	: 215/60 R16	Yokohama	7.00	mm	Sport
REAR N/S	: 215/60 R16	Yokohama	7.00	mm	Sport

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the front portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 5 working days to complete.
5. Enclosed number of photograph : 82 copies.
6. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SBK 8635 J
Report No: TP/ 17029-06/AY / 2017

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Bonnet <i>20/84C</i>	Damage	\$ 1001.60	\$ 1001.60
1	Bonnet lock <i>17</i>	Damage	\$ 96.00	\$ 96.00 <i>OK</i>
1	Bonnet chrome moulding <i>CNE</i>	Damage	\$ 72.00	\$ 72.00
2	Front headlamps <i>N/C CNE</i>	Damage <i>7698</i>	\$ 1539.60	\$ 1539.60 <i>12C</i>
1	Front grille c/w logo <i>CNE</i>	Necessary	\$ 99.70	\$ 99.70
1	Front grille chrome moulding (1 set) <i>N/C</i>	Necessary	\$ 92.50	\$ 92.50
1	Front bumper <i>DD</i>	Damage	\$ 468.60	\$ 468.60
1	Front bumper fog lamp <i>CNE</i>	Damage	\$ 135.60	\$ 135.60
1	Front bumper inner sponge <i>To. n</i>	Damage	\$ 92.00	\$ 92.00
1	Front bumper lower grille <i>To. n</i>	Damage	\$ 112.30	\$ 112.30
1	Front bumper reinforcement <i>N</i>	Repair	\$ 438.40	\$ 438.40 <i>OK</i>
2	Front bumper side retainers <i>N/C</i>	Necessary	\$ 60.00	\$ 60.00 <i>OK</i>
1	Front support panel <i>N</i>	Repair	\$ 838.20	\$ 838.20
			\$ 5046.50	\$ 3769.90
	Discount	20.0%	\$ 1009.30	\$ 753.98
			\$ 4037.20	\$ 3015.92
<u>Special Nett Items</u>				
1	Front number plate <i>CNE</i>	Damage	\$ 50.00	\$ 45.00 <i>OK</i>
			\$ 50.00	\$ 45.00

1504.1
232328

Spare Parts Total \$ 4087.20 \$ 3060.92

Vehicle No: SBK 8635 J
Report No: TP/ 17029-06/AY / 2017

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 4087.20	\$ 3060.92
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 50.00	\$ 40.00 30
2	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 950.00	\$ 660.00 600
3	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 950.00	\$ 660.00 600
4	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 120.00	\$ 30.00 ✓
Total		\$ 6157.20	\$ 4450.92

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 3600.00

SDLS: THREE THOUSAND SIX HUNDRED ONLY


Qualified Appraiser

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG17011797/Usbe2-1

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 06-12-2018



ATTN : BENNIE TAN

Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GY 9187X	Veh. Inspected	SBK 8635J
Policy No.	2100228429-06000	Coverage (\$)	0.00
Claim No.	0874790774SG	Excess (\$)	0.00
Assign From	BENNIE TAN	Assign Date	05/08/2017

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI SONATA	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	KMHEU41BR6A268590	Colour	WHITE
Odometer	45285	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
L/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
R/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm
L/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/06/2017	Inspection Date	19/06/2017
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBK 8635J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	DENTED / BUCKLED	1,001.60	1,001.60
1	BONNET LOCK	NOT NECESSARY	96.00	-
1	BONNET CHROME MOULDING	CRACKED	72.00	72.00
2	FRONT HEADLAMPS	N/S CRACKED	1,539.60	769.80
1	FRONT GRILLE C/W LOGO	CRACKED	99.70	99.70
1	SET FRONT GRILLE CHROME MOULDING	NECESSARY	92.50	92.50
1	FRONT BUMPER	DENTED	468.60	468.60
1	FRONT BUMPER FOG LAMP	CRACKED	135.60	135.60
1	FRONT BUMPER INNER SPONGE	TORN	92.00	92.00
1	FRONT BUMPER LOWER GRILLE	TORN	112.30	112.30
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	438.40	-
2	FRONT BUMPER SIDE RETAINERS	NECESSARY	60.00	60.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	838.20	-
LESS 20% DISCOUNT			-1,009.30	-580.82
			4,037.20	2,323.28
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN)	CRACKED	50.00	40.00
			50.00	40.00
LABOUR				
TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.			50.00	30.00
TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WEILD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT AND FRONT SUPPORT PANEL.			950.00	600.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS PREPARE SPRAY SUCH AS MASKING TAPE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		950.00	600.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		120.00	30.00
			2,070.00	1,260.00
GRAND TOTAL			6,157.20	3,623.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,900.00

Report Ref No. CS3/AIG17011797/Usbe2-1

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.