

LD03/2002

ASS. REC. BY:

REF: CS/EG17015347/R1rbet

Special Instructions:

Surveyor

ASSIGNMENT (Office)

From (Person):

Pei Li

of

ERI

Date/Time:

8/8/17

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 2306m

at Workshop m/s

Volkswagen

Insured:

GBB 29214

of

4477 Alexandra Rd

Tel:

Charmaine 6305 7176

Policy No:

Sum Insured:

Claim No:

GBB 29214 / RH / PI

Make of Veh:

Excess:

(Client's Record)

D.O.A.

4/8/17

CA / REV / REP. / REV 24 HRS

wp 10/8/17 @ 1pm

owner waiting

Date/Time:

8/8 @ 3:54pm

Person Contacted:

Charmaine

H.O.D. Endorsement:

Date/Time

Action/Instruction () Estimate

Vehicle IN (OUT)

SKZ 2306m - x

GBB 29214 - x

27/11/17

Confirm \$16890.53, 7 days
Red: \$4972.05, 23%.

Surinder Singh

REF:

1221C

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SK2 2306 M

at Workshop m/s Volkswagen

of Mercedes

Insured: ERHO/TP

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Over under
(Policy Condition) 1 pm

Remark: The veh had commenced its repair at the time of inspection.

Ball. or Market Value: 116K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SK2 2306 M Yr Regn: 2016 / Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Tiguan 1.4 cc 1390

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 29804 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVG 2225N ZHW 035 698

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/R / STD A/Rim or

Tyre Size: F: 255/40 R19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 04/08/10

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear w/

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 10/08/17

Volkswagen (Mercedes)

Date / Time Action / Instruction

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / I.B.I. (\$) 16890.53

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee: 345

Transportation:

\$ + RS. \$

) Photos

) Others

TOTAL

345

RECEIVED 27 NOV 2017



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI17015347/rb	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 08-08-2017	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBB 2921U	Veh. Inspected	SKZ 2306M
Policy No.		Coverage (\$)	0.00
Claim No.	GBB2921U/TH/pl	Excess (\$)	0.00
Assign From	PEI LI	Assign Date	08/08/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/08/2017	Inspection Date	
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Ashley Chong (LKK Auto)

From: Ashley Chong (LKK Auto) <admin-d@lkkauto.com>
Sent: Tuesday, 8 August, 2017 4:36 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'; 'SUR'
Subject: RE: GBB2921U / TP : SKZ2306M/LKK / DOA : 04.08.2017

Dear Pei Li,

Thank you for the assignment.

Vehicle currently not in workshop, repairer will arrange.

Best Regards,

Veron | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Tuesday, 8 August, 2017 3:15 PM
To: 'admin-d@lkkauto.com'
Subject: OI : GBB2921U / TP : SKZ2306M/LKK / DOA : 04.08.2017

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **VOLKSWAGEN GROUP SINGAPORE LTD**

ADDRESS : 247 ALEXANDRA ROAD
SINGAPORE 159934

PERSON TO CONTACT : CHARMAINE KONG @ 6305 7176

ERGO OFFICER-IN-CHARGE : SHAWN LEE

Note: To survey on DIRECT SETTLEMENT basis. Please inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Best Regards

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
DID: 65 6829 9194
Fax: 65 6829 9247
Website: www.ergo.com.sg



Have you tried our new travel insurance product yet?
TravelProtect comes with comprehensive benefits at some of the most affordable prices available in the market.

ERGO
TravelProtect

your Global Safety Net

TravelProtect is underwritten by ERGO Insurance Pte. Ltd.



TravelProtect is underwritten by ERGO Insurance Pte. Ltd.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GBB2921U/TH/pl
Our Ref: CS/EG117015347/R1rb

The Motor Claims Department
ERGO Insurance Pte Ltd

Without Prejudice

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. SKZ 2306M .

We thank you for the instruction on 08/08/2017.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 10/08/2017 at the premises of M/s VOLKSWAGEN GROUP SINGAPORE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 20,345.05 .
Revised Estimate Amount	: S\$ 12,740.58 .
"Check" Items Amount	: S\$ 3,711.63 .
Market Value	: S\$.
LTA Reimbursement Value	: S\$.
Nett Value	: S\$.

Description of Damage:
The vehicle sustained damages
at the rear n/s portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully

RASUL
Automotive Assessor

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Monday, August 28, 2017 6:33 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: GBB2921U / TP : SKZ2306M/LKK / DOA : 04.08.2017
Attachments: SKZ 2306M.pdf

Dear Pei Li,

Enclosed preliminary revised for SKZ 2306M

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, August 08, 2017 4:36 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: GBB2921U / TP : SKZ2306M/LKK / DOA : 04.08.2017

Dear Pei Li,

Thank you for the assignment.

Vehicle currently not in workshop, repairer will arrange.

Best Regards,

Veron | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Tuesday, 8 August, 2017 3:15 PM
To: 'admin-d@lkkauto.com'
Subject: OI : GBB2921U / TP : SKZ2306M/LKK / DOA : 04.08.2017

Janice Lee (LKKAUTO)

From: Ong, Germaine (VWG Singapore) <Germaine.ong@vw.com.sg>
Sent: Monday, August 21, 2017 4:54 PM
To: Shu Pei (LKKAUTO); Rasul (LKKAUTO); Janice Lee (LKKAUTO)
Cc: CS A Team; Admin A; Cheong, Pearlyn (VWG Singapore); Kong, Charmaine (VWG Singapore); Wong, Mei (VWG Singapore); Leong, Kevin (VWG Singapore); Oh, Aik Seong (VWG Singapore); SUR; Foo, John (VWG Singapore)
Subject: RE: SKZ2306M - SUPPLEMENTARY

Dear LKK

Please note that we have send these on Wednesday and till date there is no reply from your end

Please note that due to these delay we are not processing the job.. LOU should the insurance don't pay to us, we will use these email as a proof.


Germaine Ong
Insurance Service Advisor
Aftersales

Volkswagen Centre Singapore
17 TUAS AVE 9

HP: +65 92361588

Germaine.ong@vw.com.sg
<http://www.vw.com.sg>

*Pis proceed with the repair while
we ~~verify~~ verify on the price
of the 2 pcs of moulding.*



From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Monday, 21 August, 2017 2:32 PM
To: Ong, Germaine (VWG Singapore); Rasul (LKKAUTO); Janice Lee (LKKAUTO)
Cc: CS A Team; Admin A; Cheong, Pearlyn (VWG Singapore); Kong, Charmaine (VWG Singapore); Wong, Mei (VWG Singapore); Leong, Kevin (VWG Singapore); Oh, Aik Seong (VWG Singapore); SUR
Subject: RE: SKZ2306M - SUPPLEMENTARY

Hi Germaine,

Thank you for your email.

Hi Rasul / Janice,

FYI. CS/EG117015347/R1rb

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ong, Germaine (VWG Singapore) [<mailto:Germaine.ong@vw.com.sg>]

Sent: Monday, 21 August, 2017 2:27 PM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>

Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Cheong, Pearlyn (VWG Singapore) <Pearlyn.cheong@vw.com.sg>; Kong, Charmaine (VWG Singapore) <charmaine.kong@vw.com.sg>; Wong, Meiy (VWG Singapore) <meiy.wong@vw.com.sg>; Leong, Kevin (VWG Singapore) <kevin.leong@vw.com.sg>; Oh, Aik Seong (VWG Singapore) <Aikseong.Oh@vw.com.sg>

Subject: RE: SKZ2306M - SUPPLEMENTARY

Dear Rasul & LKK


Please revert on the supplementary

Germaine Ong
Insurance Service Advisor
Aftersales

Volkswagen Centre Singapore
17 TUAS AVE 9

HP: +65 92361588

Germaine.ong@vw.com.sg
<http://www.vw.com.sg>



From: Ong, Germaine (VWG Singapore)

Sent: Wednesday, 16 August, 2017 6:40 PM

To: Rasul (LKK Auto) <Rasul@lkkauto.com> (Rasul@lkkauto.com)

Cc: cs-a@lkkauto.com; Admin A; Cheong, Pearlyn (VWG Singapore); Kong, Charmaine (VWG Singapore); Wong, Meiy (VWG Singapore); Leong, Kevin (VWG Singapore); Oh, Aik Seong (VWG Singapore)

Subject: SKZ2306M - SUPPLEMENTARY

Dear Rasul

Please see attached supplementary


Please revert.

Germaine Ong
Insurance Service Advisor
Aftersales

Volkswagen Centre Singapore
17 TUAS AVE 9

HP: +65 92361588

Germaine.ong@vw.com.sg
<http://www.vw.com.sg>



ERGO

Date: 08.08.2017
Our Reference: GBB 2921U/RH/pl
Your Reference: SKZ 2306M

Sent via Fax
or
Email

To: VOLKSWAGEN GROUP SINGAPORE

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SKZ 2306M
Insured's Vehicle: GBB 2921U
Date Of Accident: 04.08.2017


We acknowledge receipt of your request for PRS on: 07.08.2017

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

☐	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐	Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐	Our Insured's driver has not reported the accident to us to date.
☒	Others: We write to confirm our agreement to have a direct settlement of this claim with quantum to be agreed. OFFICER-IN-CHARGE ROHAINI

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

NTUC vs ERGO
Direct Out

MNII17103385-01 / NTUC Income Insurance Co-operative Ltd - HQ
ENTRY DATE & TIME: 04/08/2017 20:10

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/08/2017 20:10
Date Of Accident	04/08/2017 06:45
Exact Location Of Accident	JUNCTION OF ANG MO KIO AVE 6 AND ANG MO KIO AVE 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ2306M
Insured/Policyholder	
Name Of Registered Owner	LOW KIM HUAT
NRIC No	S7011221C
Email Address	NAMEISBEEBEE@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96709933
Alternative Phone No	OFFICE-96709933

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	VOLKSWAGEN TIGUAN 1.4CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5087257588
Cover Note Number	

Driver

Name of Driver	TAN BEE BEE
NRIC No	S7201417J
Date Of Birth	05/01/1972
Occupation	INDOOR
Date Of Driving Pass	21/08/1995
Driving Experience	21 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	+65-84996653
Fax Number	
Contact Number	
EMail Address	NAMEISBEEBEE@YAHOO.COM.SG

Address	60 SPRINGLEAF CRESCENT
Postcode	786384
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB2921U
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	WEE HOCK ANN
NRIC/Passport Number	S6848234H
Contact Number	83824218
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Details of Witness

Name	
Phone Number	
Email Address	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

TAN BEE BEE
04/08/2017 12:30

Policyholder's Signature / Date &
Time

Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

Accident Sketch Plan

Sketch Plan

The sketch plan is based on the closest scenario.
Please refer to "Circumstances of the Accident".



Describe Circumstances of the Accident

BLACK CAR : GBB2921U

WHITE CAR : SKZ2306M

DESCRIPTION :

I was on Ang Mo Kio Ave 6 intending to turn right into Ang Mo Kio Ave 5. It was a cross junction and I was on the right most lane which was a right-turn only lane. The front vehicle was slowing down and I did the same as well. Suddenly, GBB2921U collided onto the rear of my car.

Declaration

I/We declare the foregoing particulars are true in every respect.

TAN BEE BEE
04/08/2017 12:38

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Addendum Sheet

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE : Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:


Original Report No : MNII17103385 Vehicle Registration No : SKZ2306M
Name(as shown in NRIC) : TAN BEE BEE
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
NRIC/Passport No : S7201417J
Address : 60 SPRINGLEAF CRESCENT
Contact (Tel) : _____ (H/P) : 84996653
(Email) : NAMEISBEEBEE@YAHOO.COM.SG
Date of Accident : 04.08.2017 Time of Accident : 06:45HRS
Place of Accident : JUNCTION OF ANG MO KIO AVE 6 AND ANG MO KIO AVE 5
Insurance Company : INCOME

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

TO CHANGE AND ATTACHED THE CORRECT SKETCH PLAN

Vivake Menon
Manager
OrangForce



Signature of Vehicle Owner / Driver

Date: 7/8/17

10 Anson Road #06-16 International Plaza Singapore 079903 Phone : + 65 6224 0010 Fax : +65 6224 0030
Operating Hours : Monday to Friday 9am to 5pm

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 1221C

Vehicle Details

Vehicle No.: SKZ2306M

Vehicle to be Exported: No

Intended De-registration
Date: 11 Aug 2017

Vehicle Make: VOLKSWAGEN

Vehicle Model: TIGUAN 1.4 TSI AT BMT 5N22QY

Primary Colour: White

Manufacturing Year: 2015

Engine No.: CTH233106

Chassis No.: WVGZZZ5NZGW035698

Maximum Power
Output: 118.0 kW (158 bhp)

Open Market Value: \$26,384.00

Original Registration
Date: 14 Jan 2016

First Registration Date: 14 Jan 2016

Transfer Count: 0

Actual ARF Paid: \$28,938.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 13 Jan 2026

PARF Rebate Amount: \$21,703.00

Intended COE Rebate Details

COE Expiry Date: 13 Jan 2026

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$54,920.00

COE Rebate Amount: \$46,253.00

Total Rebate Amount: \$67,956.00

The information contained herein is correct as at 11 Aug 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 30 Jul 2017 at 12:58 AM

PDI TUAS

PDI TUAS

LOW KIM HUAT
60 SPRINGLEAF CRESCENT
Singapore, 786384
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV032426
Quote No. SER/QUO/1701291
QuoteDate 07/08/17
Salesperson Delsie Ong
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	TiguanGP 1.4 TSI 118 DSG6 RECY	15,399	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SKZ2306M	WVGZZZ5NZGW035698	14/01/16	Delsie Ong
Engine Code	Labor Type	Engine No.	Model Code
	1H	CTH 233106	5N22QY

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	5	UNIT		2520 4200.00
P B&P ALEX LABOUR	RE+REINSTALLED REARWINDS	1	UNIT		840.00
P B&P ALEX LABOUR	TRANSFER BOOT LID PARTS	1	UNIT		420 840.00
P B&P ALEX LABOUR	RE+REINSTALLED REAR LUAGG	1	UNIT		420 840.00
P B&P ALEX PAINT	SPRAY PAINT	5	UNIT		2400 4000.00
P B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	pcs		80.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00
	COMPULSORY TO DO AFTER AC				
P B&P MECH	ELECT WIRING & MECH COMPO	1	Time Un		280.00
	Nett				
	Sum Labor				11,560.00
P 1Q0853675Q GQF	NAME PLATE TSI	1	Pieces		66.73
P 1T0919133C 9B9	PARKING SENSOR O RING	4	Pieces		3.00
P 3AF943021A	LED LICENCE PLATE LIGHT	2	Pieces		253.04
P 5M0827505E 9B9	REAR BOOT LOCK	1	Pieces		168.61
P 5N0807305	RR BUMPER REINFORCEMENT	1	Pieces		554.95
P 5N0807393E	BUMPER BRACKET LHS	1	Pieces		27.46
	Use Predecessor 5N0807393B				
P 5N0807394D	BUMPER BRACKET RHS	1	Pieces		27.46
	Use Predecessor 5N0807394B				
Sum carried forward					12,661.25

Payments to:

- BBN: - Acc.-No.:

PDI TUAS

Phone No.

Fax No.

E-Mail

PDI TUAS

LOW KIM HUAT
60 SPRINGLEAF CRESCENT
Singapore, 786384
Singapore

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV032426
Quote No. SER/QUO/1701291
QuoteDate 07/08/17
Salesperson Delsie Ong
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	TiguanGP 1.4 TSI 118 DSG6 RECY	15,399	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SKZ2306M	WVGZZZ5NZGW035698	14/01/16	Delsie Ong
Engine Code	Labor Type	Engine No.	Model Code
	1H	CTH 233106	5N22QY

Continued

12,661.25

P 5N0807421G GRU	REAR BUMPER	1 Pieces	1,313.65
P 5N0807521AFGRU	REAR LOWER SPOILER	1 Pieces	459.45
P 5N0807568 2Z0	LOWER SPOILER INSERT	1 Pieces	509.38
	Use Predecessor 5N0807568		
P 5N0827025G	REAR LID	1 Pieces	1,486.27
	Use Predecessor 5N0827025F		
P 5N0827335J	REAR LID ADAPTER	1 Pieces	101.19
P 5N0827566AL	PUSH BUTTON W ELECTRONIC	1 Pieces	1,172.74
P 5N0827705A	REAR BOOT SEAL	1 Pieces	252.81
P 5N0827933B GRU	REAR UPPER SPOILER	1 Pieces	1,087.00
P 5N0853630 FXC	VW SIGN	1 Pieces	92.25
P 5N0853675M CWB	NAME PLATE BLUE MOTION	1 Pieces	80.28
P 5N0853687B 739	NAME PLATE TIGUAN	1 Pieces	104.56
P 5N0919397	SENSOR BRACKET	1 Pieces	15.42
P 5N0919397	SENSOR BRACKET	1 Pieces	15.42
P 5N0919491D	SENSOR BRACKET	2 Pieces	34.10
P 5N0941071	REVERSING LIGHT LHS	1 Pieces	87.64
P 5N0941072	REVERSING LIGHT RHS	1 Pieces	87.64
P 5N0945105	REFELCTOR REAR LH	1 Pieces	77.74
P 5N0945106	REFELCTOR REAR RH	1 Pieces	77.74
P 6Q6827517B	BOOT LOCK CATCH PLATE	1 Pieces	34.95

Sum carried forward

19,751.48

Payments to:

- BBN: - Acc.-No.:

Rasul
 H/ 90010068
 7⁸ days
 10/08/17 P1310

PDI TUAS

Phone No.
 Fax No.
 E-Mail

VAT Registration No. M20098505-2
 Tax No. 199101494Z

PDI TUAS

LOW KIM HUAT
 60 SPRINGLEAF CRESCENT
 Singapore, 786384
 Singapore

Service Quote

Customer No. CV032426
 Quote No. SER/QUO/1701291
 QuoteDate 07/08/17
 Salesperson Delsie Ong
 Page 3

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	TiguanGP 1.4 TSI 118 DSG6 RECY	15,399	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SKZ2306M	WVGZZZ5NZGW035698	14/01/16	Delsie Ong
Engine Code	Labor Type	Engine No.	Model Code
	1H	CTH 233106	5N22QY

Continued

19,751.48

Part No.	Description	Quantity	Unit Price	Total Price
P D 002000A2	CLEANER	1 Pieces	147.85	147.85
P D 004660M2	2K GLUE	1 Pieces	183.87	183.87
P D 00920002	PRIMER	1 Pieces	32.19	32.19
P D 00950025	APPLICATOR	2 Pieces	22.38	44.76
P D 180KU2A1	2KADHESIVE	1 Pieces	103.66	103.66
P D 181802M1	ACTIVATOR	1 Pieces	29.46	29.46
P D 822150A1	BONDAGENT	1 Pieces	74.16	74.16
	Sum Item			8,785.05

Sum Labor	11,560.00
Sum Item	8,785.05

Total	SGD	20,345.05
7% GST	20,345.05	1,424.15
Total SGD Incl. GST		21,769.20

21,862.58

Explanations

P = Proportionately Charged

Payment Terms

No Credit

Payments to:

- BBN - Acc. No.:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Supplementary or Omitted List



VEHICLE NUMBER: **SKZ2306M**
 MODEL **TIGUAN 1.4**

CLAIMS DETAILS

	LABOUR DESCRIPTION		AMOUNT
Total			\$0.00

No.	Item No.	Description	Qty	UNIT PRICE	Amount
1	5N0853817E 9B9	REAR LHS FENDER MOULDING	1	707.77	707.77 <i>cut</i> ✓
2	5N0853818E 9B9	REAR RHS FENDER MOULDING	1	707.77	707.77 <i>cut</i> ✓
3	N 10621301	NUT	6	2.14	12.84 <i>Nec</i> ✓
4	5N0863459 82V	END PANEL TRIM COVER	1	86.13	86.13 <i>Cross</i> ✓
5	5N0863988A 82V	NUT	2	1.51	3.02 <i>Nec</i> ✓
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
			TOTAL:		\$1,517.53

(A)

Total Labour & Parts

\$1,517.53

Survey By

Service Order Confirmation

SERVICE ORDER NO.: 17IP2209

CUSTOMER NO.: CV032426

CUSTOMER NAME: LOW KIM HUAT

TELEPHONE NO.:

ADDRESS: 60 SPRINGLEAF CRESCENT
Singapore

VEH No.: SKZ2306M

Order Date: 10/08/17

Reg Date: 14/01/16 KM: 15,399

VIN NO.: WVGZZZ5N2GW035698 ENGINE NO:

SA: Cheong Pearlyn

MODEL: TiguanGP 1.4 TSI 118 DSG6 REC MODEL NO.: 5N22QY

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	480		480 ✓
2	B&P MECH ELECT WIRING & MECH COMPONENT CHECK NETT	1	TU	280		280 ✓
3	B&P ALEX LABOUR LABOUR	3	UNIT	840		2,520 ✓
4	B&P ALEX PAINT SPRAY PAINT	3	UNIT	800		2,400 ✓
5	B&P ALEX LABOUR RE+REINSTALLED REARWINDSCREEN	1	UNIT	840		840 ✓
6	B&P ALEX LABOUR TRANSFER BOOT LID PARTS	0.5	UNIT	840		420 ✓
7	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
8	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
9	B&P NUMBER PLATE ✓ B&P NUMBER PLATE -NETT	1	ST	80		80 ✓
Item						
10	5N0807421G GRU REAR BUMPER	1	PCS	1,313.65		1,313.65 ✓
11	5N0807521AFGRU REAR LOWER SPOILER	1	PCS	459.45		459.45 ✓
12	5N0807393E BUMPER BRACKET LHS	1	PCS	27.46		27.46 ✓
13	5N0919397 SENSOR BRACKET	1	PCS	15.42		15.42 ✓
14	5N0919491D SENSOR BRACKET	2	PCS	17.05		34.10 ✓
15	5N0919397 SENSOR BRACKET	1	PCS	15.42		15.42 ✓
16	1T0919133C 9B9 PARKING SENSOR O RING	4	PCS	0.75		3.00 ✓
17	D 822150A1 BONDAGENT	1	PCS	74.16		74.16 ✓
18	D 180KU2A1 2KADHESIVE	1	PCS	103.66		103.66 ✓
19	5N0827025G REAR LID	1	PCS	1,486.27		1,486.27 ✓
20	5N0827933B GRU REAR UPPER SPOILER	1	PCS	1,087.00		1,087.00 ✓
21	5M0827505E 9B9 REAR BOOT LOCK	1	PCS	168.61		168.61 ✓
22	5N0827705A REAR BOOT SEAL	1	PCS	252.81		252.81 ✓
23	5N0853687B 739 NAME PLATE TIGUAN	1	PCS	104.56		104.56 ✓
24	5N0853675M CWB NAME PLATE BLUE MOTION	1	PCS	80.28		80.28 ✓
25	1Q0853675Q GQF NAME PLATE TSI	1	PCS	66.73		66.73 ✓

Service Order Confirmation

SERVICE ORDER NO: 17IP2209

CUSTOMER NO.: CV032426

CUSTOMER NAME: LOW KIM HUAT

TELEPHONE NO.:

ADDRESS: 60 SPRINGLEAF CRESCENT

Singapore

VEH No.: SKZ2306M

Order Date: 10/08/17

Reg Date: 14/01/16

KM: 15,399

SA: Cheong Pearlyn

VIN NO.: WVGZZZ5NZGW035698

ENGINE NO:

MODEL: TiguanGP 1.4 TSI 118 DSG6 REC MODEL NO.: 5N22QY

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
26	5N0853630 FXC VW SIGN	1	PCS	92.25		92.25 ✓
27	D 004660M2 2K GLUE	1	PCS	183.87		183.87 ✓
28	D 00950025 APPLICATOR	2	PCS	11.19		22.38 ✓
29	D 00920002 PRIMER	1	PCS	32.19		32.19 ✓
30	D 002000A2 CLEANER	1	PCS	147.85		147.85 ✓
31	D 181802M1 ACTIVATOR	1	PCS	29.46		29.46 ✓
32	5N0853817E 9B9 REAR LHS FENDER MOULDING	1	PCS	707.77		707.77 ✓
33	5N0853818E 9B9 REAR RHS FENDER MOULDING	1	PCS	707.77		707.77 ✓
34	5N0807305 RR BUMPER REINFORCEMENT	1	PCS	554.95		554.95 ✓
35	N 10621301 NUT	6	PCS	2.14		12.84 ✓
36	5N0807568 2Z0 LOWER SPOILER INSERT	1	PCS	509.38		509.38 ✓
37	5N0827566AL PUSH BUTTON W ELECTRONIC	1	PCS	1,172.74		1,172.74 ✓
38	5N0827335J REAR LID ADAPTER	1	PCS	101.19		101.19 ✓
39	3AF943021A LED LICENCE PLATE LIGHT	1	PCS	126.52		126.52 ✓
40	5N0841071 REVERSING LIGHT LHS	1	PCS	87.64		87.64 ✓
41	5N0863459 82V END PANEL TRIM COVER	1	PCS	86.13		86.13 ✓
42	5N0863988A 82V NUT	2	PCS	1.51		3.02 <i>nel</i>

Remarks : DIRECT SETTLEMENT WITH ERGO INSURANCE

DATE OF ACCIDENT: 04/08/2017

SURVEYED BY: RASUL LKK

3RD PARTY VEHICLE NUMBER: GBB2921U

ERGO CLAIMS OFFICER: PEI LI 88299194

Service Order Confirmation

SERVICE ORDER NO: 17IP2209

CUSTOMER NO.: CV032426

CUSTOMER NAME: LOW KIM HUAT

TELEPHONE NO.:

ADDRESS: 60 SPRINGLEAF CRESCENT

Singapore

VEH No.: SKZ2306M

Order Date: 10/08/17

Reg Date: 14/01/16 KM: 15,399

VIN NO.: WVGZZZ5NZGW035698 ENGINE NO: SA: Cheong Pearlyn

MODEL: TiguanGP 1.4 TSI 118 DSG6 REC MODEL NO.: 5N22QY

No.	DESCRIPTION	QTY	UQM	UNIT PRICE	DISC %	AMOUNT
-----	-------------	-----	-----	------------	--------	--------

TOTAL	16,890.53
GST AMOUNT	1,182.34
TOTAL AMOUNT	18,072.87

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

To: Rasul (LKK Auto)

Cc: Kong, Charmaine (VWG Singapore) (Charmaine.Kong@vw.com.sg); Wong, Mei (VWG Singapore) (meiy.wong@vw.com.sg); Leong, Kevin (VWG Singapore); Foo, John (VWG Singapore) (John.Foo@vw.com.sg)

Subject: SKK2306M - FINALISE

Dear Rasul,

Please confirmed

COR \$ 16180.53 before GST.

Best regards,

Pearlyn Cheong
Service Advisor
Aftersales Body & Paint Department

Volkswagen Group Singapore (Alexandra)
247 Alexandra Road
Singapore 159934

Direct line: +65 6305 7288
Mobile : +65 9236 1336
Main line: +65 6305 7299
Main Fax: +65 6474 3643
pearlyn.cheong@vw.com.sg
<http://www.vw.com.sg>





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD 5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Ref : CS/EGI17015347/R1rbe2 Date : 27-11-2017 Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBB 2921U	Veh. Inspected	SKZ 2306M
Policy No.		Coverage (\$)	0.00
Claim No.	GBB2921U/TH/pl	Excess (\$)	0.00
Assign From	PEI LI	Assign Date	08/08/2017
2. Vehicle Particulars & Condition			
Make & Model	VOLKSWAGEN TIGUAN 1.4	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WVGZZZ5NZGW035698	Colour	WHITE
Odometer	29804	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	255/40 R19	DUNLOP	6 mm
L/H Front Tyre	255/40 R19	DUNLOP	6 mm
R/H Rear Tyre	255/40 R19	DUNLOP	6 mm
L/H Rear Tyre	255/40 R19	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/08/2017	Inspection Date	10/08/2017
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 2306M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	NAME PLATE TSI (SN)	NECESSARY	66.73	66.73
4	PARKING SENSOR O RING (SN)	NECESSARY	3.00	3.00
2	LED LICENCE PLATE LIGHT (SN)	CRACKED	253.04	126.52
1	REAR BOOT LOCK (SN)	JAMMED	168.61	168.61
1	RR BUMPER REINFORCEMENT (SN)	BENT	554.95	554.95
1	BUMPER BRACKET LHS (SN)	NECESSARY	27.46	27.46
1	BUMPER BRACKET RHS (SN)	NOT NECESSARY	27.46	-
1	REAR BUMPER (SN)	DEFORMED	1,313.65	1,313.65
1	REAR LOWER SPOILER (SN)	CUT	459.45	459.45
1	LOWER SPOILER INSERT (SN)	CRACKED	509.38	509.38
1	REAR LID (SN)	BENT	1,486.27	1,486.27
1	REAR LID ADAPTER (SN)	CRACKED	101.19	101.19
1	PUSH BUTTON W ELECTRONIC (SN)	DISTORTED	1,172.74	1,172.74
1	REAR BOOT SEAL (SN)	NECESSARY	252.81	252.81
1	REAR UPPER SPOILER (SN)	DEFORMED	1,087.00	1,087.00
1	VW SIGN (SN)	NECESSARY	92.25	92.25
1	NAME PLATE BLUE MOTION (SN)	NECESSARY	80.28	80.28
1	NAME PLATE TIGUAN (SN)	NECESSARY	104.56	104.56
1	SENSOR BRACKET (SN)	NECESSARY	15.42	15.42
1	SENSOR BRACKET (SN)	NECESSARY	15.42	15.42
2	SENSOR BRACKET (SN)	NECESSARY	34.10	34.10
1	REVERSING LIGHT LHS (SN)	CRACKED	87.64	87.64
1	REVERSING LIGHT RHS (SN)	SERVICEABLE	87.64	-
1	REFLECTOR REAR LH (SN)	SERVICEABLE	77.74	-
1	REFLECTOR REAR RH (SN)	SERVICEABLE	77.74	-
1	BOOT LOCK CATCH PLATE (SN)	SERVICEABLE	34.95	-
1	CLEANER (SN)	NECESSARY	147.85	147.85
1	2K GLUE (SN)	NECESSARY	183.87	183.87
1	PRIMER (SN)	NECESSARY	32.19	32.19
2	APPLICATOR (SN)	NECESSARY	22.38	22.38
1	2KADHESIVE (SN)	NECESSARY	103.66	103.66

Report Ref No. CS/EGI17015347/R1rbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ACTIVATOR (SN)	NECESSARY	29.46	29.46
1	BONDAGENT (SN)	NECESSARY	74.16	74.16
1	REAR LHS FENDER MOULDING (ADDITIONAL) (SN)	CUT	707.77	707.77
1	REAR RHS FENDER MOULDING (ADDITIONAL) (SN)	CUT	707.77	707.77
6	NUT @\$2.14 (ADDITIONAL) (SN)	NECESSARY	12.84	12.84
1	END PANEL TRIM COVER (ADDITIONAL) (SN)	CRACKED	86.13	86.13
2	NUT @\$1.51 (ADDITIONAL) (SN)	NECESSARY	3.02	3.02
			10,302.58	9,870.53
	LABOUR			
	LABOUR.		4,200.00	2,520.00
	RE+REINSTALLED REARWINDS.		840.00	840.00
	TRANSFER BOOT LID PARTS.		840.00	420.00
	RE+REINSTALLED REAR LUAGG.	NOT NECESSARY	840.00	-
	SPRAY PAINT.		4,000.00	2,400.00
	B&P NUMBER PLATE.		80.00	80.00
	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC.		480.00	480.00
	ELECT WIRING & MECH COMPO.		280.00	280.00
			11,560.00	7,020.00
	GRAND TOTAL		21,862.58	16,890.53
	RECOMMENDED COST OF REPAIRS			16,890.53

Report Ref No. CS/EGI17015347/R1rbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.