

ASS. REC. BY:

Special Instruction:

X69Q

ASSIGNMENT (Office)

From (Person): Jasmine of MS/GI Date/Time: 4/8/17

Estimated Cost: _____ Bill to: _____

OD / (TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SLM 4531 Y Insured: YP 7074/K

at Workshop m/s World Auto Tel: 6451 3933

of 47 jalan Pemimpin.

Policy No: _____ Claim No: 523430

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 3/8/11

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

[illegible]

AS REC. BY: XHLREF: MC11**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s World Auto
of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time : Action / Instruction

Veh No: SLM 4531YYr Regn: 30 Mar 2017Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

HybridMake: Toyota Priusc.c. 1798Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 26637

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTD KB 3FU 503554714Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65 R15R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mm

D.O.A. _____

D.O.I. 04-08-17Survey held at W/S

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) 15/3/2017

Date/Time, File Return to?

2) _____



: Prel. Report



: Final Report

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$ _____)



: Interview (\$ _____)



: Tech. Invs (\$ _____)



: Weekend (\$ _____)

Survey Fee: 200

Transportation: _____

S + RS. SI _____

Photos 10

Others _____

TOTAL

210Report Format: OTPLump Sum / I.B.I. (\$ 2852.48)

RECEIVED

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Ref.	Adj. Submitted	Inv. Action	Status
Main	03 Aug 2017		10 Aug 2017 11:52 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CO-AL ENGINEERING INTEGRATED SERVICES PTE LTD , Co. Reg. No.: 201103683W		
Main Claimant:	LCRF PTE LTD , Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLM4531Y	Date of Loss:	03/08/2017 08:00 - :59
Claim Type:	TP / 525430	Policy/Cover Note No.:	A28991749 (Comprehensive) Coverage: 18/07/2017 - 17/07/2018
Vehicle Reg. No. (Insured):	YP7074K	Policy No. (Claimant):	
	Excess:		
Repairer:	World Auto Pte Ltd - Halcyon 2 (HQ) 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG, 577200 Bishan - Tel: 6451 3933 <i>6362 1796</i> <i>NOI</i> <i>Kranji, 10897000</i>		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550] <i>04181</i>		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 11/08/2017]		
Driver/Custodian (Insured):	ISLAM NAZMUL () , NRIC: G8334255U, Tel: +6584612966		
Adj. Asg. Remarks:	Third Party Pre-Repair Survey		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Date Due	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

10/8/17

by point

survey - 4/8/17

Denise Tay (LKKAUTO)

From: tggtan@worldauto.com.sg
Sent: Thursday, 15 March 2018 3:43 PM
To: Denise Tay (LKKAUTO)
Subject: RE: SLM 4531Y Our ref: TP/1328-17

Hi Denise

Confirmed herein at \$2852.48/5 days.

Thanks n Rdgs
Sophia Tan
World Auto Pte Ltd (Kranji)

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Thursday, 15 March 2018 11:59 AM
To: tggtan@worldauto.com.sg; Jas Khine (LKKAUTO) <jaskhine@lkkauto.com>
Cc: CS A Team <cs-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: SLM 4531Y & slj 1250T Our ref: TP/1328 & 1332-17

Dear Sophia,

Enclosed finalise,

Part by part \$2852.48, 5days

Please confirm

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 14 March 2018 1:14 PM
To: tggtan@worldauto.com.sg; Jas Khine (LKKAUTO) <jaskhine@lkkauto.com>
Cc: CS A Team <cs-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: SLM 4531Y & slj 1250T Our ref: TP/1328 & 1332-17

Dear Sophia,

SLM 4531Y – I will check and get back to you

SLJ 1250T – Handler: Jas
CC4/AXA17015155/Gya3s2 – please follow up as below

MSG

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/08/2017 13:48
Date Of Accident	03/08/2017 08:45
Exact Location Of Accident	LOYANG AVE SLIP ROAD TO TPE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM4531Y
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS-1.8 HYBRID CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995174
Cover Note Number	

Driver

Name of Driver	TAN SOO HOW
NRIC No	S1100338I
Date Of Birth	23/04/1955
Occupation	OUTDOOR
Date Of Driving Pass	25/10/1977
Driving Experience	39 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96117721
Fax Number	
Contact Number	
E Mail Address	NOEMAIL

Address
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP7074K
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness



Name
Phone Number
Email Address


Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:
(i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Sketch Plan #2

Describe Circumstances of the Accident

after coming out of slip road from highway onto the straight road,
 I drove (YB 204 K) but my car on the left hand side
 Accident happened at 0842 hr on 23/03/2017

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

08/04/2017 10:47 hr

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

WORLD AUTO PTE LTD

47 Jalan, Pemimpin #01-02/03
Halcyon 2, S'pore 577200
Tel No. : 6451 3933 Fax No. : 6455 7576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

IN

MSIG INSURANCE (SINGAPORE) PTE LTD

Estimate : ES00287

Attention : Motor Claim Department
Contact : 68277888

Date : 03/08/2017
Vehicle Num. : SLM 4531Y
Make/Model : TOYOTA PRIUS HYBRID 1.8 CVT
Chassis/Eng# :
Accident Date : 03/08/2017
Claim No. :
Reference :
Policy No. :

S/N Quantity Particular Unit Price Amount S\$

1.	1	LIST ITEMS :		
2.	1	REAR RH FENDER(PIRUS) <i>Blue</i>	817.50	<i>1723.3</i>
3.	1	REAR BUMPER (PIRUS) <i>Be</i>	423.90	
4.	1	REAR RH LAMP LEN AND BODY (TOYOTA PIRUS) <i>Get</i>	481.90	
		REAR RH COMBINATION LAMP (TOYOTA PIRUS) <i>X NN</i>	433.70	
List TotalS\$:			2,157.00	
25.00% Discount S\$:			539.25	
			1,617.75	<i>1292.48</i>

LABOUR :		
To labour charge for removing R/R fender and rear bumper out to facilitate repairs and replacement of damaged parts	1,200.00	<i>800</i>
To respray rear bumper and R/R fender	1,000.00	<i>400</i>
To deactivate and activate high voltage hybrid battery as a requirement for safety precautions	380.00	<i>240</i>
To conduct a standard of operating procedure post repairs diagnostic scan test as a requirement for hybrid cars upon completion of collision repairs	380.00	<i>2120</i>
Labour Total S\$:	2,960.00	<i>2852.48</i>

E. & O.E. Total S\$: 4,577.75

for WORLD AUTO PTE LTD

5 Days.
P/P before paint photos
Gua Qiang - 82880282
04/8/17

WORLD AUTO CONSULTANTS hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Aug 2017		10 Aug 2017 11:52 Edit Adj Rpt	S\$2,852.47 Edit Estimates	S\$2,852.47 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	CO-AL ENGINEERING INTEGRATED SERVICES PTE LTD, Co. Reg. No.: 201103683W								
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Vehicle Reg. No.:	SLM4531Y	Date of Loss:	03/08/2017 08:00 - :59						
Claim Type:	TP / 525430	Policy/Cover Note No.:	A28991749 (Comprehensive) Coverage: 18/07/2017 - 17/07/2018						
Vehicle Reg. No. (Insured):	YP7074K	Policy No. (Claimant):							
		Excess:							
Repairer:	World Auto Pte Ltd - Halcyon 2 (HQ) 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG, 577200 Bishan - Tel: 6451 3933								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 11/08/2017]								
Driver/Custodian (Insured):	ISLAM NAZMUL (), NRIC: G8334255U, Tel: +6584612966								
Adj Asg. Remarks:	Third Party Pre-Repair Survey								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLM4531Y (525430)**
[YP7074K]
TP
LCRF PTE LTD
Aug 3 2017 8:00AM
[CO-AL ENGINEERING INTEGRATED SERVICES PTE LTD]
World Auto Pte Ltd - Halcyon 2

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View In Browser](#)

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	10/08/17 11:29	Accident Statement From: SC - Reg. No: YP7074K, Claimant: CO-AL ENGINEERING INTEGRATED SERVICES PTE LTD		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/03/18 09:28	General View		Load JPG	<input checked="" type="checkbox"/>
2	15/03/18 09:28	General View		Load JPG	<input checked="" type="checkbox"/>
3	15/03/18 09:28	General View		Load JPG	<input checked="" type="checkbox"/>
4	15/03/18 09:28	General View		Load JPG	<input checked="" type="checkbox"/>
5	15/03/18 09:28	General View		Load JPG	<input checked="" type="checkbox"/>
6	15/03/18 09:28	General View		Load JPG	<input checked="" type="checkbox"/>
7	15/03/18 09:28	General View		Load JPG	<input checked="" type="checkbox"/>
8	15/03/18 09:28	General View		Load JPG	<input checked="" type="checkbox"/>
9	15/03/18 09:28	General View		Load JPG	<input checked="" type="checkbox"/>
10	15/03/18 09:28	General View		Load JPG	<input checked="" type="checkbox"/>
11	15/03/18 09:28	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
12	15/03/18 09:28	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	10/08/17 11:29	TP PRI		Load PDF	
2	10/08/17 11:29	E-FILE REPORT (SLM4531Y) From: SC - Reg. No: YP7074K, Claimant: CO-AL ENGINEERING INTEGRATED SERVICES PTE LTD		Load PDF	
3	10/08/17 11:37	EMAIL TP ON OUR AGREED COMMON SURVEYOR - LKK		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^
v

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17015401/GTBE2

Date: 19/03/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28991749

Claimant Vehicle No : SLM4531Y

Insured Vehicle No : YP7074K

Date of Loss: 03/08/2017

Nature of Claim: TP

Claim No: 525430

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM4531Y

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZRS031855

Reg. Date: 30/03/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU503554714

Colour: Silver

Odometer: 26637 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 8 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

<u>COST OF CLAIMS</u>	<u>Repairer's</u>	<u>Adjuster's</u>	<u>Difference</u>	<u>Diff %</u>
Parts	1,617.75	1,292.47	325.28	20.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,960.00	1,560.00	1,400.00	47.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,577.75	2,852.47	1,725.28	37.69
+ GST 7.00/7.00% (S\$)	320.44	199.67	120.77	37.69
Nett Amount (S\$)	4,898.19	3,052.14	1,846.05	37.69

INSPECTION

Date of Assignment: 10/08/2017

Date Inspected: 04/08/2017 Inspected At:

World Auto Pte Ltd - Halcyon 2 (HQ)
47 JALAN PEMIMPIN #01-02/03
HALCYON 2 BLDG
Singapore 577200

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Mar 2018)
Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLM4531Y)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH FENDER (PRIUS)	Buckled	817.50 FL	*817.50 FL
2	1		*REAR BUMPER (PRIUS)	Deformed	423.90 FL	*423.90 FL
3	1		*REAR RH LAMP LEN AND BODY (TOYOTA PRIUS)	Cut	481.90 FL	*481.90 FL
4	1		*REAR RH COMBINATION LAMP (TOYOTA PRIUS)	Not Necessary	433.70 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,157.00	1,723.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	539.25	430.83
Total Parts (\$\$)	1,617.75	1,292.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO LABOUR CHARGE FOR REMOVING R/R FENDER AND REAR BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	1,200.00	800.00
2	TO RESPRAY REAR BUMPER AND R/R FENDER	New	1,000.00	400.00
3	TO DEACTIVATE AND ACTIVATE HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENT FOR SAFETY PRECAUTIONS	New	380.00	240.00
4	TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST AS A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS	New	380.00	120.00
Gross Labour Cost (S\$)			2,960.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >