

ASS. REC. BY:

REF:

CS / M36717015630 / 11/10/2017

Special Instruction:

SUBMITTER:
MURMAN

ASSIGNMENT (Office)

From (Person):

JOSEPH LIM

of

MSLH

Estimated Cost:

Date/Time:

14/08/2017 3:21pm

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

G8E 8185Y

Insured:

at Workshop m/s

Sng Ah Tee

Tel:

6268 6183

of

Blk 3 Pioneer Rd North #01-18

Policy No:

828871336 MKF

Claim No:

525340

Sum Insured:

Excess:

\$ 750.00

Make of Veh:

(Client's Record)

D.O.A.

02082017

CA / REV / REP. / REV 24 HRS

Date/Time:

14/08/2017 3:35pm

Person Contacted:

Janice

H.O.D. Endorsement:

Vehicle

IN / OUT

Date/Time

Action/Instruction (✓) Estimate

G8E 8185Y - X

Surveyor Tan Jiah
Maimun

REF: mslh

ASSIGNMENT

From: _____ Date: 15082017

Estimated Cost: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: G8E 8185Y

at Workshop m/s Sng Ah Tee

of Blk 3 Pioneer Rd North #01-18

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$750.00

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: Morning
The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$75k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 1-B-1 % 3 Val.: Yes or No

CA / ☒ REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: G8E 8185Y Yr Regn: 2016 March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Cabstar c.c. 2953

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 35496 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1SC2F2Z08583J5

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/80R15

R: 155/R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Survey held at Sng Ah Tee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 6/6 mm

L/Bal. 6/6 mm

D.O.I. 15/8/17 @ 1730

Date / Time Action / Instruction-

16/8/17 mandate approved by Huey Ni.

16/8/17 @ 5.40 pm spoke to Janice, CA, Ex: 750

27/8/17 mandate approved by Huey Ni.

27/8/17 confirmed P/P \$11821.70 with Sharon.

Cred: 2349.06, 1777.

RECEIVED 27 NOV 2017

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 10

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

S + RS _____

Photos _____

Others _____

Report Format: _____

Lump Sum / ☒ (\$ 11821.70)

TOTAL

300

10

310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17015630/T1gb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 14-08-2017



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	GBE 8185Y
Policy No.	B28871336MKF	Coverage (\$)	0.00
Claim No.	525340	Excess (\$)	750.00
Assign From	MERIMEN (JOSLIN LIM)	Assign Date	14/08/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	02/08/2017	Inspection Date	14/08/2017
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Aug 2017 10:54 Sendback Est	10 Aug 2017 11:50 S\$11,308.50	14 Aug 2017 15:21 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: ACP METAL FINISHING PTE LTD, Co. Reg. No.: 198802408E									
Vehicle Reg. No.: GBE8185Y		Date of Loss: 02/08/2017 17:00 - :59							
Claim Type: OD / 525340		Policy/Cover Note No.: B28871336MKF (Comprehensive) Coverage: 01/01/2017 - 31/12/2017							
		Excess: S\$750.00							
Repairer: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2017]									
Driver/Custodian: LOH THIAM HWEE (51 / Male), NRIC: S1743477B, Tel: +6596664449									
Adj Asg. Remarks: PLEASE SURVEY AND REVERT.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	03 Aug 2017 16:34	Cim Veh Model Changed	(205033) NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A).	[I] Joslin Lim
2	03 Aug 2017 16:34	Cim Created	Reg No: GBE8185Y. Policy No: B28871336MKF. Acct Date: 2017/08/02. Claim Type: SC. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Ins.Status => Notification. Created from SAS:MSAT17102356	[I] Joslin Lim
3	10 Aug 2017 10:53	Cim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] Samantha Tan
4	10 Aug 2017 11:50	Cim Submitted	11308.50.	[R] Samantha Tan
5	14 Aug 2017 11:41	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):	[I] Eng Huey Ni
6	14 Aug 2017 11:41	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/08/15	[I] Eng Huey Ni
7	14 Aug 2017 11:41	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Eng Huey Ni
8	14 Aug 2017 11:45	Assignment 1st Accessed		[A] Ho Pei Fang
9	14 Aug 2017 15:20	Adj Assignment Cancelled	I.H.S. APPT FULL	[I] Joslin Lim
10	14 Aug 2017 15:20	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Joslin Lim
11	14 Aug 2017 15:21	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):PLEASE SURVEY AND REVERT.	[I] Joslin Lim
12	14 Aug 2017 15:21	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/08/15	[I] Joslin Lim
13	14 Aug 2017 15:21	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Joslin Lim
14	14 Aug 2017 15:31	Assignment 1st Accessed		[A] CATHERINE CHONG KAI LING
15	14 Aug 2017 15:45	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] CATHERINE CHONG KAI LING
16	16 Aug 2017 11:12	Adj Rpt Initiated		[A] LOW AI PHING
17	16 Aug 2017 13:56	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/09/13	[A] LOW AI PHING
18	16 Aug 2017 13:56	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/09/13	[A] LOW AI PHING
19	16 Aug 2017 13:57	Adj Mandate Request	Cur.Reg:11068.50:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.	[A] LOW AI PHING
20	16 Aug 2017 17:35	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/09/13	[I] Eng Huey Ni
21	16 Aug 2017 17:35	Adj Mandate Set	Approved:6393.50.	[I] Eng Huey Ni
22	23 Aug 2017 17:48	Cim Supp Created (S:630733)		[R] Janice Chang
23	23 Aug 2017 17:52	Cim Submitted (S:630733)	2685.20.	[R] Janice Chang
24	23 Aug 2017 17:52	Adj Co Assigned (S:630733)	LKK Auto Consultants Pte Ltd (HQ):	[I] Merimen Administrator
25	24 Aug 2017 10:30	Supp Combined (S:630733)		[A] LOW AI PHING
26	24 Nov 2017 14:34	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/09/13	[A] LOW AI PHING
27	24 Nov 2017 14:37	Adj Mandate Request	Cur.Reg:11821.70:Damages Consistent. Repair cost economical. Please assist check item and supplementary approval.	[A] LOW AI PHING
28	27 Nov 2017 09:40	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/09/13. Mandate Remarks: approved mandate \$11821.70 (including check items \$2843.50) before excess \$750	[I] Eng Huey Ni
29	27 Nov 2017 09:40	Adj Mandate Set	Approved:11821.70:approved mandate \$11821.70 (including check items \$2843.50) before excess \$750	[I] Eng Huey Ni

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1548008	10/08/2017 10:53	Motor	Sng Ah Tee Motor & Panel Service Pte Ltd (HQ)	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	GBE8185Y		xx.xx
1553766	16/08/2017 11:12	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBE8185Y		10.70

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	03 Aug 2017 16:34	Cim Veh Model Changed	(205033) NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A).	[I] Joslin Lim
2	03 Aug 2017 16:34	Cim Created	Reg No: GBE8185Y. Policy No: B28871336MKF. Acct Date: 2017/08/02. Claim Type: SC. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Ins.Status => Notification. Created from SAS:MSAT17102356	[I] Joslin Lim
3	10 Aug 2017 10:53	Cim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[I] Samantha Tan
4	10 Aug 2017 11:50	Cim Submitted	11308.50.	[R] Samantha Tan
5	14 Aug 2017 11:41	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):	[I] Eng Huey Ni
6	14 Aug 2017 11:41	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/08/15	[I] Eng Huey Ni
7	14 Aug 2017 11:41	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Eng Huey Ni
8	14 Aug 2017 11:45	Assignment 1st Accessed		[A] Ho Pei Fang
9	14 Aug 2017 15:20	Adj Assignment Cancelled	I.H.S. APPT FULL	[I] Joslin Lim
10	14 Aug 2017 15:20	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Joslin Lim
11	14 Aug 2017 15:21	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):PLEASE SURVEY AND REVERT.	[I] Joslin Lim
12	14 Aug 2017 15:21	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/08/15	[I] Joslin Lim
13	14 Aug 2017 15:21	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Joslin Lim
14	14 Aug 2017 15:31	Assignment 1st Accessed		[A] CATHERINE CHONG KAI LING
15	14 Aug 2017 15:45	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] CATHERINE CHONG KAI LING
16	16 Aug 2017 11:12	Adj Rpt Initiated		[A] LOW AI PHING
17	16 Aug 2017 13:56	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/09/13	[A] LOW AI PHING
18	16 Aug 2017 13:56	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/09/13	[A] LOW AI PHING
19	16 Aug 2017 13:57	Adj Mandate Request	Cur.Req:11068.50:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.	[A] LOW AI PHING
20	16 Aug 2017 17:35	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/09/13	[I] Eng Huey Ni
21	16 Aug 2017 17:35	Adj Mandate Set	Approved:6393.50.	[I] Eng Huey Ni

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1548008	10/08/2017 10:53	Motor	Sng Ah Tee Motor & Panel Service Pte Ltd (HQ)	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	GBE8185Y		xx.xx
1553766	16/08/2017 11:12	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBE8185Y		10.70

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 24 Nov 2017

Preliminary Advice

Vehicle No	: GBE8185Y	Accident Date	: 02/08/2017
Make	: NISSAN CABSTAR	Policy No.	: B28871336MKF
Assignment Date	: 14/08/2017	Excess	: S\$750.00
Date of Inspection	: 15/08/2017	Est. Duration of Repair	: 10.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,170.76	(with Supplementary \$2,645.20)
Revised Amount	:S\$	11,821.70	(with Supplementary \$2,645.20 + Check item \$2,843.50)
Check Items (Estimated)	:S\$	-	
Total	:S\$	11,821.70	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	75,000.00
COE / PARF Rebate	:S\$	35,232.00
Salvage Value	:S\$	
Margin for Repair	:S\$	39,768.00

Remarks

(X) The vehicle is economical for repair.

Please assist check item and supplementary approval.

() The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 16 Aug 2017

Preliminary Advice

Vehicle No	: GBE8185Y	Accident Date	: 02/08/2017
Make	: NISSAN CABSTAR	Policy No.	: B28871336MKF
Assignment Date	: 14/08/2017	Excess	: S\$750.00
Date of Inspection	: 15/08/2017	Est. Duration of Repair	: 10.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,308.50
Revised Amount	:S\$	6,393.50
Check Items (Estimated)	:S\$	4,675.00
Total	:S\$	11,068.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	75,000.00
COE / PARF Rebate	:S\$	35,232.00
Salvage Value	:S\$	
Margin for Repair	:S\$	39,768.00

Remarks

(X) The vehicle is economical for repair.

We have not authorise repair.

() The above survey was conducted on a 'without prejudice' basis.

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 2408E

Vehicle Details

Vehicle No.: GBE8185Y

Vehicle to be Exported: No

Intended De-registration
Date: 16 Aug 2017

Vehicle Make: NISSAN

Vehicle Model: CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5

Primary Colour: White

Manufacturing Year: 2016

Engine No.: ZD30009794N

Chassis No.: JN1SC2F24Z0858335

Maximum Power
Output: -

Open Market Value: \$24,867.00

Original Registration
Date: 31 Mar 2016

First Registration Date: 31 Mar 2016

Transfer Count: 0

Actual ARF Paid: \$1,244.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry
Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Mar 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$40,868.00

COE Rebate Amount: \$35,232.00

Total Rebate Amount: \$35,232.00

The information contained herein is correct as at 16 Aug 2017



Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 13 Aug 2017 at 12:41 AM

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 2408E

Vehicle Details

Vehicle No.: GBE8185Y

Vehicle to be
Exported: No

Intended De-
registration Date: 31 Aug 2017

Vehicle Make: NISSAN

Vehicle Model: CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5

Primary Colour: White

Manufacturing
Year: 2016

Engine No.: ZD30009794N

Chassis No.: JN1SC2F24Z0858335

Maximum Power
Output: -

Open Market
Value: \$24,867.00

Original
Registration Date: 31 Mar 2016

First Registration
Date: 31 Mar 2016

Transfer Count: 0

Actual ARF Paid: \$1,244.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility -

Expiry Date:

PARF Rebate
Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Mar 2026

COE Category: C - Goods Vehicle & Bus

COE
Period(Years): 10

PQP Paid: \$40,868.00

COE Rebate
Amount: \$35,067.00

**Total Rebate
Amount: \$35,067.00**

The information contained herein is correct as at 04 Aug 2017

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/08/2017 10:13
Date Of Accident	02/08/2017 17:00
Exact Location Of Accident	TUAS RD SLIP RD TO JLN AHMAD IBRAHIM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE8185Y
Insured/Policyholder	
Name Of Registered Owner	ACP METAL FINISHING PTE LTD
Co Reg No	198802408E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90020698
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	NISSAN
Model	CABSTAR-3.0 5M/T ABS 2DR 2WD EURO 5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B28871336MKF
Cover Note Number	
Driver	
Name of Driver	LOH THIAM HWEE
NRIC No	S1743477B
Date Of Birth	22/03/1966
Occupation	OUTDOOR
Date Of Driving Pass	16/06/1986
Driving Experience	31 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96664449
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address BLK 808C CHOA CHU KANG AVE 1 #05-590
 Postcode 683808
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 02/08/2017 AT AROUND 1700HRS, I WAS TRAVELLING FROM PIE(TUAS) EXIT TO TUAS RD TOWARDS JLN AHMAD IBRAHIM. WHILE DRIVING AT THE SLIP RD, I CHECK THE BLIND SPOT ON THE RIGHT AND WHEN I TURN BACK MY VIEW TO FRONT I NOTICE THAT VEHICLE B HAD STOP HIS VEHICLE. I APPLIED MY BRAKE BUT STILL COULD NOT STOP IN TIME AND COLLIDED ONTO HIS REAR RIGHT PORTION.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XB8695Y
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver JIANG HONG TAO
 NRIC/Passport Number G8065355M
 Contact Number 98609777
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA) I understand, acknowledge, agree and consent that :
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed By Reporting Centre Personnel

Sketch Plan



Sketch Plan Pg. 2

Describe Circumstances of the Accident

Refer to Accident Circumstances

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

<input checked="" type="checkbox"/> Claim own policy
<input type="checkbox"/> Claim third party
<input type="checkbox"/> Claim OD / TP at other workshop
<input type="checkbox"/> For record purpose
Policy No. <u>13 58671226</u>
Insurer <u>MPL</u> Veh. No. <u>BE 81854</u>

Witnessed by Reporting Centre Personnel

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No.200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type: OD (OWN DAMAGE)
Policy No: B28871336MKF
Vehicle Reg. No.: GBE8185Y
Driver Age/Info: 51 / MALE
TP Injury Involved? NO
Insured/Claimant: ACP METAL FINISHING PTE LTD
Driver: LOH THIAM HWEE

Ref. No:
Date of Loss: 02/08/2017
Driveable?
Party At Fault: UNKNOWN
Third Party Involved? YES

Make/Model: NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD
EURO 5 (A)
Vehicle Colour: BLACK
Engine No: ZD30009794N
Odometer: 5 KM

Vehicle Reg. Date: 31/03/2016
Chassis No: JN1SC2F24Z0858335

Paint Type:
Total Loss? NO
Est. Duration of Repair (day) 14

Tan Jiah 97495749
Exp 8750
10 days
17/8/17
15/8/17
Re-spray before paint

Description of Accident/Loss

ON 02/08/2017 AT AROUND 1700HRS, I WAS TRAVELLING FROM PIE(TUAS) EXIT TO TUAS RD TOWARDS JLN AHMAD IBRAHIM. WHILE DRIVING AT THE SLIP RD, I CHECK THE BLIND SPOT ON THE RIGHT AND WHEN I TURN BACK MY VIEW TO FRONT I NOTICE THAT VEHICLE B HAD STOP HIS VEHICLE. I APPLIED MY BRAKE BUT STILL COULD NOT STOP IN TIME AND COLLIDED ONTO HIS REAR RIGHT PORTION.

Present Location: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS

	Amount
Parts	8,418.50
Miscellaneous Items	0.00
Labour	2,890.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	11,308.50
- Excess (S\$)	750.00
(S\$)	10,558.50
+ GST 7.00% (S\$)	739.10
Nett Amount (S\$)	11,297.60

This claim is handled by: SAMANTHA TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 10 Aug 2017)
Parts: N/A NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBE8185Y)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER WITH REINFORCEMENT	0.00	0.00	*450.00 F
2	1		*FRONT GRILLE	0.00	0.00	*260.00 F
3	8		*FRONT GRILLE CLIP	0.00	0.00	*40.00 F
4	1		*FRONT GRILLE EMBLEM	0.00	0.00	*55.00 F
5	1		*FRONT CORNER PANEL	0.00	0.00	*185.00 F
6	1		*FRONT CORNER PANEL CABSTAR LOGO	0.00	0.00	*25.00 F
7	1		*FRONT WIPER PANEL	0.00	0.00	*320.00 F
8	2		*FRONT HEADLAMP	0.00	0.00	*540.00 F
9	1		*FRONT HEADLAMP LOWER GARNISH LH	0.00	0.00	*55.00 F
10	1		*FRONT SIDE MIRROR ARM COVER LH	0.00	0.00	*85.00 F
11	1		*FRONT SIDE MIRROR ARM TOP COVER LH	0.00	0.00	*15.00 F
12	1		*FRONT SIDE MIRROR ROUND CAP LH LH	0.00	0.00	*135.00 F
13	1		*FRONT SIDE MIRROR ARM LH	0.00	0.00	*680.00 F
14	1		*FRONT DOOR LH	0.00	0.00	*75.00 F
15	1		*FRONT DOOR INNER WEATHER STRIPS LH	0.00	0.00	*380.00 F
16	1		*FRONT DOOR GLASS LH	0.00	0.00	*80.00 F
17	1		*FRONT DOOR REGULATOR LH	0.00	0.00	*110.00 F
18	1		*FRONT DOOR LOCK LH	0.00	0.00	*80.00 F
19	2		*FRONT DOOR HINGE	0.00	0.00	*75.00 F
20	1		*FRONT DOOR WEATHER STRIPE LH	0.00	0.00	*650.00 F
21	1		*FRONT WINDSCREEN	0	0.00	*26.00 FS
22	1		*ERP BRACKET	0	0.00	*40.00 FS
23	1		*FRONT WINDSCREEN SEALANT	0.00	0.00	*90.00 F
24	1		*FRONT WINDSCREEN INNER GARNISH LH	0.00	0.00	*200.00 F
25	1		*FRONT WINDSCREEN MOULDING	0.00	0.00	*900.00 F
26	1		*FRONT DASHBOARD	0.00	0.00	*125.00 F
27	1		*FRONT DASHBOARD LOWER COVER LH	0.00	0.00	*500.00 F
28	1		*FRONT DASHBOARD SUPPORT BEAM LH	0.00	0.00	*450.00 F
29	1		*AIR CON BLOWER ASSY	0.00	0.00	*1,000.00 F
30	1		*HEATER BLOWER ASSY	0	0.00	*20.00 FS
31	1		*ROC STICKER			

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	7,661.00
+ Margin on L,N Items 10.00% (\$\$)	757.50
Total Parts (\$\$)	8,418.50

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

254350

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE & REFIX ROOFLING	New	160 100.00
2	TO REMOVE & REFIX FRONT DASHBOARD	New	✓ 180.00
3	TO REMOVE & REFIX FRONT WINDSCREEN	New	✓ 120.00
4	TO TRANSFER FRONT DOOR GLASS	New	✓ 60.00
5	TO REFILL AIR CON GAS	New	✓ 100.00
6	TO CHECK WIRING	New	✓ 30.00
7	TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS	New	1100 1,200.00
8	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	1000 1,100.00
Gross Labour Cost (\$\$)			2,890.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 23 Aug 2017)**Parts:** N/A NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for GBE8185Y)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT PANEL <i>bt</i>	0.00	0.00	✓*600.00 F
2	1		*FRT SIDE MIRROR LH <i>cut</i>	0.00	0.00	✓*80.00 F
3	1		*FRT WIPER PANEL TOP SEAL <i>cut</i>	0.00	0.00	✓*32.00 F
4	1		*FUSE BOX HOUSING <i>cut</i>	0.00	0.00	✓*300.00 F
5	1		*FRT WIPER LINKAGE ASSY <i>bt</i>	0.00	0.00	✓*75.00 F
6	1		*FRT WIPER MOTOR <i>dd</i>	0.00	0.00	✓*320.00 F
7	1		*FRT DOOR CHECKER(LH) <i>bb</i>	0.00	0.00	✓*35.00 F
8	1		*FRT DASHBOARD LH <i>de</i>	0.00	0.00	✓*320.00 F
9	1		*FRT DASHBOARD RH <i>de</i>	0.00	0.00	✓*320.00 F
10	1		*FRT DASHBOARD TOP FRONT COVER <i>cut</i>	0.00	0.00	✓*250.00 F

F=Franchise part.

Sub Total (S\$)

2,332.00

+ Margin on L,N Items 10.00% (S\$)

233.20

Total Parts (S\$)

2,565.20

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE & REFIT FRT SEAT & UPHOLSTERY <i>photo (A)</i>	New	<i>80</i> 120.00
Gross Labour Cost (S\$)			120.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 10 Aug 2017)

Parts: N/A NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBE8185Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER WITH REINFORCEMENT	0.00	0.00	*450.00 F
2	1		*FRONT GRILLE	0.00	0.00	*260.00 F
3	8		*FRONT GRILLE CLIP	0.00	0.00	*40.00 F
4	1		*FRONT GRILLE EMBLEM	0.00	0.00	*55.00 F
5	1		*FRONT CORNER PANEL	0.00	0.00	*185.00 F
6	1		*FRONT CORNER PANEL CABSTAR LOGO	0.00	0.00	*25.00 F
7	1		*FRONT WIPER PANEL	0.00	0.00	*320.00 F
8	2		*FRONT HEADLAMP LH-RH ?	0.00	0.00	*540.00 F
9	1		*FRONT HEADLAMP LOWER GARNISH LH	0.00	0.00	*55.00 F
10	1		*FRONT SIDE MIRROR ARM COVER LH	0.00	0.00	*85.00 F
11	1		*FRONT SIDE MIRROR ARM TOP COVER LH	0.00	0.00	*15.00 F
12	1		*FRONT SIDE MIRROR ROUND CAP LH LH	0.00	0.00	*15.00 F
13	1		*FRONT SIDE MIRROR ARM LH	0.00	0.00	*135.00 F
14	1		*FRONT DOOR LH	0.00	0.00	*680.00 F
15	1		*FRONT DOOR INNER WEATHER STRIPS LH	0.00	0.00	*75.00 F
16	1		*FRONT DOOR GLASS LH	0.00	0.00	*380.00 F
17	1		*FRONT DOOR REGULATOR LH	0.00	0.00	*80.00 F
18	1		*FRONT DOOR LOCK LH	0.00	0.00	*110.00 F
19	2		*FRONT DOOR HINGE	0.00	0.00	*80.00 F
20	1		*FRONT DOOR WEATHER STRIPE LH	0.00	0.00	*75.00 F
21	1		*FRONT WINDSCREEN	0.00	0.00	*650.00 F
22	1		*ERP BRACKET	0	0.00	*26.00 FS
23	1		*FRONT WINDSCREEN SEALANT	0	0.00	*40.00 FS
24	1		*FRONT WINDSCREEN INNER GARNISH LH	0.00	0.00	*90.00 F
25	1		*FRONT WINDSCREEN MOULDING	0.00	0.00	*200.00 F
26	1		*FRONT DASHBOARD	0.00	0.00	*900.00 F
27	1		*FRONT DASHBOARD LOWER COVER LH	0.00	0.00	*125.00 F
28	1		*FRONT DASHBOARD SUPPORT BEAM	0.00	0.00	*500.00 F
29	1		*AIR CON BLOWER ASSY	0.00	0.00	*450.00 F
30	1		*HEATER BLOWER ASSY	0.00	0.00	*1,000.00 F
31	1		*ROC STICKER	0	0.00	*20.00 FS

F=Franchise part, S=SpclNett.

Sub Total (\$\$)	7,661.00
+ Margin on L,N Items 10.00% (\$\$)	757.50
Total Parts (\$\$)	8,418.50

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS