

ASS. REC. BY:

REF:

CS/FCL17015644/Arbna

Special Instruction:

Supervisor:

Adnan

## ASSIGNMENT (Office)

From (Person):

CW3

Jocanna Yong

of

FCL

Date/Time:

14082017

3:40pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGY 36H

Insured:

SHC 2367T

at Workshop m/s

M6 Solution.

Tel:

6744 4165.

of

23 Kaki Bukit Ave 4

Policy No:

Claim No:

D7007821MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10082017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

14082017

3:56pm

Person Contacted:

Hong

Vehicle

IN OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

SGY 36H - NA / ALA 17015529 / 13

DFA: 10032017

SHC 2367T - CS / FCL14009238 / Ribell

DFA: 14052016

Confirm 1/5 \$9300, 5 days

Red: \$39,300.83, 81%.

ASS. REC. BY: Adrian Ling

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SGY 36H Yr Regn: 2010 / July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Porsche Panamera C.C. 3605

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 16295 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WPO ZZZ 97ZBL 000918

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 295/35R20

R: 295/35R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 15/08/17

Survey held at M6 Solution

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap.

RECEIVED 9 MAR 2018

Date/Time, File Pass to?

☐ : Preli. Report

1) typist

☒ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

38x15: 570

170+570

50

50+50

74

964

Report Form at: TP

Lump Sum / L.S. (\$ 9300)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                                    |                          |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------|--------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                            |                                                                                                                    | Ref : CS/FCI17015644/Arb |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                  |                                                                                                                    | Date : 14-08-2017        |  |
|                                                                                                                                        |                                                                                                                    | Code : FCI2              |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                                    |                          |                                                                                     |
| Insured Veh.                                                                                                                           | SHC 2367T                                                                                                          | Veh. Inspected           | SGY 36H                                                                             |
| Policy No.                                                                                                                             |                                                                                                                    | Coverage (\$)            | 0.00                                                                                |
| Claim No.                                                                                                                              | D17007821MFSH                                                                                                      | Excess (\$)              | 0.00                                                                                |
| Assign From                                                                                                                            | CWS (JOANNE YONG)                                                                                                  | Assign Date              | 14/08/2017                                                                          |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                                    |                          |                                                                                     |
| Make & Model                                                                                                                           |                                                                                                                    | c.c                      | 0                                                                                   |
| Engine No.                                                                                                                             | HIDDEN                                                                                                             | Year of Reg.             |                                                                                     |
| Chassis No.                                                                                                                            |                                                                                                                    | Colour                   |                                                                                     |
| Odometer                                                                                                                               | -                                                                                                                  | Steering                 |                                                                                     |
| Brakes                                                                                                                                 |                                                                                                                    | Modification             |                                                                                     |
| General                                                                                                                                |                                                                                                                    |                          |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                                    |                          |                                                                                     |
|                                                                                                                                        | Size                                                                                                               | Make                     | Balance                                                                             |
| R/H Front Tyre                                                                                                                         |                                                                                                                    |                          | mm                                                                                  |
| L/H Front Tyre                                                                                                                         |                                                                                                                    |                          | mm                                                                                  |
| R/H Rear Tyre                                                                                                                          |                                                                                                                    |                          | mm                                                                                  |
| L/H Rear Tyre                                                                                                                          |                                                                                                                    |                          | mm                                                                                  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                                    |                          |                                                                                     |
|                                                                                                                                        |                                                                                                                    |                          |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                                                                    |                          |                                                                                     |
| Accident Date                                                                                                                          | 10/08/2017                                                                                                         | Inspection Date          | 14/08/2017                                                                          |
| Survey held at                                                                                                                         | MG SOLUTION PTE LTD<br>23 KAKI BUKIT AVE 4<br>(SOUTH WING) #02-03B<br>VICOM INSPECTION CENTRE,<br>SINGAPORE 415933 |                          |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                                    |                          |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                                    |                          |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                                    |                 |                          |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------|-----------------|--------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                            |                                                                                                                    |                 | Ref : CS/FC117015644/Arb |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                  |                                                                                                                    |                 | Date : 14-08-2017        |  |
|                                                                                                                                        |                                                                                                                    |                 | Code : FCI2              |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                                    |                 |                          |                                                                                     |
| Insured Veh.                                                                                                                           | SHC 2367T                                                                                                          | Veh. Inspected  | SGY 36H                  |                                                                                     |
| Policy No.                                                                                                                             |                                                                                                                    | Coverage (\$)   | 0.00                     |                                                                                     |
| Claim No.                                                                                                                              | D17007821MFSH                                                                                                      | Excess (\$)     | 0.00                     |                                                                                     |
| Assign From                                                                                                                            | CWS (JOANNE YONG)                                                                                                  | Assign Date     | 14/08/2017               |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                                    |                 |                          |                                                                                     |
| Make & Model                                                                                                                           |                                                                                                                    | c.c             | 0                        |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                                                                             | Year of Reg.    |                          |                                                                                     |
| Chassis No.                                                                                                                            |                                                                                                                    | Colour          |                          |                                                                                     |
| Odometer                                                                                                                               | -                                                                                                                  | Steering        |                          |                                                                                     |
| Brakes                                                                                                                                 |                                                                                                                    | Modification    |                          |                                                                                     |
| General                                                                                                                                |                                                                                                                    |                 |                          |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                                    |                 |                          |                                                                                     |
|                                                                                                                                        | Size                                                                                                               | Make            | Balance                  |                                                                                     |
| R/H Front Tyre                                                                                                                         |                                                                                                                    |                 | mm                       |                                                                                     |
| L/H Front Tyre                                                                                                                         |                                                                                                                    |                 | mm                       |                                                                                     |
| R/H Rear Tyre                                                                                                                          |                                                                                                                    |                 | mm                       |                                                                                     |
| L/H Rear Tyre                                                                                                                          |                                                                                                                    |                 | mm                       |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                                    |                 |                          |                                                                                     |
|                                                                                                                                        |                                                                                                                    |                 |                          |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                                                                    |                 |                          |                                                                                     |
| Accident Date                                                                                                                          | 10/08/2017                                                                                                         | Inspection Date | 14/08/2017               |                                                                                     |
| Survey held at                                                                                                                         | MG SOLUTION PTE LTD<br>23 KAKI BUKIT AVE 4<br>(SOUTH WING) #02-03B<br>VICOM INSPECTION CENTRE,<br>SINGAPORE 415933 |                 |                          |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                                    |                 |                          |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                                    |                 |                          |                                                                                     |

# First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C  
GST Reg. No. M2-0001676-9

## MOTOR SURVEY ASSIGNMENT

|                    |                                                             |                      |               |
|--------------------|-------------------------------------------------------------|----------------------|---------------|
| Date               | 11-08-2017                                                  | Our Ref No.          | D17007821MFSH |
| Accident Date      | 10-08-2017                                                  | Claim Type.          | Third Party   |
| Insured Vehicle    | SHC2367T                                                    | Third Party Vehicle. | SGY36H        |
| Survey Location    | 23 KAKI BUKIT AVE 4 AAS KAKI BUKIT CENTRE#02-03             |                      |               |
| Contact Person.    | HENG YOKE HONG                                              |                      |               |
| Contact No.        | 67444165/ 0                                                 | Fax No.              | 67444604      |
| Survey Type        | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED: |                      |               |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD                                |                      |               |
| Contact Person     | NA                                                          | Fax No.              | 68416315      |
| Contact Number.    | NA                                                          |                      |               |

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

|                   |                     |                      |     |
|-------------------|---------------------|----------------------|-----|
| Cc : Workshop     | MG SOLUTION PTE LTD | Attention.           | NIL |
| Cc : TP Solicitor | NA                  | TP Solicitor Fax No. | NA  |
| Officer Incharge  | JOANNEY             |                      |     |

## IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/226813)



PRI Documents



Close



## PRI Header Details

|                   |                                                          |                                   |                                                                                                                           |                      |        |
|-------------------|----------------------------------------------------------|-----------------------------------|---------------------------------------------------------------------------------------------------------------------------|----------------------|--------|
| Claim No          | D17007821MFSH                                            | Policy No                         | D-15072701MFSH                                                                                                            | Claimant S.No & Name | 1 & MG |
| Workshop Name     | MG SOLUTION PTE LTD<br>(Contact Person : HENG YOKE HONG) | Survey Location & Contact Details | 23 KAKI BUKIT AVE 4 AAS KAKI BUKIT CENTRI<br>Mobile: 0 , Phone: 67444165 , Fax: 6744460<br>EmailId: MG3SOLUTION@GMAIL.COM |                      |        |
| Our Surveyor      | LKK AUTO CONSULTANTS PTE LTD                             | Instructions To Surveyor          | WITHOUT PREJUDICE: WE ADMIT LIABILITY Q                                                                                   |                      |        |
| Insured Name      | COMFORT TRANSPORTATION PTE LTD                           | Insured Vehicle No                | SHC2367T                                                                                                                  | TP Vehicle No        | SGY361 |
| PRI Recieved Date | 14-08-2017 02:28:19 PM                                   | Surveyor Appointed Date           | 14-08-2017 03:40:58 PM                                                                                                    | Surveyor Accept Date | 14-08- |

## Survey Report Upload

|                             |  |                      |            |                         |  |
|-----------------------------|--|----------------------|------------|-------------------------|--|
| Surveyor Inspection Date *: |  | Surveyor Report Date | 14-08-2017 | Upload Survey Report *: |  |
|-----------------------------|--|----------------------|------------|-------------------------|--|

## Vehicle Particulars

|           |                      |                |                       |         |                      |
|-----------|----------------------|----------------|-----------------------|---------|----------------------|
| Make      | Please Select Make ▼ | Model          | Please Select Model ▼ | Year    | Select               |
| Chasis No | <input type="text"/> | Engine No      | <input type="text"/>  | Mileage | <input type="text"/> |
| Color     | <input type="text"/> | Cubic Capacity | <input type="text"/>  |         |                      |

## Multiple Documents Upload

Upload Multiple Documents

File Name

Action

## Surveyor Job Remarks

## Enquire PARF/COE Rebate for Registered Vehicle

|                                |                          |
|--------------------------------|--------------------------|
| Vehicle Owner Particulars      |                          |
| Owner ID Type:                 | Singapore NRIC           |
| Owner ID:                      | 9998I                    |
| Vehicle Details                |                          |
| Vehicle No.:                   | SGY36H                   |
| Vehicle to be Exported:        | No                       |
| Intended De-registration Date: | 19 Mar 2018              |
| Vehicle Make:                  | PORSCHE                  |
| Vehicle Model:                 | PANAMERA 4               |
| Primary Colour:                | Black                    |
| Manufacturing Year:            | 2010                     |
| Engine No.:                    | B01283                   |
| Chassis No.:                   | WP0ZZZ97ZBL000918        |
| Maximum Power Output:          | 300.0 kW (402 bhp)       |
| Open Market Value:             | \$113,667.00             |
| Original Registration Date:    | 26 Jul 2010              |
| First Registration Date:       | 26 Jul 2010              |
| Transfer Count:                | 2                        |
| Actual ARF Paid:               | \$113,667.00             |
| Intended PARF Rebate Details   |                          |
| PARF Eligibility:              | Yes                      |
| PARF Eligibility Expiry Date:  | 25 Jul 2020              |
| PARF Rebate Amount:            | \$68,200.00              |
| Intended COE Rebate Details    |                          |
| COE Expiry Date:               | 25 Jul 2020              |
| COE Category:                  | B - Car (1601cc & above) |
| COE Period(Years):             | 10                       |
| QP Paid:                       | \$35,909.00              |
| COE Rebate Amount:             | \$8,436.00               |
| <b>Total Rebate Amount:</b>    | <b>\$76,636.00</b>       |

The information contained herein is correct as at 19 Mar 2018

OK



# MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

|                                                    |                               |                   |              |
|----------------------------------------------------|-------------------------------|-------------------|--------------|
| TO                                                 | : FIRST CAPITAL INSURANCE LTD | DATE              | : 14-08-2017 |
| ATTENTION                                          | : MOTOR CLAIMS DEPT           | JOB TYPE          | : T/P CLAIM  |
| ESTIMATE REPOF:                                    |                               |                   |              |
| <u>VEHICLE DETAILS</u>                             |                               |                   |              |
| VEHICLE NO                                         | : SGY36H                      | WPOZZZ972BL000918 |              |
| MODEL                                              | : PORSCHE PANAMERA 4          | Janice            |              |
| CHASSIS NO                                         |                               |                   |              |
| <u>ACCIDENT DETAIL</u> DATE : 10/08/2017           |                               |                   |              |
| TIME : 12:40HRS                                    |                               |                   |              |
| THIRD PARTY REQUESTOR / CONTACT : MS HONG / SHARON |                               |                   |              |

## CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                       | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|-----------------------------------|-----|-----------------|------------------|
| 1   | BOOTLID                           | 1   | \$ 6,520.00     | \$ 6,520.00      |
| 2   | BOOTLID " PORSCHE" EMBLEM         | 1   | \$ 226.00       | \$ 226.00        |
| 3   | BOOTLID " PANAMERA 4 " EMBLEM     | 1   | \$ 165.00       | \$ 165.00        |
| 4   | BOOTLID WEATHERSTRIP              | 1   | \$ 355.90       | \$ 355.90        |
| 5   | BOOTLID TOP LOCK                  | 1   | \$ 472.20       | \$ 472.20        |
| 6   | BOOTLID LOWER LOCK                | 1   | \$ 355.90       | \$ 355.90        |
| 7   | REAR BUMPER                       | 1   | \$ 4,480.00     | \$ 4,480.00      |
| 8   | REAR BUMPER SIDE BRACKET          | 2   | \$ 226.00       | \$ 452.00        |
| 9   | REAR BUMPER SIDE RETAINER         | 2   | \$ 121.00       | \$ 242.00        |
| 10  | REAR BUMPER SPONGE                | 1   | \$ 465.00       | \$ 465.00        |
| 11  | REAR BUMPER REINFORCEMENT         | 1   | \$ 1,124.00     | \$ 1,124.00      |
| 12  | REAR BUMPER LOWER LID             | 1   | \$ 1,980.00     | \$ 1,980.00      |
| 13  | REAR BUMPER LOWER LID COVER       | 1   | \$ 658.00       | \$ 658.00        |
| 14  | REAR BUMPER EXHAUST COVER         | 2   | \$ 463.00       | \$ 926.00        |
| 15  | TAIL LAMP                         | 2   | \$ 865.00       | \$ 1,730.00      |
| 16  | TAIL LAMP LOWER BRACKET           | 2   | \$ 294.80       | \$ 589.60        |
| 17  | REAR END PANEL                    | 1   | \$ 3,580.00     | \$ 3,580.00      |
| 18  | REAR END PANEL TOP GARNISH CHROME | 1   | \$ 655.00       | \$ 655.00        |



|    |                                         |   |             |              |             |
|----|-----------------------------------------|---|-------------|--------------|-------------|
| 19 | REAR FLOOR PANEL TOP BOARD <i>the n</i> | 1 | \$ 869.00   | \$ 869.00    | <i>x.</i>   |
| 20 | REAR EXHAUST PIPE CHROME <i>the n</i>   | 2 | \$ 2,622.10 | \$ 5,244.20  | <i>↑</i>    |
| 21 | REAR EXHAUST PIPE <i>1st Bent</i>       | 2 | \$ 6,450.00 | \$ 12,900.00 | <i>3250</i> |

*10910*

*9819*

TOTAL PRICE \$ 43,989.80

LESS 10% \$ 4,398.98

SUB TOTAL PRICE \$ 39,590.82

| S/N | DESCRIPTION                            | QTY | UNIT S/NETT | TOTAL S/NETT |            |
|-----|----------------------------------------|-----|-------------|--------------|------------|
| 1   | REAR NUMBER PLATE <i>Curved</i>        | 1   | \$ 80.00    | \$ 80.00     | <i>30</i>  |
| 2   | REAR BUMPER CLIPS (SET) <i>the</i>     | 1   | \$ 120.00   | \$ 120.00    | <i>50</i>  |
| 3   | REAR END PANEL SEALANT <i>3m</i>       | 1   | \$ 180.00   | \$ 180.00    | <i>x</i>   |
| 4   | REAR END PANEL TOP GARNISH CLIPS (SET) | 1   | \$ 180.00   | \$ 180.00    | <i>x</i>   |
| 5   | REVERSE SENSOR <i>Payed</i>            | 1   | \$ 1,600.00 | \$ 1,600.00  | <i>500</i> |

*580*

TOTAL \$ 2,160.00

#### CLAIM DETAILS: LABOUR AND SPRAY PAINTING

| S/N | JOB DESCRIPTION                                                                         | PRICE       | ADJUSTED COST | APPROVED |
|-----|-----------------------------------------------------------------------------------------|-------------|---------------|----------|
| 1   | PANEL BEATING AND REPLACE PART. INCLUSIVE OF THE REPAIR OF TAILGATE INNER BOARD HANDLE. | \$ 2,500.00 | <i>500</i>    |          |
| 2   | SPRAY PAINTING TO AFFECTED AREA                                                         | \$ 2,500.00 | <i>500</i>    |          |
| 3   | WIRING, BULB CHECKING                                                                   | \$ 550.00   | <i>60</i>     |          |
| 4   | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/ CONTROL UNIT                                | \$ 550.00   | <i>100</i>    |          |
| 5   | TO REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING                                 | \$ 250.00   | <i>100</i>    |          |
| 6   | TO TRANSFER BOOTLID MECHANISM                                                           | \$ 250.00   | <i>x</i>      |          |
| 7   | TO CONDUCT WATER LEAKAGE TEST                                                           | \$ 250.00   | <i>x.</i>     |          |

TOTAL \$ 6,850.00

*1260*

## ESTIMATE REPORT

|                       |           |
|-----------------------|-----------|
| TOTAL PARTS COST: \$  | 41,750.82 |
| TOTAL LABOUR COST: \$ | 6,850.00  |
| TOTAL REPAIR COST: \$ | 48,600.82 |

## APPROVED DETAILS

EXCESS :  
NO. OF DAYS :  
RE-SURVEY :  
PART BY PART OR LUMP SUM :  
DATE & TIME OF SURVEY :  
SURVEYED BY :  
CONTACT NUMBER :  
FAX NUMBER :

L/S Admin Lj  
15/08/17.

65 Days.

total: 11659.  
L/S 9.3K  
93k

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                                                                    |                       |                            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------|-----------------------|----------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                                                                                                    |                       | Ref : CS/FCI17015644/Arbn2 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                                                                    |                       | Date : 19-03-2018          |  |
|                                                                                                                                                                                        |                                                                                                                    |                       | Code : FCI2                |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                                                                    |                       |                            |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SHC 2367T                                                                                                          | Veh. Inspected        | SGY 36H                    |                                                                                     |
| Policy No.                                                                                                                                                                             | D-15072701MFSH                                                                                                     | Coverage (\$)         | 0.00                       |                                                                                     |
| Claim No.                                                                                                                                                                              | D17007821MFSH                                                                                                      | Excess (\$)           | 0.00                       |                                                                                     |
| Assign From                                                                                                                                                                            | JOANNE YONG                                                                                                        | Assign Date           | 14/08/2017                 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                                                                    |                       |                            |                                                                                     |
| Make & Model                                                                                                                                                                           | PORSCHE PANAMERA                                                                                                   | c.c                   | 3605                       |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                                                             | Year of Reg.          | 2010                       |                                                                                     |
| Chassis No.                                                                                                                                                                            | WP0ZZZ97ZBL000918                                                                                                  | Colour                | BLACK                      |                                                                                     |
| Odometer                                                                                                                                                                               | 165195                                                                                                             | Steering              | IN ORDER                   |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                                                           | Modification          | SPORTS RIM                 |                                                                                     |
| General                                                                                                                                                                                | GOOD                                                                                                               |                       |                            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                                                                    |                       |                            |                                                                                     |
|                                                                                                                                                                                        | Size                                                                                                               | Make                  | Balance                    |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 295/35 R20                                                                                                         | MICHELIN              | 6 mm                       |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         | 295/35 R20                                                                                                         | MICHELIN              | 6 mm                       |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 295/35 R20                                                                                                         | MICHELIN              | 6 mm                       |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          | 295/35 R20                                                                                                         | MICHELIN              | 6 mm                       |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                                                                    |                       |                            |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.                                                                                                                                     |                                                                                                                    |                       |                            |                                                                                     |
| DAMAGES SEE DETAILS.                                                                                                                                                                   |                                                                                                                    |                       |                            |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                                                                                                    |                       |                            |                                                                                     |
| Accident Date                                                                                                                                                                          | 10/08/2017                                                                                                         | Inspection Date       | 15/08/2017                 |                                                                                     |
| Survey held at                                                                                                                                                                         | MG SOLUTION PTE LTD<br>23 KAKI BUKIT AVE 4<br>(SOUTH WING) #02-03B<br>VICOM INSPECTION CENTRE,<br>SINGAPORE 415933 |                       |                            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                                                                    |                       |                            |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                                    |                       |                            |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                                                                    |                       |                            |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                                                                    | <b>5 Working Days</b> |                            |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGY 36H

| Qty                         | Description of Parts                      | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|-------------------------------------------|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                           |                      |                           |                   |
| 1                           | BOOTLID                                   | NOT NECESSARY        | 6,520.00                  | -                 |
| 1                           | BOOTLID "PORSCHE" EMBLEM                  | NOT NECESSARY        | 226.00                    | -                 |
| 1                           | BOOTLID "PANAMERA 4" EMBLEM               | NOT NECESSARY        | 165.00                    | -                 |
| 1                           | BOOTLID WEATHERSTRIP                      | NOT NECESSARY        | 355.90                    | -                 |
| 1                           | BOOTLID TOP LOCK                          | NOT NECESSARY        | 472.20                    | -                 |
| 1                           | BOOTLID LOWER LOCK                        | NOT NECESSARY        | 355.90                    | -                 |
| 1                           | REAR BUMPER                               | DISTORTED            | 4,480.00                  | 4,480.00          |
| 2                           | REAR BUMPER SIDE BRACKET @\$226.00        | NOT NECESSARY        | 452.00                    | -                 |
| 2                           | REAR BUMPER SIDE RETAINER @\$121.00       | NECESSARY            | 242.00                    | 242.00            |
| 1                           | REAR BUMPER SPONGE                        | NOT NECESSARY        | 465.00                    | -                 |
| 1                           | REAR BUMPER REINFORCEMENT                 | BENT                 | 1,124.00                  | 767.00            |
| 1                           | REAR BUMPER LOWER LID                     | DEFORMED             | 1,980.00                  | 1,285.00          |
| 1                           | REAR BUMPER LOWER LID COVER               | DEFORMED             | 658.00                    | 458.00            |
| 2                           | REAR BUMPER EXHAUST COVER @\$463.00       | DEFORMED             | 926.00                    | 428.00            |
| 2                           | TAIL LAMP @\$865.00                       | NOT NECESSARY        | 1,730.00                  | -                 |
| 2                           | TAIL LAMP LOWER BRACKET @\$294.80         | NOT NECESSARY        | 589.60                    | -                 |
| 1                           | REAR END PANEL                            | TO REPAIR SEE LABOUR | 3,580.00                  | -                 |
| 1                           | REAR END PANEL TOP GARNISH CHROME         | NOT NECESSARY        | 655.00                    | -                 |
| 1                           | REAR FLOOR PANEL TOP BOARD                | NOT NECESSARY        | 869.00                    | -                 |
| 2                           | REAR EXHAUST PIPE CHROME @\$2622.10       | NOT NECESSARY        | 5,244.20                  | -                 |
| 2                           | REAR EXHAUST PIPE @\$6450.00              | N/S BENT             | 12,900.00                 | 3,250.00          |
|                             | LESS 10% DISCOUNT                         |                      | -4,398.98                 | -1,091.00         |
|                             |                                           |                      | 39,590.82                 | 9,819.00          |
| <b>SPECIAL NETT ITEMS</b>   |                                           |                      |                           |                   |
| 1                           | REAR NUMBER PLATE (SN)                    | CRACKED              | 80.00                     | 30.00             |
| 1                           | SET REAR BUMPER CLIPS (SN)                | NECESSARY            | 120.00                    | 50.00             |
| 1                           | REAR END PANEL SEALANT (SN)               | NOT NECESSARY        | 180.00                    | -                 |
| 1                           | SET REAR END PANEL TOP GARNISH CLIPS (SN) | NOT NECESSARY        | 180.00                    | -                 |

Report Ref No. CS/FCI17015644/Arbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                                                         | Description of Parts                                                                                                             | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 1                                                                           | REVERSE SENSOR (SN)                                                                                                              | DAMAGED       | 1,600.00                  | 500.00            |
|                                                                             |                                                                                                                                  |               | 2,160.00                  | 580.00            |
|                                                                             | <b>LABOUR</b>                                                                                                                    |               |                           |                   |
|                                                                             | PANEL BEATING AND REPLACE PART.INCLUSIVE OF THE REPAIR OF TAILGATE INNER BOARD HANDLE.INCLUSIVE OF THE REPAIR OF REAR END PANEL. |               | 2,500.00                  | 500.00            |
|                                                                             | SPRAY PAINTING TO AFFECTED AREA.                                                                                                 |               | 2,500.00                  | 500.00            |
|                                                                             | WIRING,BULB CHECKING.                                                                                                            |               | 550.00                    | 60.00             |
|                                                                             | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNIT.                                                                         |               | 550.00                    | 100.00            |
|                                                                             | TO REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.                                                                         |               | 250.00                    | 100.00            |
|                                                                             | TO TRANSFER BOOTLID MECHANISM.                                                                                                   | NOT NECESSARY | 250.00                    | -                 |
|                                                                             | TO CONDUCT WATER LEAKAGE TEST.                                                                                                   | NOT NECESSARY | 250.00                    | -                 |
|                                                                             |                                                                                                                                  |               | 6,850.00                  | 1,260.00          |
| <b>GRAND TOTAL</b>                                                          |                                                                                                                                  |               | <b>48,600.82</b>          | <b>11,659.00</b>  |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                                                                  |               |                           | <b>9,300.00</b>   |

Report Ref No. CS/FCI17015644/Arbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.