

22/03/2017

ASS. REC. BY:

REF:

CS/LCR17015884/Gtb

Special Instruction:

SUBV.:

GR

ASSIGNMENT (Office)

From (Person):

Mohd Imran

of

LCR

Date/Time: 16082017 849am

Estimate Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SKV 5550A

Insured:

SLF 4940L

at Workshop m/s

159 Tick Hui

Tel:

6842 9089

of

Bk 1 Kaki Bukit Ave 6 #01-20

Policy No:

0999995054

Claim No:

2599964483SG

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11-08-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

16082017 10:20am

Person Contacted:

Connie.

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKV 5550A - X

SLF 4940L - X

lump sum \$5350 (Recd: 11838.22, 68%)

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Tick Hai Motor

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No


GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____



Veh No: SKV 5550A Yr Regn: 26 Mar 2010

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Jaguar XF c.c. 2567

Colour: Black A/C: ☒ Insured / ☐ Std / ☐ NI / NA

Sp. Reading: 85102 T/Radio: ☒ Insured / ☐ Std / ☐ NI / NA

Eng/No: _____

C/No: SAJA C0505A FR 74810

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 245/45 ZR 18

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 16-08-17

Survey held at W/S 5pm

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The ☒ U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 16 MAY 2018

Date/Time, File Pass to?

☐ : Preli. Report

☒ : Final Report

1) 16/5 Typist

Date/Time, File Return to?

2) _____

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) S + RS. \$ _____

☐ : Interview (\$ _____) Photos

☐ : Tech. Invs (\$ _____) Others

☐ : Weekend (\$ _____)

Report Format : TP

Lump Sum / I.B.I. (\$ 5350)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/LCR17015884/Gtb

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120

Date : 16-08-2017



Code : LCR

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|------------|----------------|------------|
| Insured Veh. | SLF 4940L | Veh. Inspected | SKV 5550A |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | | Excess (\$) | 0.00 |
| Assign From | MOHD IMRAN | Assign Date | 16/08/2017 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|--------|--------------|---|
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

| | |
|--|--|
| | |
|--|--|


5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 11/08/2017 | Inspection Date | 16/08/2017 |
| Survey held at | 159 TICK HAI MOTOR BLK C KAKI BUKIT AVE 6 #01-20/22/54 & #02-59 SINGAPORE 417883 | | |

5a. Remarks

| |
|--|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |
|--|

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF4940L AND SKV5550A ON 11/08/2017

From: Md Ishak, Mohd Imran
 To: assignments@lkkauto.com, admin-a@lkkauto.com
 Cc: Fong, Andy-SY, Leong, Kah Yin, Hassim, Mohd Fitri, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Lim, Sheng Yang, Tan, Lily (AIG), Fan, Winnie-LW
 Sent: Wednesday, 16 August, 2017 8:49:57 AM
 Attachments:  SLF4940L.TIF

Hi,

Please refer to the enclosed request from **ARIDAS & ASSOCIATES**

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

You may proceed to appoint **MR. ADRIAN LING** as Single Joint Expert as requested

Thank you

Sincerely,

Imran

Mohd Imran Md Ishak
 AIG
 Express Claims Adjuster II, FNOL SG Claims Operations - Auto
 Shared Services - Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
 Menara Worldwide, Level 14, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
 Tel +6 03 2719 6000 ext:1012661 | Fax +6 03 2685 5898

imran.ishak@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: aridasv@singnet.com.sg
 To: Imran.Ishak@aig.com
 Cc: Andy-SY.Fong@aig.com, KahYin.Leong@aig.com, MohdFitri.Hassim@aig.com, Baljit.Kaur@aig.com, Lee-Ying.Chin@aig.com, NoorMariesa.AbuKassim@aig.com, ShengYang.Lim@aig.com, Lily.Tan@aig.com, Winnie-LW.Fan@aig.com
 Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF4940L AND SKV5550A ON 11/08/2017
 Date: Tue, 15 Aug 2017 08:18:07 +0000

ACCIDENT INVOLVING MOTOR VEHICLES NOS. SKV 5550A AND SLF 4940L ALONG TAMPINES STREET 43 ON 11.8.2017

We thank you for your email of even date.

We are glad to inform you that our client wishes to appoint your surveyor, **MR. ADRIAN LING** from **M/S LKK AUTO CONSULTANTS PTE LTD** to do the pre-repair survey as a single joint expert.

We wish to inform you that our client's motor vehicle **SKV 5550A** can be inspected at M/s 159 Tick Hai Motor, Blk 1 Kaki Bukit Avenue 6, #01-20 Autobay @ Kaki Bukit, Singapore 417883. Please contact **Ms Connie** at office number : **6842 9089**.

Thank you.

Yours faithfully

From: Md Ishak, Mohd Imran [mailto:Imran.Ishak@aig.com]
 Sent: Tuesday, 15 August 2017 3:11 PM
 To: Aridas & Associates
 Cc: Fong, Andy-SY; Leong, Kah Yin; Hassim, Mohd Fitri; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Tan, Lily (AIG); Fan, Winnie-LW
 Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF4940L AND SKV5550A ON 11/08/2017

Without Prejudice

Your Reference : AA.21401.17.159
 Our Reference : SLF4940L

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

| Name of Surveyor | Company Name |
|--------------------------|--|
| Lim Kok Chong | AIG Asia Pacific Insurance Pte Ltd |
| Kumar Uthaya | AIG Asia Pacific Insurance Pte Ltd |
| Ken Wong | AIG Asia Pacific Insurance Pte Ltd |
| Lawrence Ng Chun Kee | Priority Services |
| Jeffrey Ong Leng Kiat | Priority Services |
| Jimmy Lee | Priority Services |
| EC Looi | Automobile Inspection Services Pte Ltd |
| Ricky Teng | RT Appraisal Pte Ltd |
| Elson Teng | RT Appraisal Pte Ltd |
| Michael Cheong | RT Appraisal Pte Ltd |
| Pang Kiah Keen (Frankie) | Formteam Adjusters Pte Ltd |
| Ng You Han | Formteam Adjusters Pte Ltd |
| Soon Han Xin (Gary) | Formteam Adjusters Pte Ltd |
| Chow Bo Xiong | Formteam Adjusters Pte Ltd |
| Chua Soo Teck (Benjamin) | Formteam Adjusters Pte Ltd |
| Kalvin Ang | LKK Auto Consultants Pte Ltd |
| Xing Guo Qiang | LKK Auto Consultants Pte Ltd |
| Marcus Chua | LKK Auto Consultants Pte Ltd |
| Mohamad Taufikh | LKK Auto Consultants Pte Ltd |
| Adrian Ling | LKK Auto Consultants Pte Ltd |
| Henry Ng | LKK Auto Consultants Pte Ltd |
| Mohammed Rasul | LKK Auto Consultants Pte Ltd |
| Steven Foong | LKK Auto Consultants Pte Ltd |
| Wei Jie | LKK Auto Consultants Pte Ltd |
| Ma Chin Fook | LKK Auto Consultants Pte Ltd |
| Kenneth Kong | LKK Auto Consultants Pte Ltd |

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you

Sincerely,

Imran

Mohd Imran Md Ishak
AIG
Express Claims Adjuster II, FNOL SG Claims Operations - Auto
Shared Services - Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 14, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel: +6 03 2719 6000 ext. 1012661 | Fax: +6 03 2685 5898

imran.ishak@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

ARIDAS & ASSOCIATES

ACRA REG. NO : 53131060D

NOTARY PUBLIC

ADVOCATES & SOLICITORS

COMMISSIONER FOR OATHS

NO. 75 BUKIT TIMAH ROAD, #05-18

BOON SIEW BUILDING

SINGAPORE 229833

TEL : 6 337 6359 (3 LINES) FAX : 6 338 2713

E-mail : aridasv @ singnet.com .sg

VYILINGAM ARIDAS

LLB (Hons) Lond. M.A.
Barrister, (Lincoln's Inn)

*Service of Court Documents
By Fax
Is Not Acceptable*

Our Ref : AA.21401.17.159

Your Ref : Please advise

15 August 2017

M/s AIG Asia Pacific

BY FAX : 6415 3727

Dear Sirs

ACCIDENT INVOLVING MOTOR VEHICLES NOS. SKV 5550A AND SLF 4940L ALONG TAMPINES STREET 43 ON 11.8.2017.

We are instructed by Lim Teng Han Ian to notify you of a road traffic accident on 11.8.2017 at about 11.45 a.m.. along Tampines Street 43 involving our client's vehicle registration number **SLF 4940L** and vehicle registration number **GX 7251L** driven by you at the material time. Copies of the Singapore Accident Statement filed and LTA search particulars are enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damage vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Our client's motor vehicle **SKV 5550A** can be inspected at M/s 159 Tick Hai Motor, Blk 1 Kaki Bukit Avenue 6, #01-20 Autobay @ Kaki Bukit, Singapore 417883. Please contact **Ms Connie** at office number : **6842 9089**.

Yours faithfully

enc



cc M/s LCRF Pte Ltd
29 Paya Lebar Road
#01-03
Singapore 409005

Text size + -

Enquire Vehicle & Owner Information (Vehicle No. SLF4940L As At 11 Aug 2017 / 11:45:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: AA.159.VK

Current Owner Details

Owner ID Type: Company

Owner ID: 201624597K

Owner Name: LCRF PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 29

Registered Street Name: PAYA LEBAR ROAD

Registered Unit No.: # 01 - 03

Registered Building Name: -

Registered Postal Code: 409005

Current Vehicle Details

Vehicle No.: SLF4940L

Make Description/Model: HONDA / VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Land Transport  Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)
Last updated on 13 Aug 2017 at 12:41 AM

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 2947A

Vehicle Details

Vehicle No.: SKV5550A

Vehicle to be Exported: No

Intended De-registration Date: 17 Aug 2017

Vehicle Make: JAGUAR

Vehicle Model: XF 3.0 V6 LUXURY AT ABS D/AB HID 2WD 4DR

Primary Colour: Green

Manufacturing Year: 2010

Engine No.: 586678333FC

Chassis No.: SAJAC05D5AFR74810

Maximum Power Output: 175.0 kW (234 bhp)

Open Market Value: \$56,599.00

Original Registration Date: 26 Mar 2010

First Registration Date: 26 Mar 2010

Transfer Count: 2

Actual ARF Paid: \$56,599.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 25 Mar 2020

PARF Rebate Amount: \$33,959.00

Intended COE Rebate Details

COE Expiry Date: 25 Mar 2020

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$36,089.00

COE Rebate Amount: \$9,400.00

Total Rebate Amount: \$43,359.00

The information contained herein is correct as at 17 Aug 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 13 Aug 2017 at 12:41 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|----------------------|
| Date Of Report | 12/08/2017 10:53 |
| Date Of Accident | 11/08/2017 11:45 |
| Exact Location Of Accident | ALONG TAMPINES ST 43 |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|------------------------|
| Vehicle Registration Number | SKV5550A |
| Insured/Policyholder | |
| Name Of Registered Owner | LIM TENG HAN IAN |
| NRIC No | S6842947A |
| Email Address | ADMIN@TICKHAIMOTOR.COM |
| Mobile Phone No | (LOCAL) +65-98801884 |
| Alternative Phone No | OFFICE-98801884 |

Vehicle Particulars

| | |
|--|--|
| Manufacturer | JAGUAR |
| Model | XF 3.0 V6 LUXURY AT ABS D/AB HID 2WD 4DR |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|---|
| Name of Insurance Company | DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | MT100322094 |
| Cover Note Number | 25/09/2016-24/09/2017 |

Driver

| | |
|----------------------|------------------------|
| Name of Driver | LIM TENG HAN IAN |
| NRIC No | S6842947A |
| Date Of Birth | 30/12/1968 |
| Occupation | INDOOR |
| Date Of Driving Pass | 04/11/1986 |
| Driving Experience | 30 YEARS AND 9 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-98801884 |
| Fax Number | |
| Contact Number | OFFICE-98801884 |
| Email Address | ADMIN@TICKHAIMOTOR.COM |

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own
 Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s)
 soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLF4940L
 Vehicle Make/Model/Colour HONDA VEZEL
 Details Of Properties
 Name of Driver
 NRIC/Passport Number S1178133J
 Contact Number 81859279
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

I was driving along Tampines Street 43.
Suddenly, vehicle B came out from a small road
without stopping at the stop line, resulting in
hitting onto the front right hand portion of my vehicle

You had been advised by workshop that in the event that you wish to claim
against your own policy (OD claim), there is a **Fourteen (14) days clause**
whereby the claim must be made within the stipulated timeframe from
the day of occurrence.


| | |
|-------------------------------------|---------------------------------|
| <input type="checkbox"/> | Reporting Only |
| <input type="checkbox"/> | Claim OD |
| <input type="checkbox"/> | Claim TP |
| <input checked="" type="checkbox"/> | Claim OD / TP at other workshop |

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time


Witnessed by Reporting Centre
Personnel

159 TICK HAI MOTOR
1 KAKI BUKIT AVE 6 #01-20 SINGAPORE 417883

TEL: 6842 9089 FAX: 6841 2869

REG NO : 53033608A

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• Supplementary item(s) must be resurveyed and
subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle Number: SKV5550A

| S/N | Item Description | Amount (\$) |
|------------|--------------------------------------|--------------|
| 1 | Front Bumper / Cut | \$ 2,828.54 |
| 2 | Front Bumper Side Bracket (RH) / De | \$ 108.00 |
| 3 | Front Fender (RH) X repair | \$ 1,636.57 |
| 4 | Front Fender Inner Garnish (RH) / De | \$ 468.00 |
| 5 | Front Bumper Undertray X NN | \$ 504.00 |
| 6 | Headlamp Assy (RH) / BR | \$ 1,792.57 |
| 7 | Front Shock Absorber (RH) X NN | \$ 588.12 |
| 8 | Front Knuckle (RH) X NN | \$ 963.00 |
| 9 | Front Hub & Bearing (RH) / MC | \$ 468.00 |
| 10 | Front Lower Arm (RH) X | \$ 909.00 |
| 11 | Front Upper Arm (RH) X | \$ 1,134.00 |
| 12 | Front Torsion Bar Linkage (RH) X | \$ 99.00 |
| 13 | Front Control Arm (RH) X | \$ 1,602.00 |
| Total : | | \$ 13,100.80 |
| Less 10% : | | \$ 1,310.08 |
| Amount : | | \$ 11,790.72 |

2732.1

429.5

5530.17

4977.15

| S/N | Special Nett Item | Amount (\$) |
|----------|-----------------------------------|-------------|
| 1 | Front Rim (RH) / Cut | \$ 1,493.50 |
| 2 | Front Tyre (RH) / Cut | \$ 450.00 |
| 3 | Front Daytime LED Light (RH) X NN | \$ 364.00 |
| Amount : | | \$ 2,307.50 |

650

140

X

790

| Labour | Amount (\$) |
|---|--------------|
| To conduct 4 wheel alignment | \$ 160.00 |
| To check front electrical wiring system | \$ 80.00 |
| To remove, and reinstall undercarriage | \$ 150.00 |
| Labour to remove, cut, change & panel beating | \$ 1,500.00 |
| To putty and respray affected areas | \$ 1,200.00 |
| Labour Total : | \$ 3,090.00 |
| Total (Parts & Labour) | \$ 17,188.22 |

60

30

50

400

400

940

6707.15

20%: 5350

4 Days.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/LCR17015884/GTBN2

Date: 16/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995054
 Claimant Vehicle No: SKV5550A Insured Vehicle No: SLF4940L
 Date of Loss: 11/08/2017 Nature of Claim: TP Claim No: 2599964483SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKV5550A Engine No: 586678333FC
 Make & Model: JAGUAR XF, 3.0 V6 LUXURY (A) Chassis No: SAJAC05D5AFR74810
 Reg. Date: 26/03/2010 (Man. Year: 2010) Odometer: 85102 km
 Colour: Black
 Engine Capacity: 2967 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45ZR18 Rear Tyre Size: 245/45ZR18
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

| | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts | 14,098.22 | 5,767.15 | 8,331.07 | 59.09 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,090.00 | 940.00 | 2,150.00 | 69.58 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 17,188.22 | 6,707.15 | 10,481.07 | 60.98 |
| Approved Total (Overridden) (S\$) | | 5,350.00 | | |
| Nett Amount (S\$) | 17,188.22 | 5,350.00 | 11,838.22 | 68.87 |

INSPECTION

Date of Assignment: 16/08/2017
 Date Inspected: 16/08/2017 Inspected At: 159 Tick Hai Motor (HQ)
 1 Kaki Bukit Avenue 6, #01-20 Autobay
 @ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|----------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Cut | 2,828.54 FL | *2,732.10 FL |
| 2 | 1 | | *FRONT BUMPER SIDE BRACKET (RH) | Deformed | 108.00 FL | *108.00 FL |
| 3 | 1 | | *FRONT FENDER (RH) | Repair | 1,636.57 FL | *- FL |
| 4 | 1 | | *FRONT FENDER INNER GARNISH (RH) | Deformed | 468.00 FL | *429.50 FL |
| 5 | 1 | | *FRONT BUMPER UNDERTRAY | Not Necessary | 504.00 FL | *- FL |
| 6 | 1 | | *HEADLAMP ASSY (RH) | Broken | 1,792.57 FL | *1,792.57 FL |
| 7 | 1 | | *FRONT SHOCK ABSORBER (RH) | Not Necessary | 588.12 FL | *- FL |
| 8 | 1 | | *FRONT KNUCKLE (RH) | Not Necessary | 963.00 FL | *- FL |
| 9 | 1 | | *FRONT HUB & BEARING (RH) | Necessary | 468.00 FL | *468.00 FL |
| 10 | 1 | | *FRONT LOWER ARM (RH) | Not Necessary | 909.00 FL | *- FL |
| 11 | 1 | | *FRONT UPPER ARM (RH) | Not Necessary | 1,134.00 FL | *- FL |
| 12 | 1 | | *FRONT TORSION BAR LINKAGE (RH) | Not Necessary | 99.00 FL | *- FL |
| 13 | 1 | | *FRONT CONTROL ARM (RH) | Not Necessary | 1,602.00 FL | *- FL |
| 14 | 1 | | *FRONT RIM (RH) | Cut | 1,493.50 FS | *650.00 FS |
| 15 | 1 | | *FRONT TYRE (RH) | Cut | 450.00 FS | *140.00 FS |
| 16 | 1 | | *FRONT DAYTIME LED LIGHT (RH) | Not Necessary | 364.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|------------------|-----------------|
| Sub Total (\$\$) | 15,408.30 | 6,320.17 |
| - List Item Discount on L Items 10.00/10.00% (\$\$) | 1,310.08 | 553.02 |
| Total Parts (\$\$) | 14,098.22 | 5,767.15 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|---|----------|------------|--------|
| <u>Labour Items</u> | | | | |
| 1 | TO CONDUCT 4 WHEEL ALIGNMENT | New | 160.00 | 60.00 |
| 2 | TO CHECK FRONT ELECTRICAL WIRING SYSTEM | New | 80.00 | 30.00 |
| 3 | TO REMOVE,AND REINSTALL UNDERCARRIAGE | New | 150.00 | 50.00 |
| 4 | LABOUR TO REMOVE,CUT,CHANGE & PANEL BEATING | New | 1,500.00 | 400.00 |
| 5 | TO PUTTY AND RESPRAY AFFECTED AREAS | New | 1,200.00 | 400.00 |
| Gross Labour Cost (S\$) | | | 3,090.00 | 940.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >