

ASS. REC. BY:

REF: CS/SMO17015935/Ggb/17

Special Instruction:

Surveyor:

ASSIGNMENT (Office)From (Person): Irene Henry of Sampo Insurance Date/Time: 16/08/2017 4:48pm

Estimated Cost: Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: FBK 252H Insured: GBF 1018Mat Workshop m/s Bike Production Tel: 6392 2555of 61b Serangoon Road S 218216Policy No: Claim No: CMTD1702848 / NSW

Sum Insured: Excess:

Make of Veh: D.O.A. 25/07/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS / WP

Date/Time: 17/8/2017 1008am Person Contacted: Wendy Mr Kwans.H Vehicle IN / OUT1808297 after 11am to 1pm

H.O.D. Endorsement:

Date/Time Action/Instruction (✓) Estimate

FBK 252H -XGBF 1018M -X22/8/17 @ 9.48am revised to Irene by email.

Surveyor: XRL

REF: SMO

ASSIGNMENT

From: _____ Date: 18082017

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBK 252H

at Workshop m/s Bike Production

of 610 Serangoon Road

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____


(Client's Record)

Make of Veh: _____

(Policy Condition)

11am to 1pm

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FBK 252H Yr Regn: 03 Feb 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Piaggio Vespa c.c. 278

Colour: Black A/C: Insured / Std / NI / NA

Sp.Reading: 17231 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 8APM 452 000.00 85677

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70-12

R: 130/70-12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. _____ D.O.I. 18-08-17

Survey held at W/S 1pm

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Finalized \$1600 with Shui. (Red \$2018.50, 56%)

RECEIVED 22 NOV 2017

Date/Time, File Pass to?

27/10/2017

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation: _____ \$ + RS _____ SI

Photos: _____

Others: _____

TOTAL

250

Report Format: TP

Lump Sum / I.B.I. (\$) 1600



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17015935/Gqb

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 17-08-2017



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 1018M	Veh. Inspected	FBK 252H
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1702848/NSW	Excess (\$)	0.00
Assign From	IRENE	Assign Date	16/08/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	25/07/2017	Inspection Date	18/08/2017
Survey held at	BIKE PRODUCTION PTE LTD 610 SERANGOON ROAD SINGAPORE 218216		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

✓			
---	--	--	--

Check By:

[Signature] 27/4/17

Case Handler

Date

catherine

From: Henry, Irene James <irene.henry@sompo.com.sg>
Sent: Wednesday, 16 August, 2017 4:48 PM
To: assignments@lkkauto.com
Cc: 'Sbk E'; Ashley Chong (LKK Auto)
Subject: RE: ACCIDENT INVOLVING GBF 1018M AND FBK 252H ON 25 JULY 2017

Our Reference: CMTD1702848/NSW

Hi,

Kindly assign your motor surveyor to conduct motor survey of the mentioned (FBK 252H).

Location: BIKE PRODUCTION
610 Serangoon Road (S) 218216
Contact: Mr Kwan S.H. – 6392 2555

Please refer to the email correspondence below.

Best Regards
Irene Henry
Claims Division
D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Britto [mailto:britto@apaclaw.com]
Sent: Wednesday, 16 August, 2017 4:27 PM
To: Henry, Irene James <irene.henry@sompo.com.sg>
Cc: 'Sbk E' <sbk5643e@yahoo.com>
Subject: ACCIDENT INVOLVING GBF 1018M AND FBK 252H ON 25 JULY 2017

WITHOUT PREJUDICE

DEAR IRENE

We refer to the above matter and we refer to your last e-mail.

Thank you for your e-mail **We will take LKK auto.**

Revert with your confirmation.

Thank you.

Regards

Britto

APAC LAW CORPORATION

ADVOCATES & SOLICITORS - NOTARY PUBLIC - COMMISSIONERS FOR OATHS

Main Office

(Conveyancing, Corporate & Litigation Practice)

430 Toa Payoh Lor 6

#12-01 OrangeTee Building

Singapore 319402

Main : +65 6397 6448

Fax : +65 6397 6449 (Conveyancing Practice)

Fax : +65 6250 3690 (Corporate & Litigation Practice)

Branch Office

(Road Traffic Accidents & Litigation Practice)

185 Toa Payoh Central

#01-320 (2nd

Storey)

Singapore

310185

Main : +65 6222 5593

Fax : +65 6224 3703

STRICTLY CONFIDENTIAL

This message, its contents and any files transmitted with it are intended SOLELY for the addressee(s) and may be legally privileged and/or confidential. Access by any other party is unauthorised without the express written permission of the sender. If you have received this message in error, you may not copy or use the contents, attachments or information in any way. Please destroy it and contact us immediately via e-mail return. This message has been prepared using information believed by the author to be reliable and accurate; we make no warranty as to its accuracy or completeness. We do not accept responsibility for changes made to this message after it was sent.

From: Henry, Irene James [<mailto:irene.henry@sompo.com.sg>]

Sent: Wednesday, 16 August, 2017 4:08 PM

To: britto@apaclaw.com

Cc: Ngo, Sau Wei Shawn

Subject: ACCIDENT INVOLVING GBF 1018M AND FBK 252H ON 25 JULY 2017

Our Reference: CMTD170284B/NSW

Your Reference: APAC.FBK252H.PRI.ns

Date: 16TH August 2017

Without Prejudice

BY EMAIL ONLY

Attention:

M/S APAC LAW CORPORATION

ACCIDENT INVOLVING GBF 1018M AND FBK 252H ON 25 JULY 2017

Dear Sir

We refer to your Notice of Accident via fax dated 16.08.2017.

Please be informed that Shawn Ngo is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Ma Chin Fook (North area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing
SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Henry, Irene James

Sent: Wednesday, 16 August, 2017 4:07 PM

To: 'britto@apaclaw.com' <britto@apaclaw.com>

Cc: Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>

Subject: ACCIDENT INVOLVING SKN 8050Z AND GY 6347X ON 12 AUG 2017

Our Reference: CMTD170284B/NSW

Your Reference: APAC.FBK252H.PRI.ns

Date: 16TH August 2017

Without Prejudice

BY EMAIL ONLY

Attention:

M/S APAC LAW CORPORATION

ACCIDENT INVOLVING GBF 1018M AND FBK 252H ON 25 JULY 2017

Dear Sir

We refer to your Notice of Accident via fax dated 16.08.2017.

Please be informed that Shawn Ngo is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Ma Chin Fook (North area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 22 August, 2017 9:48 AM
To: 'Henry, Irene James'; assignments
Cc: SUR
Subject: RE: ACCIDENT INVOLVING GBF 1018M AND FBK 252H ON 25 JULY 2017
Attachments: CSSMO17015935Gqb.pdf

Dear Irene,

Enclosed herewith preliminary advice of FBK 252H.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 17 August, 2017 10:07 AM
To: 'Henry, Irene James' <irene.henry@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: ACCIDENT INVOLVING GBF 1018M AND FBK 252H ON 25 JULY 2017

Dear Irene,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Henry, Irene James [<mailto:irene.henry@sompo.com.sg>]
Sent: Wednesday, 16 August, 2017 4:48 PM
To: assignments@lkkauto.com
Cc: 'Sbk E' <sbk5643e@yahoo.com>; Ashley Chong (LKK Auto) <admin-d@lkkauto.com>
Subject: RE: ACCIDENT INVOLVING GBF 1018M AND FBK 252H ON 25 JULY 2017

Our Reference: CMTD1702848/NSW

Hi,

Kindly assign your motor surveyor to conduct motor survey of the mentioned (FBK 252H).

Location: BIKE PRODUCTION
610 Serangoon Road (S) 218216



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1702848/NSW

Date: 22nd August 2018

Our Ref: CS/SMO17015935/Gqb

Without Prejudice

The Motor Claims Department
Sompo Insurance

Attn: Irene

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. FBK 252H .

We thank you for the instruction on 16/08/2017.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/08/2017 at the premises of M/s BIKE PRODUCTION and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,771.50</u> .
Revised Estimate Amount	: S\$ <u>1,659.50</u> .
"Check" Items Amount	: S\$ <u>387.00</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages at the front portion.



Comments/ Present Status:
Damages consistent.
Days of repair: 3 days.
We have not authorized repair.

Yours faithfully

XING GUO QIANG
Automobile Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/08/2017 14:14
Date Of Accident	25/07/2017 22:45
Exact Location Of Accident	9 TAMPINES AVE 2 SHELL PETROL STATION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBK252H
Insured/Policyholder	
Name Of Registered Owner	MOHAMMAD AMRI BIN HAMSIN
NRIC No	S8311463J
Email Address	SPLATTERSTAR@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-93804869
Alternative Phone No	OTHERS-93804869

Vehicle Particulars

Manufacturer	PIAGGIO
Model	VESPA GTS-278CC SUPER
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	MOTORCYCLE
------------------	------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	AN3153640
Cover Note Number	13/02/2017 - 12/02/2018

Driver

Name of Driver	MOHAMMAD AMRI BIN HAMSIN
NRIC No	S8311463J
Date Of Birth	17/04/1983
Occupation	INDOOR
Date Of Driving Pass	04/03/2013
Driving Experience	4 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93804869
Fax Number	
Contact Number	OTHERS-93804869
Email Address	SPLATTERSTAR@HOTMAIL.COM

Address	BLK 352 TAMPINES ST 33 #02-480
Postcode	520352
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE SKETCH PLAN BY DRIVER

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF1018M
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	NUR'KHAIRIYAH FATIN BINTE SAMSUDIN
NRIC/Passport Number	S9534897A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan Pg. 2

Describe Circumstances of the Accident

Date: 25/07/17 Time: 2245 HRS Location: 9, TAMPINES AVE 2 (SHELL PETROL STATION)

My Vehicle A: FBK 252 H Vehicle B: GBF 1018 M Vehicle C/Others: _____

ON THE NIGHT OF 25/07/17 AROUND 2245 HRS, I, VEHICLE A (FBK 252 H) WAS INFLATING MY REAR TIRE @ TAMPINES SHELL PETROL STATION. AS I WAS INFLATING I SAW ~~THE~~ VEHICLE B (GBF 1018 M) PULL UP IN FRONT OF MY VEHICLE ON A SLIGHT SLOPE. AS I LOOKED UP VEHICLE B WAS ROLLING TOWARDS MY VEHICLE. BY THE TIME I SHOUTED AT THE DRIVER TO ALERT HER THE VEHICLE WAS ALREADY MOUNTED ON THE FRONT MUDGUARD OF MY BIKE.

Vehicle B driver particulars: ★ Nur'Khairiyah Fatin Binte Samsudin
S9534 897A

() Claim OD / TP at Ah Lim Motor
() Reporting Only

☒ Claim OD/TP at other workshop

Remarks : Please forward a copy of my efile accident report to

My workshop :

Email Address :

& Myself :

Email Address : splatterstar@hotmail.com

Note : Please take note that your insurer have **14 days** timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature (If driver is not the policyholder)
Date & Time



Witnessed by Reporting Centre
Personnel

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 1463J

Vehicle Details

Vehicle No.: FBK252H

Vehicle to be Exported: No

Intended De-registration
Date: 18 Aug 2017

Vehicle Make: PIAGGIO

Vehicle Model: VESPA GTS 300 SUPER

Primary Colour: Black

Manufacturing Year: 2014

Engine No.: M454M1048553

Chassis No.: ZAPM4520000085677

Maximum Power
Output: -

Open Market Value: \$4,755.00

Original Registration
Date: 03 Feb 2015

First Registration Date: 03 Feb 2015

Transfer Count: 2

Actual ARF Paid: \$714.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry
Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 02 Feb 2025

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$4,412.00

COE Rebate Amount: \$3,290.00

Total Rebate Amount: \$3,290.00

The information contained herein is correct as at 18 Aug 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Last updated on 13 Aug 2017 at 12:41 AM

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 11 August 2017

ASSESSMENT FOR REPAIR: PIAGGIO VESPA GTS 300 SUPER - FBK252H

Chassis No.: ZAPM4520000085677

Engine No.: M454M1048553

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front Mudguard	\$330.00
1 pc	Front Wheel axle	\$115.00
1 pc	Front mudguard cover	\$120.00
1 pc	Front body cover	\$790.00
1 pc	Piaggio emblem	\$65.00
1 pc	Left mudguard cover	\$195.00
1 pc	Front suspension assy	\$550.00
	body cover moulding - cut \$170.	\$2,165.00
	Less discount 10%	\$216.50
		<u>\$1,948.50</u>

Special nett items

1)	Towing charges	\$80.00	40
2)	Dismantle, replace, realign and adjust above damaged parts	\$500.00	150
3)	Spray painting	\$400.00	200
4)	Check wiring and lighting system	\$60.00	x NN
5)	To remove/refit, replace (if damage) check and straighten front fork tubes.	\$180.00	50
6)	To knock, straighten chassis & body balancing	\$450.00	x NN
	Total Estimate	<u>\$3,618.50</u>	

Note: The above estimate is subjected to the prevailing GST of 7%

3 Days

lump sum repair

After repair photos:

Guo Qiang

18/8/17

[Signature]
22/8/17



For Bike Production Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO17015935/Gqbn2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERS SINGAPORE 048623		Date : 22-11-2017	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBF 1018M	Veh. Inspected	FBK 252H
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1702848/NSW	Excess (\$)	0.00
Assign From	IRENE	Assign Date	16/08/2017
2. Vehicle Particulars & Condition			
Make & Model	PIAGGIO VESPA	c.c	278
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	ZAPM4520000085677	Colour	BLACK
Odometer	19231	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	120/70-12	PIRELLI	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	130/70-12	PIRELLI	5 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/07/2017	Inspection Date	18/08/2017
Survey held at	BIKE PRODUCTION PTE LTD 610 SERANGOON ROAD SINGAPORE 218216		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 252H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT MUDGUARD	CUT	330.00	330.00
1	FRONT WHEEL AXLE	BENT	115.00	115.00
1	FRONT MUDGUARD COVER	CRACKED	120.00	120.00
1	FRONT BODY COVER	CUT	790.00	790.00
1	PIAGGIO EMBLEM	NECESSARY	65.00	65.00
1	LEFT MUDGUARD COVER	BROKEN	195.00	195.00
1	FRONT SUSPENSION ASSY	TO REPAIR SEE LABOUR	550.00	-
1	BODY COVER MOULDING	CUT	170.00	170.00
	LESS 10% DISCOUNT		-233.50	-178.50
			2,101.50	1,606.50
	<u>LABOUR</u>			
	TOWING CHARGES.		80.00	40.00
	DISMANTLE, REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT SUSPENSION ASSY.		500.00	150.00
	SPRAY PAINTING.		400.00	200.00
	CHECK WIRING AND LIGHTING SYSTEM.	NOT NECESSARY	60.00	-
	TO REMOVE/ REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES.		180.00	50.00
	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING.	NOT NECESSARY	450.00	-
			1,670.00	440.00
	GRAND TOTAL		3,771.50	2,046.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00

Report Ref No. CS/SMO17015935/Gqbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.