

ASS. REC. BY:

REF: CS/FCL7016656/Rinbn2

Special Instruction:

SUPERVISOR:

CWS

Raul

ASSIGNMENT (Office)

From (Person): CWS Joanne Yang of FCL Date/Time: 28/08/2017 4:09pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLQ 7827D Insured: SH 6617P

at Workshop m/s SNG AH TEE Tel: 6268 6183

of BLK 3 PIONEER RD NORTH # 01-18

Policy No: Claim No: D17007859MESH

Sum Insured: Excess:

Make of Veh: D.O.A. 11/08/2017
(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time: 28/08/2017 4:30pm Person Contacted: Samantha Tan Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLQ 7827D - X
	SH 6617P - CS/FCL13000820/Kyn DUA: 13/11/12
	Sent preli to Joanne
	Confirm with Sharon \$815.20 @ 2 days (Red. 1518.40, 65%)

08/11/17

Surveyor: *Pam*

REF: FCL

96230

ASSIGNMENT

From: _____ Date: 03/09/2017

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLQ 7827D

at Workshop m/s Sng Ah Tee

of Blk 3 Pioneer Rd North #01-18

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLQ 7827D Yr Regn: 2017 / July

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai ELANTRA 1.6A c.c 1591

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 2085 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM40841CMJ 448-7770

Gen. Cond: Good / ~~Fail~~ / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Nexen

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 11/08/17

D.O.I. 05/09/17

Survey held at Sng Ah Tee

Des. of Damages: Frt / ~~Rear~~ / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 25 SEP 2018

Date/Time, File Pass to?

1) *typist*

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format: TP

Lump Sum / I.B.I: (\$ 815.20)

110

50

50

30

240



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17016656/R1rb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 28-08-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 6617P	Veh. Inspected	SLQ 7827D
Policy No.		Coverage (\$)	0.00
Claim No.	D17007859MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	28/08/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	11/08/2017	Inspection Date	
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17007859MFSH

Our Ref: CS/FCI17016656/R1rb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLQ 7827D .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 05/09/2017 at the premises of M/s SNG AH TEE MOTOR & PANEL SERVICE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,333.60</u> .
Revised Estimate Amount	: S\$ <u>815.20</u> .
"Check" Items Amount	: S\$ <u>722.40</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

RASUL
Automotive Assessor

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	14-08-2017	Our Ref No. D17007859MFSH
Accident Date	11-08-2017	Claim Type. Third Party
Insured Vehicle	SH6617P	Third Party Vehicle. SLQ7827D
Survey Location	BLK 3 PIONEER ROAD NORTH #01-18	
Contact Person.	SAMANTHA TAN	
Contact No.	62686183/ 0	Fax No. 62681429
Survey Type	WITHOUT PREJUDICE: LIABILITY CLEAR (QUNATUM TO BE AGREED)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/226866)



PRI Documents



Close



PRI Header Details

Claim No	D17007859MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & SN SERVICE
Workshop Name	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (Contact Person : SAMANTHA TAN)	Survey Location & Contact Details	BLK 3 PIONEER ROAD NORTH #01-18 Mobile: 0 , Phone: 62686183 , Fax: 6268142 EmailId: SAM@SNGAHTEE.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: LIABILITY CLEAR (QUN/		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH6617P	TP Vehicle No	SLQ78:
PRI Recieved Date	25-08-2017 07:27:17 PM	Surveyor Appointed Date	28-08-2017 04:09:39 PM	Surveyor Accept Date	28-08-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	28-08-2017	Upload Survey Report *:	
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Friday, September 08, 2017 3:00 PM
To: 'Claim Workflow System'; JOANNEYONG@FIRST-INSURANCE.COM.SG
Cc: SUR; assignments
Subject: RE: SURVEY ASSESSMENT - D17007859MFSH/1
Attachments: SLQ 7827D.pdf

Dear Joanne,

Enclosed preliminary revised for **SLQ 7827D**.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, August 28, 2017 4:33 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17007859MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Monday, 28 August, 2017 4:09 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; JOANNEYONG@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17007859MFSH/1

Dear Sir/Mdm,

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 9623D

Vehicle Details

Vehicle No.: SLQ7827D

Vehicle to be
Exported: No

Intended De-
registration Date: 31 Aug 2017

Vehicle Make: HYUNDAI

Vehicle Model: ELANTRA AD 1.6 GLS AT

Primary Colour: Blue

Manufacturing
Year: 2017

Engine No.: G4FGHU621929

Chassis No.: KMHD841CMJU487770

Maximum Power
Output: 93.8 kW (125 bhp)

Open Market
Value: \$11,250.00

Original
Registration
Date: 24 Jul 2017

First Registration
Date: 24 Jul 2017

Transfer Count: 0

Actual ARF Paid: \$11,250.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility
Expiry Date: 23 Jul 2027

PARF Rebate
Amount: \$8,437.00

Intended COE Rebate Details

COE Expiry Date: 23 Jul 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE
Period(Years): 10

QP Paid: \$45,201.00

COE Rebate
Amount: \$44,727.00

**Total Rebate
Amount: \$53,164.00**

The information contained herein is correct as at 17 Aug 2017

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003088

FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION:

CONTACT: 6222 2311

FAX NO: 6507 3849

DATE : 29/8/2017
ACCIDENT DATE : 11/8/2017
VEHICLE NO : SLQ7827D
CHASSIS/ENG.NO :
VEHICLE MODEL : HYUNDAI ELANTRA
CLAIM NO :
POLICY NO :
REMARK : 7827FIRST TP AGST SH6617P

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER	459.00	20	367.20	367.20
2	10	PC	REAR BUMPER CLIPS	3.50	20	2.80	28.00
3	1	PC	REAR BUMPER REINFORCEMENT	303.00	20	242.40	242.40
4	2	PC	REAR BUMPER RETAINER	45.00	20	36.00	72.00
5	1	PC	REAR BUMPER LOWER SKIRT	250.00	20	200.00	200.00
6	1	PC	REAR BUMPER REFLECTOR(LH)	55.00	20	44.00	44.00

SUB-TOTAL: 953.60

** SPECIAL NETT PRICE **							
1	1	PC	REAR PARKING SENSOR	280.00		280.00	280.00
SUB-TOTAL							280.00

** WORK LABOUR **

TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS
TO PUTTY & SPARY PAINTING ON AFFECTED AREAS
TO CHECK WIRING

TO APPLY ANTI RUST COATING

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PAGE: 1 of 1

SAM

500.00	200	500.00
500.00	200	500.00
20.00		20.00
80.00	na x	80.00
SUB-TOTAL		1,100.00

SUB-TOTAL : S\$ 2,333.60
ADD 7% GST. S\$ 163.35
GRAND TOTAL : S\$ 2,496.95

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O E



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17016656/R1rhn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6617P	Veh. Inspected	SLQ 7827D	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17007859MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	28/08/2017	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDA ELANTRA 1.6 A	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KMHD841CMJU487770	Colour	BLUE	
Odometer	2085	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	NEXEN	6 mm	
L/H Front Tyre	195/65 R15	NEXEN	6 mm	
R/H Rear Tyre	195/65 R15	NEXEN	6 mm	
L/H Rear Tyre	195/65 R15	NEXEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/08/2017	Inspection Date	05/09/2017	
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 7827D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	459.00	459.00
10	REAR BUMPER CLIPS @\$3.50	NECESSARY	35.00	35.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	303.00	-
2	REAR BUMPER RETAINER @\$45.00	SERVICEABLE	90.00	-
1	REAR BUMPER LOWER SKIRT	SERVICEABLE	250.00	-
1	REAR BUMPER REFLECTOR (LH)	SERVICEABLE	55.00	-
	LESS 20% DISCOUNT		-238.40	-98.80
			953.60	395.20
SPECIAL NETT ITEMS				
1	REAR PARKING SENSOR (SN)	NOT NECESSARY	280.00	-
			280.00	-
LABOUR				
	TO KNOCK, WELD, REMOVE & FIX ON ABOVE PARTS.		500.00	200.00
	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS.		500.00	200.00
	TO CHECK WIRING.		20.00	20.00
	TO APPLY ANTI RUST COATING.	NOT NECESSARY	80.00	-
			1,100.00	420.00
GRAND TOTAL			2,333.60	815.20
RECOMMENDED COST OF REPAIRS				815.20

Report Ref No. CS/FCI17016656/R1rbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.