

VEHICLE CONDITION REPORT FORM / JOB RECORD

Allianz 

Worldwide Partners


Date: 29/08/17 Time: 02:18pm Customer Name: ZHAO Hong
 Technician Name: Sean gao Ym91487 Customer Telephone: 4108 4906
 Reg. No: SKO 693T Job No: 83808 Make/Model: Peugeot RCZ
 Odometer Reading (Customer Vehicle): 83808 Location: Richard line
 KM Travelled by Assistance Vehicle: (1 way) Time on Scene:
 Fault Reported: Accident Time Job Completed:
 Fault Found: Repaired at Breakdown Scene: Y/N
 How was vehicle repaired? n VIN No: n

Hubcaps Y/N
 Spare Wheel Y/N
 Tools Y/N
 Audio System Y/N
 Keys + Remote Y/N
 Aerial Y/N
 Cashcard (RM) Y/N
 Fuel E F
 Interior Condition: 2
 Front Seats
 Rear Seats
 Floor Covering
 Headlining

Day/Night Wet/Dry Clean/Soiled

Please circle the above as appropriate

Place X on damaged area for scratch and Y for dent






Delivery to Dealership / Date and Time: 305 alexandra RD

Vehicle received in the above condition YES/NO
 If not stated as above specify difference:

CUSTOMER DECLARATION

- I am entitled to the service requested. In the event of this subsequently not being the case I shall be responsible for the cost of any assistance provided.
- I accept that any roadside repairs will be of a temporary nature and that advice of a franchised dealer should be sought by me as soon as possible.
- In the case of forced entry, I confirm that I specifically requested that the operator forcefully enter the vehicle and that all damages occasioned thereby is and shall be my sole responsibility.
- I accept that any removable items left in the vehicle will not be the responsibility of the emergency service or their agents.

Customers Signature (white copy) 	Dealer/Workshop Signature (pink copy) 	Operators Signature (yellow copy) 	
---	---	--	---