

ASS. REC. BY:

REF: CS/CTI17016944

Special Instruction:

Surveyor:

Ma

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

31/8/2017

Estimated Cost:

Bill to:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SVV 9927H

Insured:

SJF3126B

at Workshop m/s

EM-1

Tel:

9666 6556

of

Blk 8, #0168 Sin Ming Rd

Policy No:

OMHC SN1744711700

Claim No:

SN0117005119C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30/8/17

(Client's Record)

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time:

31/8/17 12:20pm

Person Contacted:

Mr. Chia

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓)

Estimate

SVV 9927H - CS / INC13015998 / G9k3

SJF 3126B - CCG / AIG15021885 / Z93XX

Confirm with Mr Chia LLS \$4000 @ 6 days

Ref: 3024.43, 431.

(08/11/13)

AES-REC. BY: MaREF: CTI**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s EM-1

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SIV9927H Yr Regn: 02 / 2010Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis c.c. 1598Colour: white A/C: Insured / Std / NI / NASp. Reading: 65975 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR0538EE 10.6169166Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205 / 55 ZR16R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 31-08-17Survey held at w/s 5pmDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 13 AUG 2018

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 6Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____) S + RS _____☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)Report Format : TPLump Sum / LB-1: (\$ 4000)Survey Fee: 220

Transportation: _____

S + RS _____

Photos

Others

TOTAL

220




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17016944/M1rb		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 31-08-2017		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJF 3126B	Veh. Inspected	SVJ 9927H	
Policy No.	DMHCSN1744711700	Coverage (\$)	0.00	
Claim No.	SNM17D05119C02	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAY)	Assign Date	31/08/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/08/2017	Inspection Date		
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Aug 2017		31 Aug 2017 12:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	SUN YALEI
Vehicle Reg. No.:	SJV9927H
Claim Type:	TP / SNM17D05119C02
Vehicle Reg. No. (Insured):	SJF3126B
	Date of Loss: 29/08/2017 18:00 - :59
	Policy/Cover Note No.: DMHCSN1744711700
	Policy No. (Claimant):
	Excess: S\$0.00
Repairer:	Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68, 575643 Sin Ming - Tel: 64523298
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/09/2017]
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT A PRS AND REVERT WITH YOUR RECOMMENDATION

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

catherine

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Thursday, 31 August, 2017 11:26 AM
To: assignments@lkkauto.com; Admin A
Cc: Chia Sin Muk
Subject: CTP REF NO. SNM17D05119C02 EM1 REF NO. SJV9927H - ACCIDENT INVOLVING SJF3126B AND SJV9927H ON 30 AUGUST 2017

Dear Sir/Mdm,

We refer to the above matter and the email below.

Please assist to get Mr Marcus Chua from your end to liaise with Ms Chia from EM-1

Regards,

Irene Tay

Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Chia Sin Muk [mailto:em1autopteltd@gmail.com]
Sent: Thursday, 31 August, 2017 10:32 AM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: Re: CTP REF NO. SJF3126B EM1 REF NO. SJV9927H - ACCIDENT INVOLVING SJF3126B AND SJV9927H ON 30 AUGUST 2017

WITHOUT PREJUDICE

Dear Irene,

We would like to select LKK to conduct pre-repair survey for our vehicle no. SJV9927H at our workshop.

Thanks & Best Regards,

Karen, on behalf of,
Chia Sin Muk (Mr)

m: (65) 9666 6556 | o: (65) 6452 3298 | f: (65) 6457 5776

EM-1 Auto Pte Ltd

Blk 8 #01-68 Sin Ming Rd Industrial Estate Sector C Singapore 575643
Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately. You should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

On 30 August 2017 at 16:22, Irene Tay <irene.tay@sg.entaiping.com> wrote:

Without Prejudice

Save As To Costs

Dear Sir/Mdm,

We refer to your pre-repair survey request / email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

Here are the list of surveyors ;

Marcus Chua

Bryan Ang

Tay Beng Hee

See Chew Seng

Dereck Oh Siong Wee

Mohd Fadhilah Bin Osman

Cedric Ng

Steven Foong

Adrian Ling

Henry Ng

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Irene Tay

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3, Anson Road, #16-00

Springleaf Tower,

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389-6192

Fax: 6224 7175

Email: claimsdept@sg.cntaiping.com

Email: irene.tay@sg.cntaiping.com

Website: www.sg.cntaiping.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9491C
Vehicle Details	
Vehicle No.:	SJV9927H
Vehicle to be Exported:	No
Intended De-registration Date:	04 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	3ZZ4980550
Chassis No.:	MR053ZEE106169166
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,716.00
Original Registration Date:	26 Feb 2010
First Registration Date:	26 Feb 2010
Transfer Count:	1
Actual ARF Paid:	\$16,716.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Feb 2020
PARF Rebate Amount:	\$9,193.00
Intended COE Rebate Details	
COE Expiry Date:	25 Feb 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$20,340.00
COE Rebate Amount:	\$3,343.00
Total Rebate Amount:	\$12,536.00

The information contained herein is correct as at 04 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/08/2017 15:18
Date Of Accident	29/08/2017 18:40
Exact Location Of Accident	ALONG SLE TOWARDS BKE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV9927H
Insured/Policyholder	
Name Of Registered Owner	SUN YALEI
NRIC No	S7779491C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91116617
Alternative Phone No	OTHERS-91116617

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5056374054-05 (DRIVO CLASSIC)
Cover Note Number	

Driver

Name of Driver	SUN YALEI
NRIC No	S7779491C
Date Of Birth	15/03/1977
Occupation	INDOOR
Date Of Driving Pass	04/09/2012
Driving Experience	4 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91116617
Fax Number	
Contact Number	OTHERS-91116617
EEmail Address	NOEMAIL

Address	BLK 896A #10-78 WOODLANDS DRIVE 50
Postcode	730896
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT ATTACHED. (ATTENDED BY CHRISTINA)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJF3126B
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHB3099R
Vehicle Make/Model/Colour	

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SLD5698R

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name


Phone Number


Email Address


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

 30 AUG 2017
Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident


I was travelling along SLE towards BKE before Mandai Exit on lane 1, due to the heavy Traffic, I slowed down to stop, (stationary) suddenly Vehicle B hit onto my rear portion, I get down my car, Then notice that 4 vehicle was involve., I and wife (passenger) felt Injure.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time

31 AUG 2017



Witnessed by Reporting Centre Personnel

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG. NO. : 53105453E

Vehicle Number : SJV 9927H
Vehicle Model : TOYOTA ALTIS
Accident Date : 29.08.2017
Original Reg Date : 26.02.2010

Date : 30.08.2017
Chassis : MR053ZEE106169166
TP Ins. CHINA TAIPING

ESTIMATE

1	1 pc	Boot Lid		592.60	R
2	1 pc	Boot Lid Badge		52.00	
3	1 pc	Boot Lid Emblem 1.6		46.00	NEC
4	1 pc	Boot Lid Emblem COROLLA		48.00	
5	1 pc	Boot Lid Emblem ALTIS		48.00	
6	1 pc	Boot Lid Emblem ELEGANCE		46.00	
7	2 pcs	Boot Lid Lamps	160.70	321.40	XNN
8	2 pcs	Boot Lid Lamps Inner Sealer	25.00	50.00	X SVC
9	2 sets	Boot Lid Lamp Clips	20.00	40.00	X NN
10	1 pc	Boot Lid Inner Lock		121.50	BT
11	1 pc	Boot Lid Lock Catch		38.20	X SVC
12	1 pc	Boot Lid Weatherstrip		195.50	TN
13	2 pcs	Taillamps Assy	342.00	684.00	CRA
14	2 pcs	Taillamps Inner Sealer	25.00	50.00	NEC
15	2 sets	Taillamps Clips	30.00	40 60.00	NEC
16	2 pcs	Taillamp Bottom Retainers	43.00	86.00	X NN
17	1 pc	Rear Bumper		476.20	DD
18	2 pcs	Rear Bumper Side Retainers	57.00	114.00	DIS
19	2 pcs	Rear Bumper Attachment Retainers	36.10	72.20	BT
20	1 set	Rear Bumper Clips		50.00	NEC
21	1 pc	Rear Bumper Reinforcement Brackets		96.00	DD
22	1 pc	Rear Bumper Sponge		152.60	CRA
23	1 pc	Rear Bumper Reflectors RH		69.20	X NN
24	1 pc	End Panel Assy		532.80	BUC
25	1 pc	End Panel Top Trim		192.70	CRA
26	1 set	End Panel Top Trim Clips		30.00	NEC
27	1 pc	Rear Fender Inner Trim RH		338.70	X NN
28	1 set	Rear Fender Inner Trim Clips		30.00	X NN
29	1 pc	Rear Exhaust Silencer		792.10	DD
30	2 pcs	Rear Exhaust Mountings	42.00	84.00	DIS
31	1 pc	Rear Exhaust Gasket		56.20	NEC
				5,565.90	
				Less 25%	1,391.48
					4,174.43

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG. NO. : 53105453E

Vehicle No : SJV 9927H

B/F

4,174.43

Special Nett

1	1 set	Reverse Sensor		200 250.00
2	1 set	Body Panel Joint Sealant		120.00

short
60 NEC

Labour charge

Panel Beating		1,000.00
Spray painting		1,000.00
Check Wiring		50.00
Anti rust		100.00
Remove and install carpet and seat.		120.00
Remove and install reverse sensor		90.00
Remove and install rear exhaust silencer.		120.00

800
800
30
40
60
50
70

\$ 7,024.43

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Aug 2017		31 Aug 2017 12:27 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	SUN YALEI								
Vehicle Reg. No.:	SJV9927H	Date of Loss:	29/08/2017 18:00 - :59 [90 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM17D05119C02	Policy/Cover Note No.:	DMHCSN1744711700						
Vehicle Reg. No. (Insured):	SJF3126B	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68, 575643 Sin Ming - Tel: 64523298								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 12/09/2017]								
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT A PRS AND REVERT WITH YOUR RECOMMENDATION								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJV9927H (SNM17D05119C02)**
[SJF3126B]
TP
SUN YALEI
Aug 29 2017 6:00PM
[-]
Em-1 Auto Pte Ltd

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)

View [View in Browser](#) ▼

No documents found.

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#)

[Save](#)

[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17016944/DRBE2

Date: 29/08/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSN1744711700

Claimant Vehicle
No: SJV9927HInsured Vehicle
No: SJF3126B

Date of Loss: 29/08/2017

Nature of Claim: TP

Claim
No: SNM17D05119C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJV9927H

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Reg. Date: 26/02/2010 (Man. Year: 2010)

Colour: White

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

Engine No: 3ZZ4980550

Chassis No: MR053ZEE106169166

Odometer: 65975 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55Z R16

Front Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

Rear Tyre Size:

Rear Left Side:

Rear Right Side:

205/55Z R16

Hankook 6 mm

Hankook 6 mm

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,544.42	3,244.85	1,299.57	28.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,480.00	1,850.00	630.00	25.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,024.42	5,094.85	1,929.57	27.47
Approved Total (Overridden) (\$\$)		4,000.00		
(\$\$)	7,024.42	4,000.00	3,024.42	43.06
+ GST 7.00/7.00% (\$\$)	491.71	280.00	211.71	43.06
Nett Amount (\$\$)	7,516.13	4,280.00	3,236.13	43.06

INSPECTION

Date of Assignment: 31/08/2017

Date Inspected: 31/08/2017 Inspected At:

Em-1 Auto Pte Ltd (HQ)
Blk 8 Sin Ming Industrial Estate Sector C,
#01-68
Singapore 575643

Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Aug 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV9927H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair	592.60 FL	*- FL
2	1		*BOOT LID BADGE	Necessary	52.00 FL	*52.00 FL
3	1		*BOOT LID EMBLEM 1.6	Necessary	46.00 FL	*46.00 FL
4	1		*BOOT LID EMBLEM COROLLA	Necessary	48.00 FL	*48.00 FL
5	1		*BOOT LID EMBLEM ALTIS	Necessary	48.00 FL	*48.00 FL
6	2		*BOOT LID LAMPS	Not Necessary	321.40 FL	*- FL
7	2		*BOOT LID LAMPS INNER SEALER	Serviceable	50.00 FL	*- FL
8	2		*SETS BOOT LID LAMP CLIPS	Not Necessary	40.00 FL	*- FL
9	1		*BOOT LID INNER LOCK	Bent	121.50 FL	*121.50 FL
10	1		*BOOT LID LOCK CATCH	Serviceable	38.20 FL	*- FL
11	1		*BOOT LID WEATHERSTRIP	Torn	195.50 FL	*195.50 FL
12	2		*TAILLAMPS ASSY	Cracked	684.00 FL	*684.00 FL
13	2		*TAILLAMPS INNER SEALER	Necessary	50.00 FL	*50.00 FL
14	2		*SETS TAILLAMPS CLIPS	Necessary	60.00 FL	*40.00 FL
15	2		*TAILLAMP BOTTOM RETAINERS	Not Necessary	86.00 FL	*- FL
16	1		*REAR BUMPER	Dented	476.20 FL	*476.20 FL
17	2		*REAR BUMPER SIDE RETAINERS	Distorted	114.00 FL	*114.00 FL
18	2		*REAR BUMPER ATTACHEMENT RETAINERS	Bent	72.20 FL	*72.20 FL
19	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
20	1		*REAR BUMPER REINFORCEMENT BRACKETS	Dented	96.00 FL	*96.00 FL
21	1		*REAR BUMPER SPONGE	Cracked	152.60 FL	*152.60 FL
22	1		*REAR BUMPER REFLECTORS RH	Not Necessary	69.20 FL	*- FL
23	1		*END PANEL ASSY	Buckled	532.80 FL	*532.80 FL
24	1		*END PANEL TOP TRIM	Cracked	192.70 FL	*192.70 FL
25	1		*SET END PANEL TOP TRIM CLIPS	Necessary	30.00 FL	*30.00 FL
26	1		*REAR FENDER INNER TRIM RH	Not Necessary	338.70 FL	*- FL
27	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	30.00 FL	*- FL
28	1		*REAR EXHAUST SILENCER	Dented	792.10 FL	*792.10 FL
29	2		*REAR EXHAUST MOUNTINGS	Distorted	84.00 FL	*84.00 FL
30	1		*REAR EXHAUST GASKET	Necessary	56.20 FL	*56.20 FL
31	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
32	1		*SET BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*60.00 FS
33	1		*BOOT LID EMBLEM ELEGANCE	Necessary	46.00 FL	*46.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,935.90	4,239.80
- List Item Discount on L Items 25.00/25.00% (S\$)	1,391.48	994.95
Total Parts (S\$)	4,544.42	3,244.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,000.00	800.00
2	SPRAY PAINTING	New	1,000.00	800.00
3	CHECK WIRING	New	50.00	30.00
4	ANTI RUST	New	100.00	40.00
5	REMOVE AND INSTALL REVERSE SENSOR	New	90.00	50.00
6	REMOVE AND INSTALL REAR EXHAUST SILENCER	New	120.00	70.00
7	REMOVE AND INSTALL CARPET AND SEAT	New	120.00	60.00
Gross Labour Cost (\$\$)			2,480.00	1,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >