

AES REC. BY:

REF:

CS/AWA17017187/TTB⁰⁷

Special Instruction:

Surveyor: Tautiki

ASSIGNMENT (Office)

From (Person): Peggy Chan

of

AWA

Date/Time: 05/09/2017 5:30pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SBJ 7107D

Insured:

FBK 2584L

at Workshop m/s

Volkswagen

Tel:

6305 7776

of

247 Alexandra Rd

Policy No:

AVFMSB0000621700

Claim No:

FBK2584L/KW

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

03/09/2017

CA / REV / REP. / REV 24 HRS WP

06-09-2017 @ 3pm OW

H.O.D. Endorsement:

Date/Time: 05/09/2017 5:35pm

Person Contacted:

Charmaine

Vehicle IN / OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	<u>SBJ 7107D - X</u>
	<u>FBK 2584L - X</u>

Surveyor: Taylor

ASSIGNMENT

From: _____ Date: 06/09/2017

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 8BJ 7107D

at Workshop m/s Volkswagen

of 247 Alexandra Rd

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

3pm
owner waiting

/	
N/S	O/S
xx	

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR. Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 8BJ7107D Yr Regn: 2014 Nov

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Tiguan c.c 1984

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 26051 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WV 6222 SN EFW031143

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/40R19

R: 21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) SUMI / TOYO / YOKO or

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 6/9/10/15/25

Survey held at VW Alexandra

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Final Sig 85,111.39 (Red. 5338.24, 51.2)

RECEIVED 18 2017

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4

Resurvey No. of Trip: -

Survey Fee:

Transportation:

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

S + RS, SI

Photos

Others

TOTAL

150

Report Format: TP

Lump Sum / (B): (\$ 5,111.39)

Survey Department Check List (Case Handler)

Reference No. : CS/AWA17017187/Trb.
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Catherine): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: Catherine 18/11/19
Case Handler Date

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIED WORLD ASSURANCE COMPANY LTD		Ref : CS/AWA17017187/T1rb	
(SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (9th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Date : 05-09-2017	
		Code : AWA	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBK 2584L	Veh. Inspected	SBJ 7107D
Policy No.	AVFMSB0000621700	Coverage (\$)	0.00
Claim No.	FBK2584L/KW	Excess (\$)	0.00
Assign From	PEGGY CHAN	Assign Date	05/09/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	03/09/2017	Inspection Date	06/09/2017
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

catherine

From: Chan, Peggy <Peggy.Chan@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>
Sent: Tuesday, 5 September, 2017 5:30 PM
To: LKK (assignments@lkkauto.com)
Cc: SUR (sur@lkkauto.com); Kong, Charmaine (VWG Singapore) <charmaine.kong@vw.com.sg> (charmaine.kong@vw.com.sg)
Subject: TP Survey assignment for SBJ 7107D DOA: 03.09.2017 Our ref: FBK2584L/KW

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us do have consensus in the appointment of **Mohamad Taufikh / Mohammed Rasul**, as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 rd Party Vehicle	:	SBJ 7107 D
Insured Vehicle	:	FBK 2584 L
Policy Number	:	AVFMSB0000621700
Name of Workshop	:	Volkswagen Group Singapore Pte Ltd
Contact Number	:	6305 7299 / 6305 7176
Person to Contact	:	Charmaine Kong
Estimated Cost of repairs	:	\$ 10,424.88

Regards,
Claims Division

Copy to Volkswagen Group Singapore Pte Ltd via Email

Note -

1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

Regards
Motor Claims
Claims Group
Global Market

SINGAPORE ACCIDENT STATEMENT

Scene video

MSIG (Mommus)
vs

Alfred worked out

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 04/09/2017 10:54
Date Of Accident 03/09/2017 11:00
Exact Location Of Accident J'TION OF WEST COAST ROAD & CLEMENTI AVE 2
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SBJ7107D
Insured/Policyholder
Name Of Registered Owner TAN TIOW HEE EDMOND
NRIC No S0006047Z
Email Address EDTANED@GMAIL.COM
Mobile Phone No (LOCAL) +65-96300320
Alternative Phone No OFFICE-96300320

Vehicle Particulars

Manufacturer VOLKSWAGEN
Model TIGUANGP R LINE 2.0 4MOTION(A)
Exact Purpose for which vehicle was being used at time of accident PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number A 28640291 AVW
Cover Note Number

Driver

Name of Driver TAN TIOW HEE EDMOND
NRIC No S0006047Z
Date Of Birth 08/06/1953
Occupation INDOOR
Date Of Driving Pass 12/07/1971
Driving Experience 46 YEARS AND 1 MONTH
Gender MALE
Mobile Number (LOCAL) +65-96300320
Fax Number
Contact Number OFFICE-96300320
EMail Address EDTANED@GMAIL.COM

Address	62 KISMIS AVENUE
Postcode	598239
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBK2584L
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	CHENG KEJIA
NRIC/Passport Number	G2911290N
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

<p style="text-align: center;"><i>[Signature]</i></p> <p>Policyholder's Signature / Date & Time</p>	<p style="text-align: center;"><i>[Signature]</i></p> <p>Driver's Signature (if driver is not the policyholder) / Date & Time</p>	<p style="text-align: center;"><i>[Signature]</i></p> <p>Witnessed by Reporting Centre Personnel</p>
<p>Sketch Plan</p>	<p>A - S657107D</p> <p>B - FBK2584L</p>	

Sketch Plan Pg. 2


Describe Circumstances of the Accident

TIME OF ACCIDENT: 11am 3 SEPT 2017
LOCATION: JUNCTION OF WEST COAST ROAD AND CLEMENTI AVE 2
BIKE PLATE NO: FBK 2584 L
DRIVER: CHENG KEJIA LICENSE NO: G2911290N

I WAS DRIVING ALONG CLEMENTI AVENUE 2. AT THE JUNCTION OF CLEMENTI AVENUE 2 AND WEST COAST ROAD I SLOWED DOWN AT THE SLIP ROAD, WHERE THERE IS A ZEBRA CROSSING, AND STOPPED AT THE JUNCTION. BIKE FBK2584L RIDDEN BY CHENG KEJIA HIT THE BACK OF MY CAR SE37107D


Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

4 SEP 2017

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel



MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 06887
 Tel +65 6827 7888, Fax +65 6827 7800
 Co Reg No: 200412212G GST Reg No: 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
 (REPUBLIC OF SINGAPORE)
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
 OR ANY AMENDMENT, ACT, OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
 Individual Ownership

VW DRIVEEASY
 Comprehensive

Certificate No. A 28640291 AVW

Excess : SGD1,500
 Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
 3BJ7107D
2. Name of Policyholder
 Tan Tiow Hee Edmond
3. Effective Date of the Commencement of Insurance for the purposes of the Act
 28/11/2016
4. Date of Expiry of Insurance
 27/11/2017
5. Persons or Classes of Persons entitled to drive*
 Tan Tiow Hee Edmond
 Teo Ai Khim
 Tan Ying Wen Lynette
 Any other person provided he is driving on the Policyholder's order or with the policyholder's permission.
 * Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to use*
 Use only for social domestic and pleasure purposes and for the Policyholder's business.
 The policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.
 * Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT VOLKSWAGEN CENTRE SINGAPORE.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte Ltd.
 Approved Insurers

for Chief Executive Officer

Sketch Plan Pg. 4



edtaned@gmail.com

HP: 96300320

Sketch Plan Pg. 5

VEHICLES TO BE REGISTERED IN THE FOLLOWING CLASSIFICATION

CLASS	DESCRIPTION	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 Kilog. etc.	12 Jul 1971

NP 428A

Vehicle No. 50088472



Service Order Confirmation

SERVICE ORDER NO: 17IP2502

CUSTOMER NO.: CV026081

CUSTOMER NAME: TAN TIOW HEE EDMOND

TELEPHONE NO.:

ADDRESS: 62 KISMIS AVENUE
Singapore

VEH No.: SBJ7107D

Order Date: 07/09/17

Reg Date: 28/11/14 KM: 26,567

VIN NO.: WVGZZZ5N2FW031143 ENGINE NO:

SA: Cheong Pearlyn

MODEL: TiguanGP R Line 2.0 4motion(A) MODEL NO.: 5N22M9

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P DIAG	PROGRAMMING & CALIBRATION- NETT	1	TU	480	480
2	B&P MECH	ELECT WIRING & MECH COMPONENT CHECK NETT	1	TU	280	280
3	B&P ALEX LABOUR	LABOUR	1	UNIT	1,275	1,275
4	B&P ALEX PAINT	SPRAY PAINT	2	UNIT	800	1,600
5	EXT00037	Tow SVC- Quality Recovery Services	1	UNIT	0	0
6	EXT00037	Tow SVC- Quality Recovery Services	1	UNIT	0	0
Item						
7	5N0807521AFGRU	REAR LOWER SPOILER	1	PCS	459.45	459.45
8	5N0919491D	SENSOR BRACKET	2	PCS	11.37	22.74
9	5N0919397	SENSOR BRACKET	1	PCS	10.28	10.28
10	1T0919133C 9B9	PARKING SENSOR O RING	6	PCS	0.50	3.00
11	5N0853817C 9B9	FENDER MOULDING	1	PCS	274.17	274.17
12	5N0945095Q	TAILLIGHT OUTER LH	1	PCS	426.85	426.85
13	5N0945093G	TAILLIGHT	1	PCS	279.90	279.90

TOTAL	5,111.39
GST AMOUNT	357.80
TOTAL AMOUNT	5,469.19

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

PDI TUAS

PDI TUAS

TAN TIOW HEE EDMOND
62 KISMIS AVENUE
Singapore, 598239
Singapore

*Tanjiok 97495749
'wp'
6/9/17 @ 15:15
3 days
sur elkharto.com*

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV026081
Quote No. SER/QUO/1701496
QuoteDate 04/09/17
Salesperson Xiao Li Na Helena
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make Volkswagen Passeng	Model Description TiguanGP R Line 2.0 4motion(A)	Mileage 25,132	Service Advisor Cheong Pearlyn
License No. SBJ7107D	VIN WVGZZZ5NZFW031143	Initial Registration 28/11/14	Sales Advisor Xiao Li Na Helena
Engine Code	Labor Type 1H	Engine No. CCZ 459602	Model Code 5N22M9

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	4	UNIT		<i>1275</i> 3,360.00
P B&P ALEX PAINT	SPRAY PAINT	4	UNIT		<i>1600</i> 3,200.00
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		✓ 480.00
P B&P MECH	ELECT WIRING & MECH COMPO Nett	1	Time Un		✓ 280.00
	Sum Labor				7,320.00
P 1T0919133C 9B9	PARKING SENSOR O RING	6	Pieces		<i>mc</i> 3.00
P 5N0807421G GRU	REAR BUMPER	1	Pieces		<i>Rx</i> 1,313.65
P 5N0807521AFGRU	REAR LOWER SPOILER	1	Pieces		<i>de J</i> 459.45
P 5N0807568 2Z0	LOWER SPOILER INSERT Use Predecessor 5N0807568	1	Pieces		<i>NN</i> 339.59
P 5N0853817C 9B9	FENDER MOULDING	1	Pieces		<i>ut</i> 274.17
P 5N0919397	SENSOR BRACKET	1	Pieces		<i>ur</i> 10.28
P 5N0919491D	SENSOR BRACKET	2	Pieces		<i>mc</i> 22.74
	Sum Item				2,422.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

TAN TIOW HEE EDMOND
62 KISMIS AVENUE
Singapore, 598239
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV026081
Quote No. SER/QUO/1701496
QuoteDate 04/09/17
Salesperson Xiao Li Na Helena
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	TiguanGP R Line 2.0 4motion(A)	25,132	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SBJ7107D	WVGZZZ5NZFW031143	28/11/14	Xiao Li Na Helena
Engine Code	Labor Type	Engine No.	Model Code
	1H	CCZ 459602	5N22M9

Sum Labor	7,320.00
Sum Item	2,422.88
Total SGD	9,742.88
7% GST	682.00
Total SGD Incl. GST	10,424.88

Explanations

P = Proportionately Charged

10,449.63

Payment Terms No Credit



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA17017187/T1rbn2

(SINGAPORE BRANCH)

60 ANSON ROAD #08-01 (8th FLOOR)

MAPLE TREE ANSON

SINGAPORE 079914

Date : 20-12-2017



Code : AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBK 2584L	Veh. Inspected	SBJ 7107D
Policy No.	AVFMSB0000621700	Coverage (\$)	0.00
Claim No.	FBK2584L/KW	Excess (\$)	0.00
Assign From	PEGGY CHAN	Assign Date	05/09/2017

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN TIGUAN	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WVGZZZ5NZFW031143	Colour	BEIGE
Odometer	26051	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/40 R19	PIRELLI	6 mm
L/H Front Tyre	255/40 R19	PIRELLI	6 mm
R/H Rear Tyre	255/40 R19	PIRELLI	6 mm
L/H Rear Tyre	255/40 R19	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/09/2017	Inspection Date	06/09/2017
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBJ 7107D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
6	PARKING SENSOR O RING (SN)	NECESSARY	3.00	3.00
1	REAR BUMPER (SN)	TO REPAIR SEE LABOUR	1,313.65	-
1	REAR LOWER SPOILER (SN)	DEFORMED	459.45	459.45
1	LOWER SPOILER INSERT (SN)	NOT NECESSARY	339.59	-
1	FENDER MOULDING (SN)	CUT	274.17	274.17
1	SENSOR BRACKET (SN)	NECESSARY	10.28	10.28
2	SENSOR BRACKET (SN)	NECESSARY	22.74	22.74
1	TAILLIGHT OUTER LH (ADDITIONAL)(SN)	CUT	426.85	426.85
1	TAILLIGHT (ADDITIONAL)(SN)	CUT	279.90	279.90
			3,129.63	1,476.39
LABOUR				
LABOUR.INCLUSIVE OF THE REPAIR OF REAR BUMPER.			3,360.00	1,275.00
SPRAY PAINT.			3,200.00	1,600.00
PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC.			480.00	480.00
ELECT WIRING & MECH COMPO.			280.00	280.00
			7,320.00	3,635.00
GRAND TOTAL			10,449.63	5,111.39
RECOMMENDED COST OF REPAIRS				5,111.39

Report Ref No. CS/AWA17017187/T1rbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.