



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2009 KIA CERATO 1.6 (SJR5691J)

Date of Loss

September 8, 2017

Time of Loss

9.20

Loss Description

SJR5691J (OI) TURNING RIGHT AND C/W SGT4040U (TP)

Comment

Workshop Details

Total Rebate Amount

10080

Nett Loss Amount

\$12,920.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

03/28/2018



Days of work completion *

135



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SJR5691J

Registration State

SINGAPORE

Mileage

129373

Purchase Date

mm/dd/yyyy



Registration Date *

06/29/2009



Age of Vehicle

8

Driver Details

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2009

ASSESSMENT INFO...

2009

CATEGORY

Driver Name

FNOL INFORMATI...

TAI HUANG CHING

CATEGORY Make

POLICY INFORMAT... KIA

ASSESSMENT INFO... KIA

CATEGORY Model

POLICY INFORMAT... CERATO 1.6

ASSESSMENT INFO... CERATO FORTE 1.6(A) SX ABS D/AB 2v

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... KNAFH221395084296

POST SURVEY INF...

CATEGORY Date of Birth

FNOL INFORMATI... March 15, 1952

POST SURVEY INF... mm/dd/yyyy

CATEGORY Age

FNOL INFORMATI... 65

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... G4FC9H261745

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI... 38

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI... BLK 82 BEDOK NORTH ROAD, #08-320,
460082, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Residential

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Married

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S2577456F

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Detailed Assessment

Inspection Date *

09/11/2017



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

215/45R17

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good

Tyre Condition

Spare wheel

Rear Tyre Size

215/45R17

Front left side

GOODYEAR6mm

Front right side

GOODYEAR6mm

Rear left side

GOODYEAR6mm

Rear right side

GOODYEAR6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

Add Approve Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			FRONT DOOR STICKER - RH			Necessary	0			0	0	Reviewing
		2	1			FRONT DOOR RUBBER - RH			Cut	0			0	0	Reviewing
		3	1			FRONT DOOR HINGE TOP - RH			Bent	0			0	0	Reviewing
		4	1			REAR DOOR LOCK - RH			Serviceable	0	0	0	0	0	Deny
		5	1			REAR DOOR EYE - RH			Serviceable	0	0	0	0	0	Deny
		6	1			FRONT DOOR OUTER CHROME HANDLE, SMALL - RH			Damaged	0			0	0	Reviewing
		7	1			FRONT DOOR HINGE LOWER - RH			Bent	0			0	0	Reviewing
		8	1			FRONT DOOR - RH			Buckled	0			0	0	Reviewing
		9	1			REAR DOOR REGULATOR GEAR - RH			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		10	1			REAR DOOR RUBBER - RH			Serviceable	0	0	0	0	0	Deny
		11	1			REAR DOOR OUTER CORNER STICKER - RH (NPA)			Necessary	0			0	0	Reviewing
		12	1			ROCKER PANEL - RH			Repair	0	0	0	0	0	Deny
		13	1			CENTRE DOOR PILLAR - RH			Buckled	0			0	0	Reviewing
		14	1			REAR DOOR OUTER CHANNEL MOULDING - RH			Serviceable	0	0	0	0	0	Deny
		15	1			REAR DOOR HINGE LOWER - RH			Bent	0			0	0	Reviewing
		16	1			REAR DOOR HINGE TOP - RH			Bent	0			0	0	Reviewing
		17	1			FRONT DOOR OUTER CHANNEL MOULDING - RH			Serviceable	0	0	0	0	0	Deny
		18	1			FRONT DOOR LOCK - RH			Damaged	0			0	0	Reviewing
		19	1			REAR DOOR STICKER - RH			Necessary	0			0	0	Reviewing

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
		20	1			FRONT DOOR OUTER CHROME HANDLE, BIG - RH			Damaged	0			0	0	Reviewing
		21	1			REAR DOOR - RH			Buckled	0			0	0	Reviewing
		22	1			FRONT DOOR REGULATOR GEAR - RH			Serviceable	0	0	0	0	0	Deny
		23	1			REAR DOOR REGULATOR GEAR MOTOR - RH			Serviceable	0	0	0	0	0	Deny
		24	1			FRONT DOOR REGULATOR GEAR MOTOR - RH			Serviceable	0	0	0	0	0	Deny
		25	1			FRONT DOOR EYE - RH			Serviceable	0	0	0	0	0	Deny

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		TO TRANSFER 2 DOORS AND DOOR FITTING	120			Reviewing		
		2		TO REMOVE, REFIX GARNISH, CARPET, CUSHION AND RELATED PARTS	150			Reviewing		
		3		TO 4 WHEEL ALIGNMENT	0	0	0	Deny		
		4		TO RESPRAY PAINT ON ACCIDENT PORTIONS	700			Reviewing		

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVI
		5		TO KNOCK OUT DENTS, CUT/WELD RH ROCKER PANEL, RH CENTRE DOOR PILLAR, REMOVE, REPLACE ACCIDENT PARTS	1000			Reviewing		
		6		TO CHECK WIRING	20			Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR : 7 DAYS	Reviewing			
☐		2	PARTS SUPPLIED BY AXAS SUPPLIER \$1454.00	Reviewing			

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$1,990.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,990.00	\$1,990.00

Submit for Review