

22/07/2017

ASS. REC. BY:

REF: CS/MSG17017706/Arbn2

Special Instruction:

SUNVIA/01

Adrian

ASSIGNMENT (Office)

From (Person):

Monica Chung

of

MSIG

Date/Time:

12/9/17 5.23pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

EE3G

Insured:

YN 2478 Y

at Workshop m/s

SE Automobile

Tel:

6745 7367

of

No. 1 Kaki Bukit Ave 6 #02-34/36 417883

Policy No:

288009104mke

Claim No:

529119

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/9/17

CA / REV / REP. / REV 24 HRS

'05'

H.O.D. Endorsement:

Date/Time:

13/9/17 1202pm

Person Contacted:

sky

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

EE3G - X

YN2478 Y - X

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: EE3G Yr Regn: 2015 / Jan.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mercedes Benz C180 c.c. 1595Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 74248 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2050402R008941Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/50R17.R: 225/50R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental.

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 13/09/17.Survey held at SEDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP MS16.</u>
<u>25/4</u>	<u>Adrian confirmed 12 \$6800f with repirer. (Red 5050f, 40%)</u>

RECEIVED 02 MAY 2010

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 4

1)

☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

2)

Transportation:

Add Fee: ☐ : Site Insp (\$ _____)

S + RS, SI

☐ : Interview (\$ _____)

Photos

☐ : Tech. Invs (\$ _____)

Others

☐ : Weekend (\$ _____)

TOTAL

Report Format : TPLump Sum / I.B.I: (\$ 6800f)30010310

Survey Department Check List (Case Handler)

Reference No. : CE/MEG17017706/Arb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Catherine): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (Adrian): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

Adrian

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/20:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17017706/Agb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 13-09-2017		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 2478Y	Veh. Inspected	EE 3G	
Policy No.	28800904MKC	Coverage (\$)	0.00	
Claim No.	529419	Excess (\$)	0.00	
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	13/09/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	10/09/2017	Inspection Date	13/09/2017	
Survey held at	SE AUTOMOBILE SYSTEM NO.1 KAKI BUKIT AVE 6 #02-36 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Catherine Chong (LKK Auto)

From: Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msigg-asia.com>
Sent: Tuesday, 12 September, 2017 5:23 PM
To: 'bonnie kwok'; 'Ashley Chong (LKK Auto)'
Cc: Monica Chung; Rashitha Binte Shahuthuman
Subject: RE: PRE-REPAIR SURVEY - YN2478Y(OI) / EE3G ON 10/09/2017
Attachments: 12092017150811.pdf

Dear LKK,

Please assign Adrian to survey EE3G.

Please call M/s SE Automobile System at 9025 2583 to make the necessary arrangements. Thank you .

Rashitha

Senior Admin Officer





Direct line +65 6594 2582 | Direct fax +65 6225 7402 | Rashitha_shahuthuman@sg.msigg-asia.com



MSIG



2016 Insurer Claims Team of the Year

MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msigg.com.sg | Follow us on    

A member of **MS&AD** INSURANCE GROUP

From: bonnie kwok [mailto:litigation@bonniekwok.com]
Sent: Tuesday, 12 September, 2017 4:05 PM
To: Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msigg-asia.com>
Cc: Monica Chung <Monica_Chung@sg.msigg-asia.com>
Subject: Re: PRE-REPAIR SURVEY - YN2478Y(OI) / EE3G ON 10/09/2017

Dear Sirs,

Our client agrees to Adrian Ling as the Single Joint Expert (SJE).

Please let us have his report in due course.

Kindly request for the SJE to contact the repairers, M/s SE Automobile System at 9025 2583 to make the necessary arrangements.

Regards,
ST

--

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street

#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On 12 September 2017 at 15:10, Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msig-asia.com> wrote:

OUR REF -YN2478Y

WITHOUT PREJUDICE

Dear Sirs,

We propose one of the motor surveyor name in the list below to conduct the joint pre-repair survey as the single joint expert.

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd

To facilitate an expeditious claim settlement, we hope you are agreeable for any of the above surveyor to be the SJE (Single Joint Expert) .

If not, you may wish to nominate any of the 9 surveyors listed below as the SJE, depending on their availability:

- 1) Adrian Ling
- 2) Kenneth Kong
- 3) Marcus Chua
- 4) Henry Ng
- 5) Lau Kwok Kwong
- 6) Frankie Pang
- 7) Ng You Han
- 8) Gary Soon
- 9) Chow Bo Xiong

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB: If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.





Thank you.

Rashitha

Senior Admin Officer

Direct line [+65 6594 2582](tel:+6565942582) | Direct fax [+65 6225 7402](tel:+6562257402) | Rashitha_shahuthuman@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel [+65 6220 9644](tel:+6562209644) | Fax [+65 6225 6371](tel:+6562256371) | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on    

A member of **MS&AD** INSURANCE GROUP

BONNIE KWOK LLC*Advocates & Solicitors*

101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358

Tel : (65) 6536 6026
Fax : (65) 6536 2279
[Not for service of court documents]
GST Reg No. 201203547Z

Your Vehicle: YN 2478 Y
Our Vehicle: SEAuto-EE 3 G

Rashta

Date : 11 September 2017

M/s MSIG Insurance (Singapore) Pte. Ltd.
16 Raffles Quay
#24-01 Hong Leong Building
Singapore 048581

By Fax 6225 7402 Only FA

13-SEP 2017

Dear Sirs,

ACCIDENT INVOLVING EE 3 G & YN 2478 Y ON 10 SEPTEMBER 2017

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle EE 3 G at M/s SE Automobile System, No. 1 Kaki Bukit Avenue 6 #02-34/36 Singapore 417883.

Your faithfully



BONNIE KWOK
c.c. Client

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 30 Apr 2018

Preliminary Advice

Insured Vehicle : YN2478Y

No

TP Vehicle No : EE3G

Make : MERCEDES-BENZ C180

Date of : 13/09/2017

Inspection

Inspection At : SE AUTOMOBILE SYSTEM

Accident Date : 10/09/2017

Assignment Date : 13/09/2017

Est. Duration of
Repair : 4**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,850.00
Revised Amount	:S\$	6,800.00 (Lump Sum)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

MSME17120367 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 11/09/2017 15:58

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 11/09/2017 15:58
Date Of Accident 10/09/2017 15:45
Exact Location Of Accident BLK 1020 TAI SENG AVE CARPARK
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number EE3G
Insured/Policyholder
Name Of Registered Owner GAN KENG HEONG
NRIC No S7346229J
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-96234989
Alternative Phone No OFFICE-96234989
Vehicle Particulars
Manufacturer MERCEDES-BENZ
Model C180
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number M489396
Cover Note Number
Driver
Name of Driver GAN KENG HEONG
NRIC No S7346229J
Date Of Birth 13/12/1973
Occupation INDOOR
Date Of Driving Pass 02/06/1995
Driving Experience 22 YEARS AND 3 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-96234989
Fax Number
Contact Number OFFICE-96234989
Email Address NOEMAIL

Address BLK 104 LENGKONG TIGA #02-373
 Postcode 410104
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I AM STATIONARY MY CAR BEHIND (YN2478Y). LORRY REVERSE AND HIT ONTO MY CAR (EE3G).

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN2478Y
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness


Name
 Phone Number
 Email Address


Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan #2 Pg. 1


Describe Circumstances of the Accident


I stationary my car behind (YN 2478Y) lorry reverse and hit on my car (EE3G).

Location: Blk 1020 Tai Sang Ave car park exit.

Declaration

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature / Date & Time

 Gan Kang Heong
 Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Insurance Co.	India		
Vehicle NO	EE3G	Date Of Accident	10, 09, 2017
<input type="checkbox"/> Reporting Only			
<input type="checkbox"/> Own Damage Claim			
<input checked="" type="checkbox"/> Third Party Claim	3E AUTO		

SE AUTOMOBILE SYSTEM

NO. 1 KAKI BUKIT AVE 6 #02-36 AUTOBAY

SINGAPORE 417883

TEL : 9025 2583 FAX : 6841 3390

31-12-17

Our Ref : EE 3G

Gan Keng Heong

Blk 104 Lengkong Tiga

#02-373

Singapore 410104

Adrian.

Date in/out : 11/09/17 to 19/09/17

Tpmstg

Norita

WDD2050402R008941

ESTIMATE BILL ON VEH. NO. : EE 3G

MODEL : MERCEDES BENZ C180

CHASSIS NO. WDD2050402R008941

NETT ITEM

Bonnet	Dented.		1,965.00 ✓
Bonnet Lock LH			62.00 ✓
Bonnet Lock Catch (Center)			68.00 ✓
Bonnet Lock Sticker		2pcs @ 38.00	76.00 ✓
Bonnet Spring Stopper LH			32.00 ✓
Bonnet Badge	new		82.00 ✓
Front Bumper Fascia	Deformed		1,485.00 ✓
Front Bumper Beam (Top)	Damaged		415.00 ✓
Front Bumper Inner Rubber	new		28.00 ✓
Front Bumper Clips	new	10pcs @ 8.00	80.00 30
Head Lamp Assy LH	cracked		3,080.00 ✓
Front Grille	cracked		135.00 ✓
Front Grille Chorme	at 2 pieces.	4pcs @ 445.00	1,780.00 310
Front Grille Badge	new		135.00 ✓
Front Grille Badge Garnish			72.00 ✓
Front Grille Garnish			137.00 ✓
Front Grille Clips	new	8pcs @ 9.00	72.00 20
Front Support Top Panel	Dented		698.00 ✓

Front Support Top Panel Air Vent Garnish *HPM*

198.00

10,600.00

10% Less Discount

1,060.00

9,540.00

LABOUR CHARGE

To check wiring system

80.00 *30*

To reset electrical module system

280.00 *X*

To respray affected areas

950.00 *600*

To renew damaged parts, straighten & repair and aligned all parts

1,000.00 *400*

11,850.00

total 8445.50
L/S: 6.8K
04 Days

6.8K

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17017706/ARBN2

Date: 03/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28800904MKC
Claimant Vehicle No :	EE3G	Insured Vehicle No :	YN2478Y
Date of Loss:	10/09/2017	Nature of Claim:	TP
		Claim No:	529419

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EE3G	Engine No:	27491030215768
Make & Model:	MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A)	Chassis No:	WDD2050402R008941
Reg. Date:	07/01/2015 (Man. Year: 2014)	Odometer:	74248 km
Colour:	Silver		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,540.00	7,519.50	2,020.50	21.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,310.00	1,030.00	1,280.00	55.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,850.00	8,549.50	3,300.50	27.85
Approved Total (Overridden) (S\$)		6,800.00		
Nett Amount (S\$)	11,850.00	6,800.00	5,050.00	42.62

INSPECTION

Date of Assignment:	13/09/2017	
Date Inspected:	13/09/2017	Inspected At: SE Automobile System (HQ) 1 Kaki Bukit Avenue 6, #02-34/36 Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 May 2018)
Parts:	143	MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EE3G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET	Dented	1,965.00 FN	*1,965.00 FN
2	1	*BONNET LOCK LH	Not Necessary	62.00 FN	*- FN
3	1	*BONNET LOCK CATCH (CENTER)	Not Necessary	68.00 FN	*- FN
4	2	*BONNET LOCK STICKER	Not Necessary	76.00 FN	*- FN
5	1	*BONNET SPRING STOPPER LH	Not Necessary	32.00 FN	*- FN
6	1	*BONNET BADGE	Necessary	82.00 FN	*82.00 FN
7	1	*FRONT BUMPER FASCIA	Deformed	1,485.00 FN	*1,485.00 FN
8	1	*FRONT BUMPER BEAM (TOP)	Damaged	415.00 FN	*415.00 FN
9	1	*FRONT BUMPER INNER RUBBER	Not Necessary	28.00 FN	*- FN
10	10	*FRONT BUMPER CLIPS	Necessary	80.00 FN	*30.00 FN
11	1	*HEAD LAMP ASSY LH	Cracked	3,080.00 FN	*3,080.00 FN
12	1	*FRONT GRILLE	Cracked	135.00 FN	*135.00 FN
13	1	*FRONT GRILLE CHROME (4 Pcs)	Cut (2 Pc only)	1,780.00 FN	*310.00 FN
14	1	*FRONT GRILLE BADGE	Necessary	135.00 FN	*135.00 FN
15	1	*FRONT GRILLE BADGE GARNISH	Not Necessary	72.00 FN	*- FN
16	1	*FRONT GRILLE GARNISH	Not Necessary	137.00 FN	*- FN
17	8	*FRONT GRILLE CLIPS	Necessary	72.00 FN	*20.00 FN
18	1	*FRONT SUPPORT TOP PANEL AIR VENT GARNISH	Not Necessary	198.00 FN	*- FN
19	1	*FRONT SUPPORT TOP PANEL	Dented	698.00 FN	*698.00 FN

F=Franchise part. N=NetItemDisc.

Sub Total (S\$)	10,600.00	8,355.00
- Nett Item Discount on N Items 10.00/10.00% (S\$)	1,060.00	835.50
Total Parts (S\$)	9,540.00	7,519.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	80.00	30.00
2	TO RESET ELECTRICAL MODULE SYSTEM	New	280.00	-
3	TO RESPRAY AFFECTED AREAS	New	950.00	600.00
4	TO RENEW DAMAGED PARTS,STRAIGHTEN & REPAIR AND ALIGNED ALL PARTS	New	1,000.00	400.00
Gross Labour Cost (S\$)			2,310.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >