

ASS/PSC 871 PDS REF: CS/E17013298/696-1

Surveyor Richard ASSIGNMENT (Office)

From (Person) Daniel Padi of I Date/Time 13/09/2017

Estimated Cost Bill to

OD TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No FRJ 3252T Insured 848302J

at Workshop no Metoplex Tel 67476774

of 10 Kaki Bukit Road 2 #01-24

Policy No Claim No MCT17060406

Sum Insured Excess

Make of Veh D.O.A 26/6/2017


(Client's Record)

CA / REV / REP. / REV 24 HRS 11/7/2017

Date/Time 10/7/2017 3:56pm Person Contacted u nan H.O.D. Endorsement

Vehicle OUT

Date/Time	Action/Instruction ( * ) Estimate
	FRJ 3252T - 4
	848302J - 85/2701/1773 7/11/620
	Surety: 11/7/2017, disburse: 11/7/2017
1	\$9400, 5 Days.
	(Red \$2400, 20%.)

  
 19/12/2017

RECEIVED 19 DEC 2017

PRS  
RICHARD

REF: II

# ASSIGNMENT

From

Date

11/7/2017

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No.

FBJ 3252T

at Workshop m/s

mtuplex  
10 Kapek Budy Road 2 #01-24

of

Insured:

Policy No.

Claims No.

Sum Insured


Excess:

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt.

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

days Res. Yes or No

Lum Sum:

% 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No

FBJ 3252T

Yr Regn: 2014 / Mar 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Honda NC 750

cc 745

Colour

RED

A/C

Insured / Std / NI / NA

Sp. Reading

T. Radio: Insured / Std / NI / NA

Eng No.

C/No

JH2RC72B0E K003456

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size

F: 120 / 70 - 17

R: 160 / 60 - 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

METZELER

Front

Rear

R/Bal

2

mm

R/Bal

2

mm

L/Bal

mm

L/Bal

mm

D.O.A.

D.O.I.

11/7

12 pm

Survey held at

BIKEWORKZ

Des. of Damages

(Frt) Rear / O/S / (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to?

☐

: Preli. Report

1) 13/08/2017

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

) S + RS ) SI

) Photos

) Others

)

TOTAL

Report Format :

PRS

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III17013298/qb-1

64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Date : 19-09-2017



Code : III2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 8302J	Veh. Inspected	FBJ 3252T
Policy No.		Coverage (\$)	0.00
Claim No.	MCT17060906	Excess (\$)	0.00
Assign From	DANIEL POOI	Assign Date	15/09/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	26/06/2017	Inspection Date	19/09/2017
Survey held at	MOTOPLEX PTE LTD 10 KAKI BUKIT ROAD 2 #01-24 FIRST EAST CENTRE SINGAPORE 417868		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## Catherine Chong (LKK Auto)

---

**From:** Olivia Lau (LKKAuto) <olivialau@lkkauto.com>  
**Sent:** Monday, 18 September, 2017 3:54 PM  
**To:** assignments  
**Cc:** SUR  
**Subject:** RE: OUr ref : mCT17060906 // LKK Ref: CS3/III17013298/Jbe2

LKK Ref: CS3/III17013298/Jbe2

Assgn Team – Fyna pls.

Best Regards,

Olivia Lau | Admin Manager

LKK Auto Consultants

phone: 6256-3561 | email: [olivialau@lkkauto.com](mailto:olivialau@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Make  
good  
use of  
Today

---

**From:** Pooi Chin Han Daniel [mailto:[danielpooi@iii.com.sg](mailto:danielpooi@iii.com.sg)]  
**Sent:** Friday, 15 September, 2017 4:24 PM  
**To:** Mekavathanan Sarangapani <[mekavathanan@iii.com.sg](mailto:mekavathanan@iii.com.sg)>; Olivia Lau (LKKAuto) <[olivialau@lkkauto.com](mailto:olivialau@lkkauto.com)>; Sherini Pillai <[sherini@iii.com.sg](mailto:sherini@iii.com.sg)>  
**Cc:** Andrew Lim <[Andrew@iii.com.sg](mailto:Andrew@iii.com.sg)>  
**Subject:** RE: OUr ref : mCT17060906

Dear All,

Please take note that the LOD has been uploaded and rights have been granted.

Daniel Pooi

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street #04-02 IOB Building

Singapore 049711

Tel: 6347 6073 Fax: 6224 4174



---

**From:** Mekavathanan Sarangapani  
**Sent:** Tuesday, 12 September, 2017 12:12 PM  
**To:** Olivia Lau ([olivialau@lkkauto.com](mailto:olivialau@lkkauto.com)) <[olivialau@lkkauto.com](mailto:olivialau@lkkauto.com)>; Sherini Pillai <[sherini@iii.com.sg](mailto:sherini@iii.com.sg)>  
**Cc:** Andrew Lim <[Andrew@iii.com.sg](mailto:Andrew@iii.com.sg)>; Pooi Chin Han Daniel <[danielpooi@iii.com.sg](mailto:danielpooi@iii.com.sg)>  
**Subject:** OUr ref : mCT17060906

Dear Olivia,

Please do up paper survey report. LOD from Kuru & Co will be fwd – Rights given.

Case	Notified	Est Submitted	Adj Assigned
Main	11 Jul 2017		10 Jul 2017 00:00

Main	Offer Processing	Cl
------	------------------	----

  
**CLAIM SUBFOLDER DETAILS**

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R
Main Claimant:	MOHAMED HASSAN KUTHOOS, ID: S8672280A
Vehicle Reg. No.:	FBJ3252T
Claim Type:	TP / MCT17060906
Vehicle Reg. No. (Insured):	SH8302J
Repairer:	Motoplex Pte Ltd (HQ) <b>PROFILE</b> 10 KAKI BUKIT ROAD 2, # 01-24 FIRST EAST CENT
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Richard Harjai]

  
**CLAIM NOT REGISTERED**

This claim is not registered. Click **Register** to register this claim.

**Mekavathanan**

**HOD**

**Motor Claim Dept**

**India International Insurance Pte Ltd**

64 Cecil Street #04-02 IOB Building Singapore 049711

Tel: 6347 6105 Fax: 6224 4174



Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this

## ...CLAIM SUBFOLDER...(Pending for Payment)

PR1

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jul 2017		10 Jul 2017 00:00		12 Sep 2017 13:08 <b>S\$0.00</b> (S\$181.90)		<b>Pending for Payment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
<b>Insured:</b>		COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R							
<b>Main Claimant:</b>		MOHAMED HASSAN KUTHOOS, ID: S8672280A							
<b>Vehicle Reg. No.:</b>		<b>FBJ3252T</b>	<b>Date of Loss:</b>	26/06/2017 00:00 - :59					
<b>Claim Type:</b>		TP / MCT17060906	<b>Policy/Cover Note No.:</b>	MCOM0015					
<b>Vehicle Reg. No. (Insured):</b>		SH8302J	<b>Policy No. (Claimant):</b>						
		<b>Excess:</b>							
<b>Repairer:</b>		Motoplex Pte Ltd (HQ) 10 KAKI BUKIT ROAD 2, # 01-24 FIRST EAST CENTRE, 417868 Kaki Bukit - Tel: 67476774							
<b>Handling Insurer:</b>		India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]							
<b>Adjuster:</b>		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Richard Harjanto] ... [Final Rpt due 19/07/2017]							
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

OUR REF: MCT17060906-SP

YOUR REF: SH8302J/ 26.06.2017/ Bras Basah junction of Victoria Street

P PANIRCHELVAM  
BLK 850 HOUGANG CENTRAL  
#03-53 S(530850)

15 September 2017

Dear Sirs,

We refer to the above accident.

We are the insurers of SH8302J driven by you at the material time of accident.

We have received a Third party claim. We are enclosing copy of the Letter of Demand with supporting documents for your kind attention and perusal.

Kindly note that we will be carrying out investigation and proceed to defend and or negotiate a settlement of this claim and any further claims arising from this accident, as we deem fit.

If there are any further evidence which you would like to bring to our attention in support of your case and/or you have submitted a claim against the other driver please furnish us with :

1. evidence
2. Status of your claim against the owner of the other vehicle involved in the case

within (7) days from the date of this letter.

Kindly also note that you are required to notify us immediately upon receipt of all letters of claims, Writ of Summons, Traffic Police action issued against you. This includes all or any impending prosecution, inquest, fatal inquiry or offer of composition in connection with the accident.

Please note that any failure on your part to observe this will result in us exercising our rights of repudiation under the motor insurance company.

Yours faithfully

Copy by e-mail:

Sherini Pillai  
Motor Claims Department  
sherini@iil.com.sg

Comfort Transportation Pte Ltd  
383 Sin Ming Drive  
Singapore 575717

This is a computer generated letter which requires no signature.



# KURU & CO

Advocates & Solicitors  
UEN / GST Registration No: 53130937A

150 South Bridge Road  
#04-06 Fook Hai Building  
Singapore 058727

Kurubalan s/o Manickam Rengaraju  
Jan Chua Peck Kiang

Tel: 65322 009 (5 lines)

Fax: 65322 007 (Our fax no. is not for service of court documents)

Our ref: L.17.1078.lt(jt)

8 September 2017



## BY CERTIFICATE OF POSTING

Comfort Transportation Pte Ltd  
383 Sin Ming Drive  
GAS Building  
Singapore 575717

## BY HAND ONLY

India International Insurance Pte Ltd  
64 Cecil Street  
#04/05 IOB Building  
Singapore 049711

(Yr ref: SH 8302J)

(Yr ref: SH 8302J)

Dear Sirs,

ACCIDENT INVOLVING FBJ 3252T AND SH 8302J ON 26.06.17  
AT/ALONG BRAS BASAH  
INJURED RIDER: MOHAMED HASSAN KUTHOOS

We act for Mohamed Hassan Kuthoos, owner / rider of vehicle registration number FBJ 3252T who was also injured in the above-captioned road traffic accident.

We are instructed to claim for damages against you in connection with the above-captioned road traffic accident involving our client's vehicle and your vehicle registration number SH 8302J.

We are instructed that the accident was caused by your/your driver's/your insured's negligent driving and/or management of your/your insured's vehicle. As a result of the accident, our client has suffered injuries and our client's vehicle was damaged. Our client had been put to loss and expense, particulars of which are as follows:

Cost of Repair	\$11,800.00
Survey report fee	\$ 866.00
Loss of Use	\$ 1,450.00
Towing Fee	\$ 80.00
LTA fee/s	\$ 5.35
Incidentals (Inclusive of GST)	\$ 53.50
Cost at this stage (Inclusive of GST)	\$ 963.00

We shall revert with our client's claim for General Damages and related Special Damages in due course.

Enclosed are the supporting documents for your perusal:

Pre-repair Notification letter

Repair Bill

Survey report with 176 colour photographs (on your under taking to return the same within 03 days upon demand)

Our client's Police / SAS report

Letter from Traffic Police dated 5 July 2017

Your/your insured's LTA search

Certificate of Insurance and Policy Schedule

Towing Receipt from Island Towing Services dated 26.06.17

Enquiry on vehicle details for FBJ 3252T from Land Transport Authority



Our ref:

L.17.1078.lt(jt)

8 September 2017

**ACCIDENT INVOLVING FBJ 3253T AND SH 8302J ON 26.06.17  
AT/ALONG BRAS BASAH  
INJURED RIDER: MOHAMED HASSAN KUTHOOS**

We have on 10 July 2017 notified your insurer of the accident and a pre-repair inspection of our client's vehicle was carried out by your insurer on 11 July 2017.

Should you have a counterclaim against our client arising out of the accident, you are required to send us a letter giving full particulars of the counterclaim with all relevant supporting documents within **8 weeks** from your receipt of this letter.

Please also note that you or your insurer should send us an acknowledgement of receipt of this letter within **14 days** of your receipt of this letter, failing which our client will have no alternative but to commence proceedings without further notice to you or your insurer.

Yours faithfully,



Encl.

**N.B. Supporting documents are forwarded only to your insurer BY HAND**

**CC** Direct Asia Insurance (Singapore) Pte Ltd (**Mutual client – FBJ 3252T / BY FAX: 6423 1197**)  
Please do not prejudice our mutual client's claim in whatsoever way. Meanwhile, we would be obliged if you could let us have a complete set of third party's SAS/police report if you have received a copy of same for our attention.

**Cc.** Client

# KURU & CO

Advocates & Solicitors  
UEN / GST Registration No: 53130937A

150 South Bridge Road  
#04-06 Fook Hai Building  
Singapore 058727

Kurubalan s/o Manickam Rengaraju  
Jan Chua Peck Kiang

Tel: 65322 009 (5 lines)

Fax: 65322 007 (Our fax no. is not for service of court documents)

Our ref: L17.1078.lt(jt)  
(Please quote our reference when replying)

10 July 2017

India International Insurance Pte Ltd  
64 Cecil Street  
#04 / #05 IOB Building  
Singapore 049711

BY FAX ONLY : 6224 4174  
Your ref : SH 8302J

Dear Sirs,

**ACCIDENT INVOLVING FBJ 3252T AND SH 8302J ON 26.06.2017  
AT/ALONG BRAS BASAH  
NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY**

We act for **Mohamed Hussan Kuthoos**, whose vehicle registration number **FBJ 3252T** was damaged in the above accident.

A copy of the Police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully,



Encl

Cc. client



**SINGAPORE  
POLICE FORCE**

Our Ref : TP/IP/32767/2017  
Date : 5 July, 2017

Mohamed Hassan Kuthoos  
Apt Blk 51C Lengkong Empat  
#12-02  
Singapore 417660


Dear Sir/Madam

**ACCIDENT INVOLVING M/TAXI SH 8302 J AND M/CYCLE FBJ 3252 T ON 26/06/2017 AT ABOUT 2047HRS ALONG BRAS BASAH ROAD JUNCTION VICTORIA STREET NEAR L/P 11F.**

I refer to the above accident.

2. Please be informed that we have completed our investigations which shows that the driver of motor taxi SH 8302 J had committed the offence of Inconsiderate Driving under Section 65(b) of the Road Traffic Act, Chapter 276. Action has been initiated against the said driver.
3. If you have any queries, please contact the Investigation Officer Selina Wong at telephone number 6547 6423.

Yours faithfully

  
Mohd Nasir Osman, Stn Insp  
For Head Traffic Investigation  
Traffic Police

NP510

POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20170627/7005

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20170627/7005

CONTINUATION OF REPORT

Rider			
Name	MOHAMED HASSAN KUTHOOS	ID No.	S8672280A
Related Vehicle	FBJ3252T (Motorcycle)	Contact No.	91766786
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	26/06/2017	Date Discharge	26/06/2017
No. of Days granted Medical Leave	07	Degree of Injury	Serious

Brief Details.

On 26 June 2017 at about 2045hrs,  
I was riding on extreme right lane along bras bash road towards nicoll highway. The comfort taxi SH8302J was on the 3rd lane from right, on my left. Upon entering the junction of Brash Basah Rd x Victoria St, the mentioned above taxi made a swerve to its right, turning from lane 3 into victoria street. I braked hard and couldn't stop in time and collided with the taxi's right rear portion. Taxi had in car camera; there were two junction cameras at location.

Witness details.

Name: Tng Chin Seng  
Contact No: 93639238  
Vehicle No: GBE8265A

Name: KC  
Contact No: 98777452

**SINGAPORE ACCIDENT STATEMENT**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report	28/06/2017 19:47
Date Of Accident	26/06/2017 20:45
Exact Location Of Accident	BRAS BASAH JUNCTION OF VICTORIA STREET
Country/State of Loss	SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number	FBJ3252T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MOHAMED HASSAN KUTHOOS
NRIC No	S8672280A
Email Address	HASSAN8627@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91766786
Alternative Phone No	OFFICE-91766786
<b>Vehicle Particulars</b>	
Manufacturer	HONDA
Model	NC750XA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
<b>Insurance Company</b>	
Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MC/00330672
Cover Note Number	N.A.
<b>Driver</b>	
Name of Driver	MOHAMED HASSAN KUTHOOS
NRIC No	S8672280A
Date Of Birth	27/10/1986
Occupation	OUTDOOR
Date Of Driving Pass	19/04/2006
Driving Experience	11 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91766786
Fax Number	
Contact Number	OFFICE-91766786
Email Address	HASSAN8627@GMAIL.COM

**Details of Witness**

Name

Phone Number

Email Address

**DETAILS OF INJURED PERSON 1**

Name

MOHAMED HASSAN KUTHOOS

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBJ3252T

Were seat belts worn?

NO

Was injured conveyed to hospital by ambulance?

YES

Address

Postcode

Sketch Plan #2

ACCIDENT STATEMENT (2000 characters)

REFER TO POLICE REPORT

Taxi Voucher No.:

Are you claiming your own insurance  
policy for the repair of your vehicle?

No, Claim 3rd party

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
ANG QI HAO, VICTOR

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

28 June, 2017 2:45 pm

Date/Time:

28 June, 2017 2:45 pm



**Enquire Vehicle & Owner Information ( Vehicle No. SH8302J As At 26 Jun 2017 / 20:45:00 )****Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: L.17.1078.LT

**Current Owner Details**

Owner ID Type: Company

Owner ID: 199303821R

Owner Name: COMFORT TRANSPORTATION PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 383

Registered Street Name: SIN MING DRIVE

Registered Unit No: -

Registered Building Name: GAS BUILDING

Registered Postal Code: 575717

**Current Vehicle Details**

Vehicle No.: SH8302J

Make Description/Model: TOYOTA / PRIUS HYBRID 1.8 CVT

Insurance Company Name: INDIA INT'L INS PTE LTD



Co. Reg.. No.: 201212435M

Address: No.10 Kaki Bukit Road 2, #01-24 First East Centre Singapore 417868

Tel: +65 6747 6774

Email: bikeworkz@gmail.com

Date: 21.07.17

Mohamed Hassan Kuthoos

Blk 51C Lengkong Empat

#12-02

Singapore 417660

**BILL OF FBJ 3252T – HONDA NC750XA**

**Lump Sum Repair Cost**

**As recommended by Surveyor**

**\$11,800.00**

**Authorized Signature**



KM AUTO ASSESSORS PTE. LTD.  
Insurance Loss Assessors / Adjusters

47 Jalan Pemimpin  
#02-07 Halcyon 2  
Singapore 577200

T 6448 8208  
F 6442 9690  
E kmautoassessors@gmail.com  
Regn. No. 200907340Z

INVOICE  
NO. 7/TP1105

Messrs. MOHAMED HASSAN KUTHOOS  
51C LENGKONG EMPAT #12-02 S'PORE 417660

Date 20-Jul-17

7/7/TP018/I	Particulars	Amount
	<u>RE: FBJ 3252 T - HONDA NC750XA MOTOR CYCLE</u>	
	SURVEY FEE (INCL. PHOTOS & TRANSPORT CHARGES)	\$866.00
SGD:	( EIGHT HUNDRED AND SIXTY-SIX ONLY )	TOTAL: \$866.00

E. & O. E.

for KM AUTO ASSESSORS PTE. LTD.



KM AUTO ASSESSORS PTE. LTD.

Insurance Loss Assessors / Adjusters

47 Jalan Pemimpin

#02-07 Halcyon 2

Singapore 577200

T 6448 8208

F 6442 9690

E kmautoassessors@gmail.com

Regn. No. 200907340Z

# AUTOMOBILE INSPECTION REPORT NO. 7/7/TP018/I

To: MOHAMED HASSAN KUTHOOS  
51C LENGKONG EMPAT #12-02 S'PORE 417660

General Condition: ~~Poor~~/Fair/Good/Excellent

Reg. No.	FBJ 3252 T	Make/Model	HONDA NC750XA MOTOR CYCLE			Year	2014		
Engine No.	RC70E5006215	Chassis No.	JH2RC72B0EK003456			Colour	Red		
Condition of Tyres					Speedometer Reading - Km		51872		
Front N/S	METZLER 120/70ZR17	worn	10	%	Front O/S	N/A	worn	-	%
Rear N/S	METZLER 160/60ZR17	worn	10	%	Rear O/S	N/A	worn	-	%
As Requested By		YOURSELF			On	13-Jul-17		The Above Vehicle	
Was Inspected At ( 13-Jul-17 ) MOTOPLEX PL 10 KAKI BUKIT RD 2 #01-24 FIRST EAST CTR S'PORE 417868									
And The Undermentioned Damage Was Noted:-									

Front windshield grazed, sliced, bent, distorted, headlamp assy. grazed, sliced, distorted and displaced, headlamp top garnish dislodged, fastener snapped, n/s cowling grazed, sliced, bent and distorted, headlamp lower garnish bent and distorted, fastener snapped, n/s signal lamp grazed and sliced, handle bar bent and folded, n/s balancer grazed and sliced, n/s clutch lever bent, o/s balancer grazed and sliced, brake lever grazed and bent, o/s mirror broken, n/s mirror casing grazed and sliced, holder bent, handle bar holder bent, n/s top and mid fairings, fuel tank top cover dislodged, fasteners snapped, steering stem bent, front fork assy. grazed, sliced, bent and stiffened, mudguard bent and snapped, front wheel assy. grazed, sliced and bent, tyre grazed and sliced, brake disc warped, n/s fog lamp grazed, sliced, distorted and displaced, bracket twisted, n/s crash bar grazed and bent, engine n/s cover grazed and dented, lower cowling snapped and dislodged, exhaust header assy. grazed, dented and bent, n/s gear shift pedal bent and displaced, n/s footrests and bracket assy. bent, n/s side stand grazed and bent, rear swing arm assy. grazed and bent, n/s drive-chain cover grazed and sliced, rear wheel assy. bent and wobbles, n/s pillion hand rail grazed and sliced, rear box assy. grazed, sliced, bent and deformed, taillamp assy. loosened, fasteners snapped, n/s signal lamp grazed and sliced, rear no. plate bent and folded, holder assy. grazed and bent, reflector grazed and sliced.

Photographs:-	176 Copies	were taken at time of inspection and are attached .
The Repairers estimate was for a total amount of	\$	18,795.00
After adjustment the estimate was revised and agreed at	\$	15,318.80

## SPECIAL REMARKS

The Repairers were **NOT AUTHORISED** to proceed with the repairs.

**Survey was carried out without prejudice.**

The above were due to impacts to the frontal portion and side body of the motor cycle.

Alternatively, we recommend that repairs be carried out on a Lump Sum basis instead, @\$11,800/- Nett.

MICHAEL EE Dip A Eng , AMIRTE , AMSAE , AMSOE , AMIMI , MSAAA

Date 20-Jul-17



**KM AUTO ASSESSORS PTE. LTD.**  
Insurance Loss Assessors / Adjusters

47 Jalan Pemimpin  
#02-07 Halcyon 2  
Singapore 577200

T 6448 8206  
F 6442 9690  
E kmassessors@gmail.com  
Regn. No. 1909073407

# APPENDIX 'A'

TO REPORT NO: 7/7/TP018/I  
REGN. NO: FBJ 3252 T

Nature of Work and Materials	Repairers Estimate \$	Remarks	Amount Revised \$
1 pce headlamp assy.	680.00	grazed, sliced, distorted, displaced	680.00
1 pce headlamp top garnish	35.00	dislodged, fastener snapped	35.00
1 pce headlamp lower garnish	65.00	bent, distorted, fasteners snapped	65.00
2 pcs headlamp side cowlings	1,440.00	n/s only - grazed, sliced, bent	720.00
1 pce front windshield assy.	400.00	grazed, sliced, bent, distorted	400.00
1 pce n/s front signal lamp assy.	180.00	grazed & sliced	180.00
1 pce n/s front top fairing	350.00	dislodged, distorted, fasteners snapped	350.00
1 pce n/s front mid fairing	650.00	dislodged, distorted, fasteners snapped	650.00
1 pce fuel tank top cover	280.00	grazed, dislodged, fasteners snapped	280.00
2 pcs mirrors assy.	192.00	o/s broken, n/s grazed, sliced, holder bent	192.00
1 pce handle bar	250.00	bent & folded	250.00
1 set handle bar rubber grips	60.00	necessary	60.00
2 pcs handle bar balancers	130.00	grazed & sliced	130.00
1 pce n/s clutch lever	45.00	bent	45.00
1 pce o/s brake lever	68.00	grazed & bent	68.00
1 pce handle bar holder	225.00	bent	225.00
1 pce steering stem	480.00	warped	480.00
2 pcs front fork tubes	840.00	bent & stiffened	840.00
2 pcs front fork housings	870.00	o/s bent, n/s grazed, sliced, bent	870.00
2 pcs front fork oil seals	100.00	necessary	100.00
1 pce front fork oil	25.00	necessary	25.00
1 pce front mudguard	250.00	bent & snapped	250.00
1 pce front wheel rim	980.00	grazed, sliced, bent	980.00
1 pce front wheel shaft	72.00	bent	72.00
1 pce front wheel bearing	44.00	necessary	44.00
1 pce front tyre	180.00	grazed & sliced @90%	162.00
1 pce front brake disc	480.00	warped	480.00
1 pce front brake caliper assy.	630.00	not necessary	-
1 set fog lamps assy.	120.00	n/s grazed, sliced, distorted, bracket twisted	120.00
1 set front crash bars	450.00	n/s grazed & bent	450.00
1 pce engine n/s cover	320.00	grazed & dented	320.00
1 pce front lower cowling - centre	180.00	snapped & dislodged	180.00
2 pcs front lower cowlings - side	220.00	snapped & dislodged	220.00
1 pce exhaust header assy.	1,150.00	grazed, dented, bent	1,150.00
1 pce n/s gear shift pedal	145.00	bent & displaced	145.00
1 pce n/s front footrest	105.00	bent	105.00
1 pce n/s rear footrest	80.00	bent	80.00
1 pce n/s footrest bracket	375.00	bent	375.00
1 pce n/s side stand	90.00	grazed & bent	90.00
1 pce n/s drive-chain cover	90.00	grazed & sliced	90.00
1 pce rear swing arm assy.	1,300.00	grazed & bent	1,300.00
1 pce rear swing arm shaft	50.00	bent	50.00
1 pce rear swing arm bearing	120.00	necessary	120.00
1 pce n/s pillion hand rail	75.00	grazed & sliced	75.00
c/f	14,871.00		13,503.00
Total Amount Revised	\$		\$
Lump Sum Repairs Amount	\$		\$
It is estimated that the repairs will take		days to complete.	



**KM AUTO ASSESSORS PTE. LTD.**

Insurance Loss Assessors / Adjusters

47 Jalan Pemimpin

#02-07 Halcyon 2

Singapore 577200

T 6448 8208

F 6442 9690

E kmautoassessors@gmail.com

Regn. No. 200907340Z

**APPENDIX 'A'**  
**TO REPORT NO:**  
**REGN. NO:**

**7/7/TP018/I**  
**FBJ 3252 T**

Nature of Work and Materials	Repairers Estimate \$	Remarks	Amount Revised \$
b/f	14,871.00		13,503.00
1 pce rear box assy.	450.00	grazed, sliced, bent, distorted	450.00
1 pce rear box support bracket assy.	480.00	bent	480.00
1 pce rear wheel rim	1,080.00	bent & wobbles	1,080.00
1 pce rear wheel shaft	68.00	bent	68.00
1 pce rear wheel bearing	22.00	necessary	22.00
1 pce rear tyre	195.00	not necessary	-
1 pce n/s rear signal lamp assy.	165.00	grazed & sliced	165.00
1 pce taillamp assy.	198.00	loosened, displaced, fasteners snapped	198.00
1 pce rear no. plate	25.00	bent & folded	25.00
1 pce rear no. plate holder assy.	68.00	grazed & bent	68.00
1 pce rear no. plate holder reflector	38.00	grazed & sliced	38.00
1 pce front no. plate - sticker type	15.00	necessary	15.00
1 set body decals	120.00	necessary	120.00
		less 10% <i>12407</i>	16,232.00
		<i>11166.3</i>	1,623.20
	17,795.00		14,608.80
Transportation of motor-cycle to workshop charges (Twice).	100.00		80.00
Remove lamps and damaged parts, dismantle front fork assy., check, repair damaged parts, whichever possible and necessary, replace damaged parts, reassemble fork assy., refit, realign front steering and refocus headlight.	400.00		280.00 <i>250</i>
Paint replacement parts and repaint damaged sections in and outside.	500.00		350.00 <i>300</i>
			<i>630</i>
<b>TOTAL</b>	<b>18,795.00</b>	<i>11796.3</i>	<b>15,318.80</b>
		<i>20%: 9400</i>	
		<i>5 Days.</i>	
<b>Total Amount Revised</b>	<b>\$</b>	<b>15,318.80</b>	
<b>Lump Sum Repairs Amount</b>	<b>\$</b>	<b>11,800.00</b>	
<b>It is estimated that the repairs will take</b>	<b>SIX</b>	<b>days to complete.</b>	

## YOUR POLICY SCHEDULE

This document forms part of your contract with us and should be read together with your Certificate of Insurance and your Policy Details. Do let us know if any of the details shown here need to be amended or updated.

### Motorcycle Insurance

<b>Policy number</b>	: MC/00330672
<b>Period of cover</b>	: Policy begins 09/09/2016 and runs until 16/09/2017 (both dates inclusive)
<b>Premium</b>	: S\$ 348.38 (inclusive of GST)
<b>Policy Excess</b>	: S\$ 0.00
<b>Policyholder</b>	
<b>Policy holder</b>	: KUTHOOS, MOHAMED HASSAN
<b>Mailing address</b>	: 51C LENGKONG EMPAT, 12-02, Singapore 417660
<b>E-mail address</b>	: hassan8627@gmail.com
<b>No Claims Discount (NCD)</b>	: 0%
<b>Mobile Number</b>	: 91766786
<b>Offence Free Discount</b>	: No
<b>Driver Details</b>	
<b>Main Driver</b>	: KUTHOOS, MOHAMED HASSAN
<b>Date of birth</b>	: 27/10/1986
<b>Gender</b>	: Male
<b>Marital status</b>	: Married
<b>Occupation</b>	: Private sector : workers/skilled workers
<b>Driving experience</b>	: > 5
<b>Named Driver</b>	
<b>Important Note:</b> The policy only cover the main driver and the following named driver:	
<b>No named driver declared</b>	
<b>Motorcycle Details</b>	
<b>Vehicle Registration</b>	: FBJ3252T
<b>Chassis number</b>	: JH2RC72B0EK003456
<b>Make and model</b>	: Honda NC 750X
<b>Year of registration</b>	: 2014
<b>Motorcycle usage</b>	: Private Use + Commuting to work
<b>Finance company/ Hire purchase</b>	:
<b>Third-Party Only Cover Details</b>	
<b>Limits (Up to)</b>	
✓ Third-party property damage	S\$ 500,000
✓ Third-party death or bodily injury	Unlimited

**Direct Asia Insurance (Singapore) Pte. Ltd.**



**Edip Okur**  
**Chief Underwriting Officer**



3. We also wish to inform you that a payment of \$96.00 for the road tax of your vehicle for the licensing period 17 Sep 2016 to 16 Mar 2017 has been made on the same day.

4. You can login to LTA's e-Services@ONE.MOTORING (<http://www.onemotoring.com.sg>) to access a wide range of vehicle-related services using your NRIC number/FIN and SingPass. If you do not have a SingPass, you can request for it at <https://www.singpass.gov.sg/singpass/register/registerinstructions>. If you are ineligible for SingPass or do not have a FIN, please note that you will not be able to login to LTA's e-Services@ONE.MOTORING. You may contact our Customer Service hotline at 1800-CALL LTA (1800-2255 582) for assistance. A separate Transaction PIN is required for the following transactions via the Internet or at our Electronic Service Agents. Please apply for your Transaction PIN before performing these transactions. Visit <http://www.onemotoring.com.sg> > **LTA Information & Guidelines > Transaction PIN & User Account** for more information about obtaining Transaction PIN and the documents needed.

- a. Vehicle PIN - Transfer of Ownership and De-registration of Vehicle
- b. TCOE PIN - Transfer of TCOE (For Category C and E COE bid under individual)
- c. Rebate PIN - Transfer and Splitting of PARF/COE Rebate

5. All new In-vehicle Units (IUs) are covered by a 5-year warranty against manufacturer's defect.

6. Please contact our customer service officers on tel: 1800-CALL LTA (1800-2255 582) if you have any question.

Yours sincerely

NG LAY CHOO (MS)  
DEPUTY DIRECTOR, VRL SERVICE OPERATIONS  
VEHICLE SERVICES GROUP  
LAND TRANSPORT AUTHORITY

(This is a computer-generated notice that requires no signature.)

**Annex A**

Transaction ref 20160909144612669471

The owner and vehicle particulars for Vehicle No. FBJ3252T as at 09 Sep 2016 are as follows:

27. Maximum Laden Weight(kg)	: 426
28. Open Market Value	: \$6,598.00
29. PARF Eligibility	: No
30. PARF Eligibility Expiry Date	: -
31. Minimum PARF Benefit	: \$0.00
32. No. of Transfers	: 3
33. IU Label No.	: 713783357
34. COE No.	: 2014040106000292E
35. COE Expiry Date	: 16 Mar 2024
36. COE Category	: D - Motorcycle
37. Quota Premium/Prevailing Quota Premium	: \$4,001.00 / -
38. Actual Quota Premium/PQP Paid	: \$4,001.00
39. Actual ARF Paid	: \$990.00
40. CO2 Emission(g/km)	: -
41. Actual CEVS Rebate Utilised	: -
42. CEVS Surcharge Paid	: -
43. Actual Green Vehicle Rebate Utilised	: -
44. Vehicle Lifespan Expiry Date	: -
45. Road Tax Amount	: \$96.00
46. Road Tax Start Date	: 17 Sep 2016
47. Road Tax End Date	: 16 Mar 2017
48. Remarks	: To renew the COE, the Prevailing Quota Premium payable is that of Category D.

# Survey Department Check List (Case Handler)

Reference No. : CS3/II/7013298/Gqb-1  
 Policy Type: OD / (TP) / TP RES / TL / EVA

FBJ 3252T

Case Handler

Typist

**Admin** (Cithu): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

## (1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

**Surveyor** (Gua Qiang): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages


## (2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

--	--	--	--

## (3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			

## (4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Cithu 19/12/17  
 Case Handler Date



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref : CS3/III17013298/Gqbe2-1	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date : 20-12-2017	
			Code : III2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SH 8302J	Veh. Inspected	FBJ 3252T	
Policy No.		Coverage (\$)	0.00	
Claim No.	MCT17060906	Excess (\$)	0.00	
Assign From	DANIEL POOI	Assign Date	15/09/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA NC750XA	c.c	745	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JH2RC72B0EK003456	Colour	RED	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	120/70-17	METZELER	2 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60-17	METZELER	2 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	26/06/2017	Inspection Date	11/07/2017	
Survey held at	MOTOPLEX PTE LTD 10 KAKI BUKIT ROAD 2 #01-24 FIRST EAST CENTRE SINGAPORE 417868			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBJ 3252T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	HEADLAMP ASSY	GRAZED	680.00	680.00
1	HEADLAMP TOP GARNISH	DISLODGE	35.00	35.00
1	HEADLAMP LOWER GARNISH	BENT	65.00	65.00
2	HEADLAMP SIDE COWLINGS	N/S GRAZED	1,440.00	720.00
1	FRONT WINDSHIELD ASSY	GRAZED	400.00	400.00
1	N/S FRONT SIGNAL LAMP ASSY	GRAZED / SLICED	180.00	180.00
1	N/S FRONT TOP FAIRING	DISLODGE	350.00	350.00
1	N/S FRONT MID FAIRING	DISLODGE	650.00	650.00
1	FUEL TANK TOP COVER	GRAZED	280.00	280.00
2	MIRROR ASSY	O/S BROKEN / N/S GRAZED	192.00	192.00
1	HANDLE BAR	BENT / FOLDED	250.00	250.00
1	SET HANLDE BAR RUBBER GRIPS	NECESSARY	60.00	60.00
2	HANLDE BAR BALANCERS	GRAZED / SLICED	130.00	130.00
1	N/S CLUTCH LEVER	BENT	45.00	45.00
1	O/S BRAKE LEVER	GRAZED / BENT	68.00	68.00
1	HANDLE BAR HOLDER	BENT	225.00	225.00
1	STEERING STEM	WARPED	480.00	480.00
2	FRONT FORK TUBES	BENT / STIFFENED	840.00	840.00
2	FRONT FORK HOUSINGS	O/S BENT / N/S GRAZED	870.00	870.00
2	FRONT FORK OIL SEALS	NECESSARY	100.00	100.00
1	FRONT FORK OIL	NECESSARY	25.00	25.00
1	FRONT MUDGUARD	BENT / SNAPPED	250.00	250.00
1	FRONT WHEEL RIM	GRAZED	980.00	980.00
1	FRONT WHEEL SHAFT	BENT	72.00	72.00
1	FRONT WHEEL BEARING	NECESSARY	44.00	44.00
1	FRONT TYRE (90%)	GRAZED / SLICED	180.00	162.00
1	FRONT BRAKE DISC	WARPED	480.00	480.00
1	FRONT BRAKE CALIPHER ASSY	NOT NECESSARY	630.00	-
1	SET FOG LAMPS ASSY	GRAZED	120.00	120.00

Report Ref No. CS3/III17013298/Gqbe2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT CRASH BARS	GRAZED / BENT	450.00	450.00
1	ENGINE N/S COVER	GRAZED / DENTED	320.00	320.00
1	FRONT LOWER COWLING - CENTRE	SNAPPED / DISLODGE	180.00	180.00
2	FRONT LOWER COWLINGS - SIDE	SNAPPED / DISLODGE	220.00	220.00
1	EXHAUST HEADER ASSY	GRAZED	1,150.00	1,150.00
1	N/S GEAR SHIFT PEDAL	BENT / DISPLACED	145.00	145.00
1	N/S FRONT FOOTREST	BENT	105.00	105.00
1	N/S REAR FOOTREST	NOT NECESSARY	80.00	-
1	N/S FOOTREST BRACKET	NOT NECESSARY	375.00	-
1	N/S SIDE STAND	NOT NECESSARY	90.00	-
1	N/S DRIVE-CHAIN COVER	NOT NECESSARY	90.00	-
1	REAR SWING ARM ASSY	TO REPAIR SEE LABOUR	1,300.00	-
1	REAR SWING ARM SHAFT	BENT	50.00	50.00
1	REAR SWING ARM BEARING	NECESSARY	120.00	120.00
1	N/S PILLION HAND RAIL	NOT NECESSARY	75.00	-
1	REAR BOX ASSY	GRAZED	450.00	450.00
1	REAR BOX SUPPORT BRACKET ASSY	NOT NECESSARY	480.00	-
1	REAR WHEEL RIM	NOT NECESSARY	1,080.00	-
1	REAR WHEEL SHAFT	NOT NECESSARY	68.00	-
1	REAR WHEEL BEARING	NOT NECESSARY	22.00	-
1	REAR TYRE	NOT NECESSARY	195.00	-
1	N/S REAR SIGNAL LAMP ASSY	NOT NECESSARY	165.00	-
1	TAILLAMP ASSY	LOOSENED	198.00	198.00
1	REAR NO. PLATE	BENT / FOLDED	25.00	25.00
1	REAR NO. PLATE HOLDER ASSY	GRAZED / BENT	68.00	68.00
1	REAR NO. PLATE HOLDER REFLECTOR	GRAZED / SLICED	38.00	38.00
1	FRONT NO. PLATE - STICKER TYPE	NECESSARY	15.00	15.00
1	SET BODY DECALS	NECESSARY	120.00	120.00
	LESS 10% DISCOUNT		-	-1,240.70
			17,795.00	11,166.30

Report Ref No. CS3/III17013298/Gqbe2-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TRANSPORTATION OF MOTOR-CYCLE TO WORKSHOP CHARGES (TWICE).		100.00	80.00
	REMOVE LAMPS AND DAMAGED PARTS, DISMANTLE FRONT FORK ASSY, CHECK, REPAIR DAMAGED PARTS, WHICHEVER POSSIBLE AND NECESSARY, REPLACE DAMAGED PARTS, REASSEMBLE FORK ASSY, REFIT REALIGN FRONT STEERING AND REFOCUS HEADLIGHT. INCLUSIVE OF THE REPAIR OF REAR SWING ARM ASSY.		400.00	250.00
	PAINT REPLACEMENT PARTS AND REPAINT DAMAGED SECTIONS IN AND OUTSIDE.		500.00	300.00
			1,000.00	630.00
	<b>GRAND TOTAL</b>		<b>18,795.00</b>	<b>11,796.30</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>9,400.00</b>

Report Ref No. CS3/III17013298/Gqbe2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.