

22/03/2017

ASS. REC. BY:

REF: CS/FC117018114 / M/vbn2

Special Instruction:

SURVIVOR

WS

Ma

ASSIGNMENT (Office)

From (Person): Lurene Jaw

of

FC1

Date/Time: 20/9/17 9:11am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PA 7805D

Insured:

SHC 7608 R

at Workshop m/s

Lim Tan Motor

Tel:

64 520893 / 97921329

of Blk176 Sin Ming Drive #03-09 / 10/06

Policy No:

Claim No:

D1700 8896MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 26/08/2017

CA / REV / REP. / REV 24 HRS

'wp'

01-03-2018 @ after 10:30am

H.O.D. Endorsement

Date/Time: 20/9/17 9:43am

Person Contacted:

Venus Lee

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

PA 7805D-X

SHC 7608 R - CS / ICS17000530 / H1 vbn2 - D.O.A: 9/11/2017

5/3/18

Email

preli revised to FC1

1/6/18

@ 1045am LS \$ 3700 confirmed with Richard (Red 3005, 45%)

FCL

ASSIGNMENT

Date 11/3/18

Estimated Cost

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To: Inspected Vehicle No. PA 7805D
at Workshop No. Lim Tan Motor
of BIK 176 Sin Ming Drive #03-09

Insured

Policy No.

Claims No.

Sum Insured

Excess


Claims Report

After 1030 am

Make of Vehicle

Policy Condition

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value

x IDAC Accident Report Consistent? : Yes or No

GM / PR / Seat Consistent? : Yes or No

Est. Repairs days Real: Yes or No

LUM SUM % G Val: Yes or No

CA / REV / REP / 24 HRS ^{1 wks}

Date Person Contacted

Vehicle IN / OUT

Date Time Action Instruction

PA 7805D

SEP 2008

Type M Car M Cycle ☒ Van Long Taxi Bumper Motor

Truck Trailer

Make

SCANIA

17005

Model

MUR

So. Facing

624514

Eng No.

C/V

Y22K4 X20001859328

Gen. Cond. Good Fair Poor Burnt

Steering ☒ Jammed / Leaked / Burnt or

Brake ☒ Jammed / Leaked / Burnt or

Mod. ☒ N / S / R / L / STD / AIR / H /

Tyre Size

295/80/R22.5

BS / DUNLOP / NOVAT / 3Y / RS / LIZA / MIC / OHTSU / PR / SUM
TOYO / YOKO ^{B.S.}

Front

Rear

R/S

L/S

L/S

R/S

D/O

26/8/2018

D/O

7/3/2018

Survey/repair

Des. of Damages: Fr. ☒ BS ☒ N/S ☒ L/S ☒ R/S

OS Body

The L/C / Chassis frame / Body Structure affected due to collision

RECEIVED 01 JUN 2018

Date Time File Pass No.

☐ Prelim. Report
☐ Final Report

Prelim. Report

Final Report

Days Of Repair

4

Resurvey No. of Trip

-

Survey Fee

Insurance

Repair Fee

Other

Total

Remarks

Signature

Date

Date Time File Return

116- typist

Report Format

CWS

LUM SUM

LS \$3700k

Add Fee:

Storage

Insurance

Repair

Other

Total

Remarks

145
50

22

217



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17018114/M1vb

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 20-09-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7608R	Veh. Inspected	PA 7805D
Policy No.		Coverage (\$)	0.00
Claim No.	D17008896MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	20/09/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/08/2017	Inspection Date
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D17008896MFSH

Our ref: CS/FCI17018114/M1vb

Date : 5/3/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. PA 7805D


We thank you for your instruction on 20/9/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on 1/3/2018 at the premises of M/s LIM TAN MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$6,705.00
Revised Estimate Amount	: S\$4,665.00
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s body



Comments/Present Status:
Damages Consistent

Yours faithfully,

MA CHIN FOOK
Automotive Assessor

Survey Department Check List (Case Handler)

Reference No. : CS/FCI/7018114/Mlvb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 16/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	18-09-2017	Our Ref No. D17008896MFSH
Accident Date	26-08-2017	Claim Type. Third Party
Insured Vehicle	SHC7608R	Third Party Vehicle. PA7805D
Survey Location	BLK 176 SIN MING DRIVE #03-09/10/06 SIN MING AUTOCARE	
Contact Person.	VENUS LEE	
Contact No.	64520893/ 97921329	Fax No. 64589127
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LIM TAN MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/228133)



PRI Documents



Close



PRI Header Details

Claim No	D17008896MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & LIM TAN N
Workshop Name	LIM TAN MOTOR PTE LTD (Contact Person : VENUS LEE)	Survey Location & Contact Details	BLK 176 SIN MING DRIVE #03-09/10/06 SIN MING AUT Mobile: 97921329 , Phone: 64520893 , Fax: 6458912; EmailId: VENUS@LTM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7608R	TP Vehicle No	PA7805D
PRI Recieved Date	18-09-2017 10:19:05 PM	Surveyor Appointed Date	20-09-2017 09:12:45 AM	Surveyor Accept Date	20-09-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	20-09-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 5 March 2018 8:33 AM
To: 'Claim Workflow System'
Cc: LURENEJAW@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17008896MFSH/1, PA 7805D
Attachments: PA 7805D PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle PA 7805D
Date of survey: 1/3/2018
Number of days:4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 20 September 2017 9:44 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17008896MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Wednesday, 20 September, 2017 9:11 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; LURENEJAW@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17008896MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	1800K
Vehicle Details	
Vehicle No.:	PA7805D
Vehicle to be Exported:	No
Intended De-registration Date:	05 Mar 2018
Vehicle Make:	SCANIA
Vehicle Model:	KIB4X2 MT 12L ABS TURBO 19T WB-5850
Primary Colour:	Multi-Colour
Manufacturing Year:	2007
Engine No.:	6354360
Chassis No.:	YS2K4X20001859328
Maximum Power Output:	-
Open Market Value:	\$143,924.00
Original Registration Date:	15 Sep 2008
First Registration Date:	15 Sep 2008
Transfer Count:	0
Actual ARF Paid:	\$7,197.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Sep 2018
COE Category:	C - Goods Vehicle & Bus

COE Period(Years):	10
QP Paid:	\$12,659.00
COE Rebate Amount:	\$664.00
Total Rebate Amount:	\$664.00

The information contained herein is correct as at 05 Mar 2018

OK

Text size + -

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company
Cert No.: 28011800K

Owner ID Type: Business

Owner Name: LUXURY COACH SERVICE

Registered Address: 100 ORCHARD ROAD #02-09/10 CONCORDE HOTEL & SHOPPING MALL SINGAPORE 238840

Mailing Address: -

Birth Date: -

Vehicle Particulars

Vehicle No.: PA7805D

Previous Vehicle No.: -

Effective Date of
Ownership: 15 Sep 2008

Original Regn Date: 15 Sep 2008

Registration Date: 15 Sep 2008

Year of Manufacture: 2007

Vehicle Type: Private Hire (Chauffeur) Bus/Coach/Minibus

Vehicle Scheme: Public Service Vehicle (Others)

Vehicle Attachment 1: Air-Conditioned

Vehicle Attachment 2: -

Vehicle Attachment 3: -

Vehicle Make: SCANIA

Vehicle Model: KIB4X2 MT 12L ABS TURBO 19T WB-5850

Primary Colour: Multi-Colour

Secondary Colour: -

Passenger Capacity: 45

Chassis No.: YS2K4X20001859328

Engine No.: 6354360

Engine Capacity/Power
Rating: 11705 cc / -

Maximum Power Output: -

Propellant: Diesel

Max Unladen Weight: 12460 kg

Maximum Laden
Weight: 19000 kg

Open Market Value: \$143,924.00

PARF Eligibility: No

PARF Eligibility Expiry
Date: -

Minimum PARF Benefit: -

No. of Transfers: 0

IU Label No.: 2050065274

COE No.: 2008080105000531H

COE Expiry Date: 14 Sep 2018

COE Category: C - Goods Vehicle & Bus

COE Registration
Category: C - Goods Vehicle & Bus



ESTIMATE TO REPAIR

VEHICLE NO. : PA 7805 D
 MAKE : SCANIA
 MODEL : KIB4X2 MT 12L ABS TURNO 19T WB-
 YEAR : 2007
 CHASSIS NO : YS2K4X20001859328

SURVEYOR NAME : LKK
 DATE OF SURVEY : 01 MAR 2018
 TIME OF SURVEY :

DATE : 18-Sep-17
 DATE OF ACCIDENT : 26-Aug-17
 THIRD PARTY REF : SHC 7608 R / FIRST CAPITAL

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1pc	n/s front body panel	S.Nett		1800.00	1800.00
1pc	n/s front hub cap	S.Nett		950.00	950.00
10 pcs	n/s front wheel nut	S.Nett	\$5.00	50.00	50.00
10 pcs	n/s front wheel nut cap	S.Nett	\$60.00	600.00	600.00
1pc	excursion bus sticker	S.Nett		25.00	25.00
1set	n/s front body pad sticker	S.Nett		280.00	280.00
	To putty & spay paint			600	1,000.00
	To replace wheel hub & cap			80	100.00
	Labour charge			600	1,200.00
TG-VL/-	Total				\$6,705.00
Not pushan 2 hours Repair After paint photo LKK needs 1/3/2018 4w days 2700/2 4w days 5/3/18					

Bik 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No. 199307277D

GST Reg No. M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17018114/M1vbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-06-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7608R	Veh. Inspected	PA 7805D	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17008896MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	20/09/2017	
2. Vehicle Particulars & Condition				
Make & Model	SCANIA	c.c	11705	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	YS2K4X20001859328	Colour	MULTI	
Odometer	624514	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	BRIDGESTONE	8 mm	
L/H Front Tyre	295/80 R22.5	BRIDGESTONE	8 mm	
R/H Rear Tyre	295/80 R22.5	BRIDGESTONE	8 mm	
L/H Rear Tyre	295/80 R22.5	BRIDGESTONE	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/08/2017	Inspection Date	01/03/2018	
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 7805D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	O/S FRONT BODY PANEL (SN)	DISTORTED	2,500.00	1,800.00
1	O/S FRONT HUB CAP (SN)	TORN	950.00	950.00
10	O/S FRONT WHEEL NUT @\$5.00 (SN)	CUT (7 PCS ONLY)	50.00	35.00
10	O/S FRONT WHEEL NUT CAP @\$60.00 (SN)	DENTED	600.00	600.00
1	EXCURSION BUS STICKER (SN)	NOT NECESSARY	25.00	-
1	SET O/S FRONT BODY PAD STICKER (SN)	NOT NECESSARY	280.00	-
			4,405.00	3,385.00
LABOUR				
	TO PUTTY & SPRAY PAINT.		1,000.00	600.00
	TO REPLACE WHEEL HUB & CAP.		100.00	80.00
	LABOUR CHARGE.		1,200.00	600.00
			2,300.00	1,280.00
GRAND TOTAL			6,705.00	4,665.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,700.00

Report Ref No. CS/FCI17018114/M1vbn2

MA CHIN FOOK

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.