

ASS. REC. BY:

REF: CS/MSG17018334 / Aqbn2

Special Instructions:

Surveyor
Meimien

Adrian

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSG

Date/Time:

25/9/17 9:45am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJH 2692D

Insured:

8LL875L

at Workshop m/s

Precise Auto

Tel:

67457367

of No. 1 Kaki Bukit Ave 6, # 02-34/36, 417883

Policy No: 80425909 QMX

Claim No:

530556

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 21/09/2017

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

25/9/17 9:49am

Person Contacted:

Yan Hong

Vehicle IN OUT

urgent

Date/Time

Action/Instruction

(✓)

Estimate

SJH 2692D-X

8LL875L

26/9/17 @ 11:00am Informed Christina Wong, we are pending estimate from repair
06/12/17 @ 2:48pm revised to Christina Wong via Meimien.

Est. Repairs:

10 days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

'wp'

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

TP MSG.

D.O.A.

D.O.I.

25/09/17

Survey held at

Precise

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

MV: 18K

PV: 10K

Net: 8K.

RECEIVED 06 DEC 2017

Date/Time File Pass to?

06/12/17 turnst

☐

: Preli. Report

☐

: Final Report

Date/Time File Return to?

2)

Days Of Repair:

10

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

mer-TP

Lump Sum / I.B.A. (\$

7500

Survey Fee

Transportation

) S + RS S

) Photos

) Others

)

TOTAL

300

10

310