

12/09/2017

ASS. REC. BY:

REF: CS/MSG17018460/Grber

Special Instruction:

SIV/210X

GQ
mamen

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSIG

Date/Time:

26/9/17 10:39 am

Estimated Cost:

Bill to:

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKE 3797 H

Insured:

SKK9793 Y

at Workshop m/s

96 Motorsports

Tel:

67026996

of 62/64 kaki Bukit Ave 6, 417893

Policy No:

29021248QMX

Claim No:

530697

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/09/2017

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

26/9/17 11:25am

Person Contacted:

Rachel

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

Lydia

SKE 3797 H - X

SKK9793 Y - X

Sent pending est to Katherine

(08/11/13)

AS REC. BY: XPRREF: MS/G**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s 96 Motorsports

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$ 28K.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKE3797H Yr Regn: 30 Jun/2009Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Golf C.C. 1390Colour: yellow A/C: Insured / Std / NI / NASp. Reading: 157005 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZ881K89W570209Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/40R18R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 26-09-17Survey held at W/S 2:30pmDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop orN/S Frnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Confirm L/S \$ 2700 @ 4 days
Red: \$ 2202.85, 45%.

RECEIVED 2 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report1) typist☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4Resurvey No. of Trip: 1Survey Fee: 200

Transportation: _____

S + RS: _____

Photos: 10

Others: _____

TOTAL: 210Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Report Format: TPLump Sum / I.B.I. (\$ 2700)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17018460/Grb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 26-09-2017



Code : MSG

1.

Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKK 9793Y	Veh. Inspected	SKE 3797H
Policy No.	29021248QMX	Coverage (\$)	0.00
Claim No.	530697	Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	26/09/2017

2.

Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3.

Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4.

Description of Damages

--

5.

General Information

Accident Date	22/09/2017	Inspection Date	26/09/2017
Survey held at	96 MOTORSPORTS PTE LTD 62/64 KAKI BUKIT AVENUE 6 SINGAPORE 417893 ARK @ KB		

5a.

Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Sep 2017		26 Sep 2017 10:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CHIN WENG SENG, ID: S7964824H, Tel: +6581898366, Email: NOEMAIL		
Main Claimant:	Soo Yong Cai, ID: S9329515C		
Vehicle Reg. No.:	SKE3797H	Date of Loss:	22/09/2017 18:00 - :59
Claim Type:	TP / 530697	Policy/Cover Note No.:	29021248QMX (Comprehensive) Coverage: 10/09/2017 - 09/09/2018
Vehicle Reg. No. (Insured):	SKK9793Y	Policy No. (Claimant):	
		Excess:	
Repairer:	96 Motorsports Pte Ltd (HQ) 62/64 Kaki Bukit Avenue 6, 417893 Kaki Bukit - Tel: 6702 6996		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/09/2017]		
Driver/Custodian (Insured):	CHIN WENG SENG (38 / Male), NRIC: S7964824H, Tel: +6581898366		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9515C
Vehicle Details	
Vehicle No.:	SKE3797H
Vehicle to be Exported:	No
Intended De-registration Date:	28 Jun 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	NEW GOLF 1.4 AT 5K13G5
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	CAX259405
Chassis No.:	WVWZZZ1KZ9W570209
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$21,391.00
Original Registration Date:	30 Jul 2009
First Registration Date:	30 Jul 2009
Transfer Count:	2
Actual ARF Paid:	\$21,391.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jul 2019
PARF Rebate Amount:	\$11,765.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jul 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$7,090.00
COE Rebate Amount:	\$769.00
Total Rebate Amount:	\$12,534.00

The information contained herein is correct as at 28 Jun 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/09/2017 14:17
Date Of Accident	22/09/2017 18:45
Exact Location Of Accident	KPE EXIT BUANGKOK EAST DRIVE > SENGKANG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKE3797H
Insured/Policyholder	
Name Of Registered Owner	SOO YONG CAI
NRIC No	S9329515C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82289173
Alternative Phone No	OTHERS-82289173

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	NEW GOLF-1.4 TSI (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5087026127
Cover Note Number	

Driver

Name of Driver	SOO YONG CAI
NRIC No	S9329515C
Date Of Birth	11/08/1993
Occupation	INDOOR
Date Of Driving Pass	19/08/2015
Driving Experience	2 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-82289173
Fax Number	
Contact Number	OTHERS-82289173
Email Address	NOEMAIL

Address	BLK 128D #07-325 PUNGGOL FIELD WALK
Postcode	824128
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN: ATTENDED BY SITI

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKK9793Y
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF INJURED PERSON 1

Name	SOO YONG CAI
Approximate Age	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Singapore 415933
Tel: 67416697
Fax: 67492305


Email: enquiry@idac-sg.com

Name:

NRIC/FIN No.:

25 SEP 2017

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

one the stated date and time. I vehicle A was traveling on the stated Rd. As I was moving forward suddenly vehicle B cut in from my left side and collided with my front left portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Singapore 415933
Tel: 67416697
Fax: 67492505

Reporting Centre Personnel's Signature
Name: Email: vackb@singnet.com.sg
NRIC/FIN No.:

25 SEP 2017

ESTIMATE

Our Ref: SKE 3797 H

Date: 29 September 2017

Your Ref: SKK 9793 Y

Vehicle No: SKE 3797 H
Make & Model: VW New Golf 1.4 (A)
Chassis No: WVVZZZ1KZ9W570209

No	Qty	Particulars	Amount
1	1	Front Fender Panel - LH <i>Bruc</i>	662.35
2	1	Front Bumper Face <i>Cut</i>	1,390.20
3	1	Front Bumper Side Retainer - LH <i>MBL</i>	54.55
4	1	Front 18" Alloy Wheel Rim - LH <i>Cut</i>	1,420.75
Sub-Total			3,527.85
Less 0%			0.00
Total Part (S\$)			3,527.85

No	Particulars	Amount
1	To remove/install left front fender and front bumper accident damaged parts to replace, align and adjust if necessary. <i>400</i>	600.00
2	To check front lightings and electrical wiring systems include focusing both headlights and adjust if necessary. <i>NNX</i>	50.00
3	To remove/install left front wheel to transfer tyre to new alloy wheel rim include balancing the wheel. <i>30</i>	45.00
4	To putty and re-spray painting on left front fender and front bumper face. <i>400</i>	600.00
5	Rust-proofing on the left front accident affected portions. <i>NNX</i>	80.00
Total Labour (S\$)		1,375.00

GRAND TOTAL (S\$) 4,902.85

207.1
5%: 2001.75
550
830
3381.75
20%: 2700

4 Days.

62 & 64 Kaki Bukit Ave 6 Ark
@ KB Singapore 417893

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Sep 2017		26 Sep 2017 10:39 Edit Adj Rpt	S\$3,381.74 Edit Estimates	S\$3,381.74 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	CHIN WENG SENG , ID: S7964824H, Tel: +6581898366, Email: NOEMAIL								
Main Claimant:	Soo Yong Cai , ID: S9329515C								
Vehicle Reg. No.:	SKE3797H	Date of Loss:	22/09/2017 18:00 - :59 [97 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 530697	Policy/Cover Note No.:	29021248QMX (Comprehensive) Coverage: 10/09/2017 - 09/09/2018						
Vehicle Reg. No. (Insured):	SKK9793Y	Policy No. (Claimant):							
		Excess:							
Repairer:	96 Motorsports Pte Ltd (HQ) 62/64 Kaki Bukit Avenue 6, 417893 Kaki Bukit - Tel: 6702 6996								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 27/09/2017]								
Driver/Custodian (Insured):	CHIN WENG SENG (38 / Male), NRIC: S7964824H, Tel: +6581898366								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
<ul style="list-style-type: none"> MSIG_SG (08/01/2018): Photos of third party vehicle 									
ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKE3797H (530697)**
[SKK9793Y]
TP
Soo Yong Cai
Sep 22 2017 6:00PM
[CHIN WENG SENG]
96 Motorsports Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/09/17 17:26	Accident Statement From: SC - Reg. No: SKK9793Y, Claimant: CHIN WENG SENG	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/01/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
2	11/01/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
3	11/01/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
4	11/01/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
5	11/01/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
6	11/01/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
7	11/01/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
8	11/01/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
9	11/01/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
10	11/01/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
11	11/01/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
12	11/01/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
13	11/01/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
14	11/01/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
15	11/01/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
16	11/01/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
17	11/01/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
18	11/01/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
19	11/01/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
20	02/07/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
21	02/07/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
22	02/07/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
23	02/07/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
24	02/07/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
25	02/07/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
26	02/07/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/09/17 17:26	SKE3797H E FILE REPORT From: SC - Reg. No: SKK9793Y, Claimant: CHIN WENG SENG	 Load PDF	
2	25/09/17 17:27	PRI Request	 Load PDF	
3	26/09/17 10:38	TP Agree on SJE.	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17018460/GRBE2

Date: 06/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29021248QMX

Claimant Vehicle No : SKE3797H

Insured Vehicle No : SKK9793Y

Date of Loss: 22/09/2017

Nature of Claim: TP

Claim No: 530697

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKE3797H

Make & Model: VOLKSWAGEN NEW GOLF 5K13G5, 1.4 (A)

Engine No: CAX259405

Reg. Date: 30/07/2009 (Man. Year: 2009)

Chassis No: WVVZZZ1KZ9W570209

Colour: Yellow

Odometer: 157005 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18

Rear Tyre Size: 225/40 R18

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,527.85	2,551.74	976.11	27.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,375.00	830.00	545.00	39.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,902.85	3,381.74	1,521.11	31.03
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	4,902.85	2,700.00	2,202.85	44.93
+ GST 7.00/7.00% (S\$)	343.20	189.00	154.20	44.93
Nett Amount (S\$)	5,246.05	2,889.00	2,357.05	44.93

INSPECTION

Date of Assignment: 26/09/2017

Date Inspected: 26/09/2017 Inspected At:

96 Motorsports Pte Ltd (HQ)
62/64 Kaki Bukit Avenue 6
Singapore 417893

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jul 2018)
Parts:	144	VOLKSWAGEN NEW GOLF 5K13G5 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKE3797H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER PANEL - LH	Buckled	662.35 F	*662.35 FL
2	1		*FRONT BUMPER FACE	Cut	1,390.20 F	*1,390.20 FL
3	1		*FRONT BUMPER SIDE RETAINER - LH	Necessary	54.55 F	*54.55 FL
4	1		*FRONT 18 ALLOY WHEEL RIM - LH	Cut	1,420.75 FS	*550.00 FS
					Sub Total (S\$)	3,527.85
					- List Item Discount on L Items 0.00/5.00% (S\$)	0.00
					Total Parts (S\$)	3,527.85
						2,657.10
						105.36
						2,551.74

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE / INSTALL LEFT FRONT FENDER AND FRONT BUMPER ACCIDENT DAMAGED PARTS TO REPLACE, ALIGN AND ADJUST IF NECESSARY	New	600.00	400.00
2	TO CHECK FRONT LIGHTINGS AND ELECTRICAL WIRING SYSTEMS INCLUDE FOCUSING BOTH HEADLIGHTS AND ADJUST IF NECESSARY	New	50.00	0.00
3	TO REMOVE / INSTALL LEFT FRONT WHEEL TO TRANSFER TYRE TO NEW ALLOY WHEEL RIM INCLUDE BALANCING THE WHEEL	New	45.00	30.00
4	TO PUTTY AND RE-SPRAY PAINTING ON LEFT FRONT FENDER AND FRONT BUMPER FACE	New	600.00	400.00
5	RUST-PROOFING ON THE LEFT FRONT ACCIDENT AFFECTED PORTIONS	New	80.00	0.00
Gross Labour Cost (\$\$)			1,375.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >