

REF: CS/C7117018623 /R19602

Special Instructions:

Subject
Mun Mun

Result

ASSIGNMENT (Office)

From (Person):

Irene Tay

25

C71

Date/Time

28/9/17 11:21 am

Estimated Cost

133141

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF38054

Insured:

SJD 36 H

at Workshop m/s

Lee Kuan Hwa

Tel:

6269 9192

④

24 Surgeni Kadut 8truf 4, 729050

Policy No.

DMPCSN 3003101701

Claim No.

SNM17D05623C02

Sum Insured

Excess

Make of Veh:

(Client's Record)

D.O.A.

25/9/17

CA / REV / REP. / REV 24 HRS

'wp'

03.10.2017 @ after 10 am (morning)

H.O.D. Endorsement

Date/Time:

2/9/17 11:36am

Person Contacted

Chin shue Ting

Vehicle IN OUT

Date/Time

Action/Instructions

(✓) Estimate

GBF 3805 U-X

SJD 36H-X

Page

REF: CTI

3853R

ASSIGNMENT

From _____ Date 3/10/17

Estimated Cost _____

OD / (P)WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No GBF 3805 U

at Workshop no Lee Kuan Hwa

at 24, Sungai Kadut street 4, 729050

Insured _____

Policy No _____

Claims No _____

Sum Insured _____ Excess _____

(Client's Record)

Make of Veh _____

after 10 am

Policy Condition _____

Remark: The veh had commenced its repair at the time of inspection.

Bal or Market Value _____

D/O Accident Report _____ Consistent? : Yes or No

GIA PR Seen _____ Consistent? : Yes or No

Est Repairs 8 days Res. Yes or No

Lum Sum 1.81 % 3 Val. Yes or No

CA / REV / REP. / 24 HRS up

Date _____ Person Contacted _____ Vehicle IN / OUT

Date Time Action Instruction

Veh No GBF 3805U Yr Regn 2016 / SG

Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or PICK-UP

Make ISUZU TFSP67SR cc 2459

Colour GREEN Insured / Std / NI / NA

Sp. Reading 38310 T. Radio Insured / Std / NI / NA

Eng No _____

C No MPATFS86JGT013298

Gen. Cond. Good / Fair / Poor / Burnt

Steering In order / Jammed / Leaked / Burnt or

Brake In order / Jammed / Leaked / Burnt or

Mod. Nil / S/Rim / STD A/Rim or

Tyre Size F: 245/70R16 R: _____

(B) DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front _____ Rear _____

R Bal 6 mm R Bal 6 mm

L Bal 6 mm L Bal 6 mm

D/O A 28/09/17 D/O I 03/10/17

Survey held at LEE KUAN HWA

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

P/P \$5186.30
Cred: 4489.70, 467.

Date/Time File Pass to: ☐ : Preli. Report
☐ : Final Report

Date/Time File Return to:

Days Of Repair: 8

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)

Survey Fee
Transportation
() S + RS (\$)
() Photos
() Others

TOTAL

150
150

Report Format: TP
Lump Sum / (B) (\$ 5186.30)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Fédération Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17018623/R1gb	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 28-09-2017	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJD 36H	Veh. Inspected	GBF 3805U
Policy No.	DMPCSN3003101701	Coverage (\$)	0.00
Claim No.	SNM17D05623C02	Excess (\$)	0.00
Assign From	MEIRMEN (IRENE TAY)	Assign Date	28/09/2017
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	-	Steering	
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/09/2017	Inspection Date	
Survey held at	LEE KUAN HWA MOTOR SERVICE 24 SUNGEI KADUT ST. 4 SINGAPORE 729050		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Sep 2017		28 Sep 2017 11:37 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	[Created by insurer]		
Main Claimant:	RYOBI KISO (S) PTE LTD, Co. Reg. No.: 199003893R		
Vehicle Reg. No.:	GBF3805U	Date of Loss:	25/09/2017 20:00 - :59
Claim Type:	TP / SNM17D05623C02	Policy/Cover Note No.:	DMPCSN3003101701
Vehicle Reg. No. (Insured):	SJD36H	Policy No. (Claimant):	17-MV008591-R01
		Excess:	S\$0.00
Repairer:	Lee Kuan Hwa Motor Service (Sungei Kadut) 24 Sungei Kadut Street 4, 729050 Sungei Kadut - Tel: 62699192		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/10/2017]		
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMMENDATION		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#) [Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Thursday, 28 September, 2017 11:21 AM
To: Lee Kuan Hwa; assignments@lkkauto.com
Cc: assignments@lkkauto.com
Subject: CTP REF NO. SNM17D05623C02 LKH REF NO. GBF3805U - ACCIDENT INVOLVING SJD36H AND GBF3805U ON 25 SEPTEMBER 2017

Dear Sir/Mdm,

We refer to the above matter and the email below.

Please assist to get your surveyor, Adrian Ling from your end to liaise with Lee Kuan Hwa Motor Service.

Regards

Irene Tay

Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Lee Kuan Hwa [mailto:kuanhwa@singnet.com.sg]
Sent: Wednesday, 27 September, 2017 3:18 PM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: Re: CTP REF NO. SJD36H LKH REF NO. GBF3805U - ACCIDENT INVOLVING SJD36H AND GBF3805U ON 25 SEPTEMBER 2017

Dear Irene Tay,

Do let us know the surveyor company name.

Thank you.

Best Regards,
Chin Shue Ting
Lee Kuan Hwa Motor Service
Tel: 6269 9192 Fax: 6269 2239

From: Irene Tay
Sent: Wednesday, September 27, 2017 3:08 PM
To: kuanhwa@singnet.com.sg
Subject: CTP REF NO. SJD36H LKH REF NO. GBF3805U - ACCIDENT INVOLVING SJD36H AND GBF3805U ON 25 SEPTEMBER 2017

WITHOUT PREJUDICE
Save As To Costs

Dear Sir/Mdm,

We refer to your pre-repair survey request / email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

Here are the list of surveyors ;

Marcus Chua
Edward Cho
Tay Beng Hee
See Chew Seng
Dereck Oh Siong Wee
Mohd Fadhilah Bin Osman
Cedric Ng
Steven Foong
Adrian Ling
Henry Ng

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Irene Tay

Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/09/2017 11:07
Date Of Accident	25/09/2017 20:10
Exact Location Of Accident	SIMS AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF3805U
Insured/Policyholder	
Name Of Registered Owner	RYOBI KISO (S) PTE LTD
Co Reg No	199003893R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65060000

Vehicle Particulars

Manufacturer	ISUZU
Model	TFR86JSR-2.5 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MV008591-R01
Cover Note Number	

Driver

Name of Driver	JOHN NGU WEI JIENG
NRIC No	S9179595G
Date Of Birth	19/09/1991
Occupation	OUTDOOR
Date Of Driving Pass	11/04/2016
Driving Experience	1 YEAR AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94525175
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. YES

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJD36H

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel


Sketch Plan

Refer to attachment

Jalan Eunus

↑↑↑
↓↓↓

↑↑↑
↓↓↓



A: GBF 38054

B: SJD 36 H

Sims Ave

Describe Circumstances of the Accident


On the date 25/09/17 at about 2010 hours, I was driving my vehicle A GBF 3805 U along slip road from Sims Ave to Jalan Eunus. Suddenly the vehicle B SJD 36 H from behind hit onto my rear of vehicle A GBF 3805 U. I got some photo for the accident. I am claiming against the vehicle B SJD 36 H insurance policy.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Transaction ref 20161013173608624405

The owner and vehicle particulars for Vehicle No. GBF3805U as at 13 Oct 2016 are as follows:

1.	Name	: RYOBI KISO (S) PTE LTD
2.	Identification No. Type	: Company
3.	Identification No.	: 199003893R
4.	Place Of Passport Issue	: -
5.	Vehicle No.	: GBF3805U
6.	Previous Vehicle No.	: -
7.	Effective Date of Ownership	: 27 Sep 2016
8.	Original Registration Date	: 27 Sep 2016
9.	First Registration Date	: 27 Sep 2016
10.	Vehicle Type	: B31 - Goods (Open) Lorry (Metal Body)/Pickup
11.	Vehicle Scheme	: Normal
12.	Attachment 1	: With Hood
13.	Attachment 2	: -
14.	Attachment 3	: -
15.	Vehicle Make	: ISUZU
16.	Vehicle Model	: TFS86JSR
17.	Year of Manufacture	: 2016
18.	Primary Colour	: Silver
19.	Secondary Colour	: -
20.	Passenger Capacity	: 1
21.	Chassis/Trailer Chassis No.	: MPATFS86JGT013298
22.	Propellant	: Diesel
23.	Engine No./Motor No.	: PF4937
24.	Engine Capacity(cc)/Power Rating(kW)	: 2,499.0
25.	Unladen Weight(kg)	: 1940
26.	Maximum Laden Weight(kg)	: 3000
27.	Open Market Value	: \$28,969.00
28.	PARF Eligibility	: No
29.	PARF Eligibility Expiry Date	: -
30.	Minimum PARF Benefit	: -
31.	No. of Transfers	: 0
32.	IU Label No.	: 1042815936
33.	COE No.	: 2016092705001067N
34.	COE Expiry Date	: 26 Sep 2026
35.	COE Category	: C - Goods Vehicle & Bus
36.	Quota Premium/Prevailing Quota Premium	: \$16,310.00
37.	Actual Quota Premium/PQP Paid	: \$16,310.00
38.	Actual ARF Paid	: \$1,449.00
39.	CO2 Emission(g/km)	: 192.00
40.	Actual CEVS Rebate Utilised	: -
41.	CEVS Surcharge Paid	: -
42.	Actual Green Vehicle Rebate Utilised	: -
43.	Vehicle Lifespan Expiry Date	: 26 Sep 2036
44.	Road Tax Amount	: \$0.00
45.	Road Tax Start Date	: 27 Sep 2016
46.	Road Tax End Date	: 26 Mar 2017
47.	Remarks	: The vehicle is registered under Early Turnover Scheme.

LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719
Workshop: 24, Sungei Kadut Street 4 Singapore 729050
Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712
Business Reg. No: 36463500B

M/s: **China Taiping Insurance (Singapore) Pte Ltd**
105 Cecil Street #18-00/#19-00/#16-01/02
The Octagon Singapore 069534

Motor Claim Dept
Attn to: Ms Tiffany Leong/ Jownyn

Vehicle number : GBF 3805 U
Make/Model : ISUZ TFS86J
Date of accident : 25.09.2017
Claim Type : TP Claim

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: 27.09.2017

Accident involving GBF 3805 U & SJD 36 H along slip road from Sims Ave to Jalan
Eunos on 25.09.2017.

Re: Estimate

1.	1 pc	Rear tailgate	\$	1,058.00	TH
2.	2 pcs	Rear mudguard LH,RH	\$	1,404.00	R
3.	1 set	Rear bumper	\$	924.00	DE
4.	1 pc	Rear end panel	\$	1,058.00	ST
5.	1 pc	Rear no plate (S/Nett)	\$	45.00	75 TH
6.	2 pcs	Rear lamp LH,RH	\$	330.00	CRA
7.	1 pc	Rear no plate lamp (S/Nett)	\$	25.00	NS
8.	1 set	Rear reverse sensor (S/Nett)	\$	280.00	X80C
9.	2 pcs	Rear tailgate handle lock LH,RH	\$	112.00	X50C
10.	4 pcs	Rear sticker (2.5TD,70km/h,Isuzu D-max)	\$	112.00	NE
11.	1 pc	Front windscreen	\$	1,158.00	XAN
12.	1 pc	Front windscreen moulding	\$	34.00	XAN
13.	2 set	Rear Sticker (4x4)	\$	50.00	NE
14.	1 pc	Rear bumper step garnish	\$	146.00	DE
			\$	6,736.00	
To Wiring Service			\$	80.00	40
To Sealant & Inner Sponge Tape			\$	80.00	60
To Logo Service			\$	400.00	200
To Replace Windscreen Labour Charge			\$	180.00	XAN
To Replace & Repair Labour Charge			\$	1,200.00	900
To Putty & Spray Painting			\$	1,000.00	800
Total			\$	9,676.00	

Yours Faithfully
李光華 廖曉輝

LEE KUAN HWA MOTOR SERVICE
39, Westwood Avenue, Singapore 648719
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Sep 2017		28 Sep 2017 11:37 Edit Adj Rpt	S\$5,186.30 Edit Estimates	S\$5,186.30 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS				[Created by Insurer]		
Insured:	-, Co. Reg. No.: -					
Main Claimant:	RYOBI KISO (S) PTE LTD, Co. Reg. No.: 199003893R					
Vehicle Reg. No.:	GBF3805U	Date of Loss:	25/09/2017 20:00 - :59			
Claim Type:	TP / SNM17D05623C02	Policy/Cover Note No.:	DMPCSN3003101701			
Vehicle Reg. No. (Insured):	SJD36H	Policy No. (Claimant):	17-MV008591-R01			
		Excess:	S\$0.00			
Repairer:	Lee Kuan Hwa Motor Service (Sungei Kadut) 24 Sungei Kadut Street 4, 729050 Sungei Kadut - Tel: 62699192					
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]					
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 09/10/2017]					
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMMENDATION					
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail		
There are no mail for this case.						
ALL ASSOCIATED TASKS <input type="checkbox"/>						
		View All	Search Tasks	Create New Task Complete		
Due Date	Priority	Type	Task Group	Subject		
				Handler		
				Assigned By		
				Completed On		
				Created On		
				Done?		
No results.						

Claim Documents

*GBF3805U (SNM17D05623C02)

[SJD36H]

TP

RYOBI KISO (S) PTE LTD

Sep 25 2017 8:00PM

[-]

Lee Kuan Hwa Motor Service

Upload Documents		Upload Photos	Compose New Letter	View <input type="button" value="View in Browser"/>	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lee Kuan Hwa Motor Service (Sungei Kadut)		Thumbnail	Print
1	27/09/17 11:16	Accident Statement	1	Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lee Kuan Hwa Motor Service (Sungei Kadut)		Thumbnail	Print
1	27/09/17 11:14	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
2	27/09/17 11:14	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
3	27/09/17 11:14	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
4	27/09/17 11:14	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
5	27/09/17 11:14	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
6	27/09/17 11:14	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
7	27/09/17 11:14	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
8	27/09/17 11:14	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
9	27/09/17 11:14	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
10	27/09/17 11:14	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
11	27/09/17 11:14	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>

17	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
45	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
46	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
47	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
48	05/10/17 12:20	General View	1	Load JPG	<input checked="" type="checkbox"/>
49	28/12/17 16:20	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
50	28/12/17 16:20	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
51	28/12/17 16:20	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
52	28/12/17 16:20	RE-SURVEY PHOTO	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	28/09/17 11:40	GIA REPORT SJD36H	1	Load PDF	
2	28/09/17 11:40	EMAIL FROM LEE KUAN HWA (2)	1	Load PDF	
3	28/09/17 11:40	EMAIL FROM LEE KUAN HWA (1)	1	Load PDF	
No	Finalized On	Lee Kuan Hwa Motor Service (Sungei Kadut)		Thumbnail	Print
1	27/09/17 11:13	Sketch Plan [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
2	27/09/17 11:13	Sketch Plan #2 [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
3	27/09/17 11:13	Sketch Plan #3 [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
4	27/09/17 11:13	Sketch Plan #4 [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

				View	View in Browser
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lee Kuan Hwa Motor Service (Sungei Kadut)		Thumbnail	Print
1	27/09/17 11:16	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lee Kuan Hwa Motor Service (Sungei Kadut)		Thumbnail	Print
1	27/09/17 11:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	27/09/17 11:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	27/09/17 11:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	27/09/17 11:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	27/09/17 11:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	27/09/17 11:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	27/09/17 11:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	27/09/17 11:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	27/09/17 11:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	27/09/17 11:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	27/09/17 11:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lee Kuan Hwa Motor Service (Sungei Kadut)		Thumbnail	Print
1	27/09/17 11:13	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	27/09/17 11:13	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>
3	27/09/17 11:13	Sketch Plan #3		Load JPG	<input checked="" type="checkbox"/>
4	27/09/17 11:13	Sketch Plan #4		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div style="border: 1px solid black; padding: 5px; margin-bottom: 10px;"> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> <div style="text-align: right; margin-top: 5px;"> ^ v </div> </div> <p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17018623/R1GBE2

Date: 04/01/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3003101701

Claimant Vehicle
No: GBF3805UInsured Vehicle
No: SJD36H

Date of Loss: 25/09/2017

Nature of Claim: TP

Claim
No: SNM17D05623C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF3805U

Make & Model: ISUZU TFR86JSR, 2.5 D (M)

Engine No: PF4937

Reg. Date: 27/09/2016 (Man. Year: 2016)

Chassis No: MPATFS86JGT013298

Colour: Grey

Odometer: 38310 km

Engine Capacity: 2499 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/70R16	Rear Tyre Size:	245/70R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,736.00	3,186.30	3,549.70	52.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	2,000.00	940.00	31.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	9,676.00	5,186.30	4,489.70	46.40

INSPECTION

Date of Assignment: 28/09/2017

Date Inspected: 03/10/2017 Inspected At:

Lee Kuan Hwa Motor Service (Sungei
Kadut)
24 Sungei Kadut Street 4
Singapore 729050

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 04 Jan 2018)
Parts: N/A ISUZU TFR86JSR 2.5 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBF3805U)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,058.00 F	*1,058.00 FL
2	2		*REAR MUDGUARD LH,RH	Repair	1,404.00 F	*- FL
3	1		*SET REAR BUMPER	Deformed	924.00 F	*924.00 FL
4	1		*REAR END PANEL	Bent	1,058.00 F	*1,058.00 FL
5	2		*REAR LAMP LH,RH	Cracked	330.00 F	*330.00 FL
6	2		*REAR TAILGATE HANDLE LOCK LH,RH	Serviceable	112.00 F	*- FL
7	4		*REAR STICKER (2.5TD,70KM/H,ISUZU D-MAX)	Necessary	112.00 F	*112.00 FL
8	1		*FRONT WINDSCREEN	Not Necessary	1,158.00 F	*- FL
9	1		*FRONT WINDSCREEN MOULDING	Not Necessary	34.00 F	*- FL
10	2		*SET REAR STICKER (4X4)	Necessary	50.00 F	*50.00 FL
11	1		*REAR BUMPER STEP GARNISH	Deformed	146.00 F	*146.00 FL
12	1		*REAR NO PLATE	Bent	45.00 FS	*35.00 FS
13	1		*REAR NO PLATE LAMP	Distorted	25.00 FS	*25.00 FS
14	1		*SET REAR REVERSE SENSOR	Serviceable	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,736.00	3,738.00
- List Item Discount on L Items 0.00/15.00% (\$\$)	0.00	551.70
Total Parts (\$\$)	6,736.00	3,186.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO WIRING SERVICE	New	80.00	40.00
2	TO SEALANT & INNER SPONGE TAPE	New	80.00	60.00
3	TO LOGO SERVICE	New	400.00	200.00
4	TO REPLACE WINDSCREEN LABOUR CHARGE	New	180.00	-
5	TO REPLACE & REPAIR LABOUR CHARGE	New	1,200.00	900.00
6	TO PUTTY & SPRAY PAINTING	New	1,000.00	800.00
Gross Labour Cost (\$\$)			2,940.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >