

ASS. REQ. BY:

REF: CS/MSG17018715/T1rbn2

Special Instruction:

Solicitor: Taukikh

ASSIGNMENT (Office)

From (Person): Lionel Tanof MSIGDate/Time: 28/9/17 @ 3.12pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKL 2617 P

Insured:

SJZ 7131 D

at Workshop m/s

Wah Hong Motors

Tel:

6515 5988of 38 Toh Guan Rd East, # 01-57 G08 581 Jurong

Policy No:

827516384 QMY

Claim No:

530928

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 27/09/17CA / REV / REP. / REV 24 HRS 'wp4.30 pm

H.O.D. Endorsement:

Date/Time: 29/9/178.54pmPerson Contacted: MichaelVehicle N (OUT)

Date/Time

Action/Instruction (✓) Estimate

SKL 2617 P - XSJZ 7131 D - XSent preli thru mrmrm13/4/18Lionel inform owner withdraw claim

Tanaka

REF: MS19

ASSIGNMENT

From \_\_\_\_\_ Date 29/9/17  
 Estimated Cost \_\_\_\_\_  
 OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No SKL 2617 P  
 at Workshop m/s Wah Hong Motor  
 of 38 Toh Guan Rd East, # 01-57, 608581  
 Insured \_\_\_\_\_  
 Policy No \_\_\_\_\_  
 Claims No \_\_\_\_\_  
 Sum Insured \_\_\_\_\_ Excess \_\_\_\_\_  
 (Client's Record)  
 Make of Veh \_\_\_\_\_

1:30 pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bar or Market Value \_\_\_\_\_  
 DAC Accident Report \_\_\_\_\_ Consistent? Yes or No  
 GIA - PR Seen \_\_\_\_\_ Consistent? Yes or No  
 Est. Repairs 3 days Res: Yes or No  
 Lum Sum \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP / 24 HRS 'wp

Date \_\_\_\_\_ Person Contacted \_\_\_\_\_

Vehicle: IN / OUT

Date / Time Action / Instruction

13/4/18 Submit preli report

Veh No SKL 2617P Yr Regn 2013 Oct.  
 Type ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make Volkswagen Sharan cc 1984  
 Colour Silver A/C Insured / Std / NI / NA  
 Sp Reading 22382 T Radio Insured / Std / NI / NA  
 Eng No \_\_\_\_\_  
 C No WVWZZZNEV008453  
 Gen Cond: Good / Fair / Poor / Burnt \_\_\_\_\_  
 Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod: Nil / SRM / STD A/Rim or \_\_\_\_\_  
 Tyre Size F: 225/50R17  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MGC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front 6 Rear 6  
 R/Bal 6 mm R/Bal 6 mm  
 L/Bal \_\_\_\_\_ mm L/Bal \_\_\_\_\_ mm  
 D.O.A \_\_\_\_\_ D.O.I. 29/9/17  
 Survey held at Wah Hong  
 Des. of Damages: Fnt / Rear / ☒ OS / NIS / UIC / Rooftop or \_\_\_\_\_

The UIC / Chassis frame / Body Structure affected due to collision

RECEIVED 13 APR 2018

Date/Time File Pass to?

1: report

Date/Time File Return to?

3:



Preli. Report

Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)  
☐ Interview (\$)  
☐ Tech. Invs (\$)  
☐ Weekend (\$)

Survey Fee

Transportation

1. S+RS \$

2. Photos

3. Others

4. TOTAL

Report Format:

TP

Lump Sum / I.B.I: (\$)

200  
10

210



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG17018715/T1rb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 29-09-2017	
			Code : MSG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJZ 7131D		Veh. Inspected	SKL 2617P
Policy No.	B27516384QMY		Coverage (\$)	0.00
Claim No.	530928		Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)		Assign Date	29/09/2017
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	27/09/2017		Inspection Date	29/09/2017
Survey held at	WAH HONG & CREDIT PTE LTD 38 TOH GUAN ROAD EAST #01-57 ENTERPRISE HUB SINGAPORE 608581			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 13 Apr 2018

## Preliminary Advice

Insured Vehicle : SJZ7131D

No

TP Vehicle No : SKL2617P

Make : VOLKSWAGEN SHARAN

Date of : 29/09/2017

Inspection

Inspection At : WAH HONG MOTORS & CREDIT PTE LTD (HQ)  
38 TOH GUAN ROAD EAST, #01-57, ENTERPRISE HUB  
SINGAPORE 608581

Accident Date : 27/09/2017

Assignment Date : 28/09/2017

Est. Duration of  
Repair : 3.00

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,445.00
Revised Amount	:S\$	3,145.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,145.00

Lump Sum Repair :S\$

## **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

## Remarks

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Sep 2017 10:23 <a href="#">Sendback Est</a>	28 Sep 2017 10:32 <b>\$3,445.00</b>	28 Sep 2017 15:12 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	TAN KOK MING KELVIN, ID: S7043317F, Tel: +6597607234, Email: KTKM05@YAHOO.COM		
Main Claimant:	LING TECK YEW DANIEL, ID: S7506138B		
Vehicle Reg. No.:	SKL2617P	Date of Loss:	27/09/2017 07:00 - :59
Claim Type:	TP / 530928	Policy/Cover Note No.:	B27516384QMY (Comprehensive)
Vehicle Reg. No. (Insured):	SJZ7131D	Policy No. (Claimant):	Coverage: 01/06/2017 - 31/05/2018
		Excess:	S\$1,500.00
Repairer:	Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub, 608581 Jurong East - Tel: +65 65155988		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/09/2017]		
Driver/Custodian (Insured):	TAN KOK MING KELVIN (46 / Male), NRIC: S7043317F, Tel: +6597607234		
Adj Asg. Remarks:	Survey - Owner waiting 11am next Monday 02/10/17 Please contact the workshop directly @ 6515 5988 Michael		

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/09/2017 10:04
Date Of Accident	27/09/2017 07:15
Exact Location Of Accident	JUNCT OF PEMIMPIN PLACE AND PEMIMPIN TERRACE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL2617P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LING TECK YEW DANIEL
NRIC No	S7506138B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97920783
Alternative Phone No	OFFICE-97920783

### Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	SHARAN 2.0
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10699311
Cover Note Number	

### Driver

Name of Driver	LOH PATSY
NRIC No	S7527237E
Date Of Birth	11/09/1975
Occupation	INDOOR
Date Of Driving Pass	09/09/1995
Driving Experience	22 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97920783
Fax Number	
Contact Number	
EEmail Address	PATSYLOH@YAHOO.COM

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own Vehicle

-  
-  
-

Insurance Company of Driver's Own Vehicle

-  
-  
-

### General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

### Circumstances of Accident

WHEN I WAS TRAVELLING ALONG THE MENTIONED ROAD, AS THERE IS A FEW VEHICLE PARK ALONG THE SIDE OF THE ROAD, I UNABLE TO MOVE FORWARD. I HAD INFORM VEHICLE B FROM THE OPPOSITE DIRECTION TO MOVE TO THE SIDE IN ORDER TO MAKE SOME SPACE FOR ME TO MOVE ON. OUT OF A SUDDEN, I FELT AN IMPACT AT THE SIDE PORTION OF MY VEHICLE. AFTER THE IMPACT, BOTH PARTY ALIGHTED TO EXCHANGED DETAILS AND TOOK SOME PHOTOS BEFORE WE MOVE OFF FROM THE LOCATION. THERE IS NO INJURIES INVOLVED.

### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: PENDING VIDEO FROM INSURED

Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJZ7131D

Vehicle Make/Model/Colour B.M.W./535I/BLACK

Details Of Properties

Name of Driver TAN KOK MING KELVIN

NRIC/Passport Number S7043317F

Contact Number 97607234

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 1

### Details of Witness

Name

Phone Number



## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

VERIFIED BY AJAX MARS  
REPORTING OFFICER  
EUGENE KOH

Witnessed by Reporting Centre  
Personnel

#### Sketch Plan





ACCIDENT STATEMENT (2000 characters)

WHEN I WAS TRAVELLING ALONG THE MENTIONED ROAD, AS THERE IS A FEW VEHICLE PARK ALONG THE SIDE OF THE ROAD, I UNABLE TO MOVE FORWARD. I HAD INFORM VEHICLE B FROM THE OPPOSITE DIRECTION TO MOVE TO THE SIDE IN ORDER TO MAKE SOME SPACE FOR ME TO MOVE ON. OUT OF A SUDDEN, I FELT AN IMPACT AT THE SIDE PORTION OF MY VEHICLE. AFTER THE IMPACT, BOTH PARTY ALIGHTED TO EXCHANGED DETAILS AND TOOK SOME PHOTOS BEOFRE WE MOVE OFF FROM THE LOCATION. THERE IS NO INJURIES INVOLVED.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
EUGENE KOH YEW KIAT

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

Date/Time:

Identification Card

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S7527237E



Name  
LOH PATSY  
(LU PATSY)  
卢 珮 施

Race  
CHINESE

Date of birth  
11-09-1975

Sex  
F

Country of birth  
SINGAPORE



Identification Card

3834787



NRIC No. **S7527237E**

Date of Issue

**01-02-2006**

**991 BUKIT TIMAH ROAD #03-19  
SINGAPORE 589630**

NRIC No: **S7527237E**

Date: **28/06/2010**

No: **6497724**



Driving License

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)


Class 3

Motor Cars and Motor Tractors the weight of  
which unladen does not exceed 2500 kilograms

PASS DATE

09 Sep 1995

NP 428A



Licence No: S7527237E

## Wah Hong Motors &amp; Credit Pte Ltd (Co.Reg.No:199806235M)

38 Toh Guan Road East, #01-57, Enterprise Hub

Singapore 608581

Tel: +65 65155988 Fax: +65 68966321 Email: nicholas@wahhong.sg

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

TAN KOK MING KELVIN

michael@wahhong.sg

Singapore

## PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	170919
Policy No:		Date of Loss:	27/09/2017
Vehicle Reg. No.:	SKL2617P	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	VOLKSWAGEN SHARAN, 2.0 TSI AT 7N14H3 (A)	Vehicle Reg. Date:	18/10/2013
Vehicle Colour:	SILVER	Chassis No:	WVZZZ7NZE008453
Engine No:	CCZ393093		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	JUNCT OF PEMIMPIN PLACE AND PEMIMPIN TERRACE		
Present Location:	WAH HONG MOTORS & CREDIT PTE LTD (HQ)		

Tan Jiah 97495749.  
29/9/17 'WP'  
Resurvey before paint  
3 days  
sur @ 11/10/17

## COST OF CLAIMS

Parts	<b>LKK Auto Consultants</b> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	Amount
Miscellaneous Items		2,145.00
Labour		0.00
Paintwork Labour		1,300.00
Towing		0.00
	Gross Total (S\$)	3,445.00
	+ GST 7.00% (S\$)	241.15
	Nett Amount (S\$)	3,686.15

This claim is handled by: MICHEAL TEE

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System



## REPAIR DETAILS

## Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 28 Sep 2017)

**Parts:** M1-MPV VOLKSWAGEN SHARAN 2.0 TSI AT 7N14H3 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** Wah Hong Motors & Credit Pte Ltd/SKL2617P/28/09/2017 10:32

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 Pc Rear R/H Side Sliding Door	0.00	0.00	1,950.00 F
			Sub Total (S\$)			1,950.00
			+ Margin on L,N Items 10.00% (S\$)			195.00
			Total Parts (S\$)			2,145.00

Wah Hong Motors & Credit Pte Ltd/SKL2617P/28/09/2017 10:32. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS



## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	remove & replace rear sliding door and knocking & straighten up necessary affected	New	400 500.00
2	spray painting on affected areas	New	800 800.00
Gross Labour Cost (S\$)			1,300.00

Wah Hong Motors & Credit Pte Ltd/SKL2617P/28/09/2017 10:32. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17018715/T1RBN2

Date: 16/04/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B27516384QMY
Claimant Vehicle No :	SKL2617P	Insured Vehicle No :	SJZ7131D
Date of Loss:	27/09/2017	Nature of Claim:	TP
		Claim No:	530928

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SKL2617P	Engine No:	CCZ393093
Make & Model:	VOLKSWAGEN SHARAN, 2.0 TSI AT 7N14H3 (A)	Chassis No:	WWZZZ7NZE008453
Reg. Date:	18/10/2013 (Man. Year: 2013)	Odometer:	77382 km
Colour:	Silver		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,145.00	2,145.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	1,000.00	300.00	23.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,445.00</b>	<b>3,145.00</b>	<b>300.00</b>	<b>8.71</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>241.15</b>	<b>220.15</b>	<b>21.00</b>	<b>8.71</b>
<b>Nett Amount (S\$)</b>	<b>3,686.15</b>	<b>3,365.15</b>	<b>321.00</b>	<b>8.71</b>

## INSPECTION

Date of Assignment:	28/09/2017	Present Location:	Wah Hong Motors & Credit Pte Ltd (HQ)
Date Inspected:	29/09/2017	Inspected At:	Wah Hong Motors & Credit Pte Ltd (HQ)
			38 Toh Guan Road East, #01-57,
			Enterprise Hub
			Singapore 608581

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

OWNER WITHDRAW CLAIM

(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 Apr 2018)
<b>Parts:</b>	M1-MPV	VOLKSWAGEN SHARAN 2.0 TSI AT 7N14H3 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKL2617P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 Pc Rear R/H Side Sliding Door (WCP)	Bent	1,950.00 F	*1,950.00 F
						F=Franchise part.
Sub Total (S\$)					1,950.00	1,950.00
+ Margin on L,N Items 10.00/10.00% (S\$)					195.00	195.00
Total Parts (S\$)					2,145.00	2,145.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	remove & replace rear sliding door and knocking & straighten up necessary affected	New	500.00	400.00
2	spray painting on affected areas	New	800.00	600.00
Gross Labour Cost (\$\$)			1,300.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >