

ASS. REC BY:

REF: CS/MSG17018740/T19507

Special Instruction:

hold

SUPERVISOR
menimen

Tau Kich

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

MSIG

Date/Time:

29/9/17 2.42pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDA 916 E

Insured:

SJM 6475 L

at Workshop m/s:

Auto France (HQ)

Tel:

64777331

of

305 Alexandra Road, #02-01, 159942

Policy No:

28868481 QMX

Claim No:

531324

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

27/9/2017

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

29/9/17 3.30pm

Person Contacted:

Guo Xiang

Vehicle IN OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	SDA 916 E - cc6/AIG16024212 / Aug 3q2 - D.O.A: 16/12/16
	SJM 6475 L - X
07/10/17 @ 4.37pm	revised to Catherine Thia via Menimen.

Surveyor: Taufer

REF:

MSLG

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S
	<input checked="" type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : **Yes or No**

GIA / PR Seen: _____ Consistent? : **Yes or No**

Est. Repairs: 8 days Res.: **Yes or No**

Lum Sum: _____ % 3 Val.: **Yes or No**

CA / REV / REP. / 24 HRS

WP

Vehicle: **IN / OUT**

Date: _____ Person Contacted: _____

Veh No: SDA916E Yr Regn: 2017 April

Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Pugeot 508 c.c. 1199

Colour: Black A/C: **Insured / Std / NI / NA**

Sp. Reading: 7764 T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: UF3LPMN JWG.S/195604

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or _____

Brake: **Inorder / Jammed / Leaked / Burnt** or _____

Modi: **Nil / S/Rim / STD A/Rim** or _____

Tyre Size: **F:** 225 45 R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front 6 mm **Rear** 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 29/1/12

Survey held at AutoFrance

Des. of Damages: **Fr / Rear / O/S / N/S / U/C / Rooftop** or

o/s Rear, u/c

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time Action / Instruction

12,555, 8 days, confirm from e-mail
Ched to 5034, 29/1/12

RECEIVED 8 7 DEC 2012

Date/Time, File Pass to? : **Preli. Report**

11/01/12 : **Final Report**

Date/Time, File Return to?

2) _____

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee:	<u>300</u>
Transportation:	_____
_____ \$ + RS _____ \$	_____
Photos	<u>10</u>
Others	_____
TOTAL	<u>310</u>

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Report Format : WEP-TP

Lump Sum / I.B.I: (\$ 17555)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17018740/T1qb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 29-09-2017	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJM 6475L	Veh. Inspected	SDA 916E
Policy No.	28868481QMX	Coverage (\$)	0.00
Claim No.	531324	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	29/09/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	27/09/2017	Inspection Date	29/09/2017
Survey held at	AUTOFRANCE 305, ALEXANDRA ROAD SINGAPORE 159942.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Survey Department Check List (Case Handler)

Reference No.: 09/MS&17018740/T196
 Policy Type: OD / (TP) TP RES / TL / EVA

SDA 916E

Case Handler

Typist

Admin (Cath): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	✓			
C Customer Code	✓			
N Assign From	✓			
C Assign Date	✓			
C Veh No (Inspected)	✓			
C Veh No (Insured)	✓			
C D.O.A	✓			
C Policy No	✓			
C Claim No	✓			
C Insurance Authorisation (CA /REV/REP)	✓			
C Report Type	✓			
C Weekend Charges	✓			
N Survey held at/Repairer	✓			
C Excess				

Surveyor (Taufik): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C Vehicle No	✓			
C Regn Month/Year	✓			
N Vehicle Type	✓			
N Make & Model	✓			
C Engine Capacity. (C.C)	✓			
N Colour	✓			
C Odometer. (Sp.Reading)	✓			
C Chassis No	✓			
N General Condition	✓			
N Steering	✓			
N Brake	✓			
N Modification (Modi)	✓			
C Tyre Size	✓			
N Tyre Make	✓			
C Tyre Balance	✓			
C Date of Inspection	✓			
N Survey held	✓			
N Des.of Damages	✓			

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded	✓			
--	---	--	--	--

(3) Workshop Estimate/Assignment Form

N ALL Parts condition	✓			
C Market Value for OD cases				
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C Days of repair	✓			
C Finalised Amount				
C Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C Resurvey photo Uploaded	✓			
---------------------------	---	--	--	--

Check By: [Signature]
 Case Handler Date

*C: Critical *N: Non-Critical

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Sep 2017		29 Sep 2017 14:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents
Show All			
CLAIM SUBFOLDER DETAILS			
[Created by insurer]			
Insured:	HE JIAJING, ID: S8210782G, Tel: +6591849919, Email: hejiajin9@gmail.com		
Main Claimant:	HENG AIK KIAN, ID: S70728071		
Vehicle Reg. No.:	SDA916E	Date of Loss:	27/09/2017 07:00 - :59
Claim Type:	TP / 531324	Policy/Cover Note No.:	28868481QMX (Comprehensive) Coverage: 13/01/2017 - 12/01/2018
Vehicle Reg. No. (Insured):	SJM6475L	Policy No. (Claimant):	
		Excess:	
Repairer:	AutoFrance (HQ) 305 Alexandra Road, #02-01, 159942 Alexandra - Tel: 64777331		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/09/2017]		
Driver/Custodian (Insured):	HE JIAJING (35 / Male), NRIC: S8210782G, Tel: +6591849919		
ASSOCIATED MAIL RECEIVED			
View All Compose Case Mail			
There are no mail for this case.			
ALL ASSOCIATED TASKS			
View All Search Tasks Create New Task Complete			
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 02 Oct 2017

Preliminary Advice

Insured Vehicle No	: SJM6475L	Accident Date	: 27/09/2017
TP Vehicle No	: SDA916E	Assignment Date	: 29/09/2017
Make	: PEUGEOT 308	Est. Duration of Repair	: 8.00
Date of Inspection	: 29/09/2017		
Inspection At	: AUTOFRANCE (HQ) 305 ALEXANDRA ROAD, #02-01 SINGAPORE 159942		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion, undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:SS	17,594.00
Revised Amount	:SS	10,384.00
Check Items (Estimated)	:SS	3,160.00
Total	:SS	13,544.00
Lump Sum Repair	:SS	

Total Loss Consideration

New for Old Value	:SS
Pre-Accident Value	:SS
COE / PARF Rebate	:SS
Salvage Value	:SS
Margin for Repair	:SS

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID:

Vehicle Details

Vehicle No.: SDA916E

Vehicle to be Exported: No

Intended De-registration Date: 02 Oct 2017

Vehicle Make: PEUGEOT

Vehicle Model: 308 5DR ALLURE PURETECH 1.2 A/T 2WD S/R

Primary Colour: Black

Manufacturing Year: 2016

Engine No.: 10XTA40401856

Chassis No.: VF3LPHNYWGS195604

Maximum Power Output: 96.0 kW (128 bhp)

Open Market Value: \$20,211.00

Original Registration Date: 20 Apr 2017

First Registration Date: 20 Apr 2017

Transfer Count: 0

Actual ARF Paid: \$10,296.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 19 Apr 2027

PARF Rebate Amount: \$7,722.00

Intended COE Rebate Details

COE Expiry Date: 19 Apr 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$50,789.00

COE Rebate Amount: \$48,489.00

Total Rebate Amount: \$56,211.00

The information contained herein is correct as at 02 Oct 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 17 Sep 2017 at 12:38 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/09/2017 13:40
Date Of Accident	27/09/2017 19:35
Exact Location Of Accident	IRWELL BANK RD TURNING TO RIVER VALLEY RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDA916E
Insured/Policyholder	
Name Of Registered Owner	HENG AIK KIAN
NRIC No	S70728071
Email Address	AIKKIANHENG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97802589
Alternative Phone No	OFFICE-68722215
Vehicle Particulars	
Manufacturer	PEUGEOT
Model	308-1.2 5DR ACTIVE PURETECH 1.2 A/T 2W (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1928618
Cover Note Number	

Driver

Name of Driver	HENG AIK KIAN
NRIC No	S70728071
Date Of Birth	23/06/1970
Occupation	INDOOR
Date Of Driving Pass	08/05/1998
Driving Experience	19 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97802589
Fax Number	
Contact Number	OFFICE-68722215
EMail Address	AIKKIANHENG@GMAIL.COM

Address

Postcode

Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 4

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO THE ATTACH STATEMENT & SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJM6475L
Vehicle Make/Model/Colour VOLKSWAGEN BEETLE BLACK
Details Of Properties
Name of Driver HE JIAJING
NRIC/Passport Number S8210782G
Contact Number 91849919
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 28 Sept 2017
11am

Driver's Signature


(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name: WONG GEE YIANG
NRIC/FIN No.: 62658783L

Accident Sketch Plan

SKETCH PLAN



A = SDA 916E
 B = SJM 6475L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was turning into River valley road (from Irwell bank Road) from the 2nd lane of Irwell bank road, when the car B (SJM 6475L) on the 1st turning lane of Irwell bank road drove straight and hit the right back wheel side of my car, at that traffic junction.

It happened on 27 Sept 2017, about 7-35 pm.
 SJM 6475L (car B) was driving straight from Irwell bank road into (1st turning only lane) forward into Kimseng road, while her car (SJM 6475L) was in the turning lane (right turn only). My car (SDA 916E) was from the 2nd turning lane of Irwell bank road, driving right turn into river valley road, and was hit by SJM 6475L at the traffic junction, the impact was at my back (right side) wheel.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time: 29 Sept 2017
 11 AM

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Personnel's Signature
 Name: WONG GAO JIN
 NRIC/ID No: 62027732

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : **BP 3367**
 Date Estimated : **28/09/2017**
 Prepared By : **Wong Guo Xiang**

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Heng Aik Kian
 Blk 55 Lengkong Empat
 #05-01

Singapore 417642

- ACCOUNT - 2000

CASH - Sale service

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDA916E	VF3LPHNYWGS195604	20/04/2017	3081.2 Allure17	0

DESCRIPTION	VALUE
SUNDRIES	30 / 150.00
TO REPLACE/REPAIR REAR RHS QUARTER PANEL, REAR RHS DOOR, REAR BUMPER, END PANE <i>600</i>	3000 / 4,200.00
TO RESPRAY REAR BUMPER, REAR RHS QUARTER PANEL, REAR RHS DOOR, RHS ROCKER PANEL, END PANEL <i>600</i>	2400 / 4,200.00
WIRING CONNECTION & CHECKING (NETT)	✓ 150.00
TO REMOVE & REFIX REAR BOOT COMPARTMENT TRIMS & GARNISH (NETT)	✓ 300.00
TO REMOVE & REFIX FUEL TANK (NETT)	✓ 400.00
TO REMOVE & REFIX REAR SEATS & CARPET (NETT)	✓ 400.00
TO REMOVE & REFIX REAR LIGHTING SYSTEM (NETT)	✓ 150.00
TO REMOVE & REFIX REVERSE SENSOR (NETT)	✓ 150.00
TO REMOVE & REFIX REAR SUSPENSION SYSTEM ASSY (NETT)	? / 1,500.00
WHEEL ALIGNMENT (NETT)	✓ 600.00
TUFF KOTE @ \$60 PER PANEL (NETT)	60 / 180.00
BODY SEALANT @ \$90 PER PANEL (NETT)	90 / 270.00
TO CONDUCT ECU COMPUTER DIAGNOSTIC INCLUDING REPROGRAMME, RESETTING & CLEAR FAULT CODE (NETT)	✓ 600.00
TO SUPPLY 1 PCS 225/45 R17 TYRE	320 / 400.00
VEHICLE TOWED TO VAL (NETT)	✓ 200.00

Total Labour 1: **13,850.00**

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
96779897PD	ALLOY WHEEL (RUBIS J17 GREY MATT)	1	590.00	10.00	531.00

442

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



PEUGEOT

GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. :	BP 3367	Page No. :	2 of 2
Date Estimated :	28/09/2017		
Prepared By :	Wong Guo Xiang		

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDA916E	VF3LPHNYWGS195604	20/04/2017	3081.2 Allure17	0

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
1610095980	REAR WING RH	10/2.501	1,350.00	10.00	1,215.00
9677519980	ENTRY SEAL	1	120.00	10.00	108.00
9674375280	BEARING HUB	1	310.00	10.00	279.00
1616785480	RR SUSP CROSSMEMBER	750 1	1,000.00	10.00	900.00
9817349880	REAR SHOCK ABSORBER	1	90.00	10.00	81.00
1610767180	REAR BUMPER - TO BE PAINTED	1	700.00	10.00	630.00
Total Parts :					3,744.00

Taylor 97495749
8 days
'WP'
Repair before paint.
sur@lkkauto.com
29/9/17 @ 1600.
2/10/17.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Customer Service Officer	Contact	Labour 1 :	13,850.00
		Parts :	3,744.00
		Labour 2 :	0.00
		Excess :	0.00
		Total GST @ 7% :	1,231.58
		Grand Total :	18,825.58

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

17594

Measurement printout

Car standard measurement

Beissbarth © * ML 8 Easy

M * R- ** OK * USER // 112 / C

Date: 05.10.2017 11:29:02



Version (program)
v5.0b3101/v5.0b3101

Version (CCD)
v5.0b3101

Version (target data)
USER

Serial number
C10000942

Last service
27.12.2016

VANTAGE AUTOMOTIVES LIMITED
305 ALEXANDRA ROAD
SINGAPORE

Customer

Vehicle

Registration:

SDA 916 E

Order

Vehicle:

USER

PEUGEOT * 308 * Commercial vehicle

Rear Axle

		Initial Measurement	Target Data
Camber	left	-1°17'	-0°30' [-1°42'] +0°30'
	right	-0°19'	
Cross Camber		-0°58'	-0°20' [+0°00'] +0°20'
Individual Toe	left	+0°28'	-0°04' [+0°32'] +0°05'
	right	+3°07'	
Total Toe		+3°35'	-0°09' [+1°04'] +0°09'
Setback		-1°41'	
Geometrical driving axis		+1°20'	

Front Axle

		Initial Measurement	Target Data
Castor 20°	left	+3°20'	-0°30' [+5°42'] +0°30'
	right	+4°15'	
K.P.I. 20°	left	+1°10'	-0°24' [+12°54'] +0°36'
	right	+1°00'	
Toe out on turns	left	-1°31'	
	right	-1°07'	
Camber	left	-0°28'	-0°36' [-0°18'] +0°24'
	right	-0°59'	
Cross Camber		+0°31'	-0°28' [+0°12'] +0°28'
Individual Toe	left	+0°36'	-0°04' [+0°11'] +0°05'
	right	-0°53'	
Total Toe		-0°16'	-0°09' [+0°21'] +0°09'
Setback		-1°22'	
Included Angle 20°	left	+0°42'	
	right	+0°02'	

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Co. Regs. No. 52907220C GST Regs. No. M2-0000551-1

305 Alexandra Road
Vantage Automotive Centre
Singapore 159942

Service Booking: 6477 7377
Parts: 6477 7420
Vantage 24-Hour Assiet: 6473 8588
Fax: 6477 7300

**PEUGEOT****SERVICE TAX INVOICE**

RE-PRINT

REPAIR ORDER NO. Bp 113878	Date IN 05/10/2017	Invoice Number	Page No. 1 of 2
	Payment Term 30 Days From Invoice	Invoice Date	
	Customer Service Advisor Wong Guo Xiang	Invoice By Wong Guo Xiang	

CUSTOMER INFORMATION	INVOICE TO 24748
Heng Aik Kian Blk 55 Lengkong Empat #05-01 Singapore 417642	MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay #24-01 Hong Leong Building Singapore 048581

REGISTRATION No.	CHASSIS No.	STOCK No.	REGISTRATION DATE	MODEL	MILEAGE
SDA916E	VF3LPHNYWGS195604	209670	20/04/2017	3081.2 Allure17	0

CODE	DESCRIPTION	UNITS	DISC %	NETT
	SUNDRIES	1	0.00	30.00
	TO REPLACE/REPAIR REAR RHS QUARTER PANEL,REAR RHS DOOR, REAR BUMPER,END PANE	1	0.00	3,000.00
	TO RESPRAY REAR BUMPER,REAR RHS QUARTER PANEL,REAR RHS DOOR,RHS ROCKER PANEL,END PANEL	1	0.00	2,400.00
	WIRING CONNECTION & CHECKING (NETT)	1	0.00	150.00
	TO REMOVE & REFIX REAR BOOT COMPARTMENT TRJMS & GARNISH (NETT)	1	0.00	300.00
	TO REMOVE & REFIX FUEL TANK (NETT)	1	0.00	400.00
	TO REMOVE & REFIX REAR SEATS & CARPET (NETT)	1	0.00	400.00
	TO REMOVE & REFIX REAR LIGHTING SYSTEM (NETT)	1	0.00	150.00
	TO REMOVE & REFIX REVERSE SENSOR (NETT)	1	0.00	150.00
	TO REMOVE & REFIX REAR SUSPENSION SYSTEM ASSY (NETT)	1	0.00	1,500.00
	WHEEL ALIGNMENT (NETT)	1	0.00	600.00
	TUFF KOTE @ \$60 PER PANEL (NETT)	1	0.00	60.00
	BODY SEALANT @ \$90 PER PANEL (NETT)	1	0.00	90.00
	TO CONDUCT ECU COMPUTER DIAGNOSTIC INCLUDING REPROGRAMME,RESETTING & CLEAR FAULT CODE (NETT)	1	0.00	600.00
	TO SUPPLY 1 PCS 225/45 R17 TYRE (\$400 * 80%)	1	0.00	320.00
	VEHICLE TOWED TO VAL (NETT)	1	0.00	200.00
	Sub-Total :			10,350.00
CODE	DESCRIPTION	UNITS	DISC %	NETT
1610095980	REAR WING RH	1	25.00	1,012.50
1616785480	RR SUSP CROSSMEMBER	1	25.00	750.00
96779897PD	ALLOY WHEEL (RUBIS J17 GREY MATT)	1	25.00	442.50
	Sub-Total :			2,205.00

Attending CSO : Wong

Should you require further explanation, please reach me at 64777409

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Co. Regs. No. S2907220C GST Regs. No. M2-0000551-1

305 Alexandra Road
Vantage Automotive Centre
Singapore 159942

Service Booking: 6477 7377
Parts: 6477 7420
Vantage 24-Hour Assist: 6473 8588
Fax: 6477 7300

**PEUGEOT****SERVICE TAX INVOICE**

RE-PRINT

REPAIR ORDER NO. Bp 113878	Date IN 05/10/2017	Invoice Number	Page No. 2 of 2
	Payment Term 30 Days From Invoice	Invoice Date	
	Customer Service Advisor Wong Guo Xiang	Invoice By Wong Guo Xiang	

Service Packages	0.00	Total Labour/Parts/Service Package Charges	S\$ 12,555.00
Labour Charges	10,350.00	Less Insurance Excess	S\$ 0.00
Parts Charges	2,205.00	GST @ 7%	S\$ 878.85
Lubricant/Misc	0.00	Invoice Total Amounts	S\$ 13,433.85
		Less Deposit/Voucher	S\$ 0.00
Computer generated invoice. No signature is required.		Amount Payable	S\$ 13,433.85

²All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Sep 2017		29 Sep 2017 14:42 Edit Adj Rpt	S\$12,555.00 Edit Estimates	S\$12,555.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	HE JIAJING, ID: S8210782G, Tel: +6591849919, Email: hejiajin9@gmail.com		
Main Claimant:	HENG AIK KIAN, ID: S7072807I		
Vehicle Reg. No.:	SDA916E	Date of Loss:	27/09/2017 07:00 - :59
Claim Type:	TP / 531324	Policy/Cover Note No.:	28868481QMX (Comprehensive) Coverage: 13/01/2017 - 12/01/2018
Vehicle Reg. No. (Insured):	SJM6475L	Policy No. (Claimant):	
		Excess:	
Repairer:	AutoFrance (HQ) 305 Alexandra Road, #02-01, 159942 Alexandra - Tel: 64777331		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH] ... [Final Rpt due 29/10/2017]		
Driver/Custodian (Insured):	HE JIAJING (35 / Male), NRIC: S8210782G, Tel: +6591849919		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
<input type="checkbox"/> ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

*SDA916E (531324)
[SJM6475L]
TP
HENG AIK KIAN
Sep 27 2017 7:00AM
[HE JIAJING]
AutoFrance

Upload Documents		Upload Photos		Compose New Letter		View Use Viewer	
Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print		
1	29/09/17 10:59	Accident Statement From: SC - Reg. No: SJM6475L, Claimant: HE JIAJING		Load HTM			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	02/10/17 16:27	Adjuster Immediate Advice		Load HTM			
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	07/12/17 13:13	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>		
2	07/12/17 13:13	Chassis Number		Load JPG	<input checked="" type="checkbox"/>		
3	07/12/17 13:13	General View		Load JPG	<input checked="" type="checkbox"/>		
4	07/12/17 13:13	General View		Load JPG	<input checked="" type="checkbox"/>		
5	07/12/17 13:13	General View		Load JPG	<input checked="" type="checkbox"/>		
6	07/12/17 13:13	General View		Load JPG	<input checked="" type="checkbox"/>		
7	07/12/17 13:13	General View		Load JPG	<input checked="" type="checkbox"/>		
8	07/12/17 13:13	General View		Load JPG	<input checked="" type="checkbox"/>		
9	07/12/17 13:13	General View		Load JPG	<input checked="" type="checkbox"/>		
10	07/12/17 13:13	General View		Load JPG	<input checked="" type="checkbox"/>		
11	07/12/17 13:13	General View		Load JPG	<input checked="" type="checkbox"/>		
12	07/12/17 13:13	General View		Load JPG	<input checked="" type="checkbox"/>		
13	07/12/17 13:13	General View		Load JPG	<input checked="" type="checkbox"/>		
14	07/12/17 13:13	General View		Load JPG	<input checked="" type="checkbox"/>		
15	07/12/17 13:13	General View		Load JPG	<input checked="" type="checkbox"/>		
16	07/12/17 13:13	General View		Load JPG	<input checked="" type="checkbox"/>		
17	07/12/17 13:13	General View		Load JPG	<input checked="" type="checkbox"/>		
18	07/12/17 13:13	General View		Load JPG	<input checked="" type="checkbox"/>		
19	07/12/17 13:13	General View		Load JPG	<input checked="" type="checkbox"/>		
20	07/12/17 13:13	General View		Load JPG	<input checked="" type="checkbox"/>		
21	07/12/17 13:13	General View		Load JPG	<input checked="" type="checkbox"/>		
22	07/12/17 13:13	General View		Load JPG	<input checked="" type="checkbox"/>		
23	07/12/17 13:13	General View		Load JPG	<input checked="" type="checkbox"/>		
24	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
25	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
26	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
27	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
28	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
29	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
30	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
31	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
32	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
33	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		

34	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
35	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
36	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
37	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
38	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
39	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
40	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
41	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
42	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
43	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
44	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
45	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
46	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
47	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
48	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
49	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
50	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
51	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
52	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
53	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
54	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
55	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
56	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
57	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
58	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
59	07/12/17 13:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation					<input checked="" type="checkbox"/>
				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	29/09/17 10:59	SDA916E GIA RPT From:SC - Reg. No: SJM6475L, Claimant: HE JIAJING		Load PDF	
2	29/09/17 10:59	ESTIMATE		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/12/17 16:10	Workshop Invoice		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17018740/T1QBE2

Date: 28/12/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28868481QMX
Claimant Vehicle No :	SDA916E	Insured Vehicle No :	SJM6475L
Date of Loss:	27/09/2017	Nature of Claim:	TP
			Claim No: 531324

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDA916E	Engine No:	10XTA40401856
Make & Model:	PEUGEOT 308, 1.2 5DR ACTIVE PURETECH 1.2 A/T 2W (A)	Chassis No:	VF3LPHNYWGS195604
Reg. Date:	20/04/2017 (Man. Year: 2016)	Odometer:	7764 km
Colour:	Black		
Engine Capacity:	1199 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,294.00	2,555.00	1,739.00	40.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,300.00	10,000.00	3,300.00	24.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,594.00	12,555.00	5,039.00	28.64
+ GST 7.00/7.00% (S\$)	1,231.58	878.85	352.73	28.64
Nett Amount (S\$)	18,825.58	13,433.85	5,391.73	28.64

INSPECTION

Date of Assignment:	29/09/2017		
Date Inspected:	29/09/2017	Inspected At:	AutoFrance (HQ) 305 Alexandra Road, #02-01 Singapore 159942
Estimated Period of Repair:	8.0 days		

Adjuster: MOHD TAUFIKH

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2017)
Parts: 144	PEUGEOT 308 1.2 5DR ACTIVE PURETECH 1.2 A/T 2W (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDA916E)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*SUNDRIES	Necessary	150.00 FS	*30.00 FS	
2	1		*ALLOY WHELL (RUBIS J17 GREY MATT)	Cut	531.00 F	*442.50 F	
3	1		*REAR WING RH	Bent	1,215.00 F	*1,012.50 F	
4	1		*ENTRY SEAL	Not Necessary	108.00 F	*- F	
5	1		*BEARING HUB	Not Necessary	279.00 F	*- F	
6	1		*RR SUSP CROSSMEMBER	Bent	900.00 F	*750.00 F	
7	1		*REAR SHOCK ABSORBER	Not Necessary	81.00 F	*- F	
8	1		*REAR BUMPER - TO BE PAINTED	Repair	630.00 F	*- F	
9	1		*225/45 R17 TYRE (80%)	Cut	400.00 F	*320.00 F	
					Total Parts (S\$)	4,294.00	2,555.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE / REPAIR REAR RHS QUARTER PANEL, REAR RHS DOOR, REAR BUMPER, END PANE	New	4,200.00	3,000.00
2	TO RESPRAY REAR BUMPER, REAR RHS QUARTER PANEL, REAR RHS DOOR, RHS ROCKER PANEL, END PANEL	New	4,200.00	2,400.00
3	WIRING CONNECTION & CHECKING	New	150.00	150.00
4	TO REMOVE & REFIX REAR BOOT COMPARTMENT TRIMS & GARNISH	New	300.00	300.00
5	TO REMOVE & REFIX FUEL TANK	New	400.00	400.00
6	TO REMOVE & REFIX REAR SEATS & CARPET	New	400.00	400.00
7	TO REMOVE & REFIX REAR LIGHTING SYSTEM	New	150.00	150.00
8	TO REMOVE & REFIX REVERSE SENSOR	New	150.00	150.00
9	TO REMOVE & REFIX REAR SUSPENSION SYSTEM ASSY	New	1,500.00	1,500.00
10	WHEEL ALIGNMENT	New	600.00	600.00
11	TUFF KOTE @ \$60 PER PANEL	New	180.00	60.00
12	BODY SEALANT @ \$90 PER PANEL	New	270.00	90.00
13	VEHICLE TOWED TO VAL	New	200.00	200.00
14	TO CONDUCT ECU COMPUTER DIAGNOSTIC INCLUDING REPROGRAMME, RESETTNG & CLEAR FAULT CODE	New	600.00	600.00
Gross Labour Cost (S\$)			13,300.00	10,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >