

12/01/2017

Surveyor: Rane

REF:

NS/WC17018781 / Rq602

22520

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SKX 6335m

Policy No. 5088411648 090317 - 120318

Claims No. MT/0962029-002

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 1 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SMB15724

Yr Regn: 2014 / NSC

Type: M.Car / M.Cycle / Bds / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MAN ML 320F (A22)

c.c. 1608

Colour:

MULTI

A/C: Insured / Std / NI / NA

Sp. Reading

236451

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WM4A 22 220F 700 2538

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

275/70R22.5

R:

275/70R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FIAT

Front

Rear

R/Bal.

8

mm

R/Bal.

8/8

mm

L/Bal.

8

mm

L/Bal.

8/8

mm

D.O.A.

16/09/17

D.O.I.

22/09/17

Survey held at

SMEI

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SMB 15720 - X

SKX 6335m - CC3 / AXA 16 007025 / Kpa352

DOA: 120410

US \$450, 1 day (Cen \$526, 54%)

RECEIVED 20 NOV 2017

Date/Time, File Pass to?

☐

Preli. Report

1) 20/11/17 turner

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 1

Resurvey No. of Trip:

Survey Fee:

Transportation

160 S + RS, SI

Photos

Others

TOTAL

Report Format: TP

Lump Sum / I.B. (\$) 450

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17018781/R1qb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 02-10-2017
189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKX 6335M	Veh. Inspected	SMB 1572U
Policy No.	5088411648	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	29/09/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/09/2017	Inspection Date	29/09/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Cath): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Ramy)

: Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

[Signature] 20/01/17

Case Handler

Date

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1	MT/0967919-002	SMRT TAXIS PTE LTD	SHF 472U	GBF 6529Y
2	MT/0962029-002	SMRT BUSES LTD	SMB 1572U	SKX 6335M
3	MT/0968532-003	SMRT TAXIS PTE LTD	SHB 1953M	SDB 6808P
4	MT/0969143-002	SMRT TAXIS PTE LTD	SHD 6476E	SJK 7469J
5	MT/0912702-002	SMRT BUSES LTD	SMB 1630K	FQ 8465D
6	MT/0970438-001	SMRT TAXIS PTE LTD	SHB5851Y	SLQ 3128P
7	MT/0970441-001	SMRT TAXIS PTE LTD	SHB 1960S	SKM 5998P
8	MT/0959634-002	SMRT BUSES LTD	SMB 1580X	SLD 9017E
9	MT/0968476-002	SMRT TAXIS PTE LTD	SHB 5800U	SHD 2021K
10	MT/0953202-003	SMRT TAXIS PTE LTD	SHC 4540X	WC3406E

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)
[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5088411648	MICROUNIVER SK	53353934W	GPC	driva CLASSIC	SKX6335M	SKX6335M	09/03/2017	12/03/2018

Text size + -

Enquire Transfer Fee**Vehicle Details**

Vehicle No. : SMB1572U
 Vehicle Type : H20 - Public Transport Bus/Coach/Minibus
 Vehicle Attachment 1 : Air-Conditioned
 Vehicle Scheme : OmniBus (SMRT - ARF-exempted)
 Vehicle Make : MAN
 Vehicle Model : NL 320F (A22) 11L AUTO ABS TURBO
 Chassis No. : WMAA22ZZ0F7002538
 Propellant: Diesel
 Engine No. : 50339180863929
 Engine Capacity : 10518 cc
 Maximum Power Output: -
 Maximum Laden Weight: 18000 kg
 Unladen Weight: 11280 kg
 Year Of Manufacture: 2014
 Original Registration Date: 30 Dec 2014
 Lifespan Expiry Date : 29 Dec 2031
 Road Tax Expiry Date : 29 Dec 2017
 Inspection Due Date : 29 Dec 2017
 Intended Transfer Date : 02 Oct 2017
 CO2 Emission: -

The current road tax expiry is 29 Dec 2017. You may renew the road tax from 30 Sep 2017 with all pre-requisite(s) fulfilled. If the road tax is renewed after 29 Dec 2017, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.
 Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 30 Dec 2017 to 29 Jun 2018)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	11.00	-	11.00
Sub Total :			11.00
Nett Road Tax Amount (After Offsetting Over Payment) :	850.00	-	850.00
Total Amount Payable :			861.00

You may print this page for reference.

OK Print



Please read through the Privacy Statement, Terms of Use and Disclaimer.
 Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
 Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution
 Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
 Last updated on 17 Sep 2017 at 12:38 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/09/2017 10:50
Date Of Accident	16/09/2017 12:50
Exact Location Of Accident	SCOTTS RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB1572U
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64823888

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	BUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-17087563MFBP
Cover Note Number	

Driver

Name of Driver	S VIJAYAN S/O K SANKU
NRIC No	S2626044B
Date Of Birth	17/10/1960
Occupation	OUTDOOR
Date Of Driving Pass	29/04/1988
Driving Experience	29 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 11

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

Bus travelling along Scotts Road, before BS: 09219 - Far East Plaza, the traffic condition of the said rd was heavy due to road work on the left lane causing all vehicle were moving slowly. While traveling, a private car(SKX6335M) on the right lane overtake me thus hit onto the right front body of the bus. For the above accident nobody was injured.

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKY6995M

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver YU LI JUN

NRIC/Passport Number

Contact Number 96809106

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan Pg. 1

SKETCH PLAN

B43/09/17/1020

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


SMRT BUSSES LTD
6 Ang Mo Kio Street 6
Singapore 569140
Tel: 6482 3888 Fax: 6482 3867
www.smrt.com.sg

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

pls refer to GHA report.

Declaration

We declare the foregoing particulars are true in every respect.

SAATCHI & SAATCHI Ltd
6 Ang Mo Kio Street 6,
Singapore 569640
Tel: 6482 3888 Fax: 6482 3888
www.satchi.com.sg

Policyholder's Signature / Date &
Time


Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre


Reg. No : SMB1572U
 Ref. No : BUS/09/17/1020
 Reg. Date : 20/09/2017
 Vehicle Type : BUS -12M
 Make : MAN
 Model : MAN
 Name of Driver : S Vijayan S/O K Sanku
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 16/09/2017 12:50:00 PM
 Accident Reported Date / Time : 18/09/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : IDAC
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No :
 Special Instruction to ARC, if any :
 SMB1572U - FRONT RIGHT PORTION
 SKX6335M (TP) - INSURED WITH NTUC.
 Prepared Date : 20/09/2017 05:59:09 PM



Chassis No :
Work Shop :

Mileage : 0
Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	530.00	0.00
Total Spray Painting Charges	446.00	0.00
Total Material Charges	0.00	0.00
Other Charges	0.00	0.00
TOTAL	976.00	0.00
Lum Sum Total	1,000.00	0.00
No. of Repair Days	0.00	0.00
Prepared / Adjusted By		<i>1 day / Lumpsum</i>
Arc / Surveyor Sing Off Date	01/01/1900 12:00:00 AM	01/01/1900 12:00:00 AM
Prepared / Adjusted Date		<i>29/09/17</i>
Remarks		<i>@1145</i>
Prepared Date	29/09/2017 09:25:56 AM	

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No	Invoice No
Quotation Date	Invoice Date
Invoice Amount	Prepared Date

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	530.00	0.00 <i>265</i>
Total Labour	530.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	446.00	0.00 <i>300</i>
Total Spray Painting & Panel Beating	446.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
TOTAL MATERIALS										
TOTAL MATERIALS(Discounted)								0.00	0.00	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB1572U
 Ref. No : BUS/09/17/1020
 Reg. Date : 30/12/2014
 Vehicle Type : BUS -12M
 Make : MAN
 Model : MAN
 Name of Driver : S Vijayan S/O K Sanku
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 16/09/2017 12:50:00 PM
 Accident Reported Date / Time : 18/09/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : IDAC
 Vehicle is Towed Back? : No
 Towed Back Date/Time : 01/01/2000
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024092317
 Special Instruction to ARC,if any :

SMB1572U - FRONT RIGHT PORTION
 SKX6335M (TP) - INSURED WITH NTUC.

Prepared Date : 20/09/2017 05:59:09 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : WMAA22ZZ0F7002538

Mileage

0

Work Shop :

Repair Completed Date / Time :

01/01/2000

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 530.00	265.00
Total Spray Painting Charges	: 446.00	300.00
Total Material Charges	: 0.00	0.00
Other Charges	: 0.00	-100.00
TOTAL	: 976.00	465.00
Lum Sum Total	: 1,000.00	450.00
No. of Repair Days	: 2.00	1.00
Prepared / Adjusted By	:	RASUL 90010068
Arc / Surveyor Sing Off Date	: 29/10/2017 01:59:29 PM	29/10/2017 03:55:24 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 29/09/2017 09:25:56 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	530.00	265.00
Total Labour	530.00	265.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	446.00	300.00
Total Spray Painting & Panel Beating	446.00	300.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	0.00	-100.00
Total Other Costs	0.00	-100.00

265
300

565
200

452

976

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
TOTAL MATERIALS										
TOTAL MATERIALS(Discounted)							0.00	0.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17018781/R1qbn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 24-11-2017



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKX 6335M	Veh. Inspected	SMB 1572U
Policy No.	5088411648	Coverage (\$)	0.00
Claim No.	MT/0962029-002	Excess (\$)	0.00
Assign From		Assign Date	29/09/2017

2. Vehicle Particulars & Condition

Make & Model	MAN NL 320F (A22)	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WMAA22ZZ0F7002538	Colour	MULTI
Odometer	236451	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	FIRENZA	8 mm
L/H Front Tyre	275/70 R22.5	FIRENZA	8 mm
R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm
L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/09/2017	Inspection Date	29/09/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	1 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 1572U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REPAIR RH FRONT PORTION.		530.00	265.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		446.00	300.00
			976.00	565.00
	GRAND TOTAL		976.00	565.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				450.00

Report Ref No. NS/INC17018781/R1qbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.