

ASS. REC. BY:

REF: CS/FCI17018774/R19bn2

Special Instructions:

SURVEYOR

RCSU

ASSIGNMENT (Office)

CWS

From (Person): Joanne Yong

of

FCI

Date/Time: 29/9/17 2.32pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLA 6766L

Insured: SH 6777 K

at Workshop m/s

Munich Automobiles

Tel: 65667666 / 90515581

of 30 Teban Gardens Crescent

Policy No

D-15072701MF5H

Claim No:

D17009210MF5H

Sum Insured

Excess:

Make of Veh.

(Client's Record)

D.O.A. 20/09/2017

CA / REV / REP. / REV 24 HRS

wp

2/10/2017 @ Morning

H.O.D. Endorsement

Date/Time: 29/9/17 2.40pm

Person Contacted

Tan Kok Ting

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLA 6766L - X

SH 6777K - NA / TMI 15015500 / d2 - D.O.A: 13/9/15

03/10/17 @ 5.40pm revised to Joanne Yong by email.

04/10/17 @ 3.47pm confirmed with Tan Kok Ting final fig @ 6873.32,
3 days. by email. (Red # 8276.28, 43%)

Rafael

REF: FCI

ASSIGNMENT

From _____ Date 02/10/17

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No SLA G766 L

at Workshop no Munich Automobilies

of 30 Teban Gardens Crescent

Insured _____

Policy No _____

Claims No _____

Sum Insured _____ Excess _____

(Client's Record) _____

Make of Veh _____

(Policy Condition) _____

Remark: The veh had commenced its repair at the time of inspection.

Bal or Market Value: _____

DAC Accident Report _____ Consistent? Yes or No

GIA / PR Seen _____ Consistent? Yes or No

Est Repairs 3 days Res: Yes or No

Lum Sum _____ % 3 Val Yes or No

CA / REV / REP. / 24 HRS wp

Date _____ Person Contacted _____

Date / Time _____ Action / Instruction _____



Veh No SLA 6766 L Yr Regn Mar, 2016

Type ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make B.M.W M6 CC 4345

Colour BLUE A/C Insured / Std / NI / NA

Sp Reading 23071 T Radio Insured / Std / NI / NA

Eng No _____

C No WBS6E920806S38725

Gen Cond: Good ☒ Fair / Poor / Burnt

Steering ☒ In order / Jammed / Leaked / Burnt or

Brake ☒ In order / Jammed / Leaked / Burnt or

Mod Nil / ☒ S/Rim / STD A/Rim or

Tyre Size F: 265/35 2R20

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIO / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R Bal 6 mm R Bal 6 mm

L Bal 6 mm L Bal 6 mm

D.O.A 20/9/17 D.O.I 02/10/17

Survey held at Munich

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

d/s frt

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time File Pass to? ☐ : Preli. Report

1. 04/12/17 ☐ : Final Report

Date/Time File Return to? _____

Days Of Repair: 3

Resurvey No. of Trip: 1

Report Format: TP

Lump Sum / I.B.I. (\$) 10873.32

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech Invs (\$) ☐ Weekend (\$)

Survey Fee

Transportation

1. S-RE \$

2. Photo 039

3. Other 5/12/17

TOTAL

170 + 135
50
50
28
433



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17018794/R1qb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 02-10-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 6777K	Veh. Inspected	SLA 6766L
Policy No.		Coverage (\$)	0.00
Claim No.	D17009210MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNEY YONG)	Assign Date	02/10/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/09/2017	Inspection Date	02/10/2017
Survey held at	MUNICH AUTOMOBILES PTD LTD 30 TEBAN GARDENS CRESCENT SINGAPORE 608927		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Survey Department Check List (Case Handler)

Reference No.: CS/PA/7018794/196
Policy Type: OD / TP / RES / TL / EVA

SLA 6766L

Case Handler

Typist

Admin (Cather): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Ramy): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

✓			
---	--	--	--

Check By:

[Signature] 06/12/17
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	27-09-2017	Our Ref No. D17009210MFSH
Accident Date	20-09-2017	Claim Type. Third Party
Insured Vehicle	SH6777K	Third Party Vehicle. SLA6766L
Survey Location	30 TEBAN GARDENS CRESCENT	
Contact Person.	TAN KOK TING	
Contact No.	65667666/ 90515581	Fax No. 65659200
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MUNICH AUTOMOBILES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/228519)



PRI Documents



Close



PRI Header Details

Claim No	D17009210MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & MUNICH A
Workshop Name	MUNICH AUTOMOBILES PTE LTD (Contact Person : TAN KOK TING)	Survey Location & Contact Details	30 TEBAN GARDENS CRESCENT Mobile: 90515581 , Phone: 65667666 , Fax: 65659200 EmailId: KOK.TING@MUNICHAUTO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM T		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH6777K	TP Vehicle No	SLA6766L
PRI Recieved Date	28-09-2017 08:07:37 PM	Surveyor Appointed Date	29-09-2017 02:32:24 PM	Surveyor Accept Date	29-09-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	29-09-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 4 December, 2017 3:47 PM
To: Tan Kok Ting
Cc: SUR
Subject: RE: FINALISATION OF VEHICLE SLA 6766L

Dear Mr Tan,

Confirm final fig \$10,873.32 before GST and 3 repair days.

Please send the relevant documents to First Capital Insurance.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Kok Ting [<mailto:kok.ting@munichauto.com.sg>]
Sent: Monday, 4 December, 2017 12:16 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: RE: FINALISATION OF VEHICLE SLA 6766L

Hi Shiau Chan ,

Please refer to attached email. We tried to send finalize to your surveyor. But he haven't come back to me.
Can you please remind him ? Please.

Best regards
Kok ting

From: Shiau Chan (LKKAUTO) [<mailto:siewsc@lkkauto.com>]
Sent: Monday, December 04, 2017 12:04 PM
To: kok.ting@munichauto.com.sg
Subject: FINALISATION OF VEHICLE SLA 6766L

Dear Mr Tan,

Kindly advise the status of SLA 6766L.

If done for repair, please send us the final bill for finalisation.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 3 October, 2017 5:40 PM
To: 'Claim Workflow System'; assignments
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17009210MFSH/1
Attachments: CSFCI17018794R1qb.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SLA 6766L.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)

Sent: Friday, 29 September, 2017 3:25 PM

To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>

Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D17009210MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]

Sent: Friday, 29 September, 2017 2:32 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; JOANNEYONG@FIRST-INSURANCE.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D17009210MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17009210MFSH

Date: 03rd October 2017

Our Ref: CS/FCI17018794/R1qb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLA 6766L

Please be informed that we had conducted the inspection of the abovementioned vehicle on 02/10/2017 at the premises of M/s MUNICH AUTOMOBILES, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>19,149.60</u>
Revised Estimate Amount	: S\$ <u>11,206.75</u>
"Check" Items Amount	: S\$ <u>3,701.90</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
at the o/s front portion.



Yours faithfully

Mohd Rasul
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	8190W
Vehicle Details	
Vehicle No.	SLA6766L
Vehicle to be Exported	No
Intended De-registration Date	04 Dec 2017
Vehicle Make	B.M.W.
Vehicle Model	M6 GRAN COUPE LED NAV HUD
Primary Colour	Blue
Manufacturing Year	2015
Engine No.	20061105S63B44B
Chassis No.	WBS6E92080GS38725
Maximum Power Output	423.0 kW (567 bhp)
Open Market Value	\$111,962.00
Original Registration Date	04 Mar 2016
First Registration Date	04 Mar 2016
Transfer Count	0
Actual ARF Paid	\$173,532.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	03 Mar 2026
PARF Rebate Amount	\$130,149.00
Intended COE Rebate Details	
COE Expiry Date	03 Mar 2026
COE Category	E - Open Category
COE Period(Years)	10
QP Paid	\$60,003.00
COE Rebate Amount	\$49,477.00
Total Rebate Amount	\$179,626.00

The information contained herein is correct as at 04 Dec 2017

OK

Enquire Transfer Fee

Vehicle Details

Vehicle No.	SLA6766L
Vehicle Type	N18 - Passenger (Co) Company Car (Single Rate)
Vehicle Attachment 1	No Attachment
Vehicle Scheme	Normal
Vehicle Make	B.M.W.
Vehicle Model	M6 GRAN COUPE LED NAV HUD
Chassis No.	WBS6E92080GS38725
Propellant	Petrol
Engine No.	20061105S63B44B
Engine Capacity	4395 cc
Maximum Power Output	423.0 kW (567 bhp)
Maximum Laden Weight	2410 kg
Unladen Weight	1875 kg
Year Of Manufacture	2015
Original Registration Date	04 Mar 2016
Lifespan Expiry Date	-
COE Category	E - Open Category
Quota Premium	\$60,003.00
COE Expiry Date	03 Mar 2026
Road Tax Expiry Date	03 Mar 2018
PARF Eligibility Expiry Date	03 Mar 2026
Inspection Due Date	03 Mar 2019
Intended Transfer Date	04 Dec 2017
CO2 Emission	231.00 (g/km)
CEVS Rebate Utilised Amount	-

The current road tax expiry is 03 Mar 2018. You may renew the road tax from 04 Dec 2017 with all pre-requisite(s) fulfilled. If the road tax is renewed after 03 Mar 2018, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 04 Mar 2018 to 03 Sep 2018)

Munich Automobiles Pte Ltd

Company Reg No: 200910960R
GST Reg No: 200910960
30 Teban Gardens Crescent, Singapore 608927
Tel: +65 65667666 Fax: +65 65659098



ESTIMATE

Account No. **C0002**

Invoice Name & Address:

C Starhigh Asia Pacific Pte Ltd
34 Boon Leat Terrace
#04-14

Customer Name & Address:

C Starhigh Asia Pacific Pte Ltd
34 Boon Leat Terrace
#04-14

119866

119866

Email: starhigh@starhigh.com.sg

Inv. Printed By: TKT Service Advisor: Tan Kok Ting

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
W 52184	0	0		28/09/2017	16:10	1
Reg No.	Chassis No.	Model	Reg Date	Date In	Mileage	
SLA6766L	GS38725	M6 Gran Coupe LCI	04/03/2016		0	
Job Description						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
1	GEN	Remove damages part and replace affected body parts		288.00	12.00		0.00	3,456.00 1728
2	GEN	Painting front bumper and both front fender		201.00	12.00		0.00	2,412.00 1608
3	GEN	To check electrical wiring system for proper function ability include parking assist sensor		96.00	12.00		0.00	1,152.00 576
4	GEN	To Re-programmed system and delete fault code after accident repair		96.00	12.00		0.00	1,152.00 576
5	SUN	Sundry items		150.00	1.00		0.00	150.00 50
Menu Subtotal:								8,322.00

V	Rate	Service/Goods	GST

Customer's Signature

Authorized Signature

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No:

N.B. Goods sold are not returnable.



Munich Automobiles Pte Ltd

Company Reg No: 200910960R
GST Reg No: 200910960
30 Teban Gardens Crescent, Singapore 608927
Tel: +65 65667666 Fax: +65 65659098



ESTIMATE

Account No. **C0002**

Invoice Name & Address:

C Starhigh Asia Pacific Pte Ltd
34 Boon Leat Terrace
#04-14

Customer Name & Address:

C Starhigh Asia Pacific Pte Ltd
34 Boon Leat Terrace
#04-14

119866

119866

Email: starhigh@starhigh.com.sg

Inv. Printed By: TKT Service Advisor: Tan Kok Ting

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
W 52184	0	0		28/09/2017	16:10	2
Reg No.	Chassis No.	Model	Reg Date	Date In	Mileage	
SLA6766L	GS38725	M6 Gran Coupe LCI	04/03/2016		0	
Job Description						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
6		Spring frt.bumper		1.00	5.25 EACH		0.00	5.25
7		Lever		1.00	15.50 EACH		0.00	15.50
8		Bumper trim frt.-N		1.00	1,919.45 EACH		0.00	1,919.45
9		Cover		1.00	46.95 EACH		0.00	46.95
10		Cover		1.00	46.95 EACH		0.00	46.95
11		Control unit		1.00	872.10 EACH		0.00	872.10
12		Set, fan		1.00	386.15 EACH		0.00	386.15
13		LED daytime		1.00	223.55 EACH		0.00	223.55
14		LED Cornerin		1.00	767.45 EACH		0.00	767.45
15		LED module f		1.00	767.45 EACH		0.00	767.45
16		Headlight, Right		1.00	4,366.45 EACH		0.00	4,366.45
17		A011265D Gasket		4.00	4.95 EACH		0.00	19.80
18		Ultrasonic s		2.00	363.05 EACH		0.00	726.10
19		Camera		1.00	664.45 EACH		0.00	664.45

V	Rate	Service/Goods	GST

Customer's Signature

Authorized Signature

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No:

N.B. Goods sold are not returnable.



Munich Automobiles Pte Ltd

Company Reg No: 200910960R
GST Reg No: 200910960
30 Teban Gardens Crescent, Singapore 608927
Tel: +65 65667666 Fax: +65 65659098



ESTIMATE

Account No. **F0001**

Invoice Name & Address:

First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore

Customer Name & Address:

C Starhigh Asia Pacific Pte Ltd
34 Boon Leat Terrace
#04-14

068877

119866

Email: starhigh@starhigh.com.sg

Inv. Printed By: TKT Service Advisor: Tan Kok Ting

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
W 52184	23172	0	INS	17/10/2017	16:16	1
Reg No.	Chassis No.	Model	Reg Date	Date In	Mileage	
SLA6766L	GS38725	M6 Gran Coupe LCI	04/03/2016	13/10/2017	23585	
Job Description						
Body repair						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
1	GEN	Remove damages part and replace affected body parts		144.00	12.00		0.00	1,728.00
2	GEN	Painting front bumper and right front fender		134.00	12.00		0.00	1,608.00
3	GEN	To check electrical wiring system for proper function ability include parking assist sensor		48.00	12.00		0.00	576.00
4	GEN	To Re-programmed system and delete fault code after accident repair		48.00	12.00		0.00	576.00
5	SUN	Sundry items		50.00	1.00		0.00	50.00
Menu Subtotal:								4,538.00

V	Rate	Service/Goods	GST

Customer's Signature

Authorized Signature

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No:

N.B. Goods sold are not returnable.



Munich Automobiles Pte Ltd

Company Reg No: 200910960R
GST Reg No: 200910960
30 Teban Gardens Crescent, Singapore 608927
Tel: +65 65667666 Fax: +65 65659098



ESTIMATE

Account No. **F0001**

Invoice Name & Address:

First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore

068877

Customer Name & Address:

C Starhigh Asia Pacific Pte Ltd
34 Boon Leat Terrace
#04-14

119866

Email: starhigh@starhigh.com.sg

Inv. Printed By: TKT Service Advisor: Tan Kok Ting

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
W 52184	23172	0	INS	17/10/2017	16:16	2
Reg No.	Chassis No.	Model	Reg Date	Date In	Mileage	
SLA6766L	GS38725	M6 Gran Coupe LCI	04/03/2016	13/10/2017	23585	
Job Description						
Body repair						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
6		Bumper trim frt.-No		1.00	1,919.45	EACH	5.00	1,823.48
7		Headlight, Right		1.00	4,366.45	EACH	5.00	4,148.13
8		A011265D Gasket		4.00	4.95	EACH	5.00	18.81
9		Ultrasonic s		1.00	363.05	EACH	5.00	344.90

Menu Subtotal:

6,335.32

10 NOTES

Third party claim against SH6777K

D.O.A : 20/9/2017 0745hrs

D17009210MFSH-First capital Insurance

Menu Subtotal:

0.00

	V	Rate	Service/Goods	GST	Net	
Parts		6,335.32				10,873.32
Surcharge	S	7.00	10873.32	761.13	G.S.T.	761.13
Labour		4,538.00			Total	11,634.45
Sublet		0.00			Deposit	0.00
Menus		0.00			Owing	11,634.45

Customer's Signature

Authorized Signature

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No:

N.B. Goods sold are not returnable.





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17018794/R1qbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6777K	Veh. Inspected	SLA 6766L	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17009210MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	29/09/2017	
2. Vehicle Particulars & Condition				
Make & Model	BMW M6	c.c	4395	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WBS6E92080GS38725	Colour	BLUE	
Odometer	23071	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	265/35 ZR20	MICHELIN	6 mm	
L/H Front Tyre	265/35 ZR20	MICHELIN	6 mm	
R/H Rear Tyre	265/35 ZR20	MICHELIN	6 mm	
L/H Rear Tyre	265/35 ZR20	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/09/2017	Inspection Date	02/10/2017	
Survey held at	MUNICH AUTOMOBILES PTD LTD 30 TEBAN GARDENS CRESCENT SINGAPORE 608927			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 6766L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRY (SN)	NECESSARY	150.00	50.00
1	SPRING FRT BUMPER (SN)	SERVICEABLE	5.25	-
1	LEVER (SN)	SERVICEABLE	15.50	-
1	BUMPER TRIM FRT-N (SN)	SCRATCHED	1,919.45	1,823.48
1	COVER (SN)	SERVICEABLE	46.95	-
1	COVER (SN)	SERVICEABLE	46.95	-
1	CONTROL UNIT (SN)	SERVICEABLE	872.10	-
1	SET, FAN (SN)	SERVICEABLE	386.15	-
1	LED DAYTIME (SN)	SERVICEABLE	223.55	-
1	LED CORNERIN (SN)	SERVICEABLE	767.45	-
1	LED MODULE F (SN)	SERVICEABLE	767.45	-
1	HEADLIGHT, RIGHT (SN)	BROKEN	4,366.45	4,148.13
4	A011265D GASKET (SN)	NECESSARY	19.80	18.81
2	ULTRASONIC S (SN)	SCRATCHED (1PC ONLY)	726.10	344.90
1	CAMERA (SN)	SERVICEABLE	664.45	-
			10,977.60	6,385.32
LABOUR				
	REMOVE DAMAGES PART AND REPLACE AFFECTED BODY PARTS		3,456.00	1,728.00
	PAINTING FRONT BUMPER AND BOTH FRONT FENDER.		2,412.00	1,608.00
	TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER FUNCTION ABLITY INCLUDE PARKING ASSIST SENSOR		1,152.00	576.00
	TO RE-PROGRAMMED SYSTEM AND DELETE FAULT CODE AFTER ACCIDENT REPAIR.		1,152.00	576.00
	-		-	-
	-		-	-
	-		-	-
			8,172.00	4,488.00
GRAND TOTAL			19,149.60	10,873.32
RECOMMENDED COST OF REPAIRS				10,873.32

Report Ref No. CS/FC117018794/R1qbn2



Report Ref No. CS/FCI17018794/R1qbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.