CWS From (Person):	ASSIGNME			74s
	Sithara of F	CI	Date/Time 3/10/17	7.55pm
Estimated Cost		Bill to:		-
	OD RES / EVA / INV / MV / C	S	5 100 B WW.	
To Inspect Vehicle No:			SHA 0462	A
at Workshop m/s	Progressive		67415336	
of Blk 3022 4B	1 Road 1 # 01-45/4	6	\$0.50 or all	
Policy No: D-15		A CONTRACTOR OF THE PARTY OF TH	109296MFSH	
Sum Insured		Excess:	10.000	
Make of Veh			D.O.A. 29 /09/	17
(Client's Record) CA / REV / REP. / 1	REV 24 HRS 'DS'	5/10/17 @ Af	ter 10am	
Date/Time 4/10/17	8-52am Person Contacted:	Pei Wun	Vehicle_IN 1 (1)	
	ostruction (/) Estimate		100000000000000000000000000000000000000	
Date/Time Action/Ir				
SJM	8430C-X			
SJM				

ASSIGNMENT

Typer M.Cgr / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or Make: Lak-4.5.5.250 cc 2.500 Make: Lak-4	From:	Date:	Veh No:	SJM8	1430C	Yr Regn: 200	giJun.
Truck / Trailer or Make: Lakus / S 250 cc 2500 Make: Lakus / S 250 cc 25	www.cooksand	530	Typer M.Car	M.Cycle / Bu	s / Van / Lor	ry / Taxi / Prime Mov	er/
Make : Lakus - / S 250		P RES / OD RES / EVA / INV / MV	Truck	/ Trailer or			
at Workshop m/s off Insured Std / Ni / NA Sp. Reading			Make:	Lexus	18 250	C.C	2500
Sp. Reading T/Radio: Insured is Insured is Sp. Reading T/Radio: Insured is Insured is Excess: Claims No. Sum Insured: Excess:			Colour				Std / NI / NA
Eng/No: Claims No. Sum Insured: Excess: Sum Insured: Steering: Inergiar / Jammed / Leaked / Burnt or Modi: Nil SRim / STD Airlim or Tyre Size: 33 / 40 P.18 Remark: The veh had commenced its repair at the time of inspection. Nis Ois Toyo / Yoko or Sal. or Market Value: DAC Accident Rport: Consistent? Yes or No Sal. or Market Value: DAC Accident Rport: Consistent? Yes or No UBal. Ois mm UBal. Ois			03191888			T/Radio: Insured / S	Std / NI / NA
Policy No. Claims No. Sum Insured: Excess: Concern Cond Good Fair Poor Burnt Steering: Ingrafer Jammed Leaked Burnt or Steering: Ingrafer Jammed Leaked Burnt or Modi: Nil SRim STD Alkim or Tyre Size: F: 235 40 F18 Remark: The veh had commenced its repair at the time of inspection. Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA PR Seen: Consistent?: Yes or No CA REV REP. 24 HRS Date: Person Contacted: Date Time Action Instruction TP St	26.72			-			
Claims No. Sum Insured: Excess: Sum Insured: Excess: Sum Insured: Excess: Sum Insured: Steering: Ingrider / Jammed / Leaked / Burnt or Steering: Ingrider / Jammed / Leaked / Burnt or Steering: Ingrider / Jammed / Leaked / Burnt or Modi: Nil / Elimin / STD A/Rim or Tyre Size: F: 235/40 PLS R: 235				TT	HRK267	4050.9205	8.
Sum Insured: Sum Insured: Excess: Sum Insured: Excess: Sum Insured:					3 0000000 100		
Collect Record Consistent Second Consistent Second Sec	SS 1 10' 10' 10'	Evenen				Burnt or	
Modi: Nil Siftin STD AIRim or Tyre Size: F: 335 40 PL/8 R:		4	3.00 mm. 1900 mm. 190	- Children Construction			
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Lum Som: % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Person Contacted: Person Contacted: Person Contacted: The UIC / Chassis frame / Body Structure affected due to collision The UIC / Chassis frame / Body Structure affected due to collision Date / Time Action / Instruction RECEIVED 2 9 NOV 2017 Resurvey No. of Trip: Resurvey No. of Trip: Survey Fee: Transportation: 70 157 - 35 Total Transportation: 10 157 - 35 Total Transportation: 10 2 3 4 0 P.18 R: 33 / 40 P.18 Resurvey No. of Trip: Survey Fee: Transportation: 50 2 10 P.10 Resurvey No. of Trip: Survey Fee: Transportation: 70 157 - 35 Total Transportation: Total	Accessor of the control of	d)					
Remark: The veh had commenced its repair at the time of inspection. N/S O/S	make of ven:	Į.				ORIS	
Remark: The veh had commenced its repair at the time of inspection. Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Lum Sum:: % 3 Val.: Yes or No Date: Person Contacted: Date / Time: Action / Instruction TP / St Cap. Date / Time: Action / Instruction TP / St Cap. Date / Time: File Pass 107 Date / Time: File Reauris to? Date / Time: File Reauris to? Add Fee: Stite Insp. (\$ Servey Fee: Indeed) Report Format: Remark: The veh had commenced its repair at the time of inspection. Discontinue: The veh had commenced its repair at the time of inspection. Ball or Market Value: TOYO / YOKO or Front: Rear / O/S / PRIS JUM / INS			Tyre Size.		1		
repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Lim Som: % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Date / Time Action / Instruction TOY 35 C Not. 1 H K. Not. 14 104 RECEIVED 2 9 NOV 2017 Date/Time, File Pass 107 Date/Time, File Return to? Preli. Report Date/Time, File Return to? Add Fee: Site Insp (\$) \$+8\$ \$1 50 Photos Report Format: Lump Sum / I.B.I; (\$ \$60.00 h) TOY 0/YOKO or Front Rear RBal. 0 mm RBal. 0 mm RBal. 0 mm LBal. 1		North of the same	0/8		-		CHMI/
Ball or Market Value: IDAC Accident Rport: Consistent? : Yes or No GIA / PR Seen: Consistent? : Yes or No Est. Repairs: days Res.: Yes or No Lum Sum: % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Person Contacted: Person Contacted: IN/ 35 C Net : IH K Not: IH IN IN IN IN IV IV IV IV IV IV Not: IH K		ii iidd ddiiiiidiada ka			I FS I LIZA	MIC/OHISO/PIK/	SOMI /
IDAC Accident Rport: Consistent? : Yes or No GIA / PR Seen: Consistent? : Yes or No Libal. Older mm Libal. Old				NO or		Door	
Date Time Action / Instruction To 15t Cap	particular solution and	a contract to the		-/		Market Company	nm
Est. Repairs: days Res.: Yes or No Lum Sum: % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Vehicle: IN / OUT Date / Time				06			V
Lum Sum: % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Date / Time	GIA / PR Seer	2000 0440000 440	7.5532	06	mm	- 7	- T
Date: Person Contacted: Vehicle: IN / OUT Date / Time	Est. Repairs:	aajo			0.		0/11.
Date: Person Contacted: Vehicle: IN / OUT Date / Time	Lum Stim:	% 3 Val.: Yes or No	1 0000000000000000000000000000000000000	6	~ V	A CONTRACTOR AND	
Date Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision Date / Time Action / Instruction TP ISF Cap INV: 35K MV: 35 0000- PV: 21 K TA Do. 896	CA / REV /	REP. / 24 HRS	Des. of Dan	nages: Frt / I	Rear / O/S /	N/S / U/C / Rooft	op or
Date / Time Action / Instruction TP 15t Cap	5		241 AV (1744	. I Ohaasia fa	/ D-d-	Characture offseted	fue to collision
The state The	Vincent Control		Ine U/C	/ Chassis ii	rame / Body		de to complete.
Next 14 K NV 14 04 Next 15 00 Next 16 0 Next 16 0 Next 17 0 Next 17 0 Next NV NV NV NV NV NV NV N	Date / Time						
PV : 21 K							
PV : 21 K							
Neth : IH K NV : NH 04		MV:35K MV: 35 00	od-				
Date/Time, File Pass to? Preli. Report Days Of Repair: 5x15= 75 Date/Time, File Pass to? Preli. Report Preli. Report Preli. Report Preli. Report Preli. Report Preli. Resurvey No. of Trip: Survey Fee: 170+75 Date/Time, File Pass to? Preli. Report Prel						i d	
Date/Time, File Pass to? : Preli. Report Days Of Repair: Survey Fee: 130+35		Ned: 14K. NV: 14/1	- 140				
Date/Time, File Pass to? : Preli. Report Days Of Repair: Survey Fee: 130+35		RECEIV	ED 2 9 MBV 201	7			
Date/Time, File Return to? Final Report Resurvey No. of Trip: Survey Fee: 170+75		IVE OF IV		7	Di .		10-379-100
Date/Time, File Return to?	Date/Time, File Pas				1		
2) Add Fee: Site Insp (\$)S+RSSI 50	1) [[((The state of the s	Resurvey	No. of Trip:	-		
: Interview (\$) Photos 21	Date/Time, File Re	aturn to?		/e			
Report Format : (\$	2)		- Lancard				
Lump Sum / I.B.I: (\$ 9806 -) : Weekend (\$.)		Tø	-	Waller -			- 21
	3,300	15.0	-) Others	
	Lump Sum	/I.B.1; (\$ 9800 }	: We	ekend (\$		_)	Д26



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

FI	RST CAPITAL IN	SURANCE LTD	Ref : CS/FCI17018	
36	ROBINSON ROA 6-01 CITY HOUSI	AD ESINGAPORE 068877	Date: 04-10-2017	
1.		Policy Partie	Code: FCI2	
	Insured Veh.	SHA 0462A	lars :- THIRD PARTY CLA	
	Policy No.		Veh. Inspected	SJM 8430C
	Claim No.	D17009293MFSH	Coverage (\$)	0.00
	Assign From	CWS (SITHARA)	Excess (\$)	0.00
2.	AND DESCRIPTION		Assign Date	04/10/2017
	Make & Model	Vehicle F	Particulars & Condition	William Brown and the second
	Engine No.	HIDDEN	c.c	0
_	Chassis No.	HIDDEN	Year of Reg.	
	Odometer		Colour	
-	Brakes		Steering	
	General		Modification	
3.	General	Marie Control		
		Cor	ditions of Tyres	No. of the second
	R/H Front Tyre	Size	Make	Balance
	L/H Front Tyre			mm
				mm
	R/H Rear Tyre L/H Rear Tyre			mm
3657	L/H Rear Tyre			mm
\$5M	O STEEL SEEDING	Descri	ption of Damages	A STATE OF THE PARTY OF THE
12	Englewing	Gen	eral Information	
	Accident Date	29/09/2017	A CONTRACTOR OF THE PARTY OF TH	
	Survey held at	PROGRESSIVE AUTOMOTI	Inspection Date	
	1000 10000000	BLK 3022A UBI ROAD 1 #01		
1.	Constant Sales	CONTRACTOR OF THE PARTY.	Remarks	
	A)THE INSPECTIO	ON WAS CONDUCTED ON A"V CE TO YOUR INSTRUCTIONS.	Maria - 1	ELLES L'ELLOSSES

First Capital Insurance Limited

Company Reg. No. 195000106C GST Reg. No. M2-0001676-9

A FAIRFAX Company

MOTOR SURVEY ASSIGNMENT

Date

02-10-2017

Our Ref No. D17009296MFSH

Accident Date

29-09-2017

Claim Type. Third Party

Insured Vehicle

SHA0462A

Third Party Vehicle. SJM8430C

Survey Location

BLK 3022A UBI ROAD 1 #01-45/46

Contact Person.

PEIWEN

Contact No.

67415336/67415336

Fax No. 67417208

Survey Type

DIRECT SETTLEMENT:

Appointed

LKK AUTO CONSULTANTS PTE LTD

Surveyor

NA.

Fax No. 68416315

Contact Person
Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

PROGRESSIVE

AUTOMOTIVE PTE LTD

Attention, NIL

Cc : TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

SITHARA

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D17009293MFSH

Date: 29/11/2017

Our Ref: CS/FCI17018986/Atb

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJM 8430C

Please be informed that we had conducted the inspection of the abovementioned vehicle <u>05/10/20</u>17 at the premises of M/s <u>Progressive Automotive</u> at and have the following to report:-

Workshop Estimate Amount	: <u>S\$</u>	15,761.72
Revised Estimate Amount	: <u>S\$</u>	9,800.00
"Check" Items Amount	: <u>S\$</u>	
Market Value	: <u>S\$</u>	
LTA Reimbursement Value	: <u>S\$</u>	
Nett Value	: <u>S\$</u>	-

Description of Damage:

<u>The vehicle sustained damages</u>


At front, rear portion.

Repair days: 9

Yours faithfully

Adrian

Motor Surveyor



Denise Tay (LKKAuto)

From:

Denise Tay (LKKAuto)

Sent:

Wednesday, 29 November, 2017 3:24 PM

To:

Admin-D (LKKAuto); 'Claim Workflow System'; assignments

Cc: Subject: SITHARA@FIRST-INSURANCE.COM.SG; SUR RE: SURVEY ASSESSMENT - D17009296MFSH/1

Attachments:

PRELI ADVISED SJM 8430C.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJM 8430C

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)

Sent: Monday, 9 October, 2017 3:47 PM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; 'Claim Workflow System' <cwsmotorclaims@first-

insurance.com.sg>; assignments <assignments@lkkauto.com> Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D17009296MFSH/1

Dear Sir/Madam

Please be informed that we have inspected the vehicle SJM 8430C on 05-10-2017 We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Wednesday, 4 October, 2017 9:18 AM

To: 'Claim Workflow System' < cwsmotorclaims@first-insurance.com.sg>; assignments < assignments@lkkauto.com>

Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D17009296MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

			PRI Header Details		
Claim No	D17009296MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & PROGRE
Workshop Name	PROGRESSIVE AUTOMOTIVE PTE LTD (Contact Person : PEIWEN)	Survey Location & Contact Details	BLK 3022A UBI ROAD 1 #0 Mobile: 67415336 , Phone EmailId: PEIWEN@PROGA	e: 67415336	, Fax: 674172
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA0462A	TP Vehicle No	SJM8430C
PRI Recieved Date	02-10-2017 11:15:47 PM	Surveyor Appointed Date	03-10-2017 07:54:36 PM	Surveyor Accept Date	04-10-2017
		A constant	Survey Report Upload		
Surveyor Inspection Date *:		Surveyor Report Date	04-10-2017	Upload Survey Report *:	Choose File
			Vehicle Particulars		
Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			
Multiple Do	ocuments Upload				
		Upload Multiple	Documents		
File Nam	е			Action	
Surveyor Jo	ob Remarks				
TO SOUTH STATE OF THE STATE OF					

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	29/09/2017 17:45
Date Of Accident	29/09/2017 07:20
Exact Location Of Accident	ECP TOWARDS CITY BEFORE MARINE PARADE
Country/State of Loss	SINGAPORE

Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJM8430C	
Insured/Policyholder		
Name Of Registered Owner	SHARON TAN TOW YING @ SHARON TAN	
NRIC No	S6933281A	
Email Address	TANSHARON26@GMAIL.COM	

Mobile Phone No	(LOCAL) +65-97829826
Alternative Phone No	OTHERS-97829826

Vehicle Particulars

Manufacturer	TOYOTA
--------------	--------

Model	LEXUS-2.5 ES250 AUTO (A
-------	-------------------------

Exact Purpose for	oΓ	which	vehicle	was	being	used	at
time of accident							

Are you	claiming	under	vour	own	insurance	policy

Are you claiming	dilder year	Omi mooranee	
for repair to your	vehicle?		

If No, Please state action to be taken	THIRD PARTY	
Vehicle Category	PRIVATE CAR	

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

NO

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 1700032307

Cover Note Number

Driver

 Name of Driver
 TAN HWEE BOON

 NRIC No
 \$6834241D

 Date Of Birth
 12/09/1968

 Occupation
 INDOOR

Occupation INDOOR

Date Of Driving Pass 21/05/1993

Driving Experience 24 YEARS AND 4 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-97829826

Fax Number

Contact Number OTHERS-97829826

EMail Address TANSHARON26@GMAIL.COM

APT BLK 856D TAMPINES STREET 82 # 12-196

SINGAPORE

524856 Postcode

Was driver an employee of the Insured's Company NO

SPOUSE If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Address

Insurance Company of Driver's Own Vehicle

General Information of the Accident

CHAIN COLLISION Type Of Accident

Weather Conditions CLEAR DRY Road Surface

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident?

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

NO

YES

2 Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACH STATEMENT RECORDED BY JIA MIN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 67415336

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHA462A

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

LIM CHONG HOCK

NRIC/Passport Number

S1345369A

Contact Number

90234795

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SKM3879M

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

LEONG WAI KIT (LIANG WEIJIE)

S7109056F

91075022

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims,
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policytsolder's Signatu

29/9/17

Driver's Signature

If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.

Sketch Plan #2

SKETCH PLAN ECP WEST SKINGSFT OF	X GRASS
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT 1 AT MOPEN HOSTERY 07:30 AM, ON ECP	B MARAE WART
2. MY CAR NOS ON RIGHT-MOST LANT 3 BMW (SEM 3279 M) DID EMER 4 MY CAR EMERGENCY BRAVED A STOP BEHIND BMW (SEM 32 5 HONEVER, TAXI (SHA 462 A DID NOT STOP AND HIT 12 EAR 4. THE IMPACT CAUSED MY AHEAD OF HIT THE BMG 7. NO INJURY WAS SUSTAINED IN THE THEFE CHES MYOLVE	RETAIN ME. MY CAR DA THE AR TO MOVE J (3679 M) AR THE
PROPERTIES	T D IN INE INT
Policyholder's Signature Date & Time: 5 DOPM DECLARATION 1/We declare the foregoing particulars are true in every respect. Driver's Signature (if driver is not the policyholder) Date & Time: 9117 5-00PM	Reporting Centre Personnel's Signature Name: NRIC/FIN No.: PDTWEY



Car Make or Model

Search

HOME

NEW CARS

USED CARS

SELL CARS

MOTOR DIRECTORY

Feb 11 BMW 318i Sunroof.18\" Sports Rims,Pirelli Tyre

PRODUCT GUIDE

ARTICLES

FORUM

TOOLS & TIPS



MYCARFORUM Buy / Sell Parts & Accessories

> click here to visit now!



Post an Advertisement Sell it yourself! Advertise it at just

\$58 until it's SOLD!



Redularly At Serviced At Regutable Workshop, Low Shine Connect StorAd



Browse by Category

Post an Ad

Advertiser Login

Sort by Date Posted

▼ 20 results/page

6 vehicles

Lexus IS250

Model

Ways of Selling

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Search Selection

Lexus IS250

Any

Any

2009

Lexus IS250

\$37,800

\$13,020 /yr

26-Mar-2009

2.500 cc

88,199 km

Luxury

Any

Available (SEEDING)

Available

Seldom Use And Well Maintain By Previous Owner! Super Low Geninue Mileage! Best Luxury Japanese Sedan In The Mkt! Smooth, Quiet And Powerful V6 Engine! View To Believe! Please Call Us For Inquiries An...

Posted: 01-Oct-2017 Tags: 2009 Lexus IS250, 2009 Lexus IS250, Lexus IS250, Lexus IS250, Lexus, IS250, IS250, Used Lexus

Details



Lexus IS250

\$41,800

\$13,940 /vr

03-Jun-2009

2,500 cc

Luxury

Available CONTROL OFFICE

Engine Good Condition, Possible For Renew COE. Best Deal, Keen Seller, Private Message To View.

Posted: 27-Sep-2017 Tags: 2009 Lexus IS250, 2009 Lexus IS250, Lexus IS250, Lexus IS250, Lexus IS250, Lexus, IS250, IS250, Used Lexus

@ Details



Lexus IS250C

\$56,800

\$17,580 /vr

27-Jun-2009

2,500 cc

108,000 km

Sports

Available STATE OF THE PARTY OF

Q Details

We Make Sure You Are Buying A Great Car! Buy With Trust And Assurance! Expect Only Honest Deals! Loan Up To 80%! Easy Loan Approval! Call Our Friendly Sales Staff For A Non Obligatory Viewing Now! Con...

Prem Roy Motoring

Posted: 25-Aug-2017

Tags: 2009 Lexus IS250C, 2009 Lexus IS250C, Lexus IS250C, Lexus IS250C, Lexus, IS250C, IS250C, Used

Lexus IS250

\$43,800

\$13,790 /vr

Posted: 26-Aug-2017 Tags: 2009 Lexus IS250, 2009 Lexus IS250, Lexus IS250, Lexus IS250, Lexus, IS250, IS250, Used Lexus

119,250 km

Available

Car Buying

Car Ownership

Sports Rims, Black Electric Seats With Aircon Ventilated Leather Seats, Multi Function Steering, Reverse Sensors.

Prem Roy Motoring

18-Jul-2009

2,500 cc

Luxury

SERENDING SE

Details

Car Selling

On The Move

Car Aftermarket

Lifestyle

Buying a pre-owned car, but Unsure of its Condition?

Lexus IS250C Luxury

\$53,888

\$13,720 /vr

30-Jul-2009

2.500 cc

133,600 km

Get, STA Car Evaluation

Cheapest And Lowest Depreciation Guaranteed! A Powerful Lifestyle Car Made By The Extremely Reliable Lexus, Some Would Say That This Is The Purchase Of The Year. Viewings And Test Drives Are Strictly ...

Monster Motors Pte Ltd Tags: 2009 Lexus IS250C, 2009 Lexus IS250C, Lexus IS250C, Lexus IS250C, Lexus, IS250C, IS250C, Used Posted: 22-Sep-2017

Sports

Available PARHUM DE

Details

Available

Lexus IS250C

\$51,888

\$14,000 /vr

30-Jul-2009

2.500 cc

118,000 km

Upgraded 8 Pot Disc Brake Kit! This Futuristic Looking Lexus Is Still Fantastic 5 Out Of 5 In Terms Of Looks, Fuel Consumption And Performance! Flawless Interior Condition And Clean! Call Us Now To Ar.

Posted: 13-Sep-2017

Tags: 2009 Lexus IS250C, 2009 Lexus IS250C, Lexus IS250C, Lexus IS250C, Lexus, IS250C, IS250C, Used

Q Details

Save this search criteria, to get email alerts whenever a match is found.

Model

Depreciation

Reg Date Eng Cap

Mileage

Veh Type

20 ▼ results/page

riew Expired ads



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

3281A

Vehicle Details

Vehicle No.:

SJM8430C

Vehicle to be Exported:

Intended De-registration Date:

05 Oct 2017

Vehicle Make:

TOYOTA

Vehicle Model:

LEXUS IS250 AUTO STD FL

Primary Colour

Grey 2008

Manufacturing Year:

4GR0530199

Engine No.: Chassis No.:

Maximum Power Output:

JTH8K262405092058 153.0 kW (205 bhp)

Open Market Value:

\$37,374.00

Original Registration Date:

19 Jan 2009

First Registration Date:

19 Jan 2009

Transfer Count:

2

Actual ARF Paid:

\$37,374.00

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

18 Jan 2019

PARF Rebate Amount:

\$20,555.00

Intended COE Rebate Details

COE Expiry Date:

18 Jan 2019

COE Category;

B - Car (1601cc & above)

COE Period(Years):

10

QP Paid:

\$2,656,00

COE Rebate Amount:

\$341.00

Total Rebate Amount:

\$20,896.00

The information contained herein is correct as at 05 Oct 2017

PROGRESSIVE AUTOMOTIVE PTE LTD

M/S: SHARON TAN TOW YING @ SHARON TAN

APT BLK 856D TAMPINRS STREET 82

12-196 SINGAPORE 524856

ATTN: FIRST CAPITAL INSURANCE

Estimate No: Date:

EST1502817

Policy No:

29 Sep 2017

Policy No: Veh Reg No: 1700032307 SJM8430C

Veh Reg No: Make/Model:

TOYOTA LEXUS IS250

AUTO STD FL

Your Ref No:

TP 0917-4772

Claim Type:

Third Party

Accident Date:

29/09/2017

TP Veh Reg No:

SHA462A

Chassis No:

JTHBK262405092058

Engine No:

4GR0530199

Reg. Date:

19/01/2009

Estimate Repair Cost to Vehicle No :SJM8430C

Description	U/Price	Quantity	Price	Amoun
			<u>SS</u>	<u>SS</u>
List Price				
1 REAR BOOT LEXUS WORDING 3	91.40	1 PC	91.40 /	
1 REAR BOOT LEXUS WORDING 2 REAR BOOT IS250 WORDING	87.90	1 PC	87.90	
3 REAR BUMPER Distald.	957.92	1 PC	957.92 —	
4 REAR BUMPER CLIPS	4.80	10 PC	48.00	
5 REAR BUMPER SIDE HOLDER - LH 2	59.59	1 PC	59.59	
6 REAR BUMPER SIDE HOLDER - RH	59.59	1 PC	59.59	
7 REAR BUMPER RETAINER CENTRE - LH	72.70	1 PC	72.70	
8 REAR BUMPER RETAINER CENTRE - RH	72.70	1 PC	72.70 박	
9 REAR BUMPER LAMP ASSY - LH 7 ALLA	187.87	1 PC	187.87	
10 REAR BUMPER LAMP ASSY - RH	187.87	1 PC	187.87 せ	
11 REAR BUMPER TOWING COVER - LH	49.57	1 PC	49.57 ∤	
12 REAR BUMPER TOWING COVER - RH ** issi-	49.57	1 PC	49.57 -	
13 REAR BUMPER FOAM	187.20	1 PC	187.20 -	
14 REAR BUMPER REINFORCEMENT Sect	487.95	1 PC	487.95	
15 REAR PANEL Deviet	879.57	1 PC	879.57	
16 REAR PANEL TOP GARNISH De Grand	487.90	1 PC	487.90	
17 REAR EXHAUST PIPE - NO STOCK AH New	1,379.59	1 PC	1,379.59 💸	
18 REAR EXHAUST PIPE CHROME	276.87	1 PC	276.87 %	
19 GRILLE CHROME Could	595.50	1 PC	595.50 -	-
20 GRILLE ASSY Conce	879.90	1 PC	879.90 -	-
21 GRILLE LOGO ~~	157.90	1 PC	157.90 -	_
	147.90	1 PC	147.90 -	
	1,870.49		1,870.49 -	_
(Cau-o	1,870.49		1,870.49	
24 HEAD LAMP ASSY - RH \\ 25 HEAD LAMP LOWER RETAINER - LH \\ 26 PARTY 25 P	187.70		187.70+	
and the second s	187,70		187.70 4	
	789.57		789.57	
500 C.	4.80		48.00	
	99.55		99.55 -	
(🔑	99.55		99.55	
30 FRONT BUMPER SIDE HOLDER - RH 1 31 FRONT BUMPER TOWING COVER - LH 144	60.31		60.31 +	
44 (I) - MANON - MANON	127.90		127.90	_
32 FRONT BUMPER FOAM COLL	687.70		687.70 ~	/
33 FRONT BUMPER REINFORCEMENT BRACKET LH 2	327.50		327.50+	
34 FRONT BUMPER REINFORCEMENT BRACKET - LH 2	327.50		327.50 4	
35 FRONT BUMPER REINFORCEMENT BRACKET - RH * ~	5.70		-74.10	30
36 SUPPORT PANEL TOP GARNISH CLIPS	5.70	13150	13.54	

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716 TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg GST:201006949C RCB NO:201006949C

SHARON TAN TOW YING @ SHARON TAN M/S:

APT BLK 856D TAMPINRS STREET 82

12-196 SINGAPORE 524856

Estimate No:

EST1502817

Date:

29 Sep 2017

Policy No:

1700032307

Veh Reg No:

SJM8430C

Make/Model:

TOYOTA LEXUS 1S250

AUTO STD FL

Chassis No:

JTHBK262405092058

Engine No:

4GR0530199

Reg. Date:

19/01/2009

Accident Date:

Your Ref No:

Claim Type:

Third Party 29/09/2017

TP 0917-4772

TP Veh Reg No:

SHA462A

ATTN: FIRST CAPITAL INSURANCE

Estimate Repair Cost to Vehicle No :SJM8430C

	Description	U/Price	Quantity	Price	Amount
	9851-79			SS	SS
	9851.79			14,163.02	
	10		Less 10%	1.416.30	12,746.72
	Special Net				
37	FRONT NUMBER PLATE WITH CASING 304.	35.00	1 SET	35.00	_
38	REAR BUMPER SENSOR Tanged 255	220.00	1 SET	220.00 -	
	Accept New Company			255.00	255.00
	Labour				
39	TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS	1,300.00	1 JOB	1,300:00	000.
40	TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,200,00	1 JOB	1.200.00	1000
41	TO CHECK WIRING 2180	50,00	1 JOB		- 30
42	TO TRANSFER REAR BUMPER SENSOR	50.00	1 JOB	50.00	
43	TO REMOVE, REFIX REAR GARNISH	100.00	1 JOB	100.00	2.
44	TO TUFF-KOTE	60.00	1 JOB	60.00	
				2,760.00	2,760.00
				Total	\$\$ 15,761.72
			Add GST	(a) 7%	1.103.32

Total Amount Payable

S\$ 16,865.04

TOTAL: SINGAPORE DOLLAR SIXTEEN THOUSAND EIGHT HUNDRED SIXTY FIVE AND CENTS FOUR ONLY

LKK Auto Consultants hence notify

the Repairer of the following:

. To resurvey before/after spray painting

. To display damaged part(s) during resurvey Parts prices a subject to confirmation

. Third party survey is on a "Without Prejudice" basis

. No illegal modification(s) is allowed

. Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For PROGRESSIVE AUTOMOTIVE PTE

LTD

AUTHORISED SIGNATURE



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

FI	RST CAPITAL INS	SURANCE LTD	Ref : CS/FCI17018	
			Ref : CS/FCI17018	3986/Atbe2
36 #1	ROBINSON ROA 6-01 CITY HOUSE	D ESINGAPORE 068877	Date: 06-12-2017	
1.	T. Stanting of	Policy Postin	Code: FCI2	
	Insured Veh.	SHA 462A	ulars :- THIRD PARTY CLA	AIM
	Policy No.	D-15072702MFSH	Veh. Inspected	SJM 8430C
	Claim No.	D17009296MFSH	Coverage (\$)	0.00
	Assign From	SITHARA	Excess (\$)	0.00
2.	9		Assign Date	03/10/2017
	Make & Model	Vehicle I LEXUS IS250	Particulars & Condition	
	Engine No.	HIDDEN	c.c	2500
	Chassis No.		Year of Reg.	2009
	Odometer Odometer	JTHBK262405092058	Colour	GREY
	Brakes	103005	Steering	IN ORDER
	General	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
•		Cor	ditions of Tyres	
_	R/H Front Tyre	Size	Make	Balance
	L/H Front Tyre	235/40 R18	MICHELIN	6 mm
	R/H Rear Tyre	235/40 R18	MICHELIN	6 mm
	L/H Rear Tyre	235/40 R18	MICHELIN	6 mm
	Chi Kear Tyre	235/40 R18	MICHELIN	6 mm
	THE VEHICLE OU	Descri	ption of Damages	A CHARLES AND A CONTRACT OF THE PARTY OF THE
	DAMAGES SEE DE	ETAILS.	FRONT AND REAR PORTION	J.
		Gene	eral Information	among the same of
\neg	Accident Date	29/09/2017	Inspection Date	05/10/2017
	Survey held at	PROGRESSIVE AUTOMOTIV	/E PTE LTD	55/10/201 <i>[</i>
		BLK 3022A UBI ROAD 1 #01-		
			Remarks	
		SISTENT TO ACCIDENT REPO WAS CONDUCTED ON A"W TO YOUR INSTRUCTIONS	ORT. ITHOUT PREJUDICE" BASIS WE HAVE NOT AUTHORISEI	•
		Estimat	e Days of Repair	D REPAIRS.
E	STIMATED NORM	AL PERIOD FOR REPAIR:	9 Working Days	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 8430C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT LEXUS WORDING	NECESSARY	91.40	91.40
া	REAR BOOT IS250 WORDING	NECESSARY	87.90	87.90
1	REAR BUMPER	DISTORTED	957.92	957.92
10	REAR BUMPER CLIPS @\$4.80	NECESSARY	48.00	48.00
1	REAR BUMPER SIDE HOLDER - LH	NECESSARY	59.59	59.59
1	REAR BUMPER SIDE HOLDER - RH	NECESSARY	59.59	59.59
1	REAR BUMPER RETAINER CENTRE - LH	DAMAGED	72.70	72.70
1	REAR BUMPER RETAINER CENTRE - RH	DAMAGED	72.70	72.70
1	REAR BUMPER LAMP ASSY- LH	NOT NECESSARY	187.87	
1	REAR BUMPER LAMP ASSY- RH	NOT NECESSARY	187.87	9
1	REAR BUMPER TOWING COVER- LH	TO REPAIR SEE LABOUR	49.57	5
1	REAR BUMPER TOWING COVER- RH	MISSING	49.57	49.57
1	REAR BUMPER FOAM	DEFORMED	187.20	187.20
1	REAR BUMPER REINFORCEMENT	BENT	487.95	487.95
1	REAR PANEL	DENTED	879.57	879.57
1	REAR PANEL TOP GARNISH	DEFORMED	487.90	487.90
1	REAR EXHAUST PIPE - NO STOCK	NOT NECESSARY	1,379.59	3708001858
1	REAR EXHAUST PIPE CHROME	NOT NECESSARY	276.87	
1	GRILLE CHROME	CRACKED	595.50	595.50
1	GRILLE ASSY	CRACKED	879.90	879.90
1	GRILLE LOGO	NECESSARY	157.90	157.90
1	FRONT NUMBER PLATE GARNISH	CRACKED	147.90	147.90
1	HEAD LAMP ASSY - LH	CRACKED	1,870.49	1,870.49
1	HEAD LAMP ASSY - RH	CRACKED	1,870.49	1,870.49
1	HEAD LAMP LOWER RETAINER - LH	NOT NECESSARY	187.70	
1	HEAD LAMP LOWER RETAINER - RH	NOT NECESSARY	187.70	
1	FRONT BUMPER	DEFORMED	789.57	789.57
10	FRONT BUMPER CLIPS @\$4.80	NECESSARY	48.00	48.00
1	FRONT BUMPER SIDE HOLDER - LH	NECESSARY	99.55	99.55
1	FRONT BUMPER SIDE HOLDER - RH	NECESSARY	99.55	99.55

Report Ref No. CS/FCI17018986/Atbe2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	FRONT BUMPER TOWING COVER - LH	NOT NECESSARY	60.31	147
	FRONT BUMPER FOAM	CRACKED	127.90	127.9
	FRONT BUMPER REINFORCEMENT	BENT	687,70	687.7
	FRONT BUMPER REINFORCEMENT BRACKET - LH	NOT NECESSARY	327.50	
	FRONT BUMPER REINFORCEMENT BRACKET - RH	NOT NECESSARY	327.50	
13	SUPPORT PANEL TOP GARNISH CLIPS @\$5.70	NECESSARY	74.10	30.00
	LESS 10% DISCOUNT	ADDITION DESCRIPTION	-1,416.30	-1,094.64
			12,746.72	9,851.80
	SPECIAL NETT ITEMS			
1	SET FRONT NUMBER PLATE WITH CASING (SN)	BENT	35.00	35.00
1	SET REAR BUMPER SENSOR (SN)	DAMAGED	220.00	220.00
		HART VANSCOLLEGE	255.00	255.00
	LABOUR			200.00
- 1	TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER TOWING COVER- LH.		1,300.00	1,000.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		1,200.00	1,000.00
	TO CHECK WIRING.		50.00	30.00
- 1	TO TRANSFER REAR BUMPER SENSOR.		50.00	50.00
	TO REMOVE, REFIX REAR GARNISH.		100.00	60.00
- 1	TO TUFF-KOTE.		60.00	40.00
			2,760.00	2,180.00
(GRAND TOTAL		15,761.72	12,286.80

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	9,800.00
(- III III NOOIDERI GONDITION)	

Report Ref No. CS/FCI17018986/Atbe2

MARKET VALUE: \$35,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$20,896.00=NETT VALUE: \$14,104.00



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report. In whole or in part, does so at his or her own risk.