




















PAR Automotive Consultancy

Regn No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax 645 36131

Report No: 0172-17-N51

03 April 2017

ACCIDENT VEHICLE SURVEY REPORT

Twincar Leasing Pte Ltd
2 Kaki Bukit Ave 2 #01-17
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

Vehicle Reg No.	SKW1466G	Odometer:	102462km
Make & Model:	Toyota Corolla Altis 1.6	Colour:	Silver
Chassis number.	MR053REH104537680	Date of accident:	26/11/2016
Year of Regn.:	19/10/2015	Date inspected:	12/12/2016
Repairer at:	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	15/12/2016

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

