

12/03/2002

ASS. REC. BY:

REF: CS/MSG17019032/R1rb12

Special Instructions:

Signature of

Rasul

ASSIGNMENT (Office)

From (Person):

Merimen
Pecirlyn Kang

of

MSG

Date/Time: 4/10/17 9:56am

Estimated Cost:

Bill to:

① / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 1167D

Insured:

at Workshop m/s

Borneo Motors

Tel:

66311855

of

2 Pandan Crescent 128462

Policy No:

28867644 QMY

Claim No:

531588

Sum Insured:

Excess:

\$ 500.00

Make of Veh:

D.O.A. 1/10/17

(Client's Record)

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time:

4/10/17 10:08am

Person Contacted:

Shashi

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKZ 1167D - X

05/10/17

Sent peli through merimen

mandate approve ; Inform Shashi authorise repair & excess

Siti

Signature: *[Signature]*

REF:

42694

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SK2 11670

at Workshop m/s *POLARIS MOTOR*

of *2, Pannan chers*

Insured: *msik*

Policy No.

Claims No.

Sum Insured:

Excess:

500

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

86k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Final Sig \$10,123.04 (Red 3864.91, 27%)

RECEIVED

Date/Time, File Pass to?



: Preli. Report

1) *typist*



: Final Report

Date/Time, File Return to?

2)

Report Format :

OD

Lump Sum / (B.I.): (\$

10,123.04

Days Of Repair:

8

Resurvey No. of Trip:

-

Survey Fee.

Transportation

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

) \$ + RS. \$

) Photos

) Others

TOTAL

300

10

310

Veh No:

SK2 11670

Yr Regn: *2016 JAN*

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

TOYOTA COROLLA ALTIS 1.6 cc 1598

Colour

WHITE

A/C Insured / Std / NI / NA

Sp. Reading

31877

T/Radio: Insured / Std / NI / NA

Eng/No:

MR053 REH 10456147

C/No:

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ STD A/Rim or

Tyre Size:

F:

205/55 R15

R:

1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

6/10/17

D.O.I.

6/10/17

Survey held at

POLARIS MOTOR

Des. of Damages: Frt / ☒ Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Survey Department Check List (Case Handler)

Reference No.: CS/MEG17019032/Rib.
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Catherine): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

C Reference No.
C Customer Code
N Assign From
C Assign Date
C Veh No (Inspected)
C Veh No (Insured)
C D.O.A
C Policy No
C Claim No
C Insurance Authorisation (CA /REV/REP)
C Report Type
C Weekend Charges
N Survey held at/Repairer
C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Rasul)

: Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C Vehicle No
C Regn Month/Year
N Vehicle Type
N Make & Model
C Engine Capacity. (C.C)
N Colour
C Odometer. (Sp. Reading)
C Chassis No
N General Condition
N Steering
N Brake
N Modification (Modi)
C Tyre Size
N Tyre Make
C Tyre Balance
C Date of Inspection
N Survey held
N Des. of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

N ALL Parts condition
C Market Value for OD cases
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
C Days of repair
C Finalised Amount
C Re-inspection Cases to Finalize within 5 Days

✓			
✓			
✓			
✓			
✓			

(4) System - (Views/Merimen)

C Resurvey photo Uploaded

--	--	--	--

Check By:

Catherine 12/12/17
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17019032/R1rb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 04-10-2017



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SKZ 1167D
Policy No.	28867644QMY (	Coverage (\$)	0.00
Claim No.	531588	Excess (\$)	500.00
Assign From	MERIMEN (PEARLLYN KANG)	Assign Date	04/10/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

5. General Information

Accident Date	01/10/2017	Inspection Date	04/10/2017
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		

5a. Remarks

- A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Oct 2017		04 Oct 2017 09:56 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents						
Show All									
CLAIM SUBFOLDER DETAILS									
[Created by insurer]									
Insured:	YONG CHUNG WAN, ID: S7134269G, Tel: +6596421456, Email: BENIN_YONG@YAHOO.COM								
Vehicle Reg. No.:	SKZ1167D	Date of Loss:	01/10/2017 20:00 - :59						
Claim Type:	OD / 531588	Policy/Cover Note No.:	28867644QMY (Comprehensive) Coverage: 11/01/2017 - 10/01/2018						
		Excess:	S\$500.00						
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pearllyn Kang Yen Lin - 6594 2588]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/10/2017]								
Driver/Custodian:	YONG CHUNG WAN (46 / Male), NRIC: S7134269G, Tel: +6596421456								
Adj Asg. Remarks:	REVERT								
View All Compose Case Mail									
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pearllyn Kang Yen Lin

Date: 05 Oct 2017

Preliminary Advice

Vehicle No	: SKZ1167D	Accident Date	: 01/10/2017
Make	: TOYOTA COROLLA ALTIS	Policy No.	: 28867644QMY
Assignment Date	: 04/10/2017	Excess	: S\$500.00
Date of Inspection	: 04/10/2017	Est. Duration of Repair	: 8.00
Inspection At	: BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,987.95
Revised Amount	:S\$	10,123.04
Check Items (Estimated)	:S\$	1,091.72
Total	:S\$	11,214.76
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	86,000.00
COE / PARF Rebate	:S\$	58,224.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,776.00

Remarks

- (X) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.

Print Received Message

This mail is associated with :

***SKZ1167D (531588)**

OD

Oct 1 2017 8:00PM

[YONG CHUNG WAN]

Borneo Motors (S) Pte Ltd

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 05/10/2017 16:09 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10123.04) - SKZ1167D - Claim Handler: Pearllyn Kang Yen Lin

Approved:10123.04:CHECK ITEMS TO BE VERIFIED AND CONFIRMED.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Thursday, October 05, 2017 4:44 PM
To: Shashitharan@borneomotors.com.sg
Cc: SUR
Subject: SKZ 1167D

Dear Shashi,

As instructed by our client , please proceed to repair the insured vehicle **SKZ 1167D (excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

PARF/COE Rebate Enquiry

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
 Owner ID: 4269G

Vehicle Details

Vehicle No.: SKZ1167D
 Vehicle to be Exported: No
 Intended De-registration Date: 05 Oct 2017
 Vehicle Make: TOYOTA
 Vehicle Model: COROLLA ALTIS CLASSIC 1.6 CVT
 Primary Colour: White
 Manufacturing Year: 2015
 Engine No.: 1ZRX554166
 Chassis No.: MR053REH104546147
 Maximum Power Output: 90.0 kW (120 bhp)
 Open Market Value: \$17,804.00
 Original Registration Date: 11 Jan 2016
 First Registration Date: 11 Jan 2016
 Transfer Count: 0
 Actual ARF Paid: \$17,804.00

86,000
 58,224
 27,776

Intended PARF Rebate Details

PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 10 Jan 2026
 PARF Rebate Amount: \$13,353.00

Intended COE Rebate Details

COE Expiry Date: 10 Jan 2026
 COE Category: A - Car up to 1600cc & 97kW (130bhp)
 COE Period(Years): 10
 QP Paid: \$54,301.00
 COE Rebate Amount: \$44,871.00

Total Rebate Amount: \$58,224.00

The information contained herein is correct as at 05 Oct 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
 Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.
 Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution
 Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
 Last updated on 17 Sep 2017 at 12:38 AM

toyota corolla altis Used Vehicle List (6 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Toyota Corolla Altis 1.6A Elegance	\$91,888	\$9,700 /yr	23-Mar-2016	1,598 cc	23,000 km	CarTrade SG	Available
Viewing Strictly By Appointment Only. 5 Years Warranty By Borneo Motors. Pristine Condition, Mileage Clocked At Only 23000km.							
Office No. - - Bobby Boh - 86863300							
Toyota Corolla Altis 1.6A	\$87,800	\$9,320 /yr	18-Mar-2016	1,598 cc	28,000 km	AL Autocar Pte Ltd	Available
Low Price Tag Need No Compare With Others, Good Fuel Eco, 1 Fussy Owner Reluctant To Let Go, Agent Warranty, Low Depreciation, No Repair Needed, Accident Free, Trade In Welcome, Flexible Loan, Transpar...							
Office No. - 63655335 Daniel Fu - 93854303 Andrew Lau - 92959592							
Toyota Corolla Altis 1.6A (OPC)	\$74,800	\$7,330 /yr	26-Sep-2016	1,598 cc	12,492 km	Republic Auto	Available
Certified Agent Unit, Agent 5 Years Warranty. "First Class Car. Not Just Any Car. "Complimentary In-house 1 Year Maintenance Package. In-house Functional Certification. For Assistance On Test-drive Or...							
Office No. - 65672000 SK Foo Arthur - 93887787							
Toyota Corolla Altis 1.6A	\$87,800	\$8,620 /yr	25-Nov-2016	1,598 cc	17,000 km	360 VR Cars	Available
Low Mileage! Comfortable And Reliable. Full Agent Serviced, Still Under Warranty, Immaculate Condition, As Good As New! Well Maintained By Owner. Drive It Away With Style! See To Believe, View By Appo...							
Office No. - 68170836 James Tan - 90700005 Eugene Ng - 83399587							
Toyota Corolla Altis 1.6A Elegance	\$93,500	\$9,300 /yr	28-Sep-2016	1,598 cc	13,700 km		Available
Lowest Mileage, High Specs Elegance Model, Grey Metallic. 1 Owner. Agent Warranty Till Sep 2021. Serviced By Agent. Free Servicing With Agent For Next Owner. 100% Accident Free. High ARF \$19990. Come ...							
Office No. - - Ong - 83839858							
Toyota Corolla Altis 1.6A Elegance	\$89,800	\$9,320 /yr	05-May-2016	1,598 cc	25,000 km	Platinum Auto	Available
1 Ownership, 100% Accident Free, Fully Serviced At Borneo Motors With 5 Years Warranty. Like Brand New Car, High PARF Value Of \$9,795. High Loan Available, Please Call For Viewing.							
Office No. - 63859183 Richard - 98173682 Shawn - 90494620 Jackson - 97735487 Vincent C - 84821530							

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, beauty and wellness, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

TYPE OF CLAIM: ☐ OD ☒ OOD/UL ☐ DS

MCA:

Shashi

MOTOR ACCIDENT REPORT

Date Of Report: 02/10/2017 Time: 8.50pm
 Date Of Accident: 01/10/2017
 Exact Location Of Accident: Chang Road junction, intersection with Still Rd and Jln Eunor
 Country/State of Loss: Singapore ☐ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ / Johor ☐ / Perak ☐ / Kedah ☐ / Kelantan ☐ / Terengganu ☐ / Pulau Pinang ☐ / Perlis ☐ / Thailand ☐

OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: SKZ 1167 D Co. Reg. No (for Co. Vehicle)/NRIC/PP/FIN No: S7134269G
 Name Of Registered Owner: YONG CHUNG WAN Email Address: benin-yong@yahoo.com
 Mobile Number: 96421456 Alternative No:

Vehicle Particulars

Manufacturer: Toyota ☒ Lexus ☐ Suzuki ☐ Hino ☐ Model: Corolla
 Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):
 Are you claiming under your own insurance policy for repair to your vehicle? Yes ☒ Reporting Only ☐ Third Party ☐
 Vehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐

Insurance Company

Name of Insurance Company: MSIG
 Any In-Car Camera? (applicable for United Overseas Insurance Limited insured only): Yes ☐ (please attach photo) No ☐
 Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐
 Fleet Policy: Yes ☐ No ☒ Policy / Cover Note No: 028867644 QMN

DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: YONG CHUNG WAN NRIC/Passport/FIN No: S7134269G
 Date Of Birth: 26/09/1971 Occupation: Indoor ☒ Outdoor ☐
 Date Of Driving Pass: 12/1/2004 Gender: Male ☒ Female ☐
 Mobile Number: 96421456 Fax No: Alternative No:
 Address: 60 WOODLANDS DRIVE 16 #02-21 Postal Code: 737896
 Email Address:
 Was driver an employee of the Insured's Company? Yes ☐ No ☐ State relationship of the driver with the insured:
 Vehicle Registration Number of Driver's Own Vehicle (if applicable):
 Insurance Company of Driver's Own Vehicle (if applicable):

GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: CHAIN COLLISION Number of Passengers in the above vehicle (including Driver):
 Weather Conditions: Clear ☒ Raining ☐ Others ☐ (if others, please state condition):
 Road Surface: Wet ☐ Dry ☒ Others ☐ (if others, please state condition):
 Was any body injured in the Accident? No ☐ Yes ☒
 Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No: Vehicle type:
 Was any other material or property (e.g. other vehicle) damaged? No ☒ Yes ☐
 Was there any video captured by Car Camera? No ☐ Yes ☒ Are accident scene photos available for attachment? No ☐ Yes ☒
 Was the accident reported to the police? No ☐ Yes ☒ (If yes, please state which Police Station): Traffic Police Division HQ
 Was notice of intended Prosecution given? No ☒ Yes ☐ (If yes, please state against whom):
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☒ Yes ☐

DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: SKF 6328 D Vehicle Make/Model/Colour: Nissan Almera
 Details Of Properties Damage in Accident:
 Name of Driver: WONG CHONG HWI Contact Number: 9739 5619
 NRIC/Passport/FIN Number: Postal Code:
 Address:
 Insurance Company Name: No. Of Passenger (including Driver):
 Nature Of Damage:

DETAILS OF ACCIDENT INDEPENDANT WITNESS

Name:
 Phone Number:
 Email Address:

DETAILS OF INJURED PERSON 1 (Please fill Annex A if more person injured)

Name: YONG CHUNG WAN Approximate Age: 46 Postal Code: 737896
 Address: 60 WOODLANDS DRIVE 16 #02-21
 Injuries Sustained: Neck, Shoulder, Upper Spinal Cord pain Injured person in which vehicle: SKZ 1167 D
 Were seat belt worn? No ☐ Yes ☒ Were injured conveyed to hospital by ambulance? Yes ☒ No ☐

MOTOR ACCIDENT REPORT FORM

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration No.: SDT 4L	Vehicle Make / Model / Colour: Audi
Details of Property Damaged in Accident:	
Name of Driver: Sherman Leo	NRIC/Passport Number: S7147394 E
Contact Number: 8292 4224	(Post Code:)
Address:	
Insurance Company Name:	
Nature of Damage:	No. of Passengers (Including Driver): 0
Details of Witness - Name:	
Details of Witness - Contact Number:	
Details of Witness - Email Address:	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration No.:	Vehicle Make / Model / Colour:
Details of Property Damaged in Accident:	
Name of Driver:	NRIC/Passport Number:
Contact Number:	(Post Code:)
Address:	
Insurance Company Name:	
Nature of Damage:	No. of Passengers (Including Driver):
Details of Witness - Name:	
Details of Witness - Contact Number:	
Details of Witness - Email Address:	

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration No.:	Vehicle Make / Model / Colour:
Details of Property Damaged in Accident:	
Name of Driver:	NRIC/Passport Number:
Contact Number:	(Post Code:)
Address:	
Insurance Company Name:	
Nature of Damage:	No. of Passengers (Including Driver):
Details of Witness - Name:	
Details of Witness - Contact Number:	
Details of Witness - Email Address:	

DETAILS OF INJURED PERSON 2

Name	Kara Yong
Address	60 Woodlands Drive 16 #02-21
Post Code	737896
Approximate Age	4
Injuries Sustained	Neck and shoulder and upper spinal cord pain
Injured person in which vehicle	SIC2 1167 D
Were seat belts worn?	No ☐ Yes ☒
Were injured conveyed to hospital by ambulance?	No ☒ Yes ☐

DETAILS OF INJURED PERSON 3

Name	Naw Siv Reanor Hser Eh
Address	60 Woodlands Drive 16 #02-21
Post Code	737896
Approximate Age	25
Injuries Sustained	Neck, shoulder and upper spinal cord pain.
Injured person in which vehicle	SIC2 1167 D
Were seat belts worn?	No ☐ Yes ☒
Were injured conveyed to hospital by ambulance?	No ☒ Yes ☐

MOTOR ACCIDENT REPORT FORM

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicles Registration No.:	Vehicle Make / Model / Colour:
Details of Property Damaged in Accident:	
Name of Driver:	NRIC/Passport Number:
Contact Number:	(Post Code:)
Address:	
Insurance Company Name:	
Nature of Damage:	No. of Passengers (Including Driver):
Details of Witness - Name:	
Details of Witness - Contact Number:	
Details of Witness - Email Address:	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicles Registration No.:	Vehicle Make / Model / Colour:
Details of Property Damaged in Accident:	
Name of Driver:	NRIC/Passport Number:
Contact Number:	(Post Code:)
Address:	
Insurance Company Name:	
Nature of Damage:	No. of Passengers (Including Driver):
Details of Witness - Name:	
Details of Witness - Contact Number:	
Details of Witness - Email Address:	

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicles Registration No.:	Vehicle Make / Model / Colour:
Details of Property Damaged in Accident:	
Name of Driver:	NRIC/Passport Number:
Contact Number:	(Post Code:)
Address:	
Insurance Company Name:	
Nature of Damage:	No. of Passengers (Including Driver):
Details of Witness - Name:	
Details of Witness - Contact Number:	
Details of Witness - Email Address:	

DETAILS OF INJURED PERSON 2

Name	YONG CHUNG HUAT
Address	513 HOUGANG AVE 10 # 07-255
Post Code	530 513
Approximate Age	53
Injuries Sustained	Neck, Shoulder and upper spinal cord pain.
Injured person in which vehicle	SKZ 1167 D
Were seat belts worn?	No ☐ Yes ☒
Were injured conveyed to hospital by ambulance?	No ☒ Yes ☐ 5

DETAILS OF INJURED PERSON 1

Name	SEAH LAY KHENG
Address	513 HOUGANG AVE 10 # 07-255
Post Code	530 513
Approximate Age	51
Injuries Sustained	Neck, Shoulder and upper spinal cord pain.
Injured person in which vehicle	SKZ 1167 D
Were seat belts worn?	No ☐ Yes ☒
Were injured conveyed to hospital by ambulance?	No ☒ Yes ☐

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

2/10/17 4:30pm
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

[Signature]
Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

On Sunday, 1 Oct 2017, at about 8.50pm, I was driving along Changi Road. As the traffic light turned red, I stopped my vehicle at the traffic junction, intersection with Seletar Rd and Jin Eunos. All of a sudden, I heard a loud bang coming from vehicles behind us. The next moment, my vehicle also got hit. When I got down from my vehicle, I found out it was vehicle SDT 4L which first hit SKF 6328D which was also stationary and then SKF 6328P in turn hit me from the back. All my passengers including myself suffered neck, shoulder and spinal cord pain from the sudden impact. My passengers include:

1. Kava Yong
2. Yong Chung Hui
3. Seah Lay Kheng
4. Nwa Sir Reana Hser Eh.

We went to A&E and general clinic after that.

Declaration

We declare the foregoing particulars are true in every respect.

 2/10/17 4.30pm
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Ben chen_yong@yahoo.com

Benin MSIG motor insurance

Please print this for me



MSIG

MSIG Insurance (Singapore) Pte. Ltd.
45 Market Way, #11-01, VCA Centre 2, Singapore 068807
Tel: +65 6327 7888 Fax: +65 6327 7800
e-Reg No: J004122125 GST Reg No: 20-04122125

COPY

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
Individual Ownership

MOTOR MAX PLUS
Comprehensive

Certificate No. D-28867644 QNY

Excess: S\$2500

Windscreen Excess: S\$2100

1. Index Mark and Registration Number of Vehicle
SKZ1167B

2. Name of Policyholder
Yong Chung Wan

3. Effective Date of the Commencement of Insurance for the purposes of the Act
11/01/2017

4. Date of Expiry of Insurance
10/01/2018

5. Persons or Classes of Persons entitled to drive*

Yong Chung Wan

Any other person provided he is driving on the policyholder's order or with the policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.
The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 85 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers

for Chief Executive Officer



Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20171002/7011

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 02/10/2017 15:07		Vide Report No.:		Station Diary No.:	
Name of Informant: YONG CHUNG WAN					
Address: APT BLK 60 WOODLANDS DRIVE 16 #02-21 SINGAPORE 737896					
ID Type / ID No.: NRIC NO / S7134269G		Contact No.: Home/Office:		Mobile: 96421456	
Nationality: SINGAPORE CITIZEN		Email: benin_yong@yahoo.com			
Sex: Male	Age: 46	Date of Birth: 26/09/1971	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: EDUCATOR		Driving Licence Information: Class: 3		Date of Expiry:	

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 01/10/2017 20:50	Type of Location: X-Junction
Location: CHANGI ROAD Accident took place along Changi Road, intersection with Still Road and Jalan Eunus.				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

SDT4L	Car	AUDI				0
SKF6328D	Car	NISSAN	Alemera	Silver		1
SKZ1167D	Car	TOYOTA	COROLLA	White		4



**SINGAPORE
POLICE FORCE**



T/20171002/7011

2 of 4

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20171002/7011

CONTINUATION OF REPORT

Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	YONG CHUNG WAN	ID No.	S7134269G
Related Vehicle	SKZ1167D (Car)	Contact No.	96421456
Hospital/Clinic	MOUNT ELIZABETH NOVENA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	01/10/2017	Date Discharge	02/10/2017
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Name	KARA YONG	ID No.	T1326583B
Related Vehicle	SKZ1167D (Car)	Contact No.	96421456
Hospital/Clinic	MOUNT ELIZABETH NOVENA HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	01/10/2017	Date Discharge	02/10/2017
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Name	SEAH LAY KHENG	ID No.	S1807998D
Related Vehicle	SKZ1167D (Car)	Contact No.	91167255
Hospital/Clinic	HEALTHWAY HOUGANG CENTRAL CLINIC	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	02/10/2017	Date Discharge	02/10/2017
No. of Days granted Medical Leave	03	Degree of Injury	Slight



SINGAPORE POLICE FORCE



T/20171002/7011

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 4

Report No. T/20171002/7011

CONTINUATION OF REPORT

Name	YONG CHUNG HUAT		ID No.	S1645460E
Related Vehicle	SKZ1167D (Car)		Contact No.	90907255
Hospital/Clinic	24 HOUR WALK-IN CLINIC		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	01/10/2017	Date Discharge	01/10/2017	
No. of Days granted Medical Leave	01	Degree of Injury	Slight	
Name	NAW SIR REANAR HSER EH		ID No.	NIL
Related Vehicle	SKZ1167D (Car)		Contact No.	96421456
Hospital/Clinic	MOUNT ELIZABETH NOVENA HOSPITAL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	01/10/2017	Date Discharge	02/10/2017	
No. of Days granted Medical Leave	03	Degree of Injury	Slight	

Brief Details.

On Sunday, 1 October 2017, at about 8.50pm, I was driving along Changi Road. As the traffic light has turned red, I stopped my vehicle at the traffic junction along Changi Road, intersection with Still Road and Jalan Eunos. All of a sudden, I heard a bang coming from vehicles near us. The next moment, my vehicle got hit. When I got down from my vehicle, I found out it was vehicle SDT4L which first hit SKF6328D which was also stationary and SKF6328D in turned hit me from the back. All my passengers suffered neck and spinal pain upon impact. My passengers include:

1. Kara Yong
2. Yong Chung Huat
3. Jessie Yong
4. Naw Sir Reanar

We went to the A&E after the accident.



**SINGAPORE
POLICE FORCE**



T/20171002/7011

4 of 4

Report No. T/20171002/7011

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
SITIMARSITA BINTE BOHARI
Contact No.: 65476219

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
02/10/2017 15:07


Classification Of Case:

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms


12 Jan 2004



Licence No: S7134269G

NP 428A

0580995



NRIC No: S7134269G

Blood Group: B+ Date of issue: 23-10-1992

APT BLK 60 WOODLANDS DRIVE 16 #02-21
SINGAPORE 737896

NRIC No: S7134269G

Date: 28/06/2008

No: 6041100

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S7134269G
Name:

YONG CHUNG WAN
(YANG CHONGHUAN)

Birth Date: 26 Sep 1971
Issue Date: 12 Jan 2004



001079945F

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7134269G



Name

YONG CHUNG WAN
(YANG CHONGHUAN)

杨崇煥

Race:
CHINESE

Date of Birth: 26-09-1971 Sex: M

Country of Birth:
SINGAPORE



S7134269G



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Co Reg No : 196700086Z
GST Reg No: MR-8500000-9

ESTIMATEJoin Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mr Yong Chung Wan 60 Woodlands Drive 16 #02-21 La Casa Singapore 737896 Mobile: 96421456
	Document No	
	Document Date	
	0	
	03/10/2017	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ C2	ZRE171R	11/01/2016	SKZ1167D	0	27744	6UL/SKZ1167D/03101
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104546147	1ZRX554166	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:D 28867644 QMY ACC DATE:01/10/17 DRIVE IN:02/10/17 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				100.00
2	B	BP-LAB CHECK WIRING AND CONDUCT LEAK TEST				154.00
3	B	BP-LAB TRANSFER BOOT LID MECHANISM				308.00
4	B	BP-LAB R/I INTERIOR UPHOLSTERY TO FAC REPAIR				616.00
5	B	BP-LAB DRILL HOLE AND INSTALL REVERSE SENSOR				154.00
6	B	BP-LAB REPLACE ACC AFF PARTS AND PANEL				4312.00
		STRAIGHTEN AND REALIGN ACC AFF AREA				
7	B	BP-RES RESPRAY ACC AFF AREA				2530.00
8	Z	BP-SLANT SUPPLY SEALANT (NETT) 2 PANEL				160.00
9	1	SPZ061-12021 11 BACK SENSOR (040) 310A	1.00	159.75	15.00	135.79
10	2	S52182-02160 ARM, RR BUMPER LH	1.00	66.20	15.00	56.27
11	3	S52181-02190 ARM, RR BUMPER RH	1.00	66.20	15.00	56.27
12	4	S52023-02190 REINFORCEMENT, RR	1.00	386.60	15.00	328.61
13	5	S52592-02300 SEAL, RR BUMPER LH	1.00	53.30	15.00	45.30
14	6	S52591-02301 SEAL, RR BUMPER RH	1.00	53.30	15.00	45.30

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3498700

3498700

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/10/2017
TIME 09:25

VEHICLE NO SKZ1167D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motors**



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyotasingsapore.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Co Reg No : 196700086Z
GST Reg No: MR-8500000-9**ESTIMATE**Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail		Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCUA1	Mr Yong Chung Wan 60 Woodlands Drive 16 #02-21 La Casa Singapore 737896 Mobile: 96421456
		Document No	
		Document Date	
		0	
		03/10/2017	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ C2	ZRE171R	11/01/2016	SKZ1167D	0	27744	6UL/SKZ1167D/03101
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104546147	12RX554166	60	Shashitharan		--/--/----	0.00	--/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
15	7	S52576-02140 RETAINER, RR BUMPER L	1.00	105.70	15.00	89.84
16	8	S52563-02250 RETAINER, RR BUMPER L	1.00	58.30	15.00	49.55
17	9	S52575-02140 RETAINER, RR BUMPER R	1.00	105.70	15.00	89.84
18	0	S52562-02250 RETAINER, RR BUMPER R	1.00	58.30	15.00	49.55
19	1	S52159-0Z904 COVER, RR BUMPER	1.00	539.90	15.00	458.91
20	2	S52161-OK040 PIECE, RR BUMPER	4.00	3.90	15.00	13.24
21	3	S58307-02380 PANEL, LAMP LOWER	1.00	649.20	15.00	551.82
22	4	S58311-02310 PAN, RR FLOOR	1.00	796.70	15.00	677.19
23	5	S61697-02913 HOUSING, QUARTER	1.00	107.50	15.00	91.37
24	6	S61698-02913 HOUSING, QUARTER PAN	1.00	107.50	15.00	91.37
25	7	S64503-02181 ARM SUB-ASSY, LUG CO	2.00	68.00	15.00	115.60
26	8	S64461-02220 WEATHERSTRIP, LUGGAGE	1.00	170.20	15.00	144.67
27	9	S64401-02B61 PANEL SUB-ASSY, LUGG	1.00	710.10	15.00	603.58
28	0	S64600-02080 LOCK ASSY, LUGGAGE	1.00	386.60	15.00	328.61
29	1	T90467-08186 CO CLIP	2.00	2.30	15.00	3.90
30	2	S58387-02240 PLATE, RR FLOOR	1.00	234.30	15.00	199.15
31	3	S75431-02090 LUGGAGE COMP EMBLEM,	1.00	59.70	15.00	50.74
32	4	S75442-02330 PLATE, LUGGAGE COMPT	1.00	39.70	15.00	33.74
33	5	S75442-02340 PLATE, LUGGAGE COMPT	1.00	44.10	15.00	37.48
34	6	S81580-02550 R/REAR BOOT LAMP	1.00	342.60	15.00	291.21

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3498701

TO SECURITY GUARD

3498701

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 03/10/2017
TIME 09:25

VEHICLE NO SKZ1167D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail		Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCUA1	Mr Yong Chung Wan 60 Woodlands Drive 16 #02-21 La Casa Singapore 737896 Mobile: 96421456
		Document No	
		0	
		Document Date	
		03/10/2017	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGK2	C2	2RE171R	11/01/2016	SKZ1167D	0	27744 :6UL/SKZ1167D/03101'
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104546147	12RX554166	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
35	7	S81590-02550 LAMP ASSY, RR LH	1.00	342.60	15.00	291.21
36	8	S81550-02780 LAMP ASSY, RR COMB RH	1.00	367.90	15.00	312.71
37	9	S81560-02780 LAMP ASSY, RR COMBIN	1.00	367.90	15.00	312.71
38	0	S81910-02170 REFLECTOR ASSY, REFL	1.00	57.90	15.00	49.21
39	1	S81920-02110 REFLECTOR ASSY, REFL	1.00	57.90	15.00	49.21

Rahul

Hp 90010068

8 days

04/10/17 @ 1615

EXCER: 500

REVERT

Resurvey by part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	13,987.95
	Please acknowledge receipt of vehicle	Parts	GST 7.00%	979.16
		Labour	Less	0.00
		Materials		
		Lubrication/Fluid		
		Others	Amount Due	14,967.11

PLEASE TEAR ALONG PERFORATED LINE

3498702

TO SECURITY GUARD

3498702

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/10/2017
TIME 09:25

VEHICLE NO SKZ1167D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD


Inchcape

Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no : 6631 1188

ESTIMATE

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1 Document No 0 Document Date 14/10/2017	Mr Yong Chung Wan 60 Woodlands Drive 16 #02-21 La Casa Singapore 737896 Mobile: 96421456

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	C2	2RE171R	11/01/2016	SKZ1167D	27063	27744 6UL/SKZ1167D/03101
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104546147	12RX554166	60	Shashitharan	06/10/2017	8.00	14/10/2017	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	2	BP-SUNDRY SUNDRIES POLICY NO.:D 28867644 QMY ACC DATE:01/10/17 DRIVE IN:02/10/17 EXCESS:\$500 DATE-IN:06/10/17 DATE SURVEY:04/10/17 NO OF REPAIR DAYS:8 days BY:RASUL AUTHORIZED ON:06/10/17	*			50.00
2	B	BP-LAB CHECK WIRING AND CONDUCT LEAK TEST	*			154.00
3	B	BP-LAB TRANSFER BOOT LID MECHANISM	*			308.00
4	B	BP-LAE R/I INTERIOR UPHOLSTERY TO FAC REPAIR	*			616.00
5	B	BP-LAB DRILL HOLE AND INSTALL REVERSE SENSOR	*			154.00
6	B	BP-LAB REPLACE ACC AFF PARTS AND PANEL	*			2772.00
7	B	BP-RES STRAIGHTEN AND REALIGN ACC AFF AREA	*			2024.00
8	Z	BP-SLANT RESPRAY ACC AFF AREA	*			160.00
9	V	EXC SUPPLY SEALANT (NETT) 2 PANEL				-500.00
10	1	SPZ061-12021 11 Excess element of insurance repair to be paid by the insured party				
11	2	S52023-02190 BACK SENSOR (040) 310A	1.00	159.75	15.00	135.79
12	3	S52592-02301 REINFORCEMENT, RR	1.00	386.60	15.00	328.61
13	4	S52591-02301 SEAL, RR BUMPER LH	1.00	53.30	15.00	45.30
		SEAL, RR BUMPER RH	1.00	53.30	15.00	45.30

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

349746

349746

14/10/2017
14:24

SKZ1167D

WORKSHOP



Borneo Moto



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 120462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mr Yong Chung Wan 60 Woodlands Drive 16 #02-21 La Casa Singapore 737896 Mobile: 96421456
	Document No 0	
	Document Date 14/10/2017	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	C2	ZRE171R	11/01/2016	SKZ1167D	27063	27744 6UL/SKZ1167D/03101
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MRO53REH104546147	12RX554166	60	Shashitharan	06/10/2017	8.00	14/10/2017	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	5	S52576-02140 RETAINER, RR BUMPER L	1.00	105.70	15.00	89.84
15	6	S52563-02250 RETAINER, RR BUMPER L	1.00	58.30	15.00	49.55
16	7	S52575-02140 RETAINER, RR BUMPER R	1.00	105.70	15.00	89.84
17	8	S52562-02250 RETAINER, RR BUMPER R	1.00	58.30	15.00	49.55
18	9	S52159-02904 COVER, RR BUMPER	1.00	539.90	15.00	458.91
19	0	S52161-0K040 PIECE, RR BUMPER	4.00	3.90	15.00	13.24
20	1	S58307-02390 PANEL, LAMP LOWER	1.00	649.20	15.00	551.82
21	2	S64461-02220 WEATHERSTRIP, LUGGAGE	1.00	170.20	15.00	144.67
22	3	S64401-02B61 PANEL SUB-ASSY, LUGG LG	1.00	710.10	15.00	603.58
23	4	S64600-02080 LOCK ASSY, LUGGAGE	1.00	386.60	15.00	328.61
24	5	T90467-08186 CO CLIP	2.00	2.30	15.00	3.90
25	6	S58387-02240 PLATE, RR FLOOR	1.00	234.30	15.00	199.15
26	7	S75431-02090 EMBLEM, LUGGAGE COMP	1.00	59.70	15.00	50.74
27	8	S75442-02330 PLATE, LUGGAGE DOOR	1.00	39.70	15.00	33.74
28	9	S75442-02340 PLATE, LUGGAGE DR	1.00	44.10	15.00	37.48
29	0	S81550-02780 LAMP ASSY, RR COMB RH	1.00	367.90	15.00	312.71
30	1	S81560-02780 LAMP ASSY, RR COMB LH	1.00	367.90	15.00	312.71

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 3,885.04	9,623.04
		Labour 6,238.00	GST 7.00% 673.61
		Materials 0.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	
			Amount Due 10,296.65

349746

349746

14/10/2017
14:24

SKZ1167D

WORKSHOP



Borneo Motors

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17019032/R1RBN2

Date: 18/12/2017

REFERENCE

Insured/Claimant:	YONG CHUNG WAN	Policy No:	28867644QMY	
Date of Loss:	01/10/2017	Nature of Claim:	OD	Claim No: 531588

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ1167D	Engine No:	1ZR554166
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Chassis No:	MR053REH104546147
Reg. Date:	11/01/2016 (Man. Year: 2015)	Odometer:	31877 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$86,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R15	Rear Tyre Size:	205/55R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,753.95	3,935.04	1,818.91	31.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,234.00	6,188.00	2,046.00	24.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,987.95	10,123.04	3,864.91	27.63
- Excess (\$\$)	500.00	500.00	0.00	0.00
(\$\$)	13,487.95	9,623.04	3,864.91	28.65
+ GST 7.00/7.00% (\$\$)	944.16	673.61	270.55	28.66
Nett Amount (\$\$)	14,432.11	10,296.65	4,135.46	28.65

INSPECTION

Date of Assignment:	04/10/2017	
Date Inspected:	04/10/2017	Inspected At: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Dec 2017)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ1167D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*BACK SENSOR (040) 310A	Not Working	135.79 FS	*135.79 FS
3	1		*ARM,RR BUMPER LH	Serviceable	56.27 FS	*- FS
4	1		*ARM,RR BUMPER RH	Serviceable	56.27 FS	*- FS
5	1		*REINFORCEMENT,RR	Bent	328.61 FS	*328.61 FS
6	1		*SEAL,RR BUMPER LH	Necessary	45.30 FS	*45.30 FS
7	1		*SEAL,RR BUMPER RH	Necessary	45.30 FS	*45.30 FS
8	1		*RETAINER,RR BUMPER L	Necessary	89.84 FS	*89.84 FS
9	1		*RETAINER,RR BUMPER L	Necessary	49.55 FS	*49.55 FS
10	1		*RETAINER,RR BUMPER R	Necessary	89.84 FS	*89.84 FS
11	1		*RETAINER,RR BUMPER R	Necessary	49.55 FS	*49.55 FS
12	1		*COVER,RR BUMPER	Deformed	458.91 FS	*458.91 FS
13	4		*PIECE,RR BUMPER	Necessary	13.24 FS	*13.24 FS
14	1		*PANEL,LAMP LOWER	Bent	551.82 FS	*551.82 FS
15	1		*PAN,RR FLOOR	Serviceable	677.19 FS	*- FS
16	1		*HOUSING,QUARTER	Serviceable	91.37 FS	*- FS
17	1		*HOUSING,QUARTER PAN	Serviceable	91.37 FS	*- FS
18	2		*ARM SUB-ASSY,LUG CO	Serviceable	115.60 FS	*- FS
19	1		*WEATHERSTRIP,LUGGAGE	Necessary	144.67 FS	*144.67 FS
20	1		*PANEL SUB-ASSY,LUGG	Bent	603.58 FS	*603.58 FS
21	1		*LOCK ASSY,LUGGAGE	Bent	328.61 FS	*328.61 FS
22	2		*CLIP	Necessary	3.90 FS	*3.90 FS
23	1		*PLATE,RR FLOOR	Deformed	199.15 FS	*199.15 FS
24	1		*LUGGAGE COMP EMBLEM	Necessary	50.74 FS	*50.74 FS
25	1		*PLATE,LUGGAGE COMPT	Necessary	33.74 FS	*33.74 FS
26	1		*PLATE,LUGGAGE COMPT	Necessary	37.48 FS	*37.48 FS
27	1		*R/REAR BOOT LAMP	Serviceable	291.21 FS	*- FS
28	1		*LAMP ASSY,RR LH	Serviceable	291.21 FS	*- FS
29	1		*LAMP ASSY,RR COMB RH	Cracked	312.71 FS	*312.71 FS
30	1		*LAMP ASSY,RR COMBIN	Cracked	312.71 FS	*312.71 FS
31	1		*REFLECTOR ASSY,REFL	Serviceable	49.21 FS	*- FS
32	1		*REFLECTOR ASSY,REFL	Serviceable	49.21 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	5,753.95	3,935.04
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK WIRING AND CONDUCT LEAK TEST	New	154.00	154.00
2	TRANSFER BOOT LID MECHANISM	New	308.00	308.00
3	R/I INTERIOR UPHOLSTERY TO FAC REPAIR	New	616.00	616.00
4	DRILL HOLE AND INSTALL REVERSE SENSOR	New	154.00	154.00
5	REPLACE ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA	New	4,312.00	2,772.00
6	RESPRAY ACC AFF AREA	New	2,530.00	2,024.00
7	SUPPLY SEALANT 2 PANEL	New	160.00	160.00
Gross Labour Cost (S\$)			8,234.00	6,188.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >