




National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17019081/R1tb				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 05-10-2017	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FQ 8465D	Veh. Inspected	SMB 1630K	
Policy No.	5061659760-04	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	03/10/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	23/08/2017	Inspection Date	03/10/2017	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#) [Change Password](#) [Log Out](#)[My Desktop](#)
[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	S061659760-04	ABDUL AZIZ BIN AWANG @ABDUL ADZIZ BIN AWANG	S0108155A	GMC	Third Party	FQ8465D	FQ8465D	12/08/2017	11/08/2018

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1	MT/0967919-002	SMRT TAXIS PTE LTD	SHF 472U	GBF 6529Y
2	MT/0962029-002	SMRT BUSES LTD	SMB 1572U	SKX 6335M
3	MT/0968532-003	SMRT TAXIS PTE LTD	SHB 1953M	SDB 6808P
4	MT/0969143-002	SMRT TAXIS PTE LTD	SHD 6476E	SJK 7469J
5	MT/0912702-002	SMRT BUSES LTD	SMB 1630K	FQ 8465D
6	MT/0970438-001	SMRT TAXIS PTE LTD	SHB5851Y	SLQ 3128P
7	MT/0970441-001	SMRT TAXIS PTE LTD	SHB 1960S	SKM 5998P
8	MT/0959634-002	SMRT BUSES LTD	SMB 1580X	SLD 9017E
9	MT/0968476-002	SMRT TAXIS PTE LTD	SHB 5800U	SHD 2021K
10	MT/0953202-003	SMRT TAXIS PTE LTD	SHC 4540X	WC3406E

Enquire Transfer Fee

Vehicle Details																
Vehicle No.	SMB1630K															
Vehicle Type	H20 - Public Transport Bus/Coach/Minibus															
Vehicle Attachment 1	Air-Conditioned															
Vehicle Scheme	OmniBus (SMRT - ARF-exempted)															
Vehicle Make	MAN															
Vehicle Model	NL 320F (A22) 11L AUTO ABS TURBO															
Chassis No.	WMAA22ZZXF7002627															
Propellant	Diesel															
Engine No.	50339660573964															
Engine Capacity	10518 cc															
Maximum Power Output	-															
Maximum Laden Weight	18000 kg															
Unladen Weight	11280 kg															
Year Of Manufacture	2014															
Original Registration Date	13 Feb 2015															
Lifespan Expiry Date	12 Feb 2032															
Road Tax Expiry Date	12 Feb 2018															
Inspection Due Date	12 Feb 2018															
Intended Transfer Date	01 Dec 2017															
CO2 Emission	-															
<p>The current road tax expiry is 12 Feb 2018. You may renew the road tax from 13 Nov 2017 with all pre-requisite(s) fulfilled. If the road tax is renewed after 12 Feb 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.</p> <p>Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.</p> <p>Amount Payable (From 13 Feb 2018 to 12 Aug 2018)</p>																
	<table><tr><th>Amount Before GST (S\$)</th><th>GST Amount (S\$)</th><th>Amount After GST (S\$)</th></tr><tr><td>Transfer Fee</td><td>11.00</td><td>-</td><td>11.00</td></tr><tr><td>Sub Total</td><td></td><td></td><td>11.00</td></tr><tr><td>Nett Road Tax Amount (After Offsetting Over Payment)</td><td>850.00</td><td>-</td><td>850.00</td></tr></table>	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)	Transfer Fee	11.00	-	11.00	Sub Total			11.00	Nett Road Tax Amount (After Offsetting Over Payment)	850.00	-	850.00
Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)														
Transfer Fee	11.00	-	11.00													
Sub Total			11.00													
Nett Road Tax Amount (After Offsetting Over Payment)	850.00	-	850.00													

Total Amount Payable			861.00
Amount Payable (From 13 Feb 2018 to 12 Feb 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee	11.00	-	11.00
Sub Total			11.00
Nett Road Tax Amount (After Offsetting Over Payment)	1,700.00	-	1,700.00
Total Amount Payable			1,711.00

You may print this page for reference.

OK

Print

Land Transport  Authority

Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTAP [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/08/2016 16:49
Date Of Accident	23/08/2016 11:45
Exact Location Of Accident	BUKIT TIMAH RD BUS STOP (BS:42051)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB1630K
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64823888

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	BUS

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category BUS

Insurance Company

Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-IIO27592MFBP
Cover Note Number	

Driver

Name of Driver	NGOH CHEE KIAN
NRIC No	S6904784Z
Date Of Birth	17/02/1969
Occupation	OUTDOOR
Date Of Driving Pass	04/04/1987
Driving Experience	29 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident UNKNOWN - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

Was there any video captured by Car Camera? NO

Number of Passengers (Including Driver) 9

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

Bus was stationary behind a SBS bus at the bus stop of Bukit Timah Rd (Bs :42051) for passengers' activity on the stated date and time. Bus moving forwards slowly after passengers have completed activity and stopped due to a passenger at the bus stop flagged my bus to stop as such I stopped my bus and opened the bus door for her to board the bus. From my right view mirror I saw a motorcycle FQ8465D have got up from the floor. I immediately alight the bus and went to check on him and found that the motorcycle had knocked onto the rear right side of my bus. The motorcyclist was no injured and his motorcycle intact. As for my bus the rear right side bumper paint peeled off. That's all

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FQ8465D

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver ABDUL AZIZ BIN AWENG

NRIC/Passport Number

Contact Number 98614256

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

SMART BUSES LTD
6 Ang Mo Kio Street 6A
Singapore 569140
Tel: 6482 3888 Fax: 6482 3887
www.smart.com.sg

[Signature]


[Signature]

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

PL not to G1A report

Declaration

We declare the foregoing particulars are true in every respect.

SMART INSURANCE LTD
6 Ang Mo Kio Street 6A
Singapore 569140
Tel: 6482 3888 Fax: 6482 3884
www.smart.com.sg

Policyholder's Signature / Date &
Time


Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB1630K
Ref. No : BUS/08/16/1023
Reg. Date : 30/08/2016
Vehicle Type : BUS -12M
Make : MAN
Model : MAN
Name of Driver : Ngho Chee Kian
Type of Accident : HEAD TO SIDE
Date / Time of Accident : 23/08/2016 11:48:00 AM
Accident Reported Date / Time : 24/08/2016 12:00:00 AM
Surveyor is Required? : Yes
Survey by : IDAC
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No :
Special Instruction to ARC, if any :
SMB1630K - REAR RIGHT BUMPER PAINT PEELED OFF
FQ8465D (TP) - TP INSURED WITH NTUC. NO DAMAGES
Prepared Date : 30/08/2016 04:11:00 PM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Chassis No : Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	530.00	0.00
Total Spray Painting Charges	524.00	0.00
Total Material Charges	0.00	0.00
Other Charges	0.00	0.00
TOTAL	1,054.00	0.00
Lum Sum Total	1,050.00	0.00
No. of Repair Days	1.00	0.00

Prepared / Adjusted By : *[Signature]*
Arc / Surveyor Sing Off Date : 01/01/1900 12:00:00 AM
Prepared / Adjusted Date : 03/10/17
Remarks : *[Signature]* 03/10/17
01/10

Prepared Date : 03/10/2017 11:43:39 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :
Quotation Date : Invoice Date :
Invoice Amount : Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	530.00	0.00 300
Total Labour	530.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	524.00	0.00 350
Total Spray Painting & Panel Beating	524.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
TOTAL MATERIALS										
TOTAL MATERIALS(Discounted)								0.00	0.00	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

SMRT Accident Vehicle Repair Estimates


Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB1630K
Ref. No : BUS/08/16/1023
Reg. Date : 13/02/2015
Vehicle Type : BUS -12M
Make : MAN
Model : MAN
Name of Driver : Ngoh Chee Kian
Type of Accident : HEAD TO SIDE
Date / Time of Accident : 23/08/2016 11:48:00 AM
Accident Reported Date / Time : 24/08/2016 12:00:00 AM
Surveyor is Required? : Yes
Survey by : IDAC
Vehicle is Towed Back? : No
Towed Back Date/Time : 01/01/2000
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024092386

Special Instruction to ARC, if any :

SMB1630K - REAR RIGHT BUMPER PAINT PEELED OFF
FQ8465D (TP) - TP INSURED WITH NTUC. NO DAMAGES

Prepared Date : 30/08/2016 04:11:00 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : WMAA22ZZXF7002627

Mileage : 0

Work Shop :

Repair Completed Date / Time : 01/01/2000

Summary of Repair Estimates**Quotation from ARC****Adjusted by Surveyor, if applicable**

Total Labour Charges : 530.00

300.00

Total Spray Painting Charges : 524.00

350.00

Total Material Charges : 0.00

0.00

Other Charges : 0.00

0.00

TOTAL : **1,054.00****650.00**

Lum Sum Total : 0.00

0.00

No. of Repair Days : 1.00

0.50

Prepared / Adjusted By :

RASUL -LKK 90010068

Arc / Surveyor Sing Off Date : 05/11/2017 10:51:07 AM

05/11/2017 12:23:48 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 03/10/2017 11:43:39 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	530.00	300.00
Total Labour	530.00	300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	524.00	350.00
Total Spray Painting & Panel Beating	524.00	350.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

1054.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
TOTAL MATERIALS										
TOTAL MATERIALS(Discounted)								0.00	0.00	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: NS/INC17019081/R1tbe2	
73 BRAS BASAH ROAD			
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			
		Date: 01-12-2017	
		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FQ 8465D	Veh. Inspected	SMB 1630K
Policy No.	5061659760-04	Coverage (\$)	0.00
Claim No.	MT/0912702-002	Excess (\$)	0.00
Assign From		Assign Date	03/10/2017
2. Vehicle Particulars & Condition			
Make & Model	MAN NL NL320F (A22)	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WMAA22ZZXF7002627	Colour	MULTI COLOUR
Odometer	249269	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	FIRENZA	8 mm
L/H Front Tyre	275/70 R22.5	FIRENZA	8 mm
R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm
L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/08/2016	Inspection Date	03/10/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		0.500 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 1630K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REPAIR REAR PORTION.		530.00	300.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		524.00	350.00
			1,054.00	650.00
	GRAND TOTAL		1,054.00	650.00
RECOMMENDED COST OF REPAIRS (CONFIRMED)				650.00

Report Ref No. NS/INC17019081/R1tbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.