



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

#### Involving

1 2013 NISSAN NV200 1.5L MT ABS AIRBAG (GBC9176C)

#### Date of Loss

20 September 2017

#### Time of Loss

13.10

#### Loss Description

GBC9176C(INSO) C/W SKS8602E

#### Comment

### Workshop Details

#### Total Rebate Amount

31117

#### Nett Loss Amount

\$14,883.00

#### Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

#### Target Date of Completion \*

20/06/2018



#### Days of work completion \*

258



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Vehicle & Driver Details

Vehicle Registration#

GBC9176C

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date \*

21/02/2014



Mileage

100249

Age of Vehicle

3

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2013

ASSESSMENT INFO...

2013

### Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

MOHD KASSIM BIN SALLEH

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... NISSAN

ASSESSMENT INFO... NISSAN

CATEGORY Model

POLICY INFORMAT... NV200 1.5L MT ABS AIRBAG

ASSESSMENT INFO... NV200 1.5L MT ABS AIRBAG 2WD 6Df

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... VSKYBAM20U0071921

CATEGORY Date of Birth

FNOL INFORMATI... 28 October 1963

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 54

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... VSKYBAM20U0071921

CATEGORY Engine No

POLICY INFORMAT... K9KF276D052675

ASSESSMENT INFO... K9KC400D052675

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1461

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 46000

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI... Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S1595048Z

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Detailed Assessment

Inspection Date \*

06/10/2017



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

500

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

175/70R14

## Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



## Tyre Condition

Spare wheel

Rear Tyre Size

175/70R14

Front left side

MICHELIN6mm

Front right side

MICHELIN6mm

Rear left side

MICHELIN6mm

Rear right side

MICHELIN6mm





SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

### Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary
- Parts

Add

Approve

Deny

|  | EDIT | SR NO | QUAN TITY | MATERIAL | SIDE | PART NAME                   | PART NUMBER | REPAIR/REPLACE (PARTS) | CONDITION   | LIST PRICE | DEPR./ BTTR% | DISC OUNT% | SALV AGE% | PART PRICE(NET) | ACTION (PARTS) |
|--|------|-------|-----------|----------|------|-----------------------------|-------------|------------------------|-------------|------------|--------------|------------|-----------|-----------------|----------------|
|  |      | 1     | 1         |          |      | FRONT BUMPER (BLACK COLOUR) |             |                        | Cut         | 1428.8     |              | 30         |           | 1000.16         | Reviewing      |
|  |      | 2     | 1         |          |      | HOOD (SILVER COLOUR)        |             |                        | Serviceable | 0          | 0            | 0          | 0         | 0               | Deny           |

Labour

Add

Approve

Deny

|  | EDIT | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME                                                                                         | LABOUR R&R | LABOUR REPAIR | PAINT | ACTION (LABOUR) | COMMENT | REMOVE |
|--|------|-------|-------------------------|---------------------------------------------------------------------------------------------------|------------|---------------|-------|-----------------|---------|--------|
|  |      | 1     |                         | TO REPLACE FRONT HOOD AND FRONT RH BUMPER TO TRANSFER CLIPS AND REALIGN BUMPER FRAME 2 DAYS       | 480        | 0             | 0     | Reviewing       |         |        |
|  |      | 2     |                         | TO PUTTY AND SPRAY PAINT AT FRONT HOOD, RHF BUMPER & AFFECTED AREAS WITH EXISTING MATCHING COLOUR | 0          | 0             | 0     | Deny            |         |        |

# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

| EDIT                     | SR NO                                                                             | NAME | ACTION                     | AMOUNT    | COMMENT | REMOVE                                                                              |
|--------------------------|-----------------------------------------------------------------------------------|------|----------------------------|-----------|---------|-------------------------------------------------------------------------------------|
| <input type="checkbox"/> |  | 1    | DAYS OF REPAIR : 1 DAYS    | Reviewing |         |  |
| <input type="checkbox"/> |  | 2    | (REPAIR COST NOT CONCLUDE) | Reviewing |         |  |

# Assessment Details

|                            |                          |                   |               |                |               |         |
|----------------------------|--------------------------|-------------------|---------------|----------------|---------------|---------|
| General & Workshop Details | Vehicle & Driver Details | Vehicle Condition | Taxes & Ratio | Parts & Labour | Miscellaneous | Summary |
|----------------------------|--------------------------|-------------------|---------------|----------------|---------------|---------|

Claim Amount\$980.16

Claim Amount\$980.16

| CATEGORY    | ESTIMATE   | REVISED AMOUNT |
|-------------|------------|----------------|
| Labour      | \$480.00   | \$480.00       |
| Excess      | -\$500.00  | -\$500.00      |
| Spare Parts | \$1,000.16 | \$1,000.16     |

Submit for Review