

ASS. EBC BY:

REF: CS/FCI7019120/R1nb/v

Special Inspection

SURV. INT.

CWS

Rasul

ASSIGNMENT (Office)

From (Person):

Joanney Yong

of

FCI

Date/Time 4/16/17 5pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH 5195 D

Insured:

SH 7107 X

at Workshop m/z:

Ding Auto

Tel:

92394128 / WINE

of Blk 10 Sin Ming Ind Est Sec C # 01-20

Policy No:

Claim No:

D170093 67 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record):

D.O.A. 30/09/17

CA / REV / REP. / REV 24 HRS

wp, 249 Jalan Boon Lay

Date/Time:

5/10/17 8:52am

Person Contacted:

ah Fong

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time:

Action/Instruction

(✓) Estimate

SH 7107 X - CCB / ICR 17009551 / K12A342 - D.O.A.: 6/5/17

Person

REF FCI

4597K

ASSIGNMENT

From _____ Date: 5/10/17

Estimated Cost _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLH 5195 D

at Workshop m/s: Ding Auto

at: 249 Jalan Boon Lay

Insured _____

Policy No _____

Claims No _____


Sum Insured _____ Excess _____

(Client's Record) _____

Make of Veh _____

(Policy Condition) _____

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value _____

D.O.A. Accident Report Consistent? Yes or No

G/A PR Seen Consistent? Yes or No

Est. Repairs _____ days Res Yes or No

Lum Sum _____ % 3 Val. Yes or No

CA / REV / REP. / 24 HRS ¹up

Date _____ Person Contacted _____

Vehicle IN / OUT

Veh No: SLH 5195 D Yr Regr: 2016 / NOV

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: TOYOTA COROLLA ALTIS 1.6 cc: 1598

Colour: Grey A/C Insured / Std / NI / NA

Sp. Reading: 70 735 T-Radio Insured / Std / NI / NA

Eng No _____

C.No: MR053 REH / 64558747

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Order / Jammed / Leaked / Burnt or

Brake: ☒ Order / Jammed / Leaked / Burnt or

Mod: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size F: 205/55R16
R: _____

BS: ☒ SUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front	Rear
R.Ba: <u>6</u> mm	R.Ba: <u>6</u> mm
L.Ba: <u>6</u> mm	L.Ba: <u>6</u> mm

D.O.A. 30/09/17 D.O.I. 05/10/17

Survey held at: Ding Auto

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear / S

The UIC / Chassis frame / Body Structure affected due to collision

Date Time Action Instruction

4/10/17 email preli to Joanne.

23/3/18 Lump Sum \$1550 (\$5969.46, 0.79%) repair 3 days.

23/3/18 File pass to typists

RECEIVED 23 MAR 2018

Date Time File Pass to:

☐ : Preli. Report
☐ : Final Report

Date Time File Return to:

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee

Translator

1 E + RS \$

1 Photo

1 Other

TOTAL

150
50
10
20

Report Format: TP

Lump Sum / I.B.I.: (\$ 1,550)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17019120/R1gb

36 ROBINSON ROAD
#16-01 CITY HOUSES SINGAPORE 068877

Date : 05-10-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 7907X	Veh. Inspected	SLH 5195D
Policy No.		Coverage (\$)	0.00
Claim No.	D17009367MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNEY YONG)	Assign Date	05/10/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	30/09/2017	Inspection Date
Survey held at	249 JALAN BOON LAY	
Repairer	DING AUTO PTE LTD	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Survey Department Check List (Case Handler)

Reference No. : CS/FCI 17019120 / R19b
Policy Type: OD / (TP) / TP RES / TL / EVA

Case Handler *Rita* Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

C Reference No.
C Customer Code
N Assign From
C Assign Date
C Veh No (Inspected)
C Veh No (Insured)
C D.O.A
C Policy No
C Claim No
C Insurance Authorisation (CA /REV/REP)
C Report Type
C Weekend Charges
N Survey held at/Repairer
C Excess

Y-Date	N-Date	Y-Date	N-Date
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C Vehicle No
C Regn Month/Year
N Vehicle Type
N Make & Model
C Engine Capacity. (C.C)
N Colour
C Odometer. (Sp.Reading)
C Chassis No
N General Condition
N Steering
N Brake
N Modification (Modi)
C Tyre Size
N Tyre Make
C Tyre Balance
C Date of Inspection
N Survey held
N Des.of Damages

/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded

--	--	--	--

(3) Workshop Estimate/Assignment Form

N ALL Parts condition
C Market Value for OD cases
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
C Days of repair
C Finalised Amount
C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

C Resurvey photo Uploaded

--	--	--	--

Check By: *Rita* *23/3/18*
Case Handler Date

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	03-10-2017	Our Ref No.	D17009367MFSH
Accident Date	30-09-2017	Claim Type.	Third Party
Insured Vehicle	SH7907X	Third Party Vehicle.	SLH5195D
Survey Location	BLK 10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-20		
Contact Person.	YVONNE WONG		
Contact No.	62652690/ 92394128	Fax No.	64534227
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop DING AUTO PTE LTD
Cc : TP Solicitor NA

Attention. NIL

TP Solicitor Fax No. NA

Officer Incharge JOANNEY

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/228712)



PRI Documents



Close



PRI Header Details

Claim No	D17009367MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & DING AUT
Workshop Name	DING AUTO PTE LTD (Contact Person : YVONNE WONG)	Survey Location & Contact Details	BLK 10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-; Mobile: 92394128 , Phone: 62652690 , Fax: 6453422; EmailId: YVONNE.WONG@DINGAUTO.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM 1		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH7907X	TP Vehicle No	SLH5195D
PRI Recieved Date	04-10-2017 05:00:12 PM	Surveyor Appointed Date	04-10-2017 05:00:16 PM	Surveyor Accept Date	04-10-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	04-10-2017	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Norrita (LKKAUTO)

From: Kenneth Ding <kenneth.ding@dingauto.sg>
Sent: Thursday, 22 March 2018 1:40 PM
To: 'Accounts Ding Auto'; 'Yvonne Wong'; SUR; Rasul (LKKAUTO); 'Kelly Ding'; 'JingFeng'; 'Vivian'; 'Ding Ding Auto'; assignments
Subject: Finalize for SLH5195D ON 30/09/2018 - SUPPLEMENTARY ITEM PHOTO AND AFTER PAINTS
Attachments: DSC01398.jpg; DSC01399.jpg; DSC01400.jpg; DSC01401.jpg; DSC01402.jpg; DSC01403.jpg; DSC01404.jpg; DSC01405.jpg; DSC01406.jpg; DSC01407.jpg; DSC01408.jpg; 180322131112.pdf

Dear Rita, Rasul and Catherine,

As spoken, please see attached estimate, supplementary checklist and supplementary photo.

Total Repair - 03 Days

Labour	\$870 ✓
Special Netts	\$200.00 ✓
Parts	\$1139.92 ✓
Supplementary Parts	\$133.60 ✓
Total Parts	\$1273.52 ✓
Total Parts after 25%	\$955.14
Total (Labour after discount + S.N + Part)	\$2025.14

Final Amount After 20% lumpsum \$1620.11

Please help to finalize and close the file with us.

Best Regards,
Kenneth Ding
HP: 92313123
Fax: 6452 0614

----- Forwarded message -----

From: Norrita (LKKAUTO) <norrita@lkkauto.com>
Date: Wed, Mar 21, 2018 at 4:34 PM
Subject: RE: ACCIDENT INVOLVING SLH5195D ON 30/09/2018 - SUPPLEMENTARY ITEM PHOTO AND AFTER PAINTS
To: yvonne wong <yvonne.wong@dingauto.sg>, SUR <sur@lkkauto.com>, "Rasul (LKKAUTO)" <Rasul@lkkauto.com>
Cc: Accounts Ding Auto <accounts@dingauto.sg>, You jingfeng <jingfeng@dingauto.sg>

Dear Ms Yvonne,

✓ Thank you for your email. Point noted on the above.

We have yet to receive your supplementary estimate checklist. Rasul is reviewing the file

We shall revert to you the soonest.

Thank you

Best Regards,

Rita AB |

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 email: sur@lkkauto.com | Fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: yvonne wong [<mailto:yvonne.wong@dingauto.sg>]

Sent: Wednesday, 21 March 2018 4:14 PM

To: SUR <sur@lkkauto.com>

Cc: Accounts Ding Auto <accounts@dingauto.sg>; You jingfeng <jingfeng@dingauto.sg>

Subject: ACCIDENT INVOLVING SLH5195D ON 30/09/2018 - SUPPLEMENTRY ITEM PHOTO AND AFTER PAINTS

Dear Rasul / Norrita

Attach photo for your ref. (Supplementary Item)

Thank you

Yvonne Wong

Ding Auto Pte Ltd



Virus-free. www.avast.com

Norrita (LKKAUTO)

From: Kenneth Ding <kenneth.ding@dingauto.sg>
Sent: Friday, 23 March 2018 11:18 AM
To: Norrita (LKKAUTO); 'Accounts Ding Auto'; 'Yvonne Wong'; SUR; Rasul (LKKAUTO); 'Kelly Ding'; 'JingFeng'; 'Vivian'; 'Ding Ding Auto'; assignments
Subject: RE: Finalize for SLH5195D ON 30/09/2018 - SUPPLEMENTRY ITEM PHOTO AND AFTER PAINTS

Dear Rita,

Yes, we agreed with the offer and close the file.

Thank you so much.

Best Regards,
Kenneth Ding
HP: 92313123
Fax: 6452 0614

From: Norrita (LKKAUTO) [mailto:norrita@lkkauto.com]
Sent: Friday, March 23, 2018 9:13 AM
To: Kenneth Ding; 'Accounts Ding Auto'; 'Yvonne Wong'; SUR; Rasul (LKKAUTO); 'Kelly Ding'; 'JingFeng'; 'Vivian'; 'Ding Ding Auto'; assignments
Subject: RE: Finalize for SLH5195D ON 30/09/2018 - SUPPLEMENTRY ITEM PHOTO AND AFTER PAINTS

Dear Kenneth

Kndly see the attach. Confirm final amount lump sum at \$1,550.00 repair 3 days.

Please get back at your earliest .

Thank you very much .

Best Regards,

Rita AB |

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 email: sur@lkkauto.com | Fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Norrita (LKKAUTO)
Sent: Thursday, 22 March 2018 2:57 PM
To: Kenneth Ding <kenneth.ding@dingauto.sg>; 'Accounts Ding Auto' <accounts@dingauto.sg>; 'Yvonne Wong' <yvonne.wong@dingauto.sg>; SUR <sur@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>; 'Kelly Ding' <kelly.ding@dingauto.sg>; 'JingFeng' <jingfeng@dingauto.sg>; 'Vivian' <vivian.tan@dingauto.sg>; 'Ding Ding Auto'

Norrita (LKKAUTO)

From: Norrita (LKKAUTO)
Sent: Friday, 23 March 2018 11:11 AM
To: Accounts Ding Auto
Cc: Kenneth Ding; Yvonne Wong; SUR; Rasul (LKKAUTO); Kelly Ding; JingFeng; Vivian; Ding Ding Auto; assignments
Subject: RE: Finalize for SLH5195D ON 30/09/2018 - SUPPLEMENTRY ITEM PHOTO AND AFTER PAINTS

Dear Kenneth,

***For item Labour No. 9** - Base on our recommendations , since the reverse sensor wasn't replace.

Therefore, no requirement for you to respray the reverse sensor .

Appreciate your reply soonest .

Best Regards,

Rita AB |

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 email: sur@lkkauto.com | Fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Accounts Ding Auto [mailto:accounts@dingauto.sg]
Sent: Friday, 23 March 2018 10:40 AM
To: Norrita (LKKAUTO) <norrita@lkkauto.com>
Cc: Kenneth Ding <kenneth.ding@dingauto.sg>; Yvonne Wong <yvonne.wong@dingauto.sg>; SUR <sur@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>; Kelly Ding <kelly.ding@dingauto.sg>; JingFeng <jingfeng@dingauto.sg>; Vivian <vivian.tan@dingauto.sg>; Ding Ding Auto <ding@dingauto.sg>; assignments <assignments@lkkauto.com>
Subject: Re: Finalize for SLH5195D ON 30/09/2018 - SUPPLEMENTRY ITEM PHOTO AND AFTER PAINTS

Dear Rita,

Labour item (9), spray paint on reverse sensor, was not calculate in the amount.

Thus our finalize :

Labour : \$870

S/N : \$200

Parts after 25% : \$955.14

Total (Lump sum) : \$1620.11

Kindly review and revert back the confirmed finalize as soon as possible.

Norrita (LKKAUTO)

From: Accounts Ding Auto <accounts@dingauto.sg>
Sent: Friday, 23 March 2018 10:40 AM
To: Norrita (LKKAUTO)
Cc: Kenneth Ding; Yvonne Wong; SUR; Rasul (LKKAUTO); Kelly Ding; JingFeng; Vivian; Ding Ding Auto; assignments
Subject: Re: Finalize for SLH5195D ON 30/09/2018 - SUPPLEMENTRY ITEM PHOTO AND AFTER PAINTS

Dear Rita,

Labour item (9), spray paint on reverse sensor, was not calculate in the amount.

Thus our finalize :

Labour : \$870

S/N : \$200

Parts after 25% : \$955.14

Total (Lump sum) : \$1620.11

Kindly review and revert back the confirmed finalize as soon as possible.

Thank you so much.

Yours Sincerely,
Fang XinYi Michelle
Office Contact : 92394128
Ding Auto Pte Ltd
Ding Automotive Pte Ltd

On Fri, Mar 23, 2018 at 9:12 AM, Norrita (LKKAUTO) <norrita@lkkauto.com> wrote:

Dear Kenneth

Kindly see the attach. Confirm final amount lump sum at \$1,550.00 repair 3 days.

Please get back at your earliest .

Thank you very much .

Best Regards,

Rita AB |

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 email: sur@lkkauto.com | Fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Norrita (LKKAuto)

Sent: Thursday, 22 March 2018 2:57 PM

To: Kenneth Ding <kenneth.ding@dingauto.sg>; 'Accounts Ding Auto' <accounts@dingauto.sg>; 'Yvonne Wong' <yvonne.wong@dingauto.sg>; SUR <sur@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>; 'Kelly Ding' <kelly.ding@dingauto.sg>; 'JingFeng' <jingfeng@dingauto.sg>; 'Vivian' <vivian.tan@dingauto.sg>; 'Ding Ding Auto' <ding@dingauto.sg>; assignments <assignments@lkkauto.com>

Subject: RE: Finalize for SLH5195D ON 30/09/2018 - SUPPLEMENTRY ITEM PHOTO AND AFTER PAINTS

Dear Kenneth,

Point noted.

Best Regards,

Rita AB |

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 email: sur@lkkauto.com | Fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kenneth Ding [<mailto:kenneth.ding@dingauto.sg>]

Sent: Thursday, 22 March 2018 2:54 PM

To: Norrita (LKKAuto) <norrita@lkkauto.com>; 'Accounts Ding Auto' <accounts@dingauto.sg>; 'Yvonne Wong' <yvonne.wong@dingauto.sg>; SUR <sur@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>; 'Kelly Ding' <kelly.ding@dingauto.sg>; 'JingFeng' <jingfeng@dingauto.sg>; 'Vivian' <vivian.tan@dingauto.sg>; 'Ding Ding Auto' <ding@dingauto.sg>; assignments <assignments@lkkauto.com>

Subject: RE: Finalize for SLH5195D ON 30/09/2018 - SUPPLEMENTRY ITEM PHOTO AND AFTER PAINTS

Dear Rita,

As spoken, please help to expedite the finalize as soon as possible.

Thank you so much.

Best Regards,

Kenneth Ding

HP: 92313123

Fax: 6452 0614

From: Norrita (LKKAuto) [<mailto:norrita@lkkauto.com>]

Sent: Thursday, March 22, 2018 2:05 PM

To: Kenneth Ding; 'Accounts Ding Auto'; 'Yvonne Wong'; SUR; Rasul (LKKAuto); 'Kelly Ding'; 'JingFeng'; 'Vivian'; 'Ding Ding Auto'; assignments

Subject: RE: Finalize for SLH5195D ON 30/09/2018 - SUPPLEMENTRY ITEM PHOTO AND AFTER PAINTS

Dear Kenneth,

Thank you for your email. We will check and revert to you soon.

Best Regards,

Rita AB |

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 email: sur@lkkauto.com | Fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kenneth Ding [<mailto:kenneth.ding@dingauto.sg>]

Sent: Thursday, 22 March 2018 1:40 PM

To: 'Accounts Ding Auto' <accounts@dingauto.sg>; 'Yvonne Wong' <yvonne.wong@dingauto.sg>; SUR <sur@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>; 'Kelly Ding' <kelly.ding@dingauto.sg>; 'JingFeng' <jingfeng@dingauto.sg>; 'Vivian' <vivian.tan@dingauto.sg>; 'Ding Ding Auto' <ding@dingauto.sg>; assignments <assignments@lkkauto.com>

Subject: Finalize for SLH5195D ON 30/09/2018 - SUPPLEMENTRY ITEM PHOTO AND AFTER PAINTS

Dear Rita, Rasul and Catherine,

As spoken, please see attached estimate, supplementary checklist and supplementary photo.

Total Repair - 03 Days

Labour	\$870
Special Netts	\$200.00
Parts	\$1139.92
Supplementary Parts	\$133.60
Total Parts	\$1273.52
Total Parts after 25%	\$955.14
Total (Labour after discount + S.N + Part)	\$2025.14

Final Amount After 20% lumpsum \$1620.11

Please help to finalize and close the file with us.

Best Regards,

Kenneth Ding

HP: 92313123

Fax: 6452 0614

----- Forwarded message -----

From: **Norrita (LKKAUTO)** <norrita@lkkauto.com>

Date: Wed, Mar 21, 2018 at 4:34 PM

Subject: RE: ACCIDENT INVOLVING SLH5195D ON 30/09/2018 - SUPPLEMENTARY ITEM PHOTO AND AFTER PAINTS

To: yvonne wong <yvonne.wong@dingauto.sg>, SUR <sur@lkkauto.com>, "Rasul (LKKAUTO)" <Rasul@lkkauto.com>

Cc: Accounts Ding Auto <accounts@dingauto.sg>, You jingfeng <jingfeng@dingauto.sg>

Dear Ms Yvonne,

Thank you for your email. Point noted on the above.

We have yet to receive your supplementary estimate checklist. Rasul is reviewing the file

We shall revert to you the soonest.

Thank you

Best Regards,

Rita AB |

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 email: sur@lkkauto.com | Fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: yvonne wong [mailto:yvonne.wong@dingauto.sg]

Sent: Wednesday, 21 March 2018 4:14 PM

To: SUR <sur@lkkauto.com>

Cc: Accounts Ding Auto <accounts@dingauto.sg>; You jingfeng <jingfeng@dingauto.sg>

Subject: ACCIDENT INVOLVING SLH5195D ON 30/09/2018 - SUPPLEMENTRY ITEM PHOTO AND AFTER PAINTS

Dear Rasul / Norrita

Attach photo for your ref. (Supplementary Item)

Thank you

Yvonne Wong

Ding Auto Pte Ltd



Virus-free. www.avast.com

Norrita (LKKAuto)

From: yvonne wong <yvonne.wong@dingauto.sg>
Sent: Wednesday, 21 March 2018 4:14 PM
To: SUR
Cc: Accounts Ding Auto; You jingfeng
Subject: ACCIDENT INVOLVING SLH5195D ON 30/09/2018 - SUPPLEMENTRY ITEM PHOTO AND AFTER PAINTS
Attachments: DSC01398.JPG; DSC01399.JPG; DSC01400.JPG; DSC01401.JPG; DSC01402.JPG; DSC01403.JPG; DSC01404.JPG; DSC01405.JPG; DSC01406.JPG; DSC01407.JPG; DSC01408.JPG

Dear Rasul / Norrita

Attach photo for your ref. (Supplementary Item)

Thank you

Yvonne Wong
Ding Auto Pte Ltd

Ai Phing (LKKAuto)

From: Ai Phing (LKKAuto)
Sent: Monday, 9 October, 2017 3:09 PM
To: 'Claim Workflow System'
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17009367MFSH/1
Attachments: SLH 5195D.pdf

Dear Joanne,

Enclosed with preliminary advise of vehicle SLH 5195D.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 5 October, 2017 10:01 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17009367MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Wednesday, 4 October, 2017 5:00 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; JOANNEYONG@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17009367MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D17009367MFSH

Date: 09-10-2017

Our Ref: CS/FC117019120/R1gb

The Motor Claims Department
First Capital Insurance Ltd

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLH 5195D

Please be informed that we had conducted the inspection of the above mentioned vehicle on 05-10-2017 at the premises of M/s DING AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>7,385.86</u>
Revised Estimate Amount	: S\$ <u>1,929.92</u>
"Check" Items Amount	: S\$ <u>645.84</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Yours faithfully

Mohamed Rasul
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if needed.

ACCIDENT STATEMENT

Date Of Report 02/10/2017 12:22
Date Of Accident 30/09/2017 17:15
Exact Location Of Accident RIVERVALE CRESCENT
Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLH5195D
Insured/Policyholder
Name Of Registered Owner LCRF PTE LTD
Co Reg No 201624597K
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-31584255
Vehicle Particulars
Manufacturer TOYOTA
Model COROLLA ALTIS CLASSIC 1.6 CVT
Exact Purpose for which vehicle was being used at time of accident PRIVATE HIRER
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 999995174
Cover Note Number
Driver
Name of Driver LIM YEOW TECK
NRIC No S1392899A
Date Of Birth 18/08/1959
Occupation OUTDOOR
Date Of Driving Pass 27/06/1979
Driving Experience 38 YEARS AND 3 MONTHS
Gender MALE
Mobile Number
Fax Number
Contact Number
Email Address NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company NO

If No Relationship of the Driver with the Insured OTHER - RELIEF

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SH7907X

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver LIM HOCK LEONG

NRIC/Passport Number S1529195H

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claimscollectively the "Purposes";
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



BK164 Rivale Crescent



Rivale Crescent

A = 5LH519
B = 5HT790
Lim Hockle
S15291951

Describe Circumstances of the Accident

On 30/9/17 at 5:15pm I was travelling along Riverdale Crescent within my lane (Single two way lane) I was stop and wait for oncoming ^{traffic} to be clear. A few second later, I saw an impact a m/taxi SH7907X hit onto my rear left portion. I had one passengers inside my vehicle no one was injured.

Declaration

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time




Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Officer's Personnel



DING AUTO PTE LTD
 Blk 10 Sin Ming Industrial Estate Sector C
 #01-20
 Singapore 575845

249 Jalan Boon Lay
 Singapore 619523
 Tel: 6515 3011
 http://www.star.com.sg

Tel: 6452 1208 Fax: 6452 0614
 TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

03/10/2017 14:16

JOB-NO: 85007821

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD
 ADDRESS: 50 UBI AVENUE 3
 #01-12
 SINGAPORE 408866

CONTACT: 0
 0
 NIL

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SLH5195D TRANS: AUTO
 MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)
 OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.
 JOB-CODE: TP SA: Ding Auto User 1

CHASSIS: MR053REH104558747
 ENGINE: 1ZRY334849

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 REMOVE & REFIT REAR BUMPER SENSOR	1.00	120.00	0.00	120.00	-60	Y	60
2 CHECK WIRING & LIGHTING SYSTEM	1.00	100.00	0.00	100.00	-30	Y	30
3 APPLY UNDERCOATING ON AFFECTED AREA	1.00	120.00	0.00	120.00	-30	Y	30
4 STRAIGHTEN REPAIR & REPLACE DAMAGE AREAS	1.00	1,200.00	0.00	1,200.00	-300	Y	300
5 SPRAY PAINT ON REAR BUMPER	1.00	250.00	0.00	250.00	-200	Y	200
6 SPRAY PAINT ON REAR FENDER LHS	1.00	250.00	0.00	250.00	-200	Y	200
7 SPRAY PAINT ON END PANEL	1.00	250.00	0.00	250.00		Y	X AN
8 SPRAY PAINT ON TAILLAMP PANEL LH	1.00	150.00	0.00	150.00		Y	X AN
9 SPRAY PAINT ON REVERSE SENSOR	1.00	80.00	0.00	80.00	-NO	Y	X ANX
TOTAL		2,520.00	0.00	2,520.00			

MATERIALS

1 REAR BUMPER	1.00	486.55	0.00	486.55	L	Y	DE
2 REAR BUMPER REINFORCEMENT	1.00	378.42	0.00	378.42	L	Y	? 75u
3 REAR BUMPER BRACKET LHS	1.00	101.97	0.00	101.97	L	Y	me
4 REAR BUMPER RETAINER LONG LHS	1.00	104.40	0.00	104.40	L	Y	me
5 REAR BUMPER RETAINER SHORT LHS	1.00	78.02	0.00	78.02	L	Y	me
6 REAR BUMPER REFLECTOR LHS	1.00	75.60	0.00	75.60	L	Y	me
7 REAR BUMPER SPONGE	1.00	85.00	0.00	85.00	L	Y	me
8 REAR BUMPER CLIPS	6.00	48.00	0.00	48.00	L	Y	me
9 REAR EXHAUST PIPE	1.00	780.10	0.00	780.10	L	Y	X 9u
10 REAR HUBBARD LHS	1.00	427.80	0.00	427.80	L	Y	3u
11 REAR AXLE	1.00	2,100.00	0.00	2,100.00	L	Y	X 9u
12 REVERSE SENSOR	1.00	200.00	0.00	200.00	S	Y	X 9u
TOTAL:		4,865.86	0.00	4,865.86			

TOTAL PARTS & LABOUR: 7,385.86 0.00 7,385.86

EXCESS/LOADING SS 0.00

No. Of Day: 3 days

RE-SURVEY: BEFORE AFTER PAINTING

PART-BY-PART OR LUMP SUM: SS

DATE OF SURVEY: 05/10/17 P1800

Rasul

90010068

P = \$1273-52
 - 20% = - \$254-70
 25% \$408-82
 955.14 SN \$200-00/
 G-STAR-WI-ET-001-02-Rev00
 L \$870-00
 \$2088-82

62563561

assignments@1KKauto.com

Lump Sum \$1,550

790-00
 955.14
 20% 1556.11
 Total 81945

Attn: Rita

SUPPLEMENTRY ITEM

DINGAUTO

BLK 10, #01-20

Sin Ming Industrial Est, Sec C

Singapore 575645

Tel: 6457 5884

Fax: 6453 4227

VEHICLE NO:	SLH1519SD
MODEL:	Toyota Altis
CHASSIS NO:	
INSURANCE:	Ala
DATE SURVEY:	5/10/17

[illegible]

This Case is under Camp Swan Repairs

DING AUTO PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575645

249 Jalan Boon Lay
Singapore 619523
Tel: 6515 3011
http://www.star.com.sg

Tel: 6452 1208 Fax: 6452 0514

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

03/10/2017 14:16

JOB-NO: 85007821

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD

CONTACT: 0

Page 1 of 2

ADDRESS: 50 UBI AVENUE 3

0

#01-12

NIL

SINGAPORE 408866

VEHICLE DETAILS

LICENSE NO: SLH5195D

TRANS: AUTO

CHASSIS: MR053REH104556747

MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)

ENGINE: 1ZRY334849

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 REMOVE & REFIT REAR BUMPER SENSOR	1.00	120.00	0.00	120.00		Y	60
2 CHECK WIRING & LIGHTING SYSTEM	1.00	100.00	0.00	100.00		Y	30
3 APPLY UNDERCOATING ON AFFECTED AREA	1.00	120.00	0.00	120.00		Y	X
4 STRAIGHTEN REPAIR & REPLACE DAMAGE AREAS	1.00	1,200.00	0.00	1,200.00		Y	300
5 SPRAY PAINT ON REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
6 SPRAY PAINT ON REAR FENDER LHS	1.00	250.00	0.00	250.00		Y	200
7 SPRAY PAINT ON END PANEL	1.00	250.00	0.00	250.00		Y	X
8 SPRAY PAINT ON TAILLAMP PANEL LH	1.00	150.00	0.00	150.00		Y	X
9 SPRAY PAINT ON REVERSE SENSOR	1.00	80.00	0.00	80.00		Y	X
TOTAL:		2,520.00	0.00	2,520.00			
MATERIALS							
1 REAR BUMPER	1.00	486.55	0.00	486.55	L	Y	DE
2 REAR BUMPER REINFORCEMENT	1.00	378.42	0.00	378.42	L	Y	?
3 REAR BUMPER BRACKET LHS	1.00	101.97	0.00	101.97	L	Y	AM
4 REAR BUMPER RETAINER LONG LHS	1.00	104.40	0.00	104.40	L	Y	?
5 REAR BUMPER RETAINER SHORT LHS	1.00	78.02	0.00	78.02	L	Y	?
6 REAR BUMPER REFLECTOR LHS	1.00	75.60	0.00	75.60	L	Y	DE
7 REAR BUMPER SPONGE	1.00	85.00	0.00	85.00	L	Y	?
8 REAR BUMPER CLIPS	6.00	48.00	0.00	48.00	L	Y	AM
9 REAR EXHAUST PIPE	1.00	780.10	0.00	780.10	L	Y	X
10 REAR HUBBELL LHS	1.00	427.80	0.00	427.80	L	Y	300
11 REAR AXLE	1.00	2,100.00	0.00	2,100.00	L	Y	X
12 REVERSE SENSOR	1.00	200.00	0.00	200.00	S	Y	X
TOTAL:		4,865.86	0.00	4,865.86			

TOTAL PARTS & LABOUR :

7,385.86

0.00

7,385.86

EXCESS/LOADING: \$ 0.00

No. Of Day:

3 days

7519.46

RE-SURVEY: BEFORE AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY:

05 / 10 / 17 P1800

Rasul

90010068

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

SURVEYED BY:

Rahul

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17019120/R1nbq2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 26-03-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 7907X	Veh. Inspected	SLH 5195D
Policy No.	D-15072701MFSH	Coverage (\$)	0.00
Claim No.	D17009367MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	04/10/2017

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA ALTIS 1.6	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104558747	Colour	GREY
Odometer	70735	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	DUNLOP	6 mm
L/H Front Tyre	205/55 R16	DUNLOP	6 mm
R/H Rear Tyre	205/55 R16	DUNLOP	6 mm
L/H Rear Tyre	205/55 R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/09/2017	Inspection Date	05/10/2017
Survey held at	249 JALAN BOON LAY		
Repairer	DING AUTO PTE LTD		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 5195D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	486.55	486.55
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	378.42	-
1	REAR BUMPER BRACKET LHS	NECESSARY	101.97	101.97
1	REAR BUMPER RETAINER LONG LHS	SERVICEABLE	104.40	-
1	REAR BUMPER RETAINER SHORT LHS	SERVICEABLE	78.02	-
1	REAR BUMPER REFLECTOR LHS	BROKEN	75.60	75.60
1	REAR BUMPER SPONGE	SERVICEABLE	85.00	-
6	REAR BUMPER CLIPS	NECESSARY	48.00	48.00
1	REAR EXHAUST PIPE	SERVICEABLE	780.10	-
1	REAR TAIL LAMP LHS	SCRATCHED	427.80	427.80
1	REAR AXLE	SERVICEABLE	2,100.00	-
1	AIR DUCT RHS (ADDITIONAL)	DISTORTED	133.60	133.60
	LESS 25% DISCOUNT		-	-318.38
			4,799.46	955.14
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	NOT WORKING	200.00	200.00
1	REVERSE SENSOR (SN) (ADDITIONAL)	REPEATED	200.00	-
			400.00	200.00
<u>LABOUR</u>				
	REMOVE & REFIT REAR BUMPER SENSOR .		120.00	60.00
	CHECK WIRING & LIGHTING SYSTEM.		100.00	30.00
	APPLY UNDERCOATING ON AFFECTED AREA.	NOT NECESSARY	120.00	-
	STRAIGHTEN ,REPAIR & REPLACE DAMAGE AREAS.		1,200.00	300.00
	SPRAY PAINT ON REAR BUMPER.		250.00	200.00
	SPRAY PAINT ON REAR FENDER LHS .		250.00	200.00
	SPRAY PAINT ON END PANEL .	NOT NECESSARY	250.00	-
	SPRAY PAINT ON TAILLAMP PANEL LH .	NOT NECESSARY	150.00	-
	SPRAY PAINT ON REVERSE SENSOR .	NOT NECESSARY	80.00	-
			2,520.00	790.00

Report Ref No. CS/FCI17019120/R1nbq2



GRAND TOTAL		7,719.46	1,945.14
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,550.00

Report Ref No. CS/FCI17019120/R1nbq2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.