

22/03/2002

ASS. REC. BY:

REF: CS/FCU7019274/T1dbnz

Special Instruction:

Survivor

ASSIGNMENT (Office)

From (Person): CWS Joanne Yung of FCL Date/Time: 06/02/17 520pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJD 3023A Insured: SIA 1267R

at Workshop m/s Hwa Peng Auto Tel: 96885655

of 70 Woodlands Ind Park E

Policy No: Claim No: D17009310MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 24092017
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJD 3023A - X
	SIA 1267R - X

Insurance: *Taylor*

REF:


FCI

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SSP3023A Yr Regn: _____
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Harley Davidson C.C. 1799
 Colour: Black A/C: _____ Insured / Std / NI / NA
 Sp. Reading: 161828 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JHMF016308S214635
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ Inorder / Jammed / Leaked / Burnt or
 Brake: ☒ Inorder / Jammed / Leaked / Burnt or
 Modi: ☒ Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/60R15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. _____	D.O.I. <u>11/10/17 10 am</u>

Survey held at Alwa Pery
 Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Submit LS \$2050 (Red 4048, 88, 6672)

RECEIVED 04 DEC 2018

The vehicle de-registered.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) S + PS (\$)

) Photos

) Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format: TP

Lump Sum / I.B.I: (\$ 2,050)

145

50

25

220

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	02-10-2017	Our Ref No. D17009310MFSH
Accident Date	29-09-2017	Claim Type. Third Party
Insured Vehicle	SHA1267R	Third Party Vehicle. SJD3023A
Survey Location	Blk 70 Woodlands Industrial Park E	
Contact Person.	MR FRANCIS	
Contact No.	96885655/ 96885655	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HWA PENG AUTO SERVICE (1996)	Attention. NIL
Cc : TP Solicitor	CHEONGHOH LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Celine Fong (LKKAUTO)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Tuesday, 6 November 2018 8:30 AM
To: assignments
Cc: CWS Motor Claims; Joanne Yong Lai fong
Subject: REMINDER - 2: REQUEST OF SURVEY REPORT-OUR REF:D17009310MFSH;ACCIDENT INVOLVING SHA1267R AND SJD3023A ON 29-09-2017

Dear Sir,

We received LOD from workshop/solicitor.

Please let us have the **Survey Report including Vehicle Inspection Photos & Survey Fees Invoice** asap.

Kindly upload the survey report through CWS from document management screen by selecting option Survey report.

Thanks & Regards,
Motor Claims Department
MS First Capital Insurance Ltd
cwsmotorclaims@msfirstcapital.com.sg

Cheonghoh Law Corporation

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 . Singapore 160053
Co. Reg No.201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

In reply please quote our Reference Number

Our Ref: LCH.my/W1HP-70798.17

05 10 17

BY FAX NO. 65073849 AND BY HAND

First Capital Insurance Ltd (Claims Dept.)
36 Robinson Road
City House #16-01
Singapore 068877

BY CERTIFICATE OF POSTING

Comfort Transportation Pte Ltd
383 Sin Ming Drive
Gas Building
Singapore 575717

BY CERTIFICATE OF POSTING

Dear Sirs

We are instructed by Tw Premium Automobile Pte Ltd to notify you of a road traffic accident on 29.09.17 at about 12:25 pm at Sims Avenue involving our client's vehicle registration number SJD 3023 A and vehicle registration number SHA 1267 R driven by your insured driver/you/your driver at the material time. A copy of the Singapore accident statement filed is available.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

For the avoidance of doubt, our client will be claiming for compensation for loss of use/rental of a replacement vehicle in the instances enumerated in the State Courts Practice Direction Amendment No. 1 of 2016 paragraphs 7.1 and 7.2 of the Appendix C of the Pre-action Protocol for Non-Injury Motor Accident Cases which compensation is additional to any other claim for loss of use/rental of a replacement vehicle which our client may make against your insured and/or your insured's driver and or you/your driver.

Yours faithfully

Cheonghoh Law Corporation

encls:

This is a computer-generated document and requires no signature

cc: client (via e-mail/fax only) - SJD 3023 A

Cheonghoh Law Corporation

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 . Singapore 160053
Co. Reg No.201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

In reply please quote our Reference Number

Our Ref: LCH.my/W1HP-70798.17

05.10.17

BY FAX NO. 65073849 AND BY HAND

First Capital Insurance Ltd (Claims Dept.)
36 Robinson Road
City House #16-01
Singapore 068877

BY CERTIFICATE OF POSTING

Comfort Transportation Pte Ltd
383 Sin Ming Drive
Gas Building
Singapore 575717

BY CERTIFICATE OF POSTING

Dear Sirs

We are instructed by Tw Premium Automobile Pte Ltd to notify you of a road traffic accident on 29.09.17 at about 12:25 pm at Sims Avenue involving our client's vehicle registration number SJD 3023 A and vehicle registration number SHA 1267 R driven by your insured driver/you/your driver at the material time. A copy of the Singapore accident statement filed is available.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

For the avoidance of doubt, our client will be claiming for compensation for loss of use/rental of a replacement vehicle in the instances enumerated in the State Courts Practice Direction Amendment No. 1 of 2016 paragraphs 7.1 and 7.2 of the Appendix C of the Pre-action Protocol for Non-Injury Motor Accident Cases which compensation is additional to any other claim for loss of use/rental of a replacement vehicle which our client may make against your insured and/or your insured's driver and or you/your driver.

Yours faithfully

Cheonghoh Law Corporation

encs:

This is a computer-generated document and requires no signature

cc: client (via e-mail/fax only) - SJD 3023 A

I/We hereby acknowledge receipt
of original of this letter and its
enclosure(s)

Date/Signature/Co. Stamp



From: Cheong Hoh Lee mail@cheonghoh.sg
Subject: Re: Our Ref: D17009310MFSH; Notice of Accident- Traffic accident involving SJD 3023 A (our client) and SHA 1267 R (your insured) on 29 September 2017 at/along Sims Avenue - Our ref: LCH.my/W1HP-70798.17
Date: October 6, 2017 at 4:01 PM
To: Claim Workflow System cwsmotorclaims@first-insurance.com.sg
Cc: Joanne Yong@first-insurance.com.sg
Bcc: Cheonghoh Law Corporation Corporation mail@cheonghoh.sg

Dear Sir/ Madam,

We refer to your email of even date.

Our client hereby nominate LKK Auto Consultants Pte Ltd ("LKK") to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please be informed that our client's vehicle, SJD 3023 A is ready at our client's workshop, Hwa Peng Auto Service (1996), Blk 70 Woodlands Industrial Park E Singapore 757836. Kindly contact the person in charge Mr Francis at 9688 5655 before your surveyor attending at the said workshop.

Thank you.

Regards,

Melody

Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 6337 8700
Fax: 6337 3700

On Oct 6, 2017, at 12:04 PM, Claim Workflow System <cwsmotorclaims@first-insurance.com.sg> wrote:

Dear Sirs,

We refer to your survey request.

Please find below our list of surveyors for your reference. Kindly select from our list below and inform us of your choice within the next 2 days.

1. LKK Auto Consultants Pte Ltd
2. Vicom Ltd


Once you inform us of your choice, the surveyor will be appointed within 2 working days of your email.

If you do not agree to any of the surveyors above, you may proceed to appoint your own surveyor. In this instance, we will also appoint a surveyor from our list above to conduct the PRI. Upon completion of repairs, please contact our appointed surveyor to conduct a physical re-inspection of the vehicle.

Kindly provide **Workshop details** to process.

Thank you.

Regards,
Admin Team
Claim Workflow System
Motor Claims Department
First Capital Insurance Limited



華平汽車服務
HWA PENG AUTO SERVICE (1996)

70 Woodlands Industrial Park E9 Singapore 757836

TEL: 6365 6100 FAX: 6365 6101

Spray Painting • Panel Beating • Body Repair • Engine Tuning • Towing Service • Insurance Claim • L.T.A. Inspection Service
Co. Reg 52823719E

To : TW Premium Automobile Pte Ltd
Mark/Model : Honda Civic (A)
Vehicle No. : SJD 3023A
Date Of Accident : 29 Sept 2017

Date : 24/09/2018

FINAL BILL

AMOUNT(SS)

Total repair cost for the abovementioned vehicle

\$ 2,050.00

HWA PENG AUTO SERVICE (1996)



NG YONG PENG



GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

RECORDS MANAGEMENT CENTRE



GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

RECORDS MANAGEMENT CENTRE

SEARCH RESULTS

Our Ref No: GR-17-171619
Date of Request: 15/11/2017

Your Ref No: LCH.MYW1HP-70798.17

CHEONGHOH LAW CORPORATION
53 Chin Swee Road #03-05
Singapore 160053

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 29/09/2017
Place of Accident: SIMS AVENUE
Client Vehicle No: SJD3023A

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
SHA1267R	SIMS AVE TWDS PAYA LEBAR	29/09/2017 12:25

Thank You

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

TAX INVOICE

Our Ref No: GR-17-171619
Date of Request: 15/11/2017

Your Ref No: LCH.MYW1HP-70798.17

CHEONGHOH LAW CORPORATION
53 Chin Swee Road #03-05
Singapore 160053

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 29/09/2017
Place of Accident: SIMS AVENUE
Client Vehicle No: SJD3023A

DESCRIPTION	AMOUNT (\$S)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque



**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-17-171696
Date of Request: 16/11/2017

Your Ref No: LCH.MY/W1HP-70798.17

CHEONGHOH LAW CORPORATION
53 Chin Swee Road #03-05
Singapore 160053

Dear Sir/Madam,

Date of Accident: 29/09/2017
Vehicle No: SJD3023A
Place of Accident: Along Sims Ave
Involving Vehicle No: SHA1267R

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SHA1267R	Along Sims Ave	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

Enquire Vehicle & Owner Information (Vehicle No. SHA1267R As At 29 Sep 2017 / 12:25:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: 70798/MY

Current Owner Details

Owner ID Type: Company

Owner ID: 199303821R

Owner Name: COMFORT TRANSPORTATION PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 383

Registered Street Name: SIN MING DRIVE

Registered Unit No.: -

Registered Building Name: GAS BUILDING

Registered Postal Code: 575717

Current Vehicle Details

Vehicle No.: SHA1267R

Make Description/Model: HYUNDAI / SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO

Insurance Company Name: FIRST CAPITAL INS LTD



Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)

Last updated on 17 Sep 2017 at 12:38 AM

Cheonghoh Law Corporation

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 . Singapore 160053
Co. Reg No.201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

In reply please quote our Reference Number
Our Ref: LCH.my/W1HP-70798.17

28 September 2018

WITHOUT PREJUDICE

BY HAND

CERTIFICATE OF POSTING

First Capital Insurance Ltd (Claims Dept.)
36 Robinson Road
City House #16-01
Singapore 068877

Comfort Transportation Pte Ltd
383 Sin Ming Drive
Gas Building
Singapore 575717

Tan Chong Pat @ Chan Chong Pat
Blk 403 Serangoon Avenue 1
#11-29
Singapore 550403

Attn: Motor Claims Dept.
(Vehicle No. SHA 1267 R)

Dear Sirs

TRAFFIC ACCIDENT INVOLVING YOUR/YOUR INSURED'S VEHICLE SHA 1267 R AND SJD 3023 A ON 29 SEPTEMBER 2017 AT 12:25 PM ALONG/AT SIMS AVENUE

We act for the claimant **Tw Premium Automobile Pte Ltd**, the owner of the above said motor vehicle no. **SJD 3023 A**.

We are instructed to claim damages against you/your driver/your insured in connection with the above-captioned accident involving our client's vehicle registration number **SJD 3023 A** and vehicle registration number **SHA 1267 R** driven by you/your driver/your insured at the material time.

We are instructed that the accident was caused by you/your driver's/your insured's negligent driving and/or management of motor-vehicle **SHA 1267 R**. As a result, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as stated in Part 1 of the Annexure.

A copy each of the supporting documents as stated in Part 2 of the Annexure is enclosed.

We have on 5 October 2018 notified your insurer (abovenamed addressee) of the accident and a pre-repair survey of our client's vehicle was carried out on 9 October 2018. Our client's claim for costs of repairs is based on the amount negotiated and agreed with surveyor from LKK Auto Consultants whom your insurer have appointed/agreed after the pre-repair survey was completed.

Please note that:

- if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer;
- you or your insurer should send to us an acknowledgment of receipt of this letter within 14 days of your/your insurer receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer;
- if you have a counterclaim against our client arising out of this accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

For the avoidance of doubt, unless otherwise indicated, this letter of claim is sent to the abovenamed addressees.

Yours faithfully


Lee Cheong Hoh
Cheonghoh Law Corporation

enc.: supporting documents in paragraph 4 enclosed in covering letter to insurers only
cc: client (via email /fax only) - SJD 3023 A

017/9310/ctpl/JY

3110



ANNEXURE

Part 1 - particulars of loss and expense

Cost of repairs	\$2,050.00
Loss of rental income @ 3 days	540.00
Survey Report	0.00
GIA Reports/LTA, RCB searches	39.00
Loss of rental income for PRS (4 days x \$180)	720.00
Incidentals	50.00
Costs Contribution	550.00
TOTAL	<u>\$3,949.00</u>

Part 2 - list of supporting documents enclosed in the letter of claim.


LTA search

GIA reports/Police reports & type-written transcripts

repairer's bill and evidence of payment (if any)

the insurer has been notified of the accident and allowed to carry out a pre-repair inspection of claimant's vehicle
supporting documents for all other expenses claimed (if any)

Correspondences with the defendant's relating to pre-repair survey and/or post repair inspection of the claimant's vehicle



華平汽車服務 HWA PENG AUTO SERVICE (1996)

70 Woodlands Industrial Park E9 Singapore 757836

TEL: 6365 6100 FAX: 6365 6101

Spray Painting • Panel Beating • Body Repair • Engine Tuning • Towing Service • Insurance Claim • L.T.A. Inspection Service
Co. Reg 52823719E

ESTIMATE REPORT

TW Premium Automobile Pte Ltd
C/o 70 Woodlands Industrial Park E9
Singapore 757836

Vehicle Number : SJD3023A
Make And Model : Honda Civic (A)
Date of Accident : 29 September 2017

S/No	Parts	QTY	Unit Price	List Price
1	Rear bumper	1	\$	738.00 <i>de✓</i>
2	Rear bumper side retainer LH	1	\$	33.20 <i>nee</i>
3	Rear bumper side retainer RH	1	\$	33.20 <i>nee</i>
4	Rear bumper bracket LH	1	\$	38.80 <i>nee✓</i>
5	Rear bumper bracket RH	1	\$	38.80 <i>nee✓</i>
6	Rear end panel	1	\$	400.50 <i>TR</i>
7	Rear end panel top garnish	1	\$	112.40 <i>de✓</i>
8	Rear taillamp LH	1	\$	309.10 <i>x nh✓</i>
9	Rear taillamp RH	1	\$	309.10 <i>x nh✓</i>
10	Rear bootlid	1	\$	760.00 <i>R✓</i>
11	Rear bootlid lock	1	\$	164.00 <i>x</i>
12	Rear bootlid reflector lamp LH	1	\$	224.50 <i>x</i>
13	Rear bootlid reflector lamp RH	1	\$	224.50 <i>x</i>
14	Rear bootlid weatherstrip	1	\$	187.10 <i>at✓</i>
15	Rear bootlid emblem 'H'	1	\$	55.60 <i>nee</i>
16	Rear bootlid emblem '1.8'	1	\$	35.80 <i>nee</i>
17	Rear bootlid emblem 'CIVIC'	1	\$	38.80 <i>nee</i>
18	Rear bootlid emblem 'i-vtec'	1	\$	32.70 <i>nee</i>

\$ 3,736.10 *1344.40*
Less 20% \$ 747.22
Total \$ 2,988.88 *1075.52*

Special Nett Item

19	Rear bumper clips	\$	60.00 <i>30 nee</i>
20	Rear number plate with casing	\$	50.00 <i>x 27</i>
21	Rear end panel top garnish clips	\$	40.00 <i>20 nee</i>
22	Rear bootlid inner trim clips	\$	50.00 <i>x 27</i>
23	Joint sealant	\$	80.00 <i>x 27</i>
24	Reverse sensor	\$	280.00 <i>200mm✓</i>
Total			\$ <u>560.00</u> <i>250.</i>

To be continued page 2



華平汽車服務
HWA PENG AUTO SERVICE (1996)

70 Woodlands Industrial Park E9 Singapore 757836

TEL: 6365 6100 FAX: 6365 6101

Spray Painting • Panel Beating • Body Repair • Engine Tuning • Towing Service • Insurance Claim • L.T.A. Inspection Service
Co. Reg 52823719E

Page 2

Labour & Misc Charges

To dismantle, replace & panel beating affected parts for rear portion.
To spray paint on affected areas for rear portion.
To apply anti-rust on affected areas.
To remove/refit rear upholstery.
To remove/refit bootlid mechanism & trimming.
To remove/refit reverse sensors.
To check wiring for rear portion.

\$	1,000.00	500
\$	1,000.00	600
\$	100.00	30
\$	200.00	50
\$	100.00	× 112
\$	100.00	30
\$	50.00	30
Total	\$ 2,550.00	1240

Grand Total : \$ 6,098.88

2565.52
4/8 \$ 2050

4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17019274/T1cbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 05-12-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1267R	Veh. Inspected	SJD 3023A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17009310MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	06/10/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	-	
Chassis No.	JHMF16308S214635	Colour	BLACK	
Odometer	161828	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/09/2017	Inspection Date	11/10/2017	
Survey held at	HWA PENG AUTO SERVICE (1996) 70 WOODLAND INDUSTRIAL PARK E SINGAPORE 757836			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJD 3023A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	738.00	738.00
1	REAR BUMPER SIDE RETAINER LH	NECESSARY	33.20	33.20
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	33.20	33.20
1	REAR BUMPER BRACKET LH	NECESSARY	38.80	38.80
1	REAR BUMPER BRACKET RH	NECESSARY	38.80	38.80
1	REAR END PANEL	TO REPAIR SEE LABOUR	400.50	-
1	REAR END PANEL TOP GARNISH	DEFORMED	112.40	112.40
1	REAR TAILLAMP LH	NOT NECESSARY	309.10	-
1	REAR TAILLAMP RH	NOT NECESSARY	309.10	-
1	REAR BOOTLID	TO REPAIR SEE LABOUR	760.00	-
1	REAR BOOTLID LOCK	NOT NECESSARY	164.00	-
1	REAR BOOTLID REFLECTOR LAMP LH	NOT NECESSARY	224.50	-
1	REAR BOOTLID REFLECTOR LAMP RH	NOT NECESSARY	224.50	-
1	REAR BOOTLID WEATHERSTRIP	CUT	187.10	187.10
1	REAR BOOTLID EMBLEM "H"	NECESSARY	55.60	55.60
1	REAR BOOTLID EMBLEM "1.8"	NECESSARY	35.80	35.80
1	REAR BOOTLID EMBLEM "CIVIC"	NECESSARY	38.80	38.80
1	REAR BOOTLID EMBLEM "I-VTEC"	NECESSARY	32.70	32.70
	LESS 20% DISCOUNT		-747.22	-268.88
			2,988.88	1,075.52
SPECIAL NETT ITEMS				
1	REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	REAR NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	50.00	-
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	40.00	20.00
1	REAR BOOTLID INNER TRIM CLIPS (SN)	NOT NECESSARY	50.00	-
1	JOINT SEALANT (SN)	NOT NECESSARY	80.00	-
1	REVERSE SENSOR (SN)	NOT WORKING	280.00	200.00
			560.00	250.00

Report Ref No. CS/FCI17019274/T1cbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISMANTLE, REPLACE & PANEL BEATING AFFECTED PARTS FOR REAR PORTION. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR BOOTLID.		1,000.00	500.00
	TO SPRAY PAINT ON AFFECTED AREAS FOR REAR PORTION.		1,000.00	600.00
	TO APPLY ANTI-RUST ON AFFECTED AREAS.		100.00	30.00
	TO REMOVE/REFIT REAR UPHOLSTERY.		200.00	50.00
	TO REMOVE/REFIT BOOTLID MECHANISM & TRIMMING.	NOT NECESSARY	100.00	-
	TO REMOVE/REFIT REVERSE SENSORS.		100.00	30.00
	TO CHECK WIRING FOR REAR PORTION.		50.00	30.00
			2,550.00	1,240.00
	GRAND TOTAL		6,098.88	2,565.52
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,050.00

Report Ref No. CS/FCI17019274/T1cbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.