

23/03/2007

ASS. REC. BY:

REF: CS/FCI/7019412/Drbn2

Special Instruction:

Survivor:

WS

Bryan

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time: 9/10/17 @ 5:37pm

Estimated Cost:

Bill to:

OD (IP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 8824X

Insured:

SHD 4326T

at Workshop m/s

Pegasus

Tel:

6858 1846

of

51 Defu Lane 10

Policy No:

Claim No:

D17009437MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 04/10/2017

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement

Date/Time: 10/10/17 @ 10:26am

Person Contacted:

Annie

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate


SLN 8824X - X

SHD 4326T - X

Revert thru email

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)

Remark: The vsh had commenced its repair at the time of inspection.

Salvage / Market Value: _____

IDAC Accident Report: _____ Consistent? (Yes or No)

GIA / PR / Seen: _____ Consistent? (Yes or No)

Est. Repairs: 2 days Res. Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Ver No: SLH 8824X Date: 2017 May
 Type: MC / MCycle / Bus / Van / Lorry / Taxi / Prime Mover
 Truck / Trailer or
 Make: Toyota Vios DO: 1496
 Colour: Silver A/C: _____ Insured / Std / Nil / NA
 Sp Reading: 36727 T-Pad: _____ Insured / Std / Nil / NA
 Eng No: 2NRX150315
 Ch No: MHFB29F3802010633
 Gen. Cond: 6 / Fair / Poor / Burnt
 Steering: 6 / Jammed / Leaked / Burnt / or
 Brake: 6 / Jammed / Leaked / Burnt / or
 Mod: Nil / 6 / STD A/Rim / or
 Tyre Size: F: 195/50 R16
 R: — 11 —
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or: Bridgestone
 Front: _____ Rear: _____
 R.Bal: 5 mm R.Bal: 5 mm
 L.Bal: 5 mm L.Bal: 5 mm
 D.O.A: 04/10/2017 D.O.I: 29/12/2017
 Survey held at: Pegasus 29th Lane
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
O/S Rvw
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

16/04/18 First Cap SHP 4326 T
Jimma TIP 910.93 with 2 days 8 m
Red: \$456.37, 33.1.

RECEIVED 16 APR 2018

Date/Time: File Pass to: ☐ : Preli. Report

typist ☒ : Final Report

Date/Time: File Return to:

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee

Transcription

Printed

Other

Total

Add Fee:

☐

Site Insp

\$

☐

Inter. Insp

\$

☐

Tech. Insp

\$

☐

Rep. Insp

\$

100

50

50

30

230

Report Format:

TP

Lum. Sum / (B.I.):

910.93



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17019412/Drb

36 ROBINSON ROAD

#16-01 CITY HOUSES SINGAPORE 068877

Date : 10-10-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4326T	Veh. Inspected	SLN 8824X
Policy No.		Coverage (\$)	0.00
Claim No.	D17009437MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	10/10/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	04/10/2017	Inspection Date	29/12/2017
Survey held at	51 DEFU LANE 10		
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	05-10-2017	Our Ref No. D17009437MFSH
Accident Date	04-10-2017	Claim Type. Third Party
Insured Vehicle	SHD4326T	Third Party Vehicle. SLN8824X
Survey Location	51 DEFU LANE 10	
Contact Person.	ROEL CRUZ	
Contact No.	68581846/ 0	Fax No. 64876070
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PEGASUS ENGINEERING & TRADING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/228790)



PRI Documents



Close



PRI Header Details

Claim No	D17009437MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & PEGASUS PTE LTD
Workshop Name	PEGASUS ENGINEERING & TRADING PTE LTD (Contact Person : ROEL CRUZ)	Survey Location & Contact Details	51 DEFU LANE 10 Mobile: 0 , Phone: 68581846 , Fax: 64876070 EmailId: CLAIMS@PEGASUSENGRG.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD4326T	TP Vehicle No	SLN8824X
PRI Recieved Date	09-10-2017 02:54:53 PM	Surveyor Appointed Date	09-10-2017 05:36:39 PM	Surveyor Accept Date	10-10-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	10-10-2017	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Enquire Transfer Fee**Vehicle Details**

Vehicle No.: SLN8824X
 Vehicle Type: Z10 - Private Hire (Chauffeur) Motor Car
 Vehicle Attachment 1: No Attachment
 Vehicle Scheme: Normal
 Vehicle Make: TOYOTA
 Vehicle Model: VIOS 1.5E CVT
 Chassis No.: MHFB29F3802010633
 Propellant: Petrol
 Engine No.: 2NRX150315
 Engine Capacity: 1496 cc
 Maximum Power Output: 79.0 kW (105 bhp)
 Maximum Laden Weight: 1500 kg
 Unladen Weight: 1065 kg
 Year Of Manufacture: 2017
 Original Registration Date: 22 May 2017
 Lifespan Expiry Date: -
 COE Category: A - Car up to 1600cc & 97kW (130bhp)
 Quota Premium: \$52,000.00
 COE Expiry Date: 21 May 2027
 Road Tax Expiry Date: 21 Nov 2017
 PARF Eligibility Expiry Date: 21 May 2027
 Inspection Due Date: 21 May 2020
 Intended Transfer Date: 31 Dec 2017
 CO2 Emission: 130.00 (g/km)
 CEVS Rebate Utilised Amount: \$5,000.00

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use [Enquire Road Tax Payable](#) for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 22 Nov 2017 to 21 May 2018)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	11.00	-	11.00
Sub Total:			11.00
Nett Road Tax Amount (After Offsetting Over Payment):	341.00	-	341.00
Total Amount Payable:			352.00

Amount Payable (From 22 Nov 2017 to 21 Nov 2018)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	11.00	-	11.00
Sub Total:			11.00
Nett Road Tax Amount (After Offsetting Over Payment):	682.00	-	682.00
Total Amount Payable:			693.00

You may print this page for reference.

OK Print

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
 Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
 Best viewed with IE 8.0 SP3 and above, 1024 X 768 resolution
 Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
 Last updated on 17 Sep 2017 at 12:38 AM

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : CRUZ ROEL OLERO Tel : Email :	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :

reg LKK Bryan.
29.12.2017 @ 1405hrs.

Quotation No : QO17/10-1019	Quotation Date : 04/10/2017	Terms : 30 DAYS
Vehicle No : SLN8824X	Chassis No : MHFB29F3802010633	Third Party Insurer :
Model : VIOS		Date of Accident :
Remarks : TP INSURER: FIRST CAPITAL, TP INSURED'S VEH: SHD4326T, DATE OF ACCIDENT: 04.10.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER <i>cut / crack mounting</i>	1	504.9000	504.90 ✓
2	REAR BUMPER SIDE RETAINERS <i>SN</i>	1	116.3000	116.30 X
3	REAR BUMPER SIDE HOLDER <i>SN</i>	1	22.6000	22.60 X
4	REAR BUMPER CLIPS <i>SN HCC</i>	10	4.3000	43.00 ✓
5	REAR BUMPER REFLECTOR <i>HCC</i>	1	130.5000	130.50 X
6	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	250.0000	250.00 ✓
7	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	300.0000	300.00 ✓

29/12/2017 @ 1430hrs.

Not Antimal
PIP 2 days.

Ryan

LKK Auto

Photos & 4 spray.

Sub Total 1,367.30
GST(7.00%) 95.71
Total (SGD) 1,463.01



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17019412/Drbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4326T	Veh. Inspected	SLN 8824X	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17009437MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	09/10/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MHFB29F3802010633	Colour	SILVER	
Odometer	36727	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R16	BRIDGESTONE	5 mm	
L/H Front Tyre	195/50 R16	BRIDGESTONE	5 mm	
R/H Rear Tyre	195/50 R16	BRIDGESTONE	5 mm	
L/H Rear Tyre	195/50 R16	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/10/2017	Inspection Date	29/12/2017	
Survey held at	51 DEFU LANE 10			
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 8824X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	MOUNTING CRACKED / CUT	504.90	504.90
1	REAR BUMPER SIDE RETAINERS	SERVICEABLE	116.30	-
1	REAR BUMPER SIDE HOLDER	SERVICEABLE	22.60	-
10	REAR BUMPER CLIPS @\$4.30	NECESSARY	43.00	43.00
1	REAR BUMPER REFLECTOR	NOT NECESSARY	130.50	-
	LESS 25% DISCOUNT		-	-136.97
			817.30	410.93
LABOUR				
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.		250.00	200.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		300.00	300.00
			550.00	500.00
GRAND TOTAL			1,367.30	910.93
RECOMMENDED COST OF REPAIRS				910.93

Report Ref No. CS/FCI17019412/Drbn2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.