

ASS. REC. BY:

REF:

CS/SM017017485/Arbn2

Special Instruction:

Surveyor: Adrian

**ASSIGNMENT (Office)**

From (Person): Sheng Wong of GND Date/Time: 11/02/07 1056am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLC 1627C Insured: PA 3116K

at Workshop m/s New Hock Teck Tel: 6747 9241

of Blk 1 Kaki Bukit Ave 6 #01-43

Policy No: Claim No: CM701703568 / NSW

Sum Insured: Excess:

Make of Veh: D.O.A. 11/02/07  
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time: 11/02/07 11:56am Person Contacted: Suby Vehicle: IN / OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	SLC 1627C - x
	PA 3116K - x
	Sent preli to Sheng

ASS. REC. BY: Adrian Ling

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLC1627C Yr Regn: 2016 MayType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis c.c. 1598Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 28447 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MRO53REH104547079Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 11/10/17Survey held at NHTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Sampo

Confirm LIS \$6200, 6 days  
Red: \$13,465.45, 68%

RECEIVED 12 DEC 2017

Date/Time, File Pass to?

☐ : Preli. Report1) typist☒ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 6Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

450

Report Format: TPLump Sum / I.B.I. (\$) 6200Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17019485/Arb

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 11-10-2017



Code : SMO

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PA 3116K	Veh. Inspected	SLC 1627C
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1703568/NSW	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	11/10/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	11/10/2017	Inspection Date	11/10/2017
Survey held at	NEW HOCK TECK MOTOR WORKSHOP BLOCK 1, KAKI BUKIT AVE 6 #01-43 SINGAPORE 417883		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## Nivitha (LKK Auto)

---

**From:** Wong, Shi Yi Shery <Shery.Wong@sompo.com.sg>  
**Sent:** Wednesday, 11 October, 2017 10:56 AM  
**To:** assignments@lkkauto.com  
**Cc:** Catherine Chong (LKK Auto); Henry, Irene James; Ngo, Sau Wei Shawn  
**Subject:** FW: SLC1627C CLAIMING AGAINST PA3116K DOA 11.10.17

Our Reference: CMTD1703568/NSW

Hi,

Kindly assign your motor surveyor to conduct motor survey of the mentioned (SLC1627C).

Please refer to the email correspondence below.

Best Regards

**Shery Wong**

Claims Division

D: 6329 5339 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

---

**From:** Admin . [mailto:admin@nhtmotor.com]  
**Sent:** Wednesday, October 11, 2017 10:53 AM  
**To:** Wong, Shi Yi Shery  
**Cc:** Henry, Irene James; Ngo, Sau Wei Shawn; reena@nhtmotor.com  
**Subject:** SLC1627C CLAIMING AGAINST PA3116K DOA 11.10.17

Hi Shery

Please arrange for Marcus Chua of LKK.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1703568/NSW  
Our Ref: CS/SMO17019485/Arb

The Motor Claims Department  
SOMPO INSURANCE SINGAPORE PTE LTD

*Without Prejudice*

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO. SLC 1627C**


We thank you for the instruction on 11/10/2017.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11/10/2017 at the premises of M/s NEW HOCK TECK PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 19,665.45
Revised Estimate Amount	: S\$ 8,168.78
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

**Description of Damage:**

The vehicle sustained damages  
at the o/s body and undercarriage.



**Comments/ Present Status:**  
Damages Consistent.

Yours faithfully

ADRIAN  
Automotive Assessor

Best Regards,

*Sukyi*

**NEW HOCK TECK MOTOR PTE. LTD.**

1 Kaki Bukit Ave 6 Blk C #01-43 Autobay@Kaki Bukit S(417883)  
Tel: 6747 9241 Fax: 6741 7276

On October 11, 2017 at 8:19 AM "Wong, Shi Yi Shery" <[Shery.Wong@sompo.com.sg](mailto:Shery.Wong@sompo.com.sg)> wrote:

Our Reference: CMTD1703568/NSW

Your Reference: SLC1627C

Date: 11<sup>TH</sup> October 2017

**Without Prejudice**

**BY EMAIL ONLY**

**Attention:**

**M/S NEW HOCK TECK MOTOR**

**Accident involving SLC1627C and PA3116K on 11/10/2017**

Dear Sir

We refer to your Notice of Accident via email dated 11/10/2017.

Please be informed that Shawn is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

	<b>Motor Surveyor</b>	<b>Surveyor</b>	<b>Selection (Indicate as tick)</b>
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Ma Chin Fook (North area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

**Shery Wong**

Claims Division

D: 6329 5339 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

---

**From:** Admin . [<mailto:admin@nhtmotor.com>]

**Sent:** Wednesday, October 11, 2017 10:33 AM

**To:** Motor Survey

**Cc:** [reena@nhtmotor.com](mailto:reena@nhtmotor.com)

**Subject:** SLC1627C CLAIMING AGAINST PA3116K DOA 11.10.17

Hi Motor Claim Dept

Please send your list of surveyor for PRI.

Thank you.

Best Regards,

*Sukyi*

**NEW HOCK TECK MOTOR PTE. LTD.**

1 Kaki Bukit Ave 6 Blk C #01-43 Autobay@Kaki Bukit S(417883)  
Tel: 6747 9241 Fax: 6741 7276



## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9300J
Vehicle Details	
Vehicle No.:	SLC1627C
Vehicle to be Exported:	No
Intended De-registration Date:	11 Oct 2017
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	1ZRX557384
Chassis No.:	MR053REH104547079
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,589.00
Original Registration Date:	03 May 2016
First Registration Date:	03 May 2016
Transfer Count:	0
Actual ARF Paid:	\$19,589.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 May 2026
PARF Rebate Amount:	\$14,691.00
Intended COE Rebate Details	
COE Expiry Date:	02 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,300.00
COE Rebate Amount:	\$40,480.00
<b>Total Rebate Amount:</b>	<b>\$55,171.00</b>

The information contained herein is correct as at 11 Oct 2017

MSME17135329 / SME Motor Pte Ltd - Kaki Bukit  
ENTRY DATE & TIME: 11/10/2017 16:45

## SINGAPORE ACCIDENT STATEMENT

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report 11/10/2017 16:45  
Date Of Accident 11/10/2017 08:10  
Exact Location Of Accident JALAN EUNOS  
Country/State of Loss SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number SLC1627C  
**Insured/Policyholder**  
Name Of Registered Owner JEE TAI HAI  
NRIC No S1749300J  
Email Address NOEMAIL  
Mobile Phone No (LOCAL) +65-94381450  
Alternative Phone No OFFICE-94381450

**Vehicle Particulars**

Manufacturer TOYOTA  
Model ALTIS

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

**Insurance Company**

Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE. LTD.  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number D17MTPV01006301  
Cover Note Number

**Driver**

Name of Driver JEE TAI HAI  
NRIC No S1749300J  
Date Of Birth 25/04/1966  
Occupation INDOOR  
Date Of Driving Pass 30/05/1990  
Driving Experience 27 YEARS AND 4 MONTHS  
Gender MALE  
Mobile Number (LOCAL) +65-94381450  
Fax Number  
Contact Number OFFICE-94381450  
EMail Address NOEMAIL

Address BLK 842D TAMPINES STREET 82 #06-62  
 Postcode 524842  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

I WAS STOPPED AND STATIONARY AT JALAN EUNOS ON SECOND LANE OF 5 LANES. VEHICLE B AT MY RIGHT SIDE WHEN TURNED RIGHT, THE REAR PORTION SWIPE MY VEHICLE RIGHT PORTION AND CAUSED DAMAGES. I WISH TO LODGE REPORT FOR CLAIM AGAINST VEHICLE B.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number PA3116K  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE B  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**Details of Witness**

Name  
 Phone Number  
 Email Address

## Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stopped and stationary at Jalan Eunos on 2nd lanes of 5 lanes.

Veh "B" at my right side when turned right, the rear portion swiped my veh right portion and caused damages.

I wish lodge report for claim against veh "B".

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

*Simon*

*Simon*

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

KIEW HOCK TECK



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

AO LINN LKK  
SOMPO

JEE TAI HAI

13/10/2017

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

Accident date: 11/10/2017

Estimated repair cost for vehicle no: SLC1627C TOYOTA ALTIS 1.6 A '16

TP Sampo

Janice

MROS3REH104547079

S/n	Qty	Items	U/price	Amount
1	1	Front R/H Head Lamp LED <i>lt</i>		<u>\$2,816.10</u> 1712
2	1	Front Bumper <i>torn</i>		\$481.10 ✓
3	10	Front Bumper Clip <i>m</i>	\$6.50	\$65.00 30 ✓
4	1	Front R/H Bumper Side Retainer <i>m</i>		\$132.25 ✓
5	1	Front R/H Fender <i>Dented</i>		\$561.60 ✓
6	1	Front R/H Fender Vvti Logo <i>NOC</i>		\$121.35 ✓
7	1	Front R/H Fender Cowling <i>Deformed</i>		\$183.10 ✓
8	10	Front R/H Fender Cowling Clip <i>m</i>	\$6.50	\$65.00 30 ✓
9	1	Front R/H Door <i>Dented</i>		\$978.30 ✓
10	2	Front R/H Door Frame Sticker <i>mr</i>	\$121.20	\$242.40 60 (50) ✓
11	1	Front R/H Door Side Mirror Assy <i>cracked</i>		\$987.30 ✓
12	1	Front R/H Door Side Mirror Cover <i>3mm</i>		\$83.20 +
13	1	Front R/H Door Side Mirror Signal Lamp <i>3mm</i>		\$83.10 +
14	1	Front R/H Rim <i>lt</i>		\$550.00 ✓
15	1	Front R/H Tyre <i>4mm</i>		\$1,180.00 +
16	1	Front R/H Lower Arm <i>Set</i>		\$374.25 ✓
17	1	Front R/H Knuckle Arm <i>Set</i>		\$391.90 ✓
18	1	Front R/H Knuckle Arm Bearing <i>m</i>		\$174.55 ✓
19	1	Front R/H Shock Absorber <i>Set</i>		\$311.40 ✓
20	1	Front R/H Drive Shaft <i>4mm</i>		\$1,718.85 +
21	1	Front Steering Rack <i>Set</i>		\$1,712.40 ✓
22	1	Front Crossmember <i>Not m</i>		\$1,763.50 +

8181.5

S.N. 60

Subtotal :- \$14,976.65

6136.12

## Labour charges

To remove & refit front R/H door, glass, lock, gear motor, trim board & frame sticker	<del>\$180.00</del> 80
To remove & refit front R/H undercarriage	<del>\$380.00</del> 220
To remove & refit front R/H drive shaft, steering rack & crossmember	<del>\$550.00</del> 150
To check wheel alignment	<del>\$150.00</del> 80
To check wiring	<del>\$100.00</del> 30
Tuff kote	\$150.00 X
Towing fee	1560 \$100.00 X
Panel beating	<del>\$1,600.00</del> 400
Spray painting	<del>\$1,600.00</del> 600

Subtotal :- \$4,810.00

Total:- \$19,665.45

total: 7756.12 19786.65  
c/s: 6.2K.  
06 days

6.2K

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17019485/Arbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 18-12-2017



Code : SMO

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PA 3116K	Veh. Inspected	SLC 1627C
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1703568/NSW	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	11/10/2017

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104547079	Colour	BLUE
Odometer	28447	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	11/10/2017	Inspection Date	11/10/2017
Survey held at	NEW HOCK TECK MOTOR WORKSHOP BLOCK 1, KAKI BUKIT AVE 6 #01-43 SINGAPORE 417883		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 1627C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT R/H HEAD LAMP LED	CUT	2,816.10	1,712.00
1	FRONT BUMPER	TORN	481.10	481.10
10	FRONT BUMPER CLIP @\$6.50	NECESSARY	65.00	30.00
1	FRONT R/H BUMPER SIDE RETAINER	NECESSARY	132.25	132.25
1	FRONT R/H FENDER	DENTED	561.60	561.60
1	FRONT R/H FENDER VVTI LOGO	NECESSARY	121.35	121.35
1	FRONT R/H FENDER COWLING	DEFORMED	183.10	183.10
10	FRONT R/H FENDER COWLING CLIP @\$6.50	NECESSARY	65.00	30.00
1	FRONT R/H DOOR	DENTED	978.30	978.30
1	FRONT R/H DOOR SIDE MIRROR ASSY	CRACKED	987.30	987.30
1	FRONT R/H DOOR SIDE MIRROR COVER	NOT NECESSARY	83.20	-
1	FRONT R/H DOOR SIDE MIRROR SIGNAL LAMP	NOT NECESSARY	83.10	-
1	FRONT R/H RIM	CUT	550.00	550.00
1	FRONT R/H TYRE	NOT NECESSARY	1,180.00	-
1	FRONT R/H LOWER ARM	BENT	374.25	374.25
1	FRONT R/H KNUCKLE ARM	BENT	391.90	391.90
1	FRONT R/H KNUCKLE ARM BEARING	NECESSARY	174.55	174.55
1	FRONT R/H SHOCK ABSORBER	BENT	311.40	311.40
1	FRONT R/H DRIVE SHAFT	NOT NECESSARY	1,718.85	-
1	FRONT STEERING RACK	BENT	1,712.40	1,712.40
1	FRONT CROSSMEMBER	NOT NECESSARY	1,763.50	-
	LESS 25% DISCOUNT		-	-2,182.88
			14,734.25	6,548.62
<b><u>SPECIAL NETT ITEMS</u></b>				
2	FRONT R/H DOOR FRAME STICKER @\$121.20 (SN)	NECESSARY	242.40	60.00
			242.40	60.00
<b><u>LABOUR</u></b>				
	TO REMOVE & REFIT FRONT R/H DOOR, GLASS, LOCK, GEAR MOTOR, TRIM BOARD & FRAME STICKER.		180.00	80.00
	TO REMOVE & REFIT FRONT R/H UNDERCARRIAGE.		380.00	220.00
	TO REMOVE & REFIT FRONT R/H DRIVE SHAFT, STEERING RACK & CROSSMEMBER.		550.00	150.00
	TO CHECK WHEEL ALIGNMENT.		150.00	80.00

Report Ref No. CS/SMO17019485/Arbn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.	NOT NECESSARY	150.00	-
	TOWING FEE.	NOT NECESSARY	100.00	-
	PANEL BEATING.		1,600.00	400.00
	SPRAY PAINTING.		1,600.00	600.00
			4,810.00	1,560.00
	GRAND TOTAL		19,786.65	8,168.62
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,200.00

Report Ref No. CS/SMO17019485/Arbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.