



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

General Details

Involving
TPVD NISSAN NV200-1.5 D L ABS AIRBAG 2WD 6DR (M) (GBC5401D)

Date of Loss
September 23, 2017

Time of Loss
21.10

Loss Description
SJZ6111T (INSD) C/W GBC5401D (TP)

Comment

Workshop Details

Total Rebate Amount

Nett Loss Amount
\$0.00

Assigned Workshop
LKK AUTO CONSULTANTS PTE LTD (TP)

Target Date of Completion *

Days of work completion *



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Vehicle & Driver Details

Vehicle Registration#
GBC5401D

Registration State
SINGAPORE

Mileage
113337

Purchase Date
mm/dd/yyyy

Registration Date *
12/26/2012

Age of Vehicle
4

CATEGORY	Manufacturing Year
POLICY INFORMATION	
ASSESSMENT INFORMATION	2011

CATEGORY	Make
POLICY INFORMATION	TPVD NISSAN

CATEGORYModel

POLICY INFORMATIONNV200-1.5 D L ABS AIRBAG 2WD 6DR (M)

ASSESSMENT INFORMATIONNV200-1.5 D L ABS AIRBAG 2WD 6DR (M)

CATEGORYType

POLICY INFORMATION

ASSESSMENT INFORMATION

CATEGORYType of Paint

POLICY INFORMATION

ASSESSMENT INFORMATION

CATEGORYChassis No

POLICY INFORMATION

ASSESSMENT INFORMATIONVSKYBAM20U0033404

CATEGORYEngine No

POLICY INFORMATION

ASSESSMENT INFORMATIONK9KF276D126733

CATEGORYEngine Capacity

POLICY INFORMATION

ASSESSMENT INFORMATION1461

CATEGORYSum Insured



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Detailed Assessment

Inspection Date *

10/16/2017



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Age of Tyres

Front Tyre Size

175/50R14

Front left side

ROADSTONE 6mm

Front right side

ROADSTONE 6mm

Spare wheel

Rear Tyre Size

175/50R14



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Discount%

30

Salvage%

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Save

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

	
1	
1	
FRONT BUMPER	
Repair	
0	
0	
0	
0	
0	
Deny	
	
☐	
	

2

10

FRONT BUMPER CLIPS

Necessary

5

30

35

Reviewing



Labour

Add

Approve

Deny



1

LABOUR TO FACILITATE REPAIR

200

0

0

Reviewing



2

TO RESPRAY AFFECTED AREAS

200

0

0

Reviewing





Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount
\$435.00

CATEGORY	Spare Parts
ESTIMATE	\$35.00
REVISED AMOUNT	\$35.00

CATEGORY	Labour
ESTIMATE	\$400.00
REVISED AMOUNT	\$400.00

Submit for Review

