

Edwin. Cairn @ cyclecam.sg

ASS. REC. BY: Surveyor REF: CS/SPF17019512/Tlg/012 Special Instruction:

ASSIGNMENT (Office)

From (Person): Abdul Rahman of SPF Date/Time: 9/10/17

Estimated Cost: _____ Bill to: _____

OD ☒ TD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJW 7943T Insured: Qx 305T

at Workshop m/s: Cycle & Camiarex Tel: 65684501

of 209 Pandan Gardens, 609339

Policy No: _____ Claim No: AEMD/105/009/2017/137

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A: 3/10/2017
(Client's Record)

CA / REV / REP. / REV 24 HRS: 'wp' H.O.D. Endorsement: _____

Date/Time: 10/10/17 9:20am Person Contacted: Don Bong Vehicle IN/OUT: ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SJW 7943T-X</u>
	<u>Qx 305T-X</u>

Similar *Tanpin*


REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SSW7943T Yr Regn: 2010 April
Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Kia Forte C.C. 1591
Colour: white A/C: Insured / Std / NI / NA
Sp. Reading: 115 223 Ti/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: ICNA FW611M45 223789
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/45K17
R: ~ ~
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front: _____ Rear: _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 8/12/17 @ 1730
Survey held at: O&C Pandan Garden
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/4/18

\$1867, 3 days email to hi. (Ref \$7418, 56%)

RECEIVED 23 APR 2018

Date/Time, File Pass to?

11/3/18 *dyas*

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) 1867

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Invs (\$) ☐ : Weekend (\$)

Survey Fee:

Transportation: _____

_____ \$ + RS _____ \$

) Photos

) Others

TOTAL

200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION			Ref : CS/SPF17019512/T1qb	
ACCIDENT CLAIM SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333			Date : 11-10-2017 Code : SPF	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 305T	Veh. Inspected	SJW 7943T	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2017/137	Excess (\$)	0.00	
Assign From	ABDUL RAHMAN	Assign Date	11/10/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/10/2017	Inspection Date	11/10/2017	
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref : SJW7943T

Our Ref : AEMD/105/009/2017/137

Date : 9 Oct 2017

Tel: 64784840

Fax: 64784848

LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir/Madam,

ACCIDENT ON 3 OCTOBER 2017 INVOLVING GOVT VEHICLE QX305T AND OTHER VEHICLE SJW7943T

We refer to the above matter.

- 2 Kindly arrange for an Inspection of vehicle no. **SJW7943T** at Cycle & Carriage Automotive Pte Ltd of 209 Pandan Gardens, Singapore 609339.
- 3 For appointment kindly contact Edwin Caina at DID: 65684501. *9:20am*
- 4 Estimates were provided by the workshop.
- 5 Thank you.

Yours faithfully,

Abdul Rahman
Accident Claims Officer
for ASST DIRECTOR

A FORCE FOR THE NATION

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/10/2017 15:56
Date Of Accident	03/10/2017 19:00
Exact Location Of Accident	PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW7943T
Insured/Policyholder	
Name Of Registered Owner	WONG EI LI
NRIC No	S8006931F
Email Address	WONG_EILI@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96844887
Alternative Phone No	OTHERS-96844887
Vehicle Particulars	
Manufacturer	KIA
Model	CERATO FORTE KOUP-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100204571
Cover Note Number	
Driver	
Name of Driver	WONG EI LI
NRIC No	S8006931F
Date Of Birth	02/03/1980
Occupation	INDOOR
Date Of Driving Pass	13/03/2002
Driving Experience	15 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96844887
Fax Number	
Contact Number	OTHERS-96844887
Email Address	WONG_EILI@YAHOO.COM.SG

Address	BLK 160A PUNGGOL CENTRAL #12-99
Postcode	821160
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PUNGGOL N.P.C
Police Station Address	ROAD: 21A TEBING LANE , POSTCODE: 828837 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX305T
Vehicle Make/Model/Colour	COROLLA ALTIS 1.6/WHITE
Details Of Properties	
Name of Driver	HAIRI BIN ANUAR
NRIC/Passport Number	
Contact Number	90032413
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature


Date & Time:

4/10/17, 3.10pm


Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

P15



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer To Police Report .

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20171003/2207

1 of 3

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

Report No. T/20171003/2207

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/10/2017 22:47		Vide Report No.:		Station District No.: 70	
Informant's Particulars					
Name of Informant: WONG EI LI			Address: APT BLK 160A PUNGGOL CENTRAL #12-99 SINGAPORE 821160		
ID Type / ID No.: NRIC NO / S8006931F			Contact No.: Home/Office:		Mobile: 96844887
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 37	Date of Birth: 02/03/1980	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: HR			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Police Vehicle	Drink Drive: No	Date/Time of Accident: 03/10/2017 19:00	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY Along PIE lane 1				
Weather: Raining		Road Surface: Wet		Road Speed
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QX305T	Car	TOYOTA	COROLLA ALTIS 1.6 AUTO	White	No Damage	3
SJW7943T	Car	KIA	CERATO FORTE Koup 1.6 AT SX ABS D/AB SR	White	Slightly Damaged	0



Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

Report No. T/20171003/2207

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJW7943T	AIG ASIA PACIFIC INSURANCE PTE. LTD.	2100204571	20/04/2017	19/04/2018

Brief Details.

On 03/10/2017 at about 1900hrs, I was driving my vehicle SJW7943T along PIE at lane 1. There was a vehicle in front of me that had already slowed down as such I applied brake and slows down my vehicle. Subsequently, I felt an impact from the rear of my vehicle. As such I stationary stopped my vehicle and make a check.

I then discovered that I had an accident with a police vehicle QX305T. I then spoke to the officer and he informed me the brake is not working. I saw there were at least three officers including the driver in the vehicle. He then asked me to move my vehicle forward so he can check the damages. We exchanged particulars and took photo of the scene. We were unable to verify the damages as it was raining as such we agreed to leave the scene and check for damages afterwards.

I then drove my vehicle back home. After I parked my vehicle, I discovered that there were damages at the rear of my vehicle. I then contacted the police officer who drove the vehicle and he informed me to lodge a traffic accident report within 24 hours.



**SINGAPORE
POLICE FORCE**



T/20171003/2207

3 of 3

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

Report No. T/20171003/2207

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 IVIN ONG HONG CHUAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / DDGVT /

Sr Staff Sgt CHONG GUAN FATT

Contact No.: 65476198

Signature Of Informant:

Date/Time:

03/10/2017 22:47

Classification Of Case:

Authentication Stamp

NP168



HOTLINE TEL: (65) 6419 3000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

KIA AUTO PROTECTOR

CERTIFICATE NO. 2100204571-07000

OWN DAMAGE EXCESS S\$1000.00 (1)
WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

SUM INSURED Market Value
INSURING WITH COE/PARF No
SJW7943T

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

Wong Ei Li (Huang Yuning)

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

20 Apr 2017

4) DATE OF EXPIRY OF INSURANCE

19 Apr 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *
SUBJECT TO AGE CONDITION :35 years old and above

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business. The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / KIA AUTHORISED REPAIRERS

1. Cycle & Carriage Pandan Gardens Service Centre - 209 Pandan Gardens (Tel: 6568 4555)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. Ethoz - 30 Bukit Batok Cres (Tel: 66547777)

4. Glass-Fix - 32 Ubi Ave 3 (Tel: 62780887) - For windscreen only 5. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560)

6. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110) 7. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892)

8. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336) 9. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE 15 Days Replacement Car only for repairs at C & C - Refer to policy wordings for details

NAMED DRIVER NA

HIRE PURCHASE COMPANY DBS BANK LTD
/ EMPLOYER'S LOAN

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 28 Mar 2017

AIG Asia Pacific Insurance Pte. Ltd.

500710-050
C & C FULCO-CORP SALES
22 UBI ROAD 4
FULCO BUILDING
SINGAPORE 408617
ANSP - MOTOR

AUTHORISED REPRESENTATIVE

ORIGINAL

SSCZSS

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S8006931F**
 Name: **WONG EI LI (HUANG YUNING)**

Birth Date: 02 Mar 1980
 Issue Date: 04 Mar 2003

000255720G

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE
 IDENTITY CARD NO. **S8006931F**

WONG EI LI
 (HUANG YUNING)
 黄于宁

RACE: CHINESE
 Date of birth: 02-03-1980 Sex: F
 Country of birth: SINGAPORE

4661584

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	13 Mar 2002

NP 429A


Licence No: S8006931F

4661584

S8006931F

Date of issue: 27-12-2010

Address: APT BLK 160A PUNGGOL CENTRAL #12-99 SINGAPORE 821160



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ms Wong Ei Li (huang Yuning)	Cust No/Name /Ms Wong Ei Li (huang Yuning)
Blk 160a Punggol Ctr1	Reg No/Reg Date SJW7943T / 20/04/201
#12-99	Date In/Mileage / 0
Singapore 821160	Chassis No KNAFW611MA5223789
Contact No Mobile: 96844887	Engine No G4FCAH381582
	Make/Model KIA/FORTE KOUP 1.6A SX SR
	Colour/Trim UD Clear White / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	05/10/2017/ 18:48	QUE	261/ Edwin Caina	16024		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							550 1100.00
RENEW & RE-ALIGN RR DAMAGED PORTION:							
RENEW RR BUMPER							
REPAIR RR END PNL							
E PNT98000							420 840.00
RESPRAY RR BUMPER & RR END PNL							
E PNT88000							120 150.00
REMOVE & REFIT SPARETYE BOARD,TRIM,CARPET TO FACILITATE REPAIR							30 50.00
A 54900099							200.00
CHECK WIRING & ELECTRICAL SYSTEM							
A 10028901							80 100.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							20 30.00
E PNT88000							
REMOVE & REFIT REVERSE SENSOR							
M SUNDRY							
Sundries							
M COVER-RR BUMPER				1.00	607.00	00.00	607.00
M COVER-RR BUMPER,CTR				1.00	381.00	00.00	381.00
M ABSORBER-REAR BUMPER ENERGY ?				1.00	156.00	00.00	156.00
M RAIL ASSY-REAR BUMPER ?				1.00	559.00	00.00	559.00
M BRACKET ASSY-RR BUMPER SIDE,LH?				1.00	23.00	00.00	23.00
M BRACKET ASSY-RR BUMPER SIDE,RH?				1.00	23.00	00.00	23.00

SURVEYOR NAME: Taufik 97495744

SURVEYOR SIGNATURE:

DATE: 8/12/17 @ 1730

REMARKS: 3 days

Confirm & accepted by


 Resony new parts

 sure (WhatsApp)

 7% GST on **Nett** 4,219.00
 295.33
Total Payable 4,514.33

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

Emailed
15/12/17.
8.30pmVEHICLE NO : SJW 7943TMODEL : Forte K2 Koup 1.6 SXWIP : 16024LKK
Tandebh -

Material	:	\$	<u>447.00</u>
Labour	:	\$	<u>1,420.00</u>
Sub-Total	:	\$	<u>1,867.00</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>1,867.00</u>
GST 7%	:	\$	<u>130.69</u>
Grand Total	:	\$	<u>1,997.69</u>
Finalise By/Date : <u>Loi on 15/12/17</u>			

REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 3 WORKING DAYS + 2 Days (1 Weekends)
 + - Days (Public holiday)
 = 5 Days

TP claim QX 305 TClaim GIA / LTA fee \$ -Claim Loss of Use / Loss of Rental = - days x \$ - /Day = \$ -Claim Medical Fee / Others = \$ -



CYCLE & CARRIAGE


CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ms Wong Ei Li (huang Yuning)	Cust No/Name /Ms Wong Ei Li (huang Yuning)
Blk 160a Punggol Ctrl	Reg No/Reg Date SJW7943T / 20/04/2010
#12-99	Date In/Mileage 08/12/2017/ 115223
Singapore 821160	Chassis/Package KNAFW611MA5223789
Contact No Mobile: 96844887	Engine No G4FCAH381582
	Make/Model KIA/FORTE KOUP 1.6A SX SR
	Colour/Trim UD Clear White / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
CSM00081	Cash	14/12/2017/ 10:45	TLE	261 / Edwin Caina	16024	81349097

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW & RE-ALIGN RR DAMAGED PORTION: RENEW RR BUMPER CENTRE REPAIR RR BUMPER				✓ 550.00
E PNT88000 REMOVE & REFIT SPARETYE BOARD, TRIM, CARPET TO FACILITATE REPAIR				✓ 120.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				✓ 30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓ 200.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR				✓ 80.00
M SUNDRY Sundries				✓ 20.00
Z TEXT TP CLAIM-POLICE VEH Qx 305 T SURV:TAUFIKH 08.12.2017 DOA:03.10.2017 3 DAYS				✓ 420.00
S SPECIALISTJOB RESpray REAR BUMPER				✓ 381.00
X COVER-RR BUMPER,CTR	1.00	✓ 381.00	00.00	381.00
X LAMP ASSY-LICENSE PLATE,RH	1.00	33.00	00.00	de 33.00
X LAMP ASSY-LICENSE PLATE,LH } Supp.	1.00	33.00	00.00	de 33.00
"Guarantee your warranty, maintain with Cycle & Carriage."				

Parts	447.00	Nett	1,867.00
Labour	980.00	7% GST on	130.69
Standard Menu	0.00		
Specialist Job	420.00	Total Payable	1,997.69
Diagnostics Job	0.00	Paid	0.00
Sundry/Others	20.00	Total Due	1,997.69
Total (w/o GST)	1,867.00		

Payment should be made strictly by cash, NETS or credit cards. Thank you.
 Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



INSURANCE CO. : Singapore Police Force

Supplementary Parts For Registration No.: SJW 7943 T

<u>Material</u>		<u>Cost (\$)</u>
1	Lamp assy-License plate, RH	33.00
2	Lamp assy-License plate, LH	33.00

Total Materials		66.00
Total Taxable		66.00
7% GST		4.62
Grand total		<u>70.62</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD


LOI AI TING
CUSTOMER SERVICE ADVISOR
DID : 6568 45556 / 6568 4501
FAX : 6567 5258 / 6565 1240

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF17019512/T1qbn2

ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE)

1 MOUNT PLEASANT ROAD

BLK 8 OLD POLICE ACADEMYSINGAPORE 298333

Date : 24-04-2018



Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 305T	Veh. Inspected	SJW 7943T
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2017/137	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	09/10/2017

2. Vehicle Particulars & Condition

Make & Model	KIA FORTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	KNAFW611MA5223789	Colour	WHITE
Odometer	115223	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	DUNLOP	6 mm
L/H Front Tyre	225/45 R17	DUNLOP	6 mm
R/H Rear Tyre	225/45 R17	DUNLOP	6 mm
L/H Rear Tyre	225/45 R17	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	03/10/2017	Inspection Date	08/12/2017
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 7943T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER-RR BUMPER (SN)	TO REPAIR SEE LABOUR	607.00	-
1	COVER-RR BUMPER CTR (SN)	CUT	381.00	381.00
1	ABSORBER-REAR BUMPER ENERGY (SN)	NOT NECESSARY	156.00	-
1	RAIL ASSY-REAR BUMPER (SN)	NOT NECESSARY	559.00	-
1	BRACKET ASSY-RR BUMPER SIDE,LH (SN)	NOT NECESSARY	23.00	-
1	BRACKET ASSY-RR BUMPER SIDE,RH (SN)	NOT NECESSARY	23.00	-
1	SUNDRIES (SN)	NECESSARY	30.00	20.00
1	LAMP ASSY-LICENSE PLATE,RH (ADDITIONAL)(SN)	DEFORMED	33.00	33.00
1	LAMP ASSY-LICENSE PLATE,LH (ADDITIONAL)(SN)	DEFORMED	33.00	33.00
			1,845.00	467.00
LABOUR				
	RENEW & RE-ALIGN RR DAMAGED PORTION: RENEW RR BUMPER. REPAIR RR END PNL.INCLUSIVE OF THE REPAIR OF COVER-RR BUMPER.		1,100.00	550.00
	RESPRAY RR BUMPER & RR END PNL.		840.00	420.00
	REMOVE & REFIT SPARETYE BOARD,TRIM,CARPET TO FACILITATE REPAIR.		150.00	120.00
	CHECK WIRING & ELECTRICAL SYSTEM.		50.00	30.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		200.00	200.00
	REMOVE & REFIT REVERSE SENSOR.		100.00	80.00
			2,440.00	1,400.00
GRAND TOTAL			4,285.00	1,867.00
RECOMMENDED COST OF REPAIRS				1,867.00

Report Ref No. CS/SPF17019512/T1qbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.