

A/S. REC. BY:

REF: CS/MSG17019686 / Arb2

Special Instruction:

Meimien

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSG

Date/Time: 13/10/17 @ 8:24am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 4373 H

Insured:

GBB 9243 Y

at Workshop no/s

Peoples Vehicle Recovery Service

Tel:

G743 8552

of Blk 3023A Ubi Rd 1 # 01-60, 408717

Policy No: MSD/VCT/17-001967

Claim No:

MSCV/17-001579

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 12/10/2017

CA / REV / REP. / REV 24 HRS

wp'

H.O.D. Endorsement

Date/Time: 13/10/17 @ 9:00am

Person Contacted:

jimmy

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

GBC 4373 H-X

GBB 9243 Y-NBA/MSG15004952/e1-D.O.A:22/03/2015

Est. Repairs:

days

Res.: Yes or No

D.O.A.

D.O.I.

16/10/17.

Lum Sum:

%

3 Val.: Yes or No

Survey held at

Paya Ubi.

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP MSG16 People Recovery.

23/10

Adrian confirmed LE \$850f and 3 days with repairer. (Red 5050.30, 85%)

RECEIVED 02 MAY 2018

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

2

1)

☐

: Final Report

Resurvey No. of Trip:

-

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

Survey Fee:

200

Transportation:

10

☐

: Interview (\$

Photos

☐

: Tech. Invs (\$

Others

☐

: Weekend (\$

TOTAL

210

Report Format:

TP

Lump Sum / I.B.I. (\$

850f