

ASS. RE. BY:

REF:

CS/SPF17019741/Titber

Special Instruction:

Survive

Tawfik

ASSIGNMENT (Office)

From (Person):

Abdul Rahman

of

SPF

Date/Time:

12.10.2017

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SKZ 8910D

Insured:

TP 1104G

at Workshop m/s

Performance

Tel:

6319 0174

of

303 Alexandra Road

Policy No:

Claim No:

AEMD/105/009/2017/TP1104G

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11.10.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

17.10.2017 @ 10:30am owner writing

H.O.D. Endorsement

Date/Time: 13.10.2017 5:04pm

Person Contacted:

Caroline

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

Do Not Finalize

SKZ 8910D - X

TP 1104G - X

Not sent in for repair according to menner.

Submit preli advise

Smileyer

Taufm

REF: SPF

ASSIGNMENT

From: Date: 17.10.2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKZ 8910D

at Workshop m/s Performance

of 303 Alexandra Rd

Insured:

Policy No.


Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Mefina

(Policy Condition)

10:30am
owner waitingRemark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAQ Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKZ 8910D Yr Regn: 2015 Nov

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 116D c.c. 1496

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 22682 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WB41V7201 DV250049

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 24

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/8 RE-OPEN AMEND THE REPAIR RANGE TO 3500 - 4500

RECEIVED 09 MAY 2018

Repair range: \$2500-\$3500 Celine 21/07/2020

4 Weekdays

1 Weekend

total 5

Reopen input repair range/days

Date/Time, File Pass to?

1) 9/5 Typist

Date/Time, File Return to?

2)

☒ : Preli. Report☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: —

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : TP

Lump Sum / I.B.I: (\$)

250

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF17019741/T1tb		
ACCIDENT CLAIM SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333		Date : 13-10-2017		
		Code : SPF		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	TP 1104G	Veh. Inspected	SKZ 8910D	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2017/TP1104G	Excess (\$)	0.00	
Assign From	ABDUL RAHMAN	Assign Date	12/10/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/10/2017	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref: SKZ8910D

Our Ref: AEMD/105/009/2017/TP1104G

Date: 12 October 2017

Tel: 64784840

Fax: 64784848

LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir/Madam,

ACCIDENT ON 11 OCTOBER 2017 INVOLVING GOVT VEHICLE TP1104G AND OTHER VEHICLE SKZ8910D

We refer to the above matter.

- 2 Please assist to arrange for a PRI of Vehicle no. **SKZ8910D** at **Performance Motors Ltd** of 303 Alexandra Road, Singapore 159941.
- 3 For appointment kindly contact Ms Caroline at Tel: 63190174.
- 4 Estimates were provided by the workshop.
- 5 Thank you.

Yours faithfully,

Abdul Rahman
Accident Claims Officer
for Assistant Director

A FORCE FOR THE NATION

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/10/2017 16:22
Date Of Accident	11/10/2017 11:50
Exact Location Of Accident	ALONG CLEMENTI RD TWDS WESTCOAST HIGHWAY NEAR BUS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ8910D
Insured/Policyholder	
Name Of Registered Owner	LOO JUN MUN TRSITAN
NRIC No	S8933956A
Email Address	TRISTANLOO@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96263641
Alternative Phone No	OFFICE-64126118

Vehicle Particulars

Manufacturer	BMW
Model	116D
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1690256
Cover Note Number	

Driver

Name of Driver	LOO JUN MUN TRSITAN
NRIC No	S8933956A
Date Of Birth	01/10/1989
Occupation	INDOOR
Date Of Driving Pass	22/06/2010
Driving Experience	7 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96263641
Fax Number	
Contact Number	OFFICE-64126118
EMail Address	TRISTANLOO@YAHOO.COM.SG

Address	126B LORONG KISMIS
Postcode	598053
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	BUKIT TIMAH NPP
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	TP TOOK THE SD CARD, NO SD CARD TO UPLOAD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	TP1104G
Vehicle Make/Model/Colour	MOTORCYCLE WHITE
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF INJURED PERSON 1

Name	UNKNOWN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	TP1104G
Were seat belts worn?	
Was injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims;
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA, to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]

11/10/2017

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

MERINA CHIA SAN SAN
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 150941

[Signature]

11 OCT 2017

Sketch Plan



Sketch Plan Pg. 2

Describe Circumstances of the Accident

Refer to police report

Declaration

I/We declare the foregoing particulars are true in every respect.

MA

11/10/2017 15.40

Policyholder's Signature / Date & Time

Driver's Signature (# driver is not the policyholder) / Date & Time

MERINA CHIA SAN SAN
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Witnessed by Reporting Centre
Personnel

11 OCT 1952

Sketch Plan Pg. 3



**SINGAPORE
POLICE FORCE**



T/20171011/2089

1 of 3

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

Report No. T/20171011/2089

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/10/2017 14:23	Vide Report No.: D/20171011/0060	Station Diary No.: 10
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: LOO JUN MUN, TRISTAN			Address: 126B LORONG KISMIS SINGAPORE 598053	
ID Type / ID No.: NRIC NO / S8933956A			Contact No.: Home/Office: Mobile: 96263641	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 28	Date of Birth: 01/10/1989	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: IT CONSULTANT			Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 11/10/2017 11:50	Type of Location: Straight Road
Location: Along Road 1 CLEMENTI ROAD				
Along Clementi Road towards West Coast Highway, near busstop B22				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control:	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKZ8910D	Car	BMW	116D 5DR HATCHBAC K DSC LED	Blue	Slightly Damaged	0
TP1104G	Motorcycle	YAMAHA	Traffic Police bike	White		0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKZ8910D	AXA INSURANCE SINGAPORE PTE LTD	P1690256	27/11/2016	26/11/2017

Sketch Plan Pg. 4



**SINGAPORE
POLICE FORCE**



T/20171011/2089

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

2 of 3

Report No. T/20171011/2089

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LOO JUN MUN, TRISTAN	ID No.	S8933956A
Related Vehicle	SKZ8910D (Car)	Contact No.	96263641
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 11/10/2017 at about 1130hrs, I left Mindef (Bukit Gombak Camp) going to my work place located at 30 Science Park Road, I was driving my own car registration plate number SKZ8910D.

I drove along Clementi Road towards West Coast Highway and during which after the bridge of Clementi Road near to busstop B22, I noticed there was a construction work on the extreme right lane and behind the construction there was another vehicle red in colour, registration plate number SJA219M, Suzuki Swift trying to change his lane to the center lane.

Upon seeing it, I choose to slow down to prevent any accident, as such I felt an impact coming from the back of my vehicle. I step out and I saw 1 Traffic Police bike and the rider wearing white jacket lying down behind my car.

I wish to state that, later another Traffic Police came to scene and took my CCTV Car SD card from me for their investigation. A form NP 323 was issued to me.

Sketch Plan Pg. 5



SINGAPORE
POLICE FORCE



T/20171011/2089

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

3 of 3

Report No. T/20171011/2089

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /

Staff Sgt MUHAMMAD TAUFIQ BIN RAMLI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

11/10/2017 14:23

Officer In Charge Of Case:

TP / GIA /

Staff Sgt TANG SIEW PING

Contact No.: 65476430

Classification Of Case:

Authentication Stamp

NP158



Signature :

Singapore Police Force

SN 038



SINGAPORE POLICE FORCE
ACKNOWLEDGEMENT SLIP

Ref: Report No: D/2017/1011/0060

I, SSgt T08395 Syafiq
(Recipient's Name, NRIC or Passport No. / Rank and No.)

of TP HQ
(Address / Police Station / NPC / NPP)

hereby acknowledge receipt of the below mentioned items of:

- 1 1 X Strontium 32GB SD card
- 2 _____
- 3 _____
- 4 _____
- 5 _____
- 6 _____
- 7 _____
- 8 _____
- 9 _____
- 10 _____

from Loo Jun Mun, Tristan, S89 33956A
(Name, NRIC or Passport No. / Rank and No.)

of DBB Lorong Kismis
(Address / Police Station / NPC / NPP)

on 11/10/17 at 1245
(Date) (Time)

Witnessed by / * Handed over by:

(* Delete if applicable)

[Signature]
(Signature)

Loo Jun Mun, Tristan, S8933956A
(Name, NRIC or Passport No. / Rank and No.)

Received by:

[Signature]
(Signature)

S T8395- Syafiq
(Name, NRIC or Passport No. / Rank and No.)

Other Remarks: _____

POLICE DEPARTMENT

OFFICE NOTES

D/20171011/0060

IO Ridzan

Tel. 65476185

① Dodge Accident
report.

NP 364(94)

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159544
Tel. 63190528 (AfterSales)
63190533/930 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)Survey only
17/10 8 am
10.30

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

12 OCT 2017

Estimate No. : b1 44435
Date Estimated : 12/10/2017
Prepared By : Merina Chia San San

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -Loo Jun Mun, Tristan
126B Lorong Kismis

Singapore 598053

- ACCOUNT - 40000Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKZ8910D	V250049	27/11/2015	116d	0

DESCRIPTIONTo replace rear bumper including attachments etc and
to knock out dented area caused by accident

850. 1,700.00

To paint rear bumper

934 1,038.00

To replace rear exhaust silencer including alignment
system and conduct checks for leak.

451? 531.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct checks for
proper function.

150. 177.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150. 177.00

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230. 271.00

Sundries.

? 80.00

Total Labour 1: **3,974.00****PART NUMBER DESCRIPTION**

18308597035	REAR SILENCER
51127240912	REAR BUMPER CARRIER
51127371712	REAR BUMPER CENTRE GUIDE (M)
51127371751	REAR BUMPER TOWING EYE COVER PRIMED
51127371753	REAR BUMPER LH MOUNT
51127371754	REAR BUMPER RH MOUNT
51127429752	REAR BUMPER PANEL PRIMED
63267193294	NUMBER PLATE LIGHT LED
66202220666	PDC sensor
66206923000	DECOUPLING RING PDC TORQUE CONVERTE

QTY	PRIC	VALUE
1	864.80	? 864.80
1	375.90	bt ✓ 375.90
1	56.05	? 56.05
1	49.10	de ✓ 49.10
1	141.65	? 141.65
1	141.65	? 141.65
1	880.25	de ✓ 880.25
1	23.20	dis ✓ 23.20
2	363.05	? 726.10
4	4.95	neu ✓ 19.80

Total Parts : **3,278.50**

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770260, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 44435
Date Estimated : 12/10/2017
Prepared By : Merina Chia San San

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKZ8910D	V250049	27/11/2015	116d	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time 17/10/17	Excess S\$ _____
Surveyor's Name Taufik	Sign <i>Taufik</i>
Surveyor's Tel 97495749	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR ☒ Yes / No PML Yes / No _____	
Surveyor's E-mail taufik@lkkauto.com	
No. of Working Days Recommend 3 days	

Labour 1	:	3,974.00
Parts	:	3,278.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	507.68
Grand Total	:	7,760.18

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF17019741/T1tbe2

ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE)
1 MOUNT PLEASANT ROAD
BLK 8 OLD POLICE ACADEMY SINGAPORE 298333

Date : 15-05-2018



Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	TP 1104G	Veh. Inspected	SKZ 8910D
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2017/TP1104G	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	12/10/2017

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 116D	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WBA1V72010V250049	Colour	BLUE
Odometer	22686	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	PIRELLI	6 mm
L/H Front Tyre	205/55 R16	PIRELLI	6 mm
R/H Rear Tyre	205/55 R16	PIRELLI	6 mm
L/H Rear Tyre	205/55 R16	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	11/10/2017	Inspection Date	17/10/2017
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 8910D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	* CHECK	80.00	-
1	REAR SILENCER (SN)	* CHECK	864.80	-
1	REAR BUMPER CARRIER (SN)	BENT	375.90	375.90
1	REAR BUMPER CENTRE GUIDE (M) (SN)	* CHECK	56.05	-
1	REAR BUMPER TOWING EYE COVER PRIMED (SN)	DEFORMED	49.10	49.10
1	REAR BUMPER LH MOUNT (SN)	* CHECK	141.65	-
1	REAR BUMPER RH MOUNT (SN)	* CHECK	141.65	-
1	REAR BUMPER PANEL PRIMED (SN)	DEFORMED	880.25	880.25
1	NUMBER PLATE LIGHT LED (SN)	DISTORTED	23.20	23.20
2	PDC SENSOR (SN)	* CHECK	726.10	-
4	DECOUPLING RING PDC TORQUE CONVERTE (SN)	NECESSARY	19.80	19.80
			3,358.50	1,348.25
LABOUR				
	TO REPLACE REAR BUMPER INCLUDING ATTACHMENTS ETC AND TO KNOCK OUT DENTED AREA CAUSED BY ACCIDENT.		1,700.00	850.00
	TO PAINT REAR BUMPER.		1,038.00	934.00
	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK.	* CHECK	531.00	-
	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.		177.00	150.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS.		271.00	230.00
			-	-
			-	-
			-	-
			-	-
			-	-
			3,894.00	2,314.00
GRAND TOTAL			7,252.50	3,662.25

Report Ref No. CS/SPF17019741/T1tbe2



RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$2,541.25 NETT)			3,662.25
---	--	--	----------

Report Ref No. CS/SPF17019741/T1tbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.