

22/03/2002

ASS. PEC. BY:

REF:

09/FCL 7019904/T1rbet

Special Instruction:

condition

Surveyor:

Taufiq

ASSIGNMENT (Office)

From (Person):

W3 Wurne Jew

of

FCL

Date/Time:

16-10-2017 750pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SCJ 9807S

Insured:

SHA 9718D

at Workshop m/s

Falcon - Air

Tel:

6779 6663

of

No. 8 Pandan Loop (BKK/BK1)

Policy No:

Claim No:

017009752MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12-10-2017

CA / REV / REP. / REV 24 HRS

DB

H.O.D. Endorsement:

Date/Time:

16-10-2017 905am

Person Contacted:

Andy

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SCJ 9807S - X

SHA 9718D - NS / IN (1701) / MYBOM2

DO: 200617

Sent poli thru email

- (ase reopen to amend report
(Repair day))

✓ 5/6/18

05/06/18 1st closed date = 06/03/2018, Reopen by Kim becoe has to amend report.
(Repair day)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17019904/T1rbe2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 05-03-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9718D	Veh. Inspected	SCJ 9807S
Policy No.	D-15072702MFSH	Coverage (\$)	0.00
Claim No.	D17009752MFSH	Excess (\$)	0.00
Assign From	LURENE JAW	Assign Date	16/10/2017

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	ZSU600049616	Colour	BLACK
Odometer	60641	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/55 R18	MICHELIN	6 mm
L/H Front Tyre	235/55 R18	MICHELIN	6 mm
R/H Rear Tyre	235/55 R18	MICHELIN	6 mm
L/H Rear Tyre	235/55 R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	12/10/2017	Inspection Date	17/10/2017
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 8 PANDAN LOOP SINGAPORE 128226		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	15 Working Days
-------------------------------------	-----------------