

ASS. REC. BY:

REF: CS/FWD17019997/Gg b n2

Special Instruction:

Servicitor:  
M. M. M.

Gid.

## ASSIGNMENT (Office)

From (Person): Clara Li of FWD Date/Time: 17-10-2017 5:02pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKW 6482B Insured:

at Workshop m/s Trans Eurokars Tel: 4618 5991

of 5 Ubi Close

Policy No: YNPV7016-00000110 Claim No: 1207 00 006571

Sum Insured: Excess: \$300.00

Make of Veh: D.O.A. 09.10.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

24.10.2017 @ after 10am

H.O.D. Endorsement:

Date/Time: 19.10.2017 9:38am Person Contacted: Eric Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKW 6482B-X
15/10/17 @ 9.59am	revert to Clara Li via M. M. M.
15/10/17 @ 10.03am	Clara Li informed C/A via M. M. M. & Ex: \$300.
15/10/17 @ 11.10am	Informed Hon C/A & Ex: \$300 by email.
04/12/17 @ 9.26am	confirmed with Catherine final fig \$3350.63, 3 days by email. (led \$4558.82, 58%)

REF: FWD

## ASSIGNMENT

From: Date: 24/10/17

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SKW 6482 B

at Workshop m/s TransEurokars

of 5 ubi close

Insured:

Policy No.

Claims No.

Sum Insured: Excess: \$300.00

(Client's Record)

Make of Veh:

After 10 am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$70k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKW 6482 B Yr Regn: 09 Nov 2015

Type: M.Carp / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda-2 C.C. 1496

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 2302 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM 60J2HAA. 01100598

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STDA/Rim or

Tyre Size: F: 185/60 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 23 JAN 2016

Date/Time, File Pass to?

1) 23/11/17 Trans

Date/Time, File Return to?

2)

Report Format: MCF-00

Lump Sum / I.B.I.: (\$ 3350.63)

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee: Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

200  
10

210



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FWD SINGAPORE PTE LTD		Ref : CS/FWD17019997/Gqb		
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4 SINGAPORE 038986		Date : 19-10-2017		
		Code : FWD		
<b>1. Policy Particulars :- OWN DAMAGE</b>				
Insured Veh.		Veh. Inspected	SKW 6482B	
Policy No.		Coverage (\$)	0.00	
Claim No.	1201700006571	Excess (\$)	0.00	
Assign From	CLARA LI	Assign Date	17/10/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date		Inspection Date		
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 25 Oct 2017

**Preliminary Advice**

Vehicle No	: SKW6482B	Accident Date	: 09/10/2017
Make	: MAZDA 2	Policy No.	: PNPV2016-00000110
Assignment Date	: 24/10/2017	Excess	: S\$0.00
Date of Inspection	: 24/10/2017	Est. Duration of Repair	: 4.00
Inspection At	: TRANS EUROKARS PTE LTD NO. 5 UBI CLOSE, SINGAPORE SINGAPORE 408605		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,909.45
Revised Amount	:S\$	3,350.63
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,350.63

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	49,595.00
Salvage Value	:S\$	
Margin for Repair	:S\$	20,405.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

# Survey Department Check List (Case Handler)

Reference No. C5/FWD17019997/64b  
Policy Type OD / TP / TP RES / TL / EVA

SKW 6482B

Case Handler

Typist

**Admin** ( C.H. ): Case handler to make sure all information created by the assignment team are **ACCURATE**.

## (1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

**Surveyor** ( Guo Bing ): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

## (2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

## (3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			
✓			

## (4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

C.H. 04/12/17  
Case Handler Date

**Catherine Chong (LKK Auto)**

---

**From:** motorclaims.sg@fwd.com  
**Sent:** Tuesday, 17 October, 2017 5:02 PM  
**To:** sur@lkkauto.com; assignments@lkkauto.com; admin-d@lkkauto.com; admin-a@lkkauto.com  
**Cc:** belliana@fwd.com  
**Subject:** FW: OUR REF: SKW6482B OWN DAMAGE CLAIM Our Ref: 1201700006571  
**Attachments:** 0949\_001.zip

Hi LKK team,

Please refer to the email below and liaise with the repairer for OD survey.

Attached is the repair estimate and OI GIA report. Policy excess \$300.00.

Please create the case in Merimen and revert to us with prelim advice.

Thank you.

Clara Li  
Senior Executive, Claims



FWD Singapore Pte Ltd

6 Temasek Boulevard, #18-01  
Suntec Tower 4, Singapore 038986  
T +65 6727 5722  
E [clara.li@fwd.com](mailto:clara.li@fwd.com)

With FWD, you get to keep your  
50% NCD for Life. No matter what.

get a quick quote now >



F  
Ins

**From:** eric.pau@eurokars.com.sg [mailto:eric.pau@eurokars.com.sg]  
**Sent:** Tuesday, 17 October, 2017 4:56 PM  
**To:** Motor Claims SG - SG Common; vion.lim@eurokars.com.sg  
**Cc:** jess.francis@eurokars.com.sg; ronald.yap@eurokars.com.sg; catherinechua@eurokars.com.sg; kevin.lee@eurokars.com.sg  
**Subject:** OUR REF: SKW6482B OWN DAMAGE CLAIM

**OUR REF: SKW6482B OWN DAMAGE CLAIM**



Dear Sir/Mdm,

Kindly arrange the survey of our client's vehicle.

Attached is the ESTIMATE, SAS REPORT, SKETCH PLAN for your perusal.

Liaise with Vion for survey arrangement.

Best Regards,

**Eric Pau**

Insurance Claims Officer

**TRANS EUROKARS PTE LTD**

5 Ubi Close, Singapore 408605

D: (65) 6395 8685 H: (65) 9618 5991

E: [eric.pau@eurokars.com.sg](mailto:eric.pau@eurokars.com.sg)

*This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

**From:** [mazdacanon@mazda.com.sg](mailto:mazdacanon@mazda.com.sg) [<mailto:mazdacanon@mazda.com.sg>]

**Sent:** Tuesday, October 17, 2017 5:05 PM

**To:** Eric Pau <[eric.pau@eurokars.com.sg](mailto:eric.pau@eurokars.com.sg)>

**Subject:** Attached Image

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Monday, 4 December, 2017 9:26 AM  
**To:** catherinechua@eurokars.com.sg; Guo Qiang (LKKAUTO)  
**Cc:** CS A Team; Admin A; vion.lim@eurokars.com.sg; SUR  
**Subject:** RE: SKW6482B - FINALISATION OF COR

Dear Catherine,

Confirm final fig \$3,350.63 before excess \$300.00 & GST and 3 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Asher Sng (LKKAUTO)  
**Sent:** Monday, 4 December, 2017 8:45 AM  
**To:** catherinechua@eurokars.com.sg; Guo Qiang (LKKAUTO) <[GuoQiang@lkkauto.com](mailto:GuoQiang@lkkauto.com)>; Shiau Chan (LKKAUTO) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Cc:** CS A Team <[cs-a@lkkauto.com](mailto:cs-a@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; vion.lim@eurokars.com.sg; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SKW6482B - FINALISATION OF COR

Hi Catherine,

We acknowledge your email below.

Hi Guo Qiang / Shiau Chan,

FYNA.

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** [catherinechua@eurokars.com.sg](mailto:catherinechua@eurokars.com.sg) [mailto:[catherinechua@eurokars.com.sg](mailto:catherinechua@eurokars.com.sg)]  
**Sent:** Saturday, 2 December, 2017 9:51 AM  
**To:** Guo Qiang (LKKAUTO) <[GuoQiang@lkkauto.com](mailto:GuoQiang@lkkauto.com)>



## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Wednesday, 25 October, 2017 11:10 AM  
**To:** vion.lim@eurokars.com.sg; Admin-D (LKKAUTO)  
**Cc:** ronald.yap@eurokars.com.sg; jess.francis@eurokars.com.sg; eric.pau@eurokars.com.sg;  
SUR  
**Subject:** RE: YOUR REF: SKW6482B OWN DAMAGE CLAIM Our Ref: 1201700006571

Dear Vion,

As instructed by our client **FWD Insurance**, please proceed to repair the insured vehicle **SKW 6482B (Excess \$300/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sjewsc@lkkauto.com](mailto:sjewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** vion.lim@eurokars.com.sg [mailto:vion.lim@eurokars.com.sg]  
**Sent:** Thursday, 19 October, 2017 9:35 AM  
**To:** Admin-D (LKKAUTO) <admin-d@lkkauto.com>  
**Subject:** RE: YOUR REF: SKW6482B OWN DAMAGE CLAIM Our Ref: 1201700006571

Dear Catherine,

Vehicle not in workshop yet. We will re-arrange the survey apt with you.

Thank you.

Best Regards,

 **EUROKARS GROUP**

**Vion Lim**

Insurance Claims Officer

**TRANS EUROKARS PTE LTD**

5 Ubi Close, Singapore 408605

D: (65) 6395 7877 H: (65) 9111 7463

E: [vion.lim@eurokars.com.sg](mailto:vion.lim@eurokars.com.sg)

Website: [www.eurokars.com.sg](http://www.eurokars.com.sg)

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	24 Oct 2017 19:24	Clim Dtl Modified	Claimant's Name: -> GILBERT TAN BUCK HAI. Claimant's ID: -> S1666443Z.	[A] CATHERINE CHONG KAI LING
2	24 Oct 2017 19:24	Clim Veh Model Changed	(205335) MAZDA 2 1.5 HATCHBACK (A).	[A] CATHERINE CHONG KAI LING
3	24 Oct 2017 19:24	Clim Created	Reg No: SKW6482B. Policy No: PNPV2016-00000110. Acct Date: 2017/10/09. Claim Type: OD. Insurer: FWD Singapore Pte. Ltd. (HQ). Workshop: Trans Eurokars Pte Ltd ()	[A] CATHERINE CHONG KAI LING
4	24 Oct 2017 19:24	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : Infiniti Appraisal Service.	[A] CATHERINE CHONG KAI LING
5	24 Oct 2017 19:24	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/11/02	[A] CATHERINE CHONG KAI LING
6	24 Oct 2017 19:24	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
7	24 Oct 2017 19:24	Adj Adjuster Assigned	[None] -> XING GUO QIANG	[A] CATHERINE CHONG KAI LING
8	25 Oct 2017 09:56	Adj Rpt Initiated		[A] SHIAU CHAN
9	25 Oct 2017 09:56	Clim Details Notified		[A] SHIAU CHAN
10	25 Oct 2017 09:58	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/11/02	[A] SHIAU CHAN
11	25 Oct 2017 09:59	Adj Mandate Request	Cur.Reg:3350.63:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
12	25 Oct 2017 10:01	Clim Registration Modified	Excess: -> 300.00.	[I] Clara Li Zi Rong
13	25 Oct 2017 10:03	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/11/02. Mandate Remarks: Policy excess \$300.00	[I] Clara Li Zi Rong
14	25 Oct 2017 10:03	Adj Mandate Set	Approved:3350.63:Policy excess \$300.00	[I] Clara Li Zi Rong

### ACTIVITY

No record

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1619388	25/10/2017 09:56	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKW6482B		10.70

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	6443Z
Vehicle Details	
Vehicle No.	SKW6482B
Vehicle to be Exported	No
Intended De-registration Date	24 Oct 2017
Vehicle Make	MAZDA
Vehicle Model	MAZDA2 5-DOOR HATCHBACK 1.5L SP.6EAT
Primary Colour	Grey
Manufacturing Year	2015
Engine No.	P520328046
Chassis No.	JM6DJ2HAA01100598
Maximum Power Output	85.0 kW (113 bhp)
Open Market Value	\$16,087.00
Original Registration Date	09 Nov 2015
First Registration Date	09 Nov 2015
Transfer Count	0
Actual ARF Paid	\$6,087.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	08 Nov 2025
PARF Rebate Amount	\$4,565.00
Intended COE Rebate Details	
COE Expiry Date	08 Nov 2025
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$56,001.00
COE Rebate Amount	\$45,030.00
<b>Total Rebate Amount</b>	<b>\$49,595.00</b>

The information contained herein is correct as at 24 Oct 2017

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	10/10/2017 15:42
Date Of Accident	09/10/2017 07:55
Exact Location Of Accident	HOUGANG AVE 10
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW6482B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GILBERT TAN BUCK HAI
NRIC No	S1666443Z
Email Address	GILBERTTANBH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97552315
Alternative Phone No	OFFICE-97552315

### Vehicle Particulars

Manufacturer	MAZDA
Model	-
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2016-00000110
Cover Note Number	

### Driver

Name of Driver	GILBERT TAN BUCK HAI
NRIC No	S1666443Z
Date Of Birth	21/08/1964
Occupation	INDOOR
Date Of Driving Pass	20/10/1983
Driving Experience	33 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97552315
Fax Number	
Contact Number	OFFICE-97552315
E Mail Address	GILBERTTANBH@GMAIL.COM

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

### General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions CLEAR

Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 0

### Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name HOUGANG NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 60 HOUGANG AVE 9 , POSTCODE: 538775 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-4890999 - FAX NO: 63128989

Was notice of intended Prosecution given? NO

If Yes, against whom?

### Circumstances of Accident

REFER TO ATTACHMENT.

### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number UNKNOWN

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

### Details of Witness

Name

Phone Number

Email Address


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



### Sketch Plan #2

### SKETCH PLAN

Vehicle No

A -

B -

Legend

Vehicle

Bike

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.  
Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the stipulated timeframe from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature \_\_\_\_\_  
Date & Time \_\_\_\_\_

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/Fin No.:

## POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20171009/2032

1 of 3

Police Station Of Origin:  
Hougang N.P.C  
60 Hougang Avenue 9 SINGAPORE 538775  
Tel No: 1800-4890999

Report No. T/20171009/2032

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/10/2017 11:01		Vide Report No.:		Station Diary No.: 22	
<b>Informant's Particulars</b>					
Name of Informant: GILBERT TAN BUCK HAI			Address: APT BLK 711 HOUGANG AVENUE 2 #10-143 SINGAPORE 530711		
ID Type / ID No.: NRIC NO / S1666443Z			Contact No.: Home/Office: Mobile: 97552315		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 53	Date of Birth: 21/08/1964	Type of Informant: Vehicle Owner		
Race: Chinese			Language:		Institution / School Name:
Occupation: TRAFFIC CONTROLLER			Driving Licence Information: Class: 3 Date of Expiry:		

## General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 09/10/2017 07:55	Type of Location: Car Park
Location: Along Road 1 HOUGANG AVENUE 10 Block 814 Hougang Ave 10, Open Carpark HG 55, parking lot 25				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKW6482B	Car	MAZDA	MAZDA2 5-DOOR HATCHBACK 1.5L SP.6EAT	Grey	Slightly Damaged	0



**SINGAPORE  
POLICE FORCE**



T/20171009/2032

2 of 3

Report No. T/20171009/2032

Police Station Of Origin:  
Hougang N.P.C  
60 Hougang Avenue 9 SINGAPORE 538775  
Tel No: 1800-4890999

CONTINUATION OF REPORT

**Brief Details.**

On 09/10/2017 at about 0730hrs, I arrived at the said location and parked my vehicle (SKW6482B) at the open carpark (HDB HG55) in parking lot 25. My car was intact before I proceeded nearby to buy my breakfast.

On 09/10/2017 at about 0755hrs, I returned to my vehicle and realized that there are several scratches and a dent at the bottom bumper near to the left front wheel. I wish to inform that there is no note or notice left behind by the owner of the other vehicle. There is an in car CCTV installed in my vehicle. However it was not operating at the time of the incident and thus, I was unable to obtain any information regarding the other driver. I also wish to inform that there is an ERP gantry camera located near the incident location.

# POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20171009/2032

3 of 3

Police Station Of Origin:  
Hougang N.P.C  
60 Hougang Avenue 9 SINGAPORE 538775  
Tel No: 1800-4890999

Report No. T/20171009/2032

CONTINUATION OF REPORT

## Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 TAN KAI JUN, CHRISTIAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / HRT /

Sr Staff Sgt ESTHER CHONG

Contact No: 65476368

SN 005

Authentication Stamp

NP168

Singapore Police Force

Signature Of Informant:

Date/Time:

09/10/2017 11:01

Classification Of Case:



**TRANS EUROKARS PTE LTD**  
**NO:5 UBI CLOSE, SINGAPORE 408605**  
**QUOTATION**



<b>FWD Singapore Pte Ltd</b> 6 Temasek Boulevard, #18-01 Suntec Tower 4, Singapore 038986 <b>ATTN. :</b> MOTOR CLAIMS <b>FAX :</b>		<b>NAME :</b> Mr Gilbert Tan Buck Hai <b>ADDRESS :</b> Blk 711 Hougang Avenue 2 #10-143 Singapore 530711 <b>TEL :</b> 97552315		<b>WIP :</b> 38960 <b>EXCESS :</b> <b>DATE:</b> 17-Oct-17	
<b>VEH NO :</b>	<b>SKW6482B</b>	<b>DATE IN :</b>		<b>CONTACT PERSON :</b>	VION 6395 7877
<b>CHASSIS NO :</b>	JM6DJ2HAA01100598	<b>MILEAGE :</b>		<b>TYPE OF CLAIM :</b>	OWN DAMAGE CLAIM
<b>MODEL :</b>	MAZDA2 HB	<b>DATE REG.:</b>	9-Nov-15	<b>POLICY NO. :</b>	
<b>NATURE OF WORKS</b>					
<b>Parts Description</b>					
NO	QTY			REVISED	PRICES
1	FRONT BUMPER / <i>Wt</i>	1	MD09H-50-031EBB		\$ 832.10
2	RETAINER(LHS), FRONT BUMPER / <i>Mc</i>	1	MD09H-50-0U1B		\$ 16.20
3	GARNISH(LHS), FOGLAMP X <i>NN</i>	1	MD09T-50-C22		\$ 80.50
4	RIVET, FRONT BUMPER /	4	MS51S-51-833		\$ 15.20
5	RIVET, FRONT BUMPER /	4	MTK21-50-355		\$ 34.80
6	GROMMET, FRONT BUMPER / <i>Mc</i>	2	MGHP9-50-0Z5		\$ 5.40
7	CLIP, FRONT BUMPER /	11	MC274-50-133		\$ 38.50
8	FASTENER, FRONT BUMPER /	5	MB45A-56-146A		\$ 14.00
9	SEAL, FRONT BUMPER /	2	MD09H-50-A81A		\$ 21.40
10	LHS FRONT FENDER / <i>Buc</i>	1	MD09H-52-211		\$ 323.10
11	STAY(LHS), FRONT FENDER X	1	MD0YH-52-21Y		\$ 48.60
12	LHS FRONT MUDGUARD X <i>NN</i>	1	MD09H-56-141D		\$ 63.60
13	HEADLAMP LHS X	1	MDA6K-51-041B		\$ 2,393.60
14	CLIP, HEADLAMP X	2	MGG2M-51-689		\$ 20.20
15	RIVET, HEADLAMP X	1	MB092-51-833		\$ 3.30
<b>TOTAL PARTS</b>					\$ 3,910.50
<b>LESS 10%</b>					\$ 391.05
<b>TOTAL PARTS COST</b>					<b>\$ 3,519.45</b>
<b>Labour Description</b>					
1	MZ-BR-FRONT7	TO REPLACE FRONT BUMPER AND FRONT FENDER. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			<i>630</i> \$ 1,890.00
2	MZ-SP-SFRT07	TO RESPRAY FRONT BUMPER AND FRONT FENDER.			<i>1200</i> \$ 1,800.00
3	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			<i>150</i> \$ 250.00

4	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
5	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 100.00

TOTAL LABOUR	\$ -	\$ 4,390.00
TOTAL PARTS	\$ -	\$ 3,519.45
TOTAL	\$ -	\$ 7,909.45
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

**REMARKS:**

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

**TRANS EUROKARS PTE LTD**

\_\_\_\_\_  
Authorised Signature

U/Days.

GROSS \$ 300

Not Authorised..

24/10/17

Eno Q: up - 62880282

before paint photos.

*[Signature]*  
25/10/17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



**TRANS EUROKARS PTE LTD**  
**NO:5 UBI CLOSE, SINGAPORE 408605**  
**FINALISED COST OF REPAIR**



<b>FWD Singapore Pte Ltd</b> 6 Temasek Boulevard, #18-01 Suntec Tower 4, Singapore 038986		<b>NAME :</b> Mr Gilbert Tan Buck Hai <b>ADDRESS :</b> Blk 711 Hougang Avenue 2 #10-143 Singapore 530711 <b>TEL :</b> 97552315		<b>WIP :</b> 38960 <b>EXCESS :</b> \$ 300.00 <b>DATE:</b> 17-Oct-17	
<b>ATTN. :</b> MOTOR CLAIMS <b>FAX :</b>					
<b>VEH NO :</b>	<b>SKW6482B</b>	<b>DATE IN :</b>		<b>CONTACT PERSON :</b>	VION 6395 7877
<b>CHASSIS NO :</b>	JM6DJ2HAA01100598	<b>MILEAGE :</b>		<b>TYPE OF CLAIM :</b>	OWN DAMAGE CLAIM
<b>MODEL :</b>	MAZDA2 HB	<b>DATE REG.:</b>	9-Nov-15	<b>POLICY NO. :</b>	
<b>NATURE OF WORKS</b>					
<b>Parts Description</b>					
<b>NO</b>	<b>QTY</b>			<b>REVISED</b>	<b>PRICES</b>
1	FRONT BUMPER	1	MD09H-50-031EBB	\$ 832.10	\$ 832.10
2	RETAINER(LHS), FRONT BUMPER	1	MD09H-50-0U1B	\$ 16.20	\$ 16.20
3	GARNISH(LHS), FOGLAMP	1	MD09T-50-C22		\$ 80.50
4	RIVET, FRONT BUMPER	4	MS51S-51-833	\$ 15.20	\$ 15.20
5	RIVET, FRONT BUMPER	4	MTK21-50-355	\$ 34.80	\$ 34.80
6	GROMMET, FRONT BUMPER	2	MGHP9-50-0Z5	\$ 5.40	\$ 5.40
7	CLIP, FRONT BUMPER	11	MC274-50-133	\$ 38.50	\$ 38.50
8	FASTENER, FRONT BUMPER	5	M845A-56-146A	\$ 14.00	\$ 14.00
9	SEAL, FRONT BUMPER	2	MD09H-50-A81A	\$ 21.40	\$ 21.40
10	LHS FRONT FENDER	1	MD09H-52-211	\$ 323.10	\$ 323.10
11	STAY(LHS), FRONT FENDER	1	MD0YH-52-21Y		\$ 48.60
12	LHS FRONT MUDGUARD	1	MD09H-56-141D		\$ 63.60
13	HEADLAMP LHS	1	MDA6K-51-041B		\$ 2,393.60
14	CLIP, HEADLAMP	2	MGG2M-51-689		\$ 20.20
15	RIVET, HEADLAMP	1	MB092-51-833		\$ 3.30
<b>TOTAL PARTS</b>				\$ 1,300.70	\$ 3,910.50
<b>LESS 10%</b>				\$ 130.07	\$ 391.05
<b>TOTAL PARTS COST</b>				\$ 1,170.63	\$ 3,519.45
<b>Labour Description</b>					
1	MZ-BR-FRONT7	TO REPLACE FRONT BUMPER AND FRONT FENDER. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		\$ 630.00	\$ 1,890.00
2	MZ-SP-SFRT07	TO RESPRAY FRONT BUMPER AND FRONT FENDER.		\$ 1,200.00	\$ 1,800.00
3	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 150.00	\$ 250.00
4	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$ 180.00	\$ 350.00



5	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
			TOTAL LABOUR	\$ 2,180.00 \$ 4,390.00
			TOTAL PARTS	\$ 1,170.63 \$ 3,519.45
			TOTAL	\$ 3,350.63 \$ 7,909.45
			LESS EXCESS	\$ 300.00 \$ -
			TOTAL AFTER EXCESS	\$ 3,050.63
			GST 7%	\$ 213.54 \$ -
			GRAND TOTAL	\$ 3,264.17 \$ -

REMARKS: SKW6482B

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.  
6 Temasek Boulevard, #18-01 Suntec Tower 4  
Singapore 038986

Our File No: CS/FWD17019997/GQBN2

Date: 24/01/2018

## REFERENCE

Insured/Claimant: GILBERT TAN BUCK HAI Policy No: PNPV2016-00000110  
Date of Loss: 09/10/2017 Nature of Claim: OD Claim No: 1201700006571

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKW6482B  
Make & Model: MAZDA 2, 1.5 HATCHBACK (A) Engine No: P520328046  
Reg. Date: 09/11/2015 (Man. Year: 2015) Chassis No: JM6DJ2HAA01100598  
Colour: Grey Odometer: 23021 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: S\$70,000.00  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 185/60 R16 Rear Tyre Size: 185/60 R16  
Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm  
Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,619.45	1,190.63	2,428.82	67.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,290.00	2,160.00	2,130.00	49.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,909.45</b>	<b>3,350.63</b>	<b>4,558.82</b>	<b>57.64</b>
<b>- Excess (S\$)</b>	<b>300.00</b>	<b>300.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>7,609.45</b>	<b>3,050.63</b>	<b>4,558.82</b>	<b>59.91</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>532.66</b>	<b>213.54</b>	<b>319.12</b>	<b>59.91</b>
<b>Nett Amount (S\$)</b>	<b>8,142.11</b>	<b>3,264.17</b>	<b>4,877.94</b>	<b>59.91</b>

## INSPECTION

Date of Assignment: 17/10/2017

Date Inspected: 24/10/2017 Inspected At:

Trans Eurokars Pte Ltd  
NO. 5 UBI CLOSE, SINGAPORE  
Singapore 408605

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 24 Jan 2018)
<b>Parts:</b> 144	MAZDA 2 1.5 HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKW6482B)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	832.10 FL	*832.10 FL
2	1		*RETAINER (LHS) FRONT BUMPER	Necessary	16.20 FL	*16.20 FL
3	1		*GARNISH (LHS) FOGLAMP	Not Necessary	80.50 FL	*- FL
4	4		*RIVET FRONT BUMPER	Necessary	15.20 FL	*15.20 FL
5	4		*RIVET FRONT BUMPER	Necessary	34.80 FL	*34.80 FL
6	2		*GROMMET FRONT BUMPER	Necessary	5.40 FL	*5.40 FL
7	11		*CLIP,FRONT BUMPER	Necessary	38.50 FL	*38.50 FL
8	5		*FASTENER,FRONT BUMPER	Necessary	14.00 FL	*14.00 FL
9	2		*SEAL,FRONT BUMPER	Necessary	21.40 FL	*21.40 FL
10	1		*LHS FRONT FENDER	Buckled	323.10 FL	*323.10 FL
11	1		*STAY (LHS) FRONT FENDER	Not Necessary	48.60 FL	*- FL
12	1		*LHS FRONT MUDGUARD	Not Necessary	63.60 FL	*- FL
13	1		*HEADLAMP LHS	Not Necessary	2,393.60 FL	*- FL
14	2		*CLIP,HEADLAMP	Not Necessary	20.20 FL	*- FL
15	1		*RIVET,HEADLAMP	Not Necessary	3.30 FL	*- FL
16	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,010.50</b>	<b>1,320.70</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>391.05</b>	<b>130.07</b>
<b>Total Parts (\$\$)</b>	<b>3,619.45</b>	<b>1,190.63</b>

Report was unsubmitted during this print-out.

**Recommended Miscellaneous Items**

There are no new miscellaneous items selected.

**Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT BUMPER AND FRONT FENDER.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	1,890.00	630.00
2	TO RESPRAY FRONT BUMPER AND FRONT FENDER	New	1,800.00	1,200.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
4	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
Gross Labour Cost (\$\$)			4,290.00	2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >