

ASS. REC. BY:

REF: CS/MS(170)2017/Gdn2 Special Instruction:

ASSIGNMENT (Office)

From (Person): Lena Tan of MSLH Date/Time: 20/10/2017 9:38am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OP  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKQ 635Z Insured: SKJ 1935m

at Workshop m/s Wearnes Tel: 9129 4556

of 249 Alexandra Road

Policy No: A28951820 QMX Claim No: 532059

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 04-10-2017

(Client's Record) \_\_\_\_\_

CA / REV / REP. / REV 24 HRS 'wp' \_\_\_\_\_ H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 20/10/2017 11:56am Person Contacted: Michelle Vehicle IN/OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	SKQ 635Z . x
	SKJ 1935m - PCC /ATA 16015276 / R1pg352 DOA: 140816

Surveyor

*XML*

REF: MSIG

ASSIGNMENT

From: \_\_\_\_\_ Date: 25/10/2017

Estimated Cost: \_\_\_\_\_

OD  WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKQ 635 Z

at Workshop n/s Wearnes

of 249 Alexandra Road

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition) gam

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No


GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lump Sum: 1.8-1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT



Veh No: SKQ635Z Yr Regn: 30 Oct 2014

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or scenic II

Make: Renault Grand. 1461

Colour: Brown A/C: Insured / Std / NI / NA

So Reading: 61557 T/Radio: Insured / Std / NI / NA

Eng No: \_\_\_\_\_

C/No: VF/JZS OBE 51517349

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or

Brake:  In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/50 R17

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front 6 mm R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 25-10-17

Survey held at w/s 10AM

Des. of Damages: Frt /  Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time	Action / Instruction
<u>26/10/17</u>	<u>Rev prot in merimen.</u>
<u>15/12/17</u>	<u>confirmed final fig \$ 3164.50 with Michelle.</u> <u>(Red: 1799.55, 36%).</u>

RECEIVED 15 DEC 2017

Date/Time File Pass to?  : Preli. Report

1)  : Final Report

Date/Time File Return to? \_\_\_\_\_

Days Of Repair: 3

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee	
Transcriber	<u>200</u>
_____ \$ - FE _____ \$	
Photo	
Diag	
	<u>10</u>
TOTAL	<u>210</u>

Add Fee:  Site Insp (\$ \_\_\_\_\_)

Interview (\$ \_\_\_\_\_)

Tech. Invs (\$ \_\_\_\_\_)

Weekend (\$ \_\_\_\_\_)

Report Format: TP

Lump Sum /  E: \$ 3164.50



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17020117/Ggb

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 20-10-2017



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKJ 1935M	Veh. Inspected	SKQ 635Z
Policy No.	A28951820QMX	Coverage (\$)	0.00
Claim No.	532059	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	20/10/2017

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	04/10/2017	Inspection Date	23/10/2017
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Oct 2017		20 Oct 2017 09:38 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

<b>Insured:</b>	YAM WAI YING, ID: S1338331F		
<b>Main Claimant:</b>	CHEONG SZU YEN, ID: S7439450G		
<b>Vehicle Reg. No.:</b>	SKQ635Z	<b>Date of Loss:</b>	04/10/2017 13:00 - :59
<b>Claim Type:</b>	TP / 532059	<b>Policy/Cover Note No.:</b>	A28951820QMX (Comprehensive) Coverage: 08/05/2017 - 10/05/2018
<b>Vehicle Reg. No. (Insured):</b>	SKJ1935M	<b>Policy No. (Claimant):</b>	
		<b>Excess:</b>	
<b>Repairer:</b>	Wearns Automotive Pte Ltd (HQ) 249 ALEXANDRA ROAD, 159935 Alexandra - Tel:		
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/10/2017]		
<b>Driver/Custodian (Insured):</b>	LIM KOK KHAY (), NRIC: S1228862Z, Tel: +6597353355		
<b>Adj Asg. Remarks:</b>	Survey Appt on 23.10.17 @ 9am		

**ASSOCIATED MAIL RECEIVED** [View All](#) | [Compose Case Mail](#)

There are no mail for this case.

---

**ALL ASSOCIATED TASKS** [View All](#) | [Search Tasks](#) | [Create New Task](#) | [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 26 Oct 2017

**Preliminary Advice**

Insured Vehicle No	: SKJ1935M	Accident Date	: 04/10/2017
TP Vehicle No	: SKQ635Z	Assignment Date	: 20/10/2017
Make	: RENAULT GRAND SCENIC III	Est. Duration of Repair	: 3.00
Date of Inspection	: 25/10/2017		
Inspection At	: WEARNS AUTOMOTIVE PTE LTD (HQ) 249 ALEXANDRA ROAD SINGAPORE 159935		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,257.00
Revised Amount	:S\$	2,503.70
Check Items (Estimated)	:S\$	624.80
Total	:S\$	3,128.50
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	9450G
Vehicle Details	
Vehicle No.	SKQ635Z
Vehicle to be Exported	No
Intended De-registration Date	26 Oct 2017
Vehicle Make	RENAULT
Vehicle Model	GRAND SCENIC III 1.5 DCI A/T 2WD 5DR S/R
Primary Colour	Brown
Manufacturing Year	2014
Engine No.	K9KN837D162149
Chassis No.	VF1JZS0BE51517349
Maximum Power Output	81.0 kW (108 bhp)
Open Market Value	\$24,875.00
Original Registration Date	30 Oct 2014
First Registration Date	30 Oct 2014
Transfer Count	0
Actual ARF Paid	\$16,825.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	29 Oct 2024
PARF Rebate Amount	\$12,618.00
Intended COE Rebate Details	
COE Expiry Date	29 Oct 2024
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$63,990.00
COE Rebate Amount	\$44,844.00
<b>Total Rebate Amount</b>	<b>\$57,462.00</b>

The information contained herein is correct as at 26 Oct 2017

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	04/10/2017 17:41
Date Of Accident	04/10/2017 13:50
Exact Location Of Accident	BUKIT BATOK EAST AVE 6 AND AVE 2
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKQ635Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHEONG SZU YEN
NRIC No	S7439450G
Email Address	SEOWS2003@YAHOO.COM
Mobile Phone No	(LOCAL) +65-98224793
Alternative Phone No	OFFICE-98224793

### Vehicle Particulars

Manufacturer	RENAULT
Model	GRAND SCENIC III 1.5-CAPACITY1461
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01013908
Cover Note Number	N.A

### Driver

Name of Driver	CHEONG SZU YEN
NRIC No	S7439450G
Date Of Birth	25/11/1974
Occupation	INDOOR
Date Of Driving Pass	21/12/1993
Driving Experience	23 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98224793
Fax Number	
Contact Number	OFFICE-98224793
EMail Address	SEOWS2003@YAHOO.COM

Address  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 3

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

I SKQ635Z was stationary and waiting for traffic light to turn green so that I can turn right to Bukit Batok East Avenue 2. The light then turned green and I was about to drive off, when I heard a "Bang!" and my car jerked forward. I got out of my car to discover that the car SKJ1935M had hit my bumper. No injuries involved.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SKJ1935M  
 Vehicle Make/Model/Colour OPEL/ ZAFIRA  
 Details Of Properties NA  
 Name of Driver LIM KOK KHAY  
 NRIC/Passport Number S1228862Z  
 Contact Number NA  
 Address NA  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**Details of Witness**

Name  
 Phone Number  
 Email Address

## Sketch Plan

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may cause insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurer to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the judgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
  - (a) I, understand, acknowledge, agree and consent that
    - (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form] and any other personal information provided by me or processed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in the accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
      - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
      - (ii) investigating the accident and/or my claims;
      - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
      - (iv) administering my claims (including the mailing of correspondence, statements, vouchers, reports, or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
      - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims;
    - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
    - (c) my Personal Information may/can be disclosed by any of the insurers, and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


**VERIFIED BY AJAX MARS  
REPORTING OFFICER  
MUHAMMAD SUMARDI BIN  
MOHD AFFANDI**

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan



Sketch Plan #2

ACCIDENT STATEMENT (2000 characters)

I SKQ635Z was stationary and waiting for traffic light to turn green so that I can turn right to Bukit Batok East Avenue 2. The light then turned green and I was about to drive off, when I heard a "Bang!" and my car jerked forward. I got out of my car to discover that the car SKJ1935M had hit my bumper.No injuries involved.

Taxi Voucher No.

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
MUHAMMAD SUMARDI BIN MOHD AFFANDI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

4 October 2017 5:24 pm

Date/Time:

4 October 2017 5:24 pm

2 Days, sur@lkkauto.com

before paint photos.

Guo Qiang - 82880282

25/10/17

*[Handwritten signature]*  
26/10/17

**SERVICE ESTIMATE**

78819 - C00001  
Ms Cheong Szu Yen  
The Petals, 95 Hillview Avenue  
#07-30  
Address Ok  
Singapore 669627

SL: SERVICE SALES - PC

GST Reg.No:M28920628X  
Inv.No. . . : B&P 0 Page 1  
Inv.date. : 17/10/2017  
WIP No. . . : 23943  
Veh.In/Out: 12/10/2017  
\*Tel.No. . . : Mobile: 98224793  
Reg.No. . . : SKQ635Z  
Reg.date . . : 30/10/2014  
Mileage .. : 0  
Chassis No: VF1JZSOBE51517349

Closed by .... : Michelle Ong Siew Be  
Svc Consultant :  
Remarks ..... : Ms Cheong Szu Yen

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER. (450)	0	900.00	0		900.00 S	450
800	TO PUTTY SPRAY PAINT ON REAR BUMPER. (400)	0	800.00	0		800.00 S	400
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.	0	330.00	0		330.00 S	/
	BUMPER REAR JZ1P RAD <del>scr</del>	1.0 EA	775.50			775.50 S	
	RIVET BLACK /	10.0 EA	6.30			63.00 S	
	BUMPER EXTENSION JZ1 ? / scr	1.0 EA	376.20			376.20 S	
	BUMPER BRACKET REAR ? x / NN	1.0 EA	152.30			152.30 S	
	BUMPER BRACKET REAR ? x / NN	1.0 EA	152.30			152.30 S	
	RIVET G4,8- /	10.0 EA	5.30			53.00 S	
	TRIM CLIP M2 /	10.0 EA	5.60			56.00 S	
	BUMPER BRACKET REAR ? x / NN	1.0 EA	320.20			320.20 S	

Labour Total 2,030.00  
Parts Total 1,948.50  
Package Total 0.00

Gross Total. 3,978.50  
Net..... 3,978.50  
GST @ 7.0% 278.50  
Total..... 4,257.00  
Paid..... 0.00

4639.30

4964.05

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Please Pay consultants here and notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Supplementary List

SERVICE ESTIMATE

78819 - C00001 SL: SERVICE SALES - PC

Ms Cheong Szu Yen  
The Petals, 95 Hillview Avenue  
#07-30  
Address Ok  
Singapore 669627

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1  
Inv.date. : 15/12/2017  
WIP No. . : 23943  
Veh.In/Out: 06/12/2017 09/12/2017  
\*Tel.No. . : Mobile: 98224793  
Reg.No. . : SKQ635Z  
Reg.date . : 30/10/2014  
Mileage .. : 63,695  
Chassis No: VF1J7S0BF51517349

Closed by .... : Michelle Ong Siew Be  
Svc Consultant : ACC  
Remarks ..... : Ms Cheong Szu Yen

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	BUMPER BEAM REAR JZ1 (A) /BT.	1.0 EA	660.80			660.80	S
--	----------------------------------	--------	--------	--	--	--------	---

Gross Total. 660.80

Labour Total	0.00
Parts Total	660.80
Package Total	0.00

Net.....	660.80
GST @ 7.0%	46.26
Total.....	707.05
Paid.....	0.00
Please Pay..	707.05

GST: S=StdRated; 0=OutOfScope; 7=ZeroRated



### SERVICE ESTIMATE

78819 - C00001 SL: SERVICE SALES - PC

Ms Cheong Szu Yen  
 The Petals, 95 Hillview Avenue  
 #07-30  
 Address Ok  
 Singapore 669627

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1  
 Inv.date. : 15/12/2017  
 WIP No. . : 23943  
 Veh.In/Out: 06/12/2017 09/12/2017  
 \*Tel.No. . : Mobile: 98224793  
 Reg.No. . : SKQ635Z  
 Reg.date .: 30/10/2014  
 Mileage .: 63,695  
 Chassis No: VF1JZS0BE51517349

Closed by .... : Michelle Ong Siew Be  
 Svc Consultant : ACC  
 Remarks ..... : Ms Cheong Szu Yen

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER.	0	450.00	0		450.00	S
800	TO PUTTY SPRAY PAINT ON REAR BUMPER.	0	400.00	0		400.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELCTRICAL MODULES.	0	330.00	0		330.00	S
①	BUMPER REAR JZ1P RAD	1.0 EA	775.50			775.50	S
②	RIVET BLACK	10.0 EA	6.30			63.00	S
③	BUMPER EXTENSION JZ1	1.0 EA	376.20			376.20	S
④	RIVET G4,8-	10.0 EA	5.30			53.00	S
⑤	TRIM CLIP M2	10.0 EA	5.60			56.00	S
	BUMPER BEAM REAR JZ1 <i>supp</i>	1.0 EA	660.80			660.80	S

Gross Total. 3,164.50

Labour Total 1,180.00  
 Parts Total 1,984.50  
 Package Total 0.00

Net..... 3,164.50  
 GST @ 7.0% 221.52  
 Total..... 3,386.00  
 Paid..... 0.00  
 Please Pay.. 3,386.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17020117/GGBN2

Date: 19/12/2017

#### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28951820QMX
Claimant Vehicle No :	SKQ635Z	Insured Vehicle No :	SKJ1935M
Date of Loss:	04/10/2017	Nature of Claim:	TP
			Claim No: 532059

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ635Z	Engine No:	K9KN837D162149
Make & Model:	RENAULT GRAND SCENIC III, 1.5 DCI (A)	Chassis No:	VF1JZS0BE51517349
Reg. Date:	30/10/2014 (Man. Year: 2014)	Odometer:	61557 km
Colour:	Brown		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	215/50R17	Rear Tyre Size:	215/50R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,609.30	1,984.50	624.80	23.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,030.00	1,180.00	850.00	41.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,639.30</b>	<b>3,164.50</b>	<b>1,474.80</b>	<b>31.79</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>324.75</b>	<b>221.52</b>	<b>103.23</b>	<b>31.79</b>
<b>Nett Amount (S\$)</b>	<b>4,964.05</b>	<b>3,386.02</b>	<b>1,578.03</b>	<b>31.79</b>

#### INSPECTION

Date of Assignment:	20/10/2017		
Date Inspected:	25/10/2017	Inspected At:	Wearns Automotive Pte Ltd (HQ) 249 ALEXANDRA ROAD Singapore 159935
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 19 Dec 2017)
<b>Parts:</b> M1-MPV	RENAULT GRAND SCENIC III 1.5 DCI (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKQ635Z)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR JZIP RAD	Scratched	775.50 FS	*775.50 FS
2	10		*RIVET BLACK	Necessary	63.00 FS	*63.00 FS
3	1		*BUMPER EXTENSION JZ1	Scratched	376.20 FS	*376.20 FS
4	1		*BUMPER BRACKET REAR	Not Necessary	152.30 FS	*- FS
5	1		*BUMPER BRACKET REAR	Not Necessary	152.30 FS	*- FS
6	10		*RIVET G4,8	Necessary	53.00 FS	*53.00 FS
7	10		*TRIM CLIP M2	Necessary	56.00 FS	*56.00 FS
8	1		*BUMPER BRACKET REAR	Not Necessary	320.20 FS	*- FS
9	1		*BUMPER BEAM REAR JZ1	Bent	660.80 FS	*660.80 FS
<b>Total Parts (S\$)</b>					<b>2,609.30</b>	<b>1,984.50</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER	New	900.00	450.00
2	TO PUTTY SPRAY PAINT ON REAR BUMPER	New	800.00	400.00
3	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	330.00	330.00
Gross Labour Cost (\$\$)			<b>2,030.00</b>	<b>1,180.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >