

21/09/2012

A.S. REC BY:

REF: CS/MSG17020197/RHber2

Special Instruction:

Surveyor
Melinda

ASSIGNMENT (Office)

From (Person): Monica Chung of MSH Date/Time: 23-10-2017 11:18gm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XD 4500S Insured: YP 5108T

at Workshop m/s Motorway Tel: 9755 7336

of 18 Tuas Ave 10

Policy No: 28677733MKT Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 17-10-2017
(Client's Record)

CA / REV / REP. / REV 24 HRS WPI 24-10-2017 H.O.D. Endorsement:

Date/Time: 23-10-2017 11:52am Person Contacted: William Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	XD 4500S - X
	YP 5108T - X
	Confirm final figure @ \$9411.13, 1 day.
	(Red: 780 : 7%)
	N 19/11/18

09/11/13

Surrey

Fasou

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: XP 4500 Sat Workshop m/s MOTORVILLAof 15, THURS MVE 10

Insured:

msch / up

Policy No:

Claims No:


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: after 1.30 pm
The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: XO 4500 S

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

C.C.

Colour

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

16114

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

295/80R22.5

R:

0/0

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

8

mm

R/Bal.

8/8

mm

L/Bal.

8

mm

L/Bal.

8/8

mm

D.O.A.

17/10/17

D.O.I.

23/10/17

Survey held at

MOTORVILLA

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

NO/STRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 20 APR 2010

Date/Time, File Pass to?



Preli. Report

1) 19/11/13 TP

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp. (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format:

TP

Lump Sum / I.B.I. (\$

9411.1330010310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17020197/R1tb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 23-10-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 5908T	Veh. Inspected	XD 4500S
Policy No.	28677733MKF	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	23/10/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	17/10/2017	Inspection Date	24/10/2017
Survey held at	18 TUAS AVE 10		
Repairer	MOTORVIVA PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Oct 2017		23 Oct 2017 11:18 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Acelink Logistics Pte Ltd, Co. Reg. No.: 199202352M		
Main Claimant:	WAREHOUSE LOGISTICS NET ASIA PTE LTD, Co. Reg. No.: NA		
Vehicle Reg. No.:	XD4500S	Date of Loss:	17/10/2017 11:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	28677733MKF (Comprehensive) Coverage: 01/01/2017 - 31/12/2017
Vehicle Reg. No. (Insured):	YP5908T	Policy No. (Claimant):	
		Excess:	
Repairer:	Motorviva Pte Ltd (HQ) 10 Tuas Avenue 18, 638894 Tuas - Tel: 68640695		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/10/2017]		
Driver/Custodian (Insured):	LIM TENG BOON (50), NRIC: S1778552D, Tel: +6598332833		
Adj Asg. Remarks:	SURVEY ON WP BASIS. Car will be at no. 18 Tuas Avenue 10, survey anytime after 1.30pm.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/10/2017 17:03
Date Of Accident	17/10/2017 11:30
Exact Location Of Accident	GREAT WORLD CITY - LOADING / UNLOADING BAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD4500S
Insured/Policyholder	
Name Of Registered Owner	WAREHOUSE LOGISTICS NET ASIA PTE LTD
Co Reg No	NA 199206696R
Email Address	SHAUNLIM@WLOA.COM
Mobile Phone No	(LOCAL) +65-90084795
Alternative Phone No	OFFICE-97989372
Vehicle Particulars	
Manufacturer	IVECO
Model	TRUCK
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5069073360-02
Cover Note Number	
Driver	
Name of Driver	LEE THAI KAY
NRIC No	S2652742B
Date Of Birth	05/06/1964
Occupation	OUTDOOR
Date Of Driving Pass	18/09/1998
Driving Experience	19 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90084795
Fax Number	
Contact Number	OFFICE-90084795
Email Address	SHAUNLIM@WLOA.COM

Address	BLK 850 JURONG WEST STREET 81 #08-269
Postcode	640850
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	YP5908T
Vehicle Make/Model/Colour	LORRY
Details Of Properties	REAR PORTION
Name of Driver	LIM TENG BOON
NRIC/Passport Number	S1778552D
Contact Number	98332833
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was at the shaded place, doing a time to unload goods and my vehicle was parked in a lot with the Rear Tailgate down. No one was in my vehicle as I was behind my behind to unload goods.

I saw a vehicle a few lots beside my vehicle who wanted to go out, so this vehicle (B) driver did not check and reversed & hit my vehicle. Left front portion causing damages. We exchange particulars.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Police Officer's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's signature
Name: *RICHA RD*
SRC/TIN No: *21253169p*

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIACC Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available as aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurers who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Person's Signature
Name: **RICHARD W. SINGHAP**
NRIC/IN No:

Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



DATE : 20/10/2017

TO : WAREHOUSE LOGISTICS NET ASIA P/L

ATTN : MR. JACKY

OFFICE / MOBILE : -

EMAIL ADDRESS : -

FROM : MOTORVIVA PTE LTD

ATTN : MR WILLIAM GO

OFFICE / MOBILE : 6864-0637 / 9755-7336

FAX NO. : 6863-0425

VEHICLE NO. : XD4500S

MODEL NO. : IVECO ML190EL25

CHASSIS NO. : ZCFA1VJ0402574162

ENGINE NO. : 778770

REG. DATE : 31/03/2011

REF. NO. : GBE/SVC/SALES-4455/171020

D.O.A. : 17/10/2016

POLICY NO. : -

CLAIM TYPE : TP CLAIM - MSIG

WORKSHOP : 10 TUAS AVE 18

S/N	PART NO.	DESCRIPTION	QUANTITY	PRICE
1	5801765367	REAR VIEW MIRROR LHS	1	\$ 2,103.89 <i>380</i>
2	5801351720	REAR VIEW MIRROR TOP GASKET LHS	1	\$ 24.10 <i>na</i>
SUB-TOTAL :				\$ 2,127.99
LESS 25% :				\$ 532.00
PARTS TOTAL :				\$ 1,595.99 ✓

LABOUR CHARGES

1 TO TOW VEHICLE BACK TO WORKSHOP.	\$ 200.00 ✓
2 TO REMOVE & REFIX REAR VIEW MIRROR ASSY.	\$ <i>380</i> 600.00 <i>450</i>
3 TO CHECK FOR & RECTIFY WIRING FAULTS, ETC. TO CARRY OUT DIAGNOSTICS CHECK.	\$ <i>810</i> 280.00 <i>200</i>
4 SUNDRIES	\$ 60.00 <i>30</i>
LABOUR TOTAL :	\$ 1,140.00
GRAND TOTAL :	\$ 2,735.99

PREPARED BY : WILLIAM GO

DATE / TIME : 23/10/17 @ 1700

SURVEYOR : RASUL

MOBILE NO. : 90010068

OFFICE FAX NO. :

EMAIL ADDRESS : rasul@lkkauto.com

REPAIR TYPE : PART-BY-PART / LUMP SUM

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : 1 day

REMARKS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SUPPLEMENTARY ESTIMATE

DATE : 25/10/2017
TO : WAREHOUSE LOGISTICS NET ASIA P/L
ATTN : MR. JACKY
OFFICE / MOBILE : -
FAX NO. : -
FROM : MOTORVIVA PTE LTD
ATTN : MR. WILLIAM GO
OFFICE / MOBILE : 6864-0637 / 9755-7336
FAX NO. : 6863-0425
VEHICLE NO. : XD4500S
MODEL NO. : IVECO ML190EL25
CHASSIS NO. : ZCFA1VJ0402574162
ENGINE NO. : 778770
REF. NO. : GBE/SVC/SALES-4455/171020
D.O.A. : 20/10/2016
POLICY NO. : -
CLAIM TYPE : TP CLAIM - MSIG
WORKSHOP : 10 TUAS AVE 18

S/N	PART NO.	DESCRIPTION	QUANTITY	PRICE
1	504116073	FRONT CORNER PANEL LHS	1	\$ 1,033.77 <i>Pha.</i>
2	504117929	FRONT CORNER PANEL SEAL LHS	1	\$ 63.13 <i>new</i>
3	504044297	FRONT CORNER PANEL RETAINER LHS	1	\$ 21.72 <i>new</i>
4	504302568	FRONT SIDE FENDER LHS	1	\$ 1,652.98 <i>CRA</i>
5	504331360	FRONT STEP GARNISH LHS	1	\$ 1,105.87 <i>CRA</i>
6	504061726	SUNVISOR	1	\$ 2,571.32 <i>CRA</i>
7	504074032	SUNVISOR SIDE LAMP LHS	1	\$ 91.40 <i>CRA</i>
SUB-TOTAL :				\$ 6,540.19
LESS 25% :				\$ 1,635.05
PARTS TOTAL :				\$ 4,905.14

LABOUR CHARGES

1 TO REMOVE & REFIX FRONT CORNER PANEL, FRONT SIDE FENDER, FRONT STEP GARNISH AND SUNVISOR ASSY.	\$ 1,500.00 <i>1200</i>
2 TO CARRY OUT SPRAY PAINTING ON FRONT CORNER PANEL, FRONT SIDE FENDER, FRONT STEP GARNISH AND SUNVISOR ASSY.	\$ 1,050.00 <i>700</i>
LABOUR TOTAL :	\$ 2,550.00
GRAND TOTAL :	\$ 7,455.14

PREPARED BY : WILLIAM GO

DATE / TIME : _____
SURVEYOR : _____
MOBILE NO. : _____
OFFICE FAX NO. : _____
EMAIL ADDRESS : _____

1019113

SUPPLEMENTARY ESTIMATE

DATE : 25/10/2017
TO : WAREHOUSE LOGISTICS NET ASIA P/L
ATTN : MR. JACKY
OFFICE / MOBILE : -
FAX NO. : -
FROM : MOTORVIVA PTE LTD
ATTN : MR. WILLIAM GO
OFFICE / MOBILE : 6864-0637 / 9755-7336
FAX NO. : 6863-0425
VEHICLE NO. : XD4500S
MODEL NO. : IVECO ML190EL25
CHASSIS NO. : ZCFA1VJ0402574162
ENGINE NO. : 778770
REF. NO. : GBE/SVC/SALES-4455/171020
D.O.A. : 20/10/2016
POLICY NO. : -
CLAIM TYPE : TP CLAIM - MSIG
WORKSHOP : 10 TUAS AVE 18

S/N	PART NO.	DESCRIPTION	QUANTITY	PRICE
1	504116073	FRONT CORNER PANEL LHS	1	\$ 1,033.77
2	504117929	FRONT CORNER PANEL SEAL LHS	1	\$ 63.13
3	504044297	FRONT CORNER PANEL RETAINER LHS	1	\$ 21.72
4	504302568	FRONT SIDE FENDER LHS	1	\$ 1,652.98
5	504331360	FRONT STEP GARNISH LHS	1	\$ 1,105.87
6	504061726	SUNVISOR	1	\$ 2,571.32
7	504074032	SUNVISOR SIDE LAMP LHS	1	\$ 91.40
SUB-TOTAL :				\$ 6,540.19
LESS 25% :				\$ 1,635.05
PARTS TOTAL :				\$ 4,905.14

LABOUR CHARGES

1 TO REMOVE & REFIX FRONT CORNER PANEL, FRONT SIDE FENDER, FRONT STEP GARNISH AND SUNVISOR ASSY.	\$ 1,200.00
2 TO CARRY OUT SPRAY PAINTING ON FRONT CORNER PANEL, FRONT SIDE FENDER, FRONT STEP GARNISH AND SUNVISOR ASSY.	\$ 900.00
LABOUR TOTAL :	\$ 2,100.00
GRAND TOTAL :	\$ 7,005.14

PREPARED BY : WILLIAM GO

DATE / TIME :
SURVEYOR :
MOBILE NO. :
OFFICE FAX NO. :
EMAIL ADDRESS :

1st Estimate : 2405.99

Supp Estimate : 7005.14

\$9411.13



MOTORVIVA PTE LTD
10 Tuas Avenue 18 Singapore 638894
Tel: +65 6685 2518 (Sales) +65 6448 2686 (Service)
Fax: +65 6561 7956 (Sales) +65 6442 5571 (Service)
Website: www.goldbell.com.sg
Co. Reg. No.: 1995076142

DATE : 20/10/2017

TO : WAREHOUSE LOGISTICS NET ASIA P/L
ATTN : MR. JACKY
OFFICE / MOBILE : - 9726891
EMAIL ADDRESS : -

FROM : MOTORVIVA PTE LTD
ATTN : MR WILLIAM GO
OFFICE / MOBILE : 6864-0637 / 9755-7336
FAX NO. : 6863-0425

VEHICLE NO. : XD4500S
MODEL NO. : IVECO ML190EL25
CHASSIS NO. : ZCFA1VJ0402574162
ENGINE NO. : 778770
REG. DATE : 31/03/2011

REF. NO. : GBE/SVC/SALES-4455/171020
D.O.A. : 17/10/2016
POLICY NO. : -
CLAIM TYPE : TP CLAIM - MSIG

WORKSHOP : 10 TUAS AVE 18

S/N	PART NO.	DESCRIPTION	QUANTITY	PRICE
1	5801765367	REAR VIEW MIRROR LHS	1	\$ 2,103.89 <i>820</i>
2	5801351720	REAR VIEW MIRROR TOP GASKET LHS	1	\$ 24.10 <i>24</i>
SUB-TOTAL :				\$ 2,127.99
LESS 25% :				\$ 532.00
PARTS TOTAL :				\$ 1,595.99
<u>LABOUR CHARGES</u>				
1	TO TOW VEHICLE BACK TO WORKSHOP.			\$ 200.00
2	TO REMOVE & REFIX REAR VIEW MIRROR ASSY.			\$ 380 600.00 <i>450</i>
3	TO CHECK FOR & RECTIFY WIRING FAULTS, ETC. TO CARRY OUT DIAGNOSTICS CHECK.			\$ 280.00 <i>200</i>
4	SUNDRIES			\$ 60.00 <i>30</i>
LABOUR TOTAL :			<i>810.00</i>	\$ 1,140.00
GRAND TOTAL :			<i>2405.99</i>	\$ 2,735.99

PREPARED BY : WILLIAM GO

DATE / TIME : 23/10/17 @ 1700
SURVEYOR : RASUL
MOBILE NO. : 90010068
OFFICE FAX NO. :
EMAIL ADDRESS : rasul@lkkauto.com

REPAIR TYPE : PART-BY-PART / LUMP SUM
RE-SURVEY : BEFORE PAINT / AFTER PAINT
NO. OF DAYS : 1 days
REMARKS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Supp

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Oct 2017		23 Oct 2017 11:18 Edit Adj Rpt	S\$9,411.13 Edit Estimates	S\$9,411.13 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Acelink Logistics Pte Ltd, Co. Reg. No.: 199202352M								
Main Claimant:	WAREHOUSE LOGISTICS NET ASIA PTE LTD, Co. Reg. No.: NA								
Vehicle Reg. No.:	XD4500S	Date of Loss:	17/10/2017 11:00 - :59 [78 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 533620	Policy/Cover Note No.:	28677733MKF (Comprehensive) Coverage: 01/01/2017 - 31/12/2017						
Vehicle Reg. No. (Insured):	YP5908T	Policy No. (Claimant):							
		Excess:							
Repairer:	Motorviva Pte Ltd (HQ) 10 Tuas Avenue 18, 638894 Tuas - Tel: 68640695								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 24/10/2017]								
Driver/Custodian (Insured):	LIM TENG BOON (50), NRIC: S1778552D, Tel: +6598332833								
Adj Asg. Remarks:	SURVEY ON WP BASIS. Car will be at no. 18 Tuas Avenue 10, survey anytime after 1.30pm.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XD4500S (533620)

[YP5908T]

TP

WAREHOUSE LOGISTICS NET ASIA PTE LTD

Oct 17 2017 11:00AM

[Acelink Logistics Pte Ltd]

Motorviva Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser		
			1 per page	☒	
Assessment Reports			Thumbnail	Print	
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	1	Load HTM	
1	17/10/17 17:33	Accident Statement			
			3 per page	☒	
Photos/Images			Thumbnail	Print	
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	1	Load JPG	☒
1	17/10/17 17:23	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
2	17/10/17 17:23	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
3	17/10/17 17:23	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
4	17/10/17 17:23	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
5	17/10/17 17:23	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
6	17/10/17 17:23	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
7	17/10/17 17:23	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
8	17/10/17 17:23	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
9	17/10/17 17:23	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
10	17/10/17 17:23	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
11	17/10/17 17:23	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
12	17/10/17 17:23	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	19/04/18 17:34	General View	1	Load JPG	☒
2	19/04/18 17:34	General View	1	Load JPG	☒
3	19/04/18 17:34	General View	1	Load JPG	☒
4	19/04/18 17:34	General View	1	Load JPG	☒
5	19/04/18 17:34	General View	1	Load JPG	☒
6	19/04/18 17:34	General View	1	Load JPG	☒
7	19/04/18 17:34	General View	1	Load JPG	☒
8	19/04/18 17:34	General View	1	Load JPG	☒
9	19/04/18 17:34	General View	1	Load JPG	☒
10	19/04/18 17:34	General View	1	Load JPG	☒
11	19/04/18 17:34	General View	1	Load JPG	☒
12	19/04/18 17:34	General View	1	Load JPG	☒
13	19/04/18 17:34	General View	1	Load JPG	☒
14	19/04/18 17:34	General View	1	Load JPG	☒
15	19/04/18 17:34	General View	1	Load JPG	☒
16	19/04/18 17:34	General View	1	Load JPG	☒
17	19/04/18 17:34	General View	1	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
18	19/04/18 17:34	General View	 Load JPG	☒
19	19/04/18 17:34	General View	 Load JPG	☒
20	19/04/18 17:34	General View	 Load JPG	☒
21	19/04/18 17:34	General View	 Load JPG	☒
22	19/04/18 17:34	General View	 Load JPG	☒
23	19/04/18 17:34	General View	 Load JPG	☒
24	19/04/18 17:34	General View	 Load JPG	☒
25	19/04/18 17:34	General View	 Load JPG	☒
26	19/04/18 17:34	General View	 Load JPG	☒
27	19/04/18 17:34	General View	 Load JPG	☒
28	19/04/18 17:34	General View	 Load JPG	☒
29	19/04/18 17:35	General View	 Load JPG	☒
30	19/04/18 17:35	General View	 Load JPG	☒
31	19/04/18 17:35	Reinspection Photo	 Load JPG	☒
32	19/04/18 17:35	Reinspection Photo	 Load JPG	☒
33	19/04/18 17:35	Reinspection Photo	 Load JPG	☒
34	19/04/18 17:35	Reinspection Photo	 Load JPG	☒
35	19/04/18 17:35	Reinspection Photo	 Load JPG	☒
36	19/04/18 17:35	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/10/17 08:56	Estimate - XD 4500 S	 Load PDF	
2	23/10/17 09:05	YP5908T	 Load PDF	
3	23/10/17 09:15	REPLY TP DIRECT SETTLEMENT DD 23.10.17	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/04/18 14:34	Supplementary	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	1 per page	☒
1	17/10/17 17:33	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	17/10/17 17:23	Accident Photo	 Load JPG	☒
2	17/10/17 17:23	Accident Photo	 Load JPG	☒
3	17/10/17 17:23	Accident Photo	 Load JPG	☒
4	17/10/17 17:23	Accident Photo	 Load JPG	☒
5	17/10/17 17:23	Accident Photo	 Load JPG	☒
6	17/10/17 17:23	Accident Photo	 Load JPG	☒
7	17/10/17 17:23	Accident Photo	 Load JPG	☒
8	17/10/17 17:23	Accident Photo	 Load JPG	☒
9	17/10/17 17:23	Accident Photo	 Load JPG	☒
10	17/10/17 17:23	Accident Photo	 Load JPG	☒
11	17/10/17 17:23	Accident Photo	 Load JPG	☒
12	17/10/17 17:23	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒

Assessment Reports				1 per page	☒
No	Finalized On		STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
No	Finalized On		STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	17/10/17 17:29		Sketch Plan	 Load JPG	☒
2	17/10/17 17:29		Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17020197/R1TBE2
Date: 20/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28677733MKF

Claimant Vehicle No: XD4500S

Insured Vehicle No: YP5908T

Date of Loss: 17/10/2017

Nature of Claim: TP Claim No: 533620

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD4500S

Make & Model: IVECO ML190EL25, 5.9 D (M)

Reg. Date: 31/03/2011 (Man. Year: 2010)

Colour: White

Engine Capacity: 5880 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 778770

Chassis No: ZCFA1VJ0402574162

Odometer: 161114 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5 (D)

Front Left Side: Hankook 8 mm

Rear Left Side: Hankook 8/8 mm

Front Right Side: Hankook 8 mm

Rear Right Side: Hankook 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,561.13	6,531.13	30.00	0.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,630.00	2,880.00	750.00	20.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,191.13	9,411.13	780.00	7.65
+ GST 7.00/7.00% (S\$)	713.38	658.78	54.60	7.65
Nett Amount (S\$)	10,904.51	10,069.91	834.60	7.65

INSPECTION

Date of Assignment: 23/10/2017

Date Inspected: 23/10/2017

Inspected At:

Motorviva Pte Ltd (HQ)
10 Tuas Avenue 18
Singapore 638894

Estimated Period of Repair: 1.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Apr 2018)	
Parts:	N/A	IVECO ML190EL25 5.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD4500S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR VIEW MIRROR LHS	Broken	2,103.89 FL	*2,103.89 FL
2	1		*REAR VIEW MIRROR TOP GASKET LHS	Necessary	24.10 FL	*24.10 FL
3	1		*SUNDRIES	Necessary	60.00 FS	*30.00 FS
4	1		*FRONT CORNER PANEL LHS	Broken	1,033.77 FL	*1,033.77 FL
5	1		*FRONT CORNER PANEL SEAL LHS	Necessary	63.13 FL	*63.13 FL
6	1		*FRONT CORNER PANEL RETAINER LHS	Necessary	21.72 FL	*21.72 FL
7	1		*FRONT SIDE FENDER LHS	Cracked	1,652.98 FL	*1,652.98 FL
8	1		*FRONT STEP GARNISH LHS	Cracked	1,105.87 FL	*1,105.87 FL
9	1		*SUNVISOR	Cracked	2,571.32 FL	*2,571.32 FL
10	1		*SUNVISOR SIDE LAMP LHS	Cracked	91.40 FL	*91.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,728.18	8,698.18
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,167.05	2,167.05
Total Parts (\$\$)	6,561.13	6,531.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TOW VEHICLE BACK TO WORKSHOP	New	200.00	200.00
2	TO REMOVE & REFIX REAR VIEW MIRROR ASSY	New	600.00	380.00
3	TO CHECK FOR & RECTIFY WIRING FAULTS, ETC. TO CARRY OUT DIAGNOSTICS CHECK	New	280.00	200.00
4	TO REMOVE & REFIX FRONT CORNER PANEL, FRONT SIDE FENDER, FRONT STEP GARNISH AND SUNVISOR ASSY	New	1,500.00	1,200.00
5	TO CARRY OUT SPRAY PAINTING ON FRONT CORNER PANEL, FRONT SIDE FENDER, FRONT STEP GARNISH AND SUNVISOR ASSY	New	1,050.00	900.00
Gross Labour Cost (S\$)			3,630.00	2,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >