

ASS. REC. BY:

REF: CS/EG17020331/Urbn2 Special Instruction:

5/11/2017

ASSIGNMENT (Office)

From (Person): Yee Pei Li of EGI Date/Time: 24/10/17 @ 12:14pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKU 9484 L Insured: SKV 9459 E

at Workshop m/s Progressive Tel: 82983043

of No. 1 Kaki Bkt Ave 6 #02-48/50 / 417883

Policy No: Claim No: DSMPC1702506

Sum Insured: Excess:

Make of Veh: D.O.A. 20/10/2017
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

R.O.D. Endorsement

Date/Time: 24/10/17 @ 12:29pm Person Contacted: Mr. Wong Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SKU 9484 L - CS3 / CTI17004999 / R19be2 - D.O.A: 28/02/2017
	SKV 9459 E - X
	Sent preli through email.

Surrounding *Mercur*

SK11

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: *SKU 9484L*
 at Workshop m/s *PA Leck*
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: *1* days Res.: Yes or No
 Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: *SKU 9484L* Yr Regn: *212*
 Type: *M* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or *CA*
 Make: *VOLVO* S60 C.C. *15-96*
 Colour: *Silver* A/C: Insured / Std / NI / NA
 Sp. Reading: *101475* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *YV1FS485BC2114062*
 Gen. Cond: *Good* / Fair / Poor / Burnt
 Steering: *Good* / Jammed / Leaked / Burnt or
 Brake: *Good* / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: *225/50R17*
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or *Continental*

Front *6* mm Rear *6* mm
 R/Bal. *6* mm L/Bal. *6* mm
 D.O.A. *20/10/17* D.O.I. *14/12/17*
 Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S mirror
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction *L1A 4855*

9/1/18 confirmed L/S \$800 with MR Wong

Red: \$569.50, 41%.

RECEIVED 10 JAN 2018

Date/Time. File Pass to?

1) *typist*

Date/Time. File Return to?

2)

Report Format: *TP*

Lump Sum / *LE*: (\$ *800*)

Days Of Repair: *1*

Resurvey No. of Trip: *1*

Add Fee:

☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation:

) Photos

) Others

TOTAL

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI17020331/Urb

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 24-10-2017



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKV 9459E	Veh. Inspected	SKU 9484L
Policy No.		Coverage (\$)	0.00
Claim No.	DSMPC1702506	Excess (\$)	0.00
Assign From	YEE PEI LEE	Assign Date	24/10/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/10/2017	Inspection Date
Survey held at	PROGRESSIVE AUTO PTE LTD NO.1 KAKI BUKIT AVE 6 #02-48/50 AUTOBAY SINGAPORE 417883	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 24 October, 2017 12:14 PM
To: 'admin-d@lkkauto.com'
Subject: OI : SKV9459E / TP : SKU9484L/LKK / DOA : 20.10.2017 (DSMPC1702506)
Attachments: SKV9459E - SAS.pdf; SKU9484L - SAS.pdf; SKU9484L - PRS FORM.pdf; Re: ACCIDENT INVOLVING SKU9484L & SKV9459E ON 20/10/2017 ALONG WOODLANDS ... (124 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **PROGRESSIVE AUTO PTE LTD,**

ADDRESS : NO 1 KAKI BUKIT AVE 6
#02-48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : MANDY @ 6844 4620

ERGO OFFICER-IN-CHARGE : ELAINE NGU

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and Inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Best Regards

Yee Pei Li
Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
DID: 65 6829 9194
Fax: 65 6829 9247
Website: www.ergo.com.sg



Have you tried our new travel insurance product yet?
TravelProtect comes with comprehensive benefits at some of the most
affordable prices available in the market.

ERGO
TravelProtect
your Global Safety Net

TravelProtect is underwritten by ERGO Insurance Plc Ltd



ERGO

Date: 24.10.2017
Our Reference: DSMPC1702506/SA/pl
Your Reference: SKU 9484L

To: PROGRESSIVE AUTO PTE LTD

Sent via Fax
or
Email

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SKU 9484L
Insured's Vehicle: SKV 9459E
Date Of Accident: 20.10.2017


We acknowledge receipt of your request for PRS on: 20.10.2017

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐ Your request for inspection does not have your client's complete GIA report, kindly forward a copy.
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐ Our Insured's driver has not reported the accident to us todate.
☒ Others: OFFICER-IN-CHARGE - SIT1

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				<u>FAX : 6829 9247</u>

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Your Ref: DSMPC1702506
Our Ref: CS/EGH17020331/Urb

The Motor Claims Department
ERGO Insurance Pte Ltd

Without Prejudice

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. SKU 9484L .

We thank you for the instruction on 24/10/2017.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14/12/2017 at the premises of M/s PROGRESSIVE AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,369.50</u> .
Revised Estimate Amount	: S\$ <u>1,000.30</u> .
"Check" Items Amount	: S\$ _____ .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:
The vehicle sustained damages
at the n/s mirror.



Comments/ Present Status:
Damages Consistent.

Yours faithfully

MARCUS CHUA
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	3939F
Vehicle Details	
Vehicle No.	SKU9484L
Vehicle to be Exported	No
Intended De-registration Date	14 Dec 2017
Vehicle Make	VOLVO
Vehicle Model	S60 T4 1.6 AT ABS D/AB 2WD 4DR TC
Primary Colour	Silver
Manufacturing Year	2011
Engine No.	B4164T1062326
Chassis No.	YV1FS485BC2114062
Maximum Power Output	132.0 kW (177 bhp)
Open Market Value	\$35,116.00
Original Registration Date	28 Feb 2012
First Registration Date	28 Feb 2012
Transfer Count	2
Actual ARF Paid	\$35,116.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	27 Feb 2022
PARF Rebate Amount	\$24,581.00
Intended COE Rebate Details	
COE Expiry Date	27 Feb 2022
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$57,009.00
COE Rebate Amount	\$23,974.00
Total Rebate Amount	\$48,555.00

The information contained herein is correct as at 14 Dec 2017

OK

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg

GST:200712509E RCB NO:200712509E

M/S : ERGO Insurance Pte Ltd
5 Temasek Boulevard #04-01

Suntec Tower Five

Singapore 038985

TEL: (65)6829 9199 (Ext: 170) FAX: (65) 6829 9247

ATTN: Motor Claim Department

Your Ref No: SKU9484L

Claim Type: Third Party

Accident Date: 20-10-2017

TP Veh Reg No: SKV9459E

Estimate No: EST0000504

Date: 27 Oct 2017

Policy No: DMPCSN1555001707

Veh Reg No: SKU9484L

Chassis No:

Engine No:

Reg. Date:

Estimate Repair Cost to Vehicle No :SKU9484L

Description	U/Price	Quantity	List Price SS	Amount SS
VOLKSWAGEN S60 T4 1.6				
List Price				
1 Front Door Side Mirror Housing	648.0000	1 PC	648.00	
2 Front Door Side Mirror Glass LH	213.0000	1 PC	213.00	
3 Front Door Side Mirror Cover LH	288.0000	1 PC	288.00	
4 Front Door Side Mirror Light LH	106.0000	1 PC	106.00	
			1,255.00	
	967	Less 10%	125.50	1,129.50
Labour				
5 To Remove & Replace Door Side Mirror	180.0000	1 PC	180.00	
6 To Spray Painting	60.0000	1 PC	60.00	
			240.00	240.00
			Total	SS 1,369.50

TOTAL: SINGAPORE DOLLAR ONE THOUSAND THREE HUNDRED SIXTY NINE AND CENTS FIFTY ONLY [1000.]

For PROGRESSIVE AUTO PTE LTD

Progressive Auto Pte Ltd

No 1 Kaki Bukit Ave 6 Autobay

#02-48/50 Singapore 417883

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Ackd
LH
h/s s 800/-
1 day.
to be photo after repair
14/12/17




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EG17020331/Urbn2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 12-01-2018	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKV 9459E	Veh. Inspected	SKU 9484L	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMPC1702506	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	24/10/2017	
2. Vehicle Particulars & Condition				
Make & Model	VOLVO S60 (A)	c.c	1596	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	YV1FS485BC2114062	Colour	SILVER	
Odometer	101475	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	CONTINENTAL	6 mm	
L/H Front Tyre	225/50 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	225/50 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	225/50 R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S MIRROR. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/10/2017	Inspection Date	14/12/2017	
Survey held at	PROGRESSIVE AUTO PTE LTD NO.1 KAKI BUKIT AVE 6 #02-48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 9484L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR SIDE MIRROR HOUSING	CRACKED	648.00	648.00
1	FRONT DOOR SIDE MIRROR GLASS LH	DAMAGED	213.00	213.00
1	FRONT DOOR SIDE MIRROR COVER LH	TO REPAIR SEE LABOUR	288.00	-
1	FRONT DOOR SIDE MIRROR LIGHT LH	SCRATCHED	106.00	106.00
	LESS 10% DISCOUNT		-125.50	-96.70
			1,129.50	870.30
	LABOUR			
	TO REMOVE & REPLACE DOOR SIDE MIRROR INCLUSIVE OF THE REPAIR OF FRONT DOOR SIDE MIRROR COVER LH. }		180.00	130.00
	TO SPRAY PAINTING. }		60.00	-
			240.00	130.00
	GRAND TOTAL		1,369.50	1,000.30
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			800.00

Report Ref No. CS/EGI17020331/Urbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.