

ASS. REC. BY: RES CS/FCI17020417/Rgb e2 Special Instruction:
 SW/NO. RUSW ASSIGNMENT (Office)
 From (Person): WS Sithara of FCI Date/Time: 25/10/17 @ 11:56am
 Estimated Cost: _____ Bill to: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: SLG 3815S Insured: SHB 2611T
 at Workshop n/o: Charm's Customcraft Tel: 62725429
 of B1K1016 Bkt Merah Lane 3 # 61-105
 Policy No: _____ Claim No: D17009482MFSH
 Sum Insured: _____ Excess: _____
 Make of Veh: _____ D.O.A. 19/10/2017
 (Client's Record)
 CA / REV / REP. / REV 24 HRS 'wp' 26.10.2017 @ 3pm-5pm
 Date/Time: 25/10/17 @ 12:06pm Person, Contacted: Sharon H.O.D. Endorsement: _____
 Vehicle IN/OUT: OUT

Date/Time	Action/Instruction (✓) Estimate
	SLG 3815S - CC3 / AIG17020198 / K1203-D-O.A: 19/10/2017
	SHB 2611T - CC3 / AIG17020198 / K1203-D-O.A: 19/10/2017

26/10/17 *Pare*

REF: FCI

95826

COT XP124: 2022/11/14

ASSIGNMENT

From: Date: 26/10/17

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLG 3815 S

at Workshop no: Charn's Customcraft

of: BLK 1010 Bkt Merah Lane 3 # 01-105

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

3pm - 5pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

95K

IDAO Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP / 24 HRS 'wp'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SLG 3815S

Page: 2007 AmL

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 325 I Convertible 2497

Colour: Black A/C Insured / Std / NI / NA

Sp. Reading: 158521 T. Radio Insured / Std / NI / NA

Eng No:

C No: WBA WL 170 20P0 75 299

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / B Rim / STD A/Rim or

Tyre Size: F: 225/40ZR18

R:

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R. Bal: 6 mm R. Bal: 6 mm

L. Bal: 6 mm L. Bal: 6 mm

D.O.A: 17/10/17 D.O.A: 26/10/17

Survey held at: Charn's Customcraft

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

27/10/17 email preli to sathara.

13/12/17 Sharon said vehicle not send in for repair, liability not clear.

15/12/17 Submit preliminary report.

MV: \$95000, LTA: \$24376, NV: \$70624

RECEIVED 15 DEC

RECEIVED 20 DEC 2017

Date/Time File Pass to:



Preli. Report



Final Report

Date/Time File Return to:

2:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transaction

1-30-31

Photo

Notes

Add Fee:



Site Insp \$



Interview \$



Tech Insp \$



Witness \$

Report Format:

Lump Sum / L.Bil: \$

110
50
32
182



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17020417/R1gb		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 25-10-2017		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2611T	Veh. Inspected	SLG 3815S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17009982MFSH	Excess (\$)	0.00	
Assign From	CWS (SITHARA)	Assign Date	25/10/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	19/10/2017	Inspection Date		
Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	24-10-2017	Our Ref No. D17009982MFSH
Accident Date	19-10-2017	Claim Type. Third Party
Insured Vehicle	SHB2611T	Third Party Vehicle. SLG3815S
Survey Location	BLK 1010 BUKIT MERAH LANE 3 #01-105	
Contact Person.	SHARON LEE	
Contact No.	62725429/ 0	Fax No. 62736676
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHARN'S CUSTOMCRAFT	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/229439)



PRI Documents



Close



PRI Header Details

Claim No	D17009982MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & CHARN'S
Workshop Name	CHARN'S CUSTOMCRAFT (Contact Person : SHARON LEE)	Survey Location & Contact Details	BLK 1010 BUKIT MERAH LANE 3 #01-105 Mobile: 0 , Phone: 62725429 , Fax: 62736676 EmailId: CHARNS@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB2611T	TP Vehicle No	SLG3815S
PRI Recieved Date	24-10-2017 08:47:33 PM	Surveyor Appointed Date	25-10-2017 11:55:40 AM	Surveyor Accept Date	25-10-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	25-10-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
File Name	Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
---------	----------------------	-------------------------------------

Ai Phing (LKKAUTO)

From: Ai Phing (LKKAUTO)
Sent: Friday, 27 October, 2017 4:45 PM
To: 'Claim Workflow System'
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17009982MFSH/1
Attachments: SLG 3815S.pdf

Dear Sithara,

Enclosed herewith preliminary advise of vehicle SLG 3815S.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 25 October, 2017 12:08 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17009982MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not In workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Wednesday, 25 October, 2017 11:56 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SITHARA@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17009982MFSH/1

Dear Sir/Mdm,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17009982MFSH

Date: 27-10-2017

Our Ref: CS/FC117020417/R1gb

The Motor Claims Department
First Capital Insurance Ltd

Without Prejudice

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLG 3815S

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26-10-2017 at the premises of M/s CHARN'S CUSTOMCRAFT and have the following to report:-

Workshop Estimate Amount	: S\$ 2,840.06
Revised Estimate Amount	: S\$ 2,095.84
"Check" Items Amount	: S\$ 408.42
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Yours faithfully

Mohamed Rasul
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/10/2017 15:26
Date Of Accident	19/10/2017 17:30
Exact Location Of Accident	MARINA SOUTH PIER CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG3815S
Insured/Policyholder	
Name Of Registered Owner	YEO CHING PING
NRIC No	S9249582E
Email Address	CHARNS@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-96382623
Alternative Phone No	OTHERS-96382623

Vehicle Particulars

Manufacturer	BMW
Model	325I CONVERTIBLE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700029456
Cover Note Number	

Driver

Name of Driver	YEO CHING PING
NRIC No	S9249582E
Date Of Birth	15/10/1992
Occupation	INDOOR
Date Of Driving Pass	06/08/2011
Driving Experience	6 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96382623
Fax Number	
Contact Number	OTHERS-96382623
Email Address	CHARNS@SINGNET.COM.SG

Address	BLK 823 JURONG WEST STREET 81 #10-468
Postcode	640823
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB2611T
Vehicle Make/Model/Colour	MERCEDES BENZ(TAXI)
Details Of Properties	
Name of Driver	CHOO SWEE HWA
NRIC/Passport Number	S1301456F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan

SKETCH PLAN

CLG38455
19/10/17

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 20/10/17 3pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name

NRIC/FIN No.:

$\Rightarrow 50419$
 50419

MARINA SUMA PIAR CORPORA

1 | Parking slot

B) 5H₂2611 T

1 loading Bay

I wanted to reverse into a parking slot on my right E Main St south
pier canyon and before I could reverse, Taxi SHB2611 T turn
out of the loading bay and hit my left rear bumper.

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature:
Name: _____
NRIC/FIN No.: ResLi WAHAB

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	9582E

Vehicle Details

Vehicle No.	SLG3815S
Vehicle to be Exported	Yes
Intended De-registration Date	20 Oct 2017
Vehicle Make	B.M.W.
Vehicle Model	325I CONVERTIBLE
Primary Colour	Blue
Manufacturing Year	2007
Engine No.	76834063N52B25AF
Chassis No.	WBAWL12020PD75299
Maximum Power Output	160.0 kW (214 bhp)
Open Market Value	\$63,270.00
Original Registration Date	02 Aug 2007
First Registration Date	02 Aug 2007
Transfer Count	3
Actual ARF Paid	\$69,597.00

Intended PARF Rebate Details

PARF Eligibility	Forfeited
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	01 Aug 2022
COE Category	E - Open Category
COE Period(Years)	5
PQP Paid	\$25,486.00
COE Rebate Amount	\$24,376.00
Total Rebate Amount	\$24,376.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 20 Oct 2017

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9249582E



Name

YEO CHONG PING

楊宗彬

Race

CHINESE

Date of birth

15-10-1992

Sex

M

Country of birth

INDONESIA

S9249582E

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S9249582E

Name

YEO CHONG PING

Birth Date: 15 Oct 1992

Issue Date: 05 Aug 2011



1001988689H



4120125

NRIC No. S9249582E



Date of issue

24-10-2007

Address


APT BLK 823 JURONG WEST STREET 81
10-468
SINGAPORE 640823

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

EFFECTIVE DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 05 Aug 2011

NP 428A



Licence No. S9249582E



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

1-3pm
thur
nirvita

AIG/FC(SHB2611T)
DOA: 19/10/2017@1730

FIRST CAPITAL INSURANCE PTE LTD

24/10/2017

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SLG 3815 S - BMW 325I CONVERTIBLE
CHASSIS NO: WBAWL12020PD75299 (2007)

1 pc Rear bumper
1 pc Rear bumper retainer LH
1 pc Rear bumper lower garnish
1 pc Rear bumper reinforcement

\$	1,345.00	CRA
\$	37.40	new
\$	335.20	CRA
\$	453.80	?
\$	2,171.40	
\$	217.14	
\$	1,954.26	

LESS 10%

Remove necessary parts; jacking, panel beating, repair and
straighten rear inner panel, rear fender LH and rear bumper.

\$ ~~300.00~~ 250

Putty and respray rear inner panel, rear fender LH and rear
bumper.

\$	400.00 300
\$	2,654.26
\$	185.80
\$	2,840.06

ADD 7% GST

Note: The above is an estimate only. If other parts requested during the
course of repair, we will inform you accordingly.

All new/O.E.M/recon parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

RASUL
3 days
Hp 90015068
4/3
28/10/17 27/10/17
@1545
Reg after
refer




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17020417/R1gbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2611T	Veh. Inspected	SLG 3815S	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17009982MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	25/10/2017	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 325i CONVERTIBLE	c.c	2497	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	WBAWL12020PD75299	Colour	BLACK	
Odometer	158521	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40Z R18	BRIDGESTONE	6 mm	
L/H Front Tyre	225/40Z R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/40Z R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/40Z R18	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/10/2017	Inspection Date	26/10/2017	
Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724			
5a. Remarks				
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)DAMAGES CONSISTENT TO ACCIDENT REPORT. C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 3815S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	CRACKED	1,345.00	1,345.00
1	REAR BUMPER RETAINER LH	NECESSARY	37.40	37.40
1	REAR BUMPER LOWER GARNISH	CRACKED	335.20	335.20
1	REAR BUMPER REINFORCEMENT	* CHECK	453.80	-
	LESS 10% DISCOUNT		-217.14	-171.76
			1,954.26	1,545.84
LABOUR				
	REMOVE NECESSARY PARTS: JACKING, PANEL BEATING, REPAIR AND STRAIGHTEN REAR INNER PANEL, REAR FENDER LH AND REAR BUMPER.		300.00	250.00
	PUTTY AND RESPRAY REAR INNER PANEL, REAR FENDER LH AND REAR BUMPER.		400.00	300.00
			700.00	550.00
GRAND TOTAL			2,654.26	2,095.84
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$408.42 NETT)				2,095.84

Report Ref No. CS/FC117020417/R1gbe2

MARKET VALUE: \$95,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$24,376.00=NETT VALUE: \$70,624.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.