

APP. REC. BY

REF CS/MSG17020422/Tlgby2

SUBJECT

Tanzh

MAINEN

FROM / PERSON

Irene Tan

ASSIGNMENT (Office)

MSG

DATE/TIME

24/10/17 @ 4:37pm

ESTIMATED COST

RMT TO

OD ☒ TI / WS / TR RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLS 1746H

Insured:

FBL 17354

at Workshop no.

Kah Motor

Tel:

81006306

of

15 Ubi Rd 4, 408610

Policy No.

MSD/VM7/17-983989

Claim No.

MSC/V/17-001621

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A 15/10/2017

CA / REV / REP. / REV 24 HRS

'up'

255 Alexandra Rd  
(Leng Kee)

27/10/2017; 11 am @ owner waiting

H.O.D. Endorsement

Date/Time

25/10/17 @ 9:30 am

Person Conducted

Any

Vehicle IN/OUT

Date/Time

Action/Instruction

☒

Estimate

SLS 1746H - NA/MSG17020164/24 - D.O.A: 15/10/17

FBL 17354 - NA/MSG17020164/24 - D.O.A: 15/10/17

31/10/17 @

3.58pm refused to Irene Tan as mainen.

22/2/18 @

4.31pm confirmed with Patrick final fig @ 2203.10, 5 days.  
LPed @ 540.67, 20%.)



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17020422/T1qb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 25-10-2017



Code : MSG

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	FBL 1735U	Veh. Inspected	SLS 1746H
Policy No.	MSD/VMT/17-983989-WTT	Coverage (\$)	0.00
Claim No.	MSC/V/17-001621	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	25/10/2017

**2. Vehicle Particulars & Condition**

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

**4. Description of Damages**

--

**5. General Information**

Accident Date	15/10/2017	Inspection Date	
Survey held at	NO.255 ALEXANDRA ROAD		
Repairer	KAH MOTOR CO SDN BERHAD		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

# Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin** ( ): Case handler to make sure all information created by the assignment team are ACCURATE.

## (1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date

**Surveyor** ( ): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages


## (2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

--	--	--	--

## (3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days


## (4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submittal	Adj. Assigned	Adj. Ret.	Adj. Submitted	Ins. Auth'd	Status
Main	16 Oct 2017		24 Oct 2017 16:37 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

#### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured: **FAST CLASS SERVICES PTE LTD**, Co. Reg. No.: 201323390W, Tel: +6585115032

Main Claimant: **TANG HUIMING JOSEPH**, ID: S8332355H

Vehicle Reg. No.: **SLS1746H** Date of Loss: 15/10/2017 20:00 - :59

Claim Type: **TP / MSC/V/17-001621** Policy/Cover Note No.: MSD/VMT/17-983989-WTT (Third Party Only)  
Coverage: 04/07/2017 - 03/07/2018

Vehicle Reg. No. (Insured): **FBL1735U** Policy No. (Claimant):  
Excess:

Repairer: **Kah Motor Co Sdn Bhd (Ubi)** 15 Ubi Road 4, 408610 Ubi - Tel: 68465671

Handling Insurer: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: +65 6827 7888 ... [Handled by **Irene Tan Gek Ing** - 6594 2541]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Imm.Advice due 25/10/2017]

Driver/Custodian (Insured): **NATARAJAN PRADEEP KRISHNEN** (), NRIC: S9971415H, Tel: +6590268530

#### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Monday, 26 February 2018 4:30 PM  
**To:** 'Patrick Mok'; SUR  
**Subject:** RE: REQUEST TO CONFIRM FINAL BILL FOR SLS1746H

Dear Patrick,

Confirm final fig \$2,203.10 before GST and 5 repair days.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Patrick Mok [<mailto:patrickmok@honda.com.sg>]  
**Sent:** Wednesday, 31 January 2018 2:51 PM  
**To:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** REQUEST TO CONFIRM FINAL BILL FOR SLS1746H

Hi Taufikh and Team,

Please to forward the final bill for your confirmation.

Kindly assist to confirm the cost of repair and the number of repair days recommended soonest.

Awaiting for your reply.

Thank you for your time.

Warm regards.

**Patrick Mok**

Bodyshop Service Advisor

Kah Motor Co. Sdn. Bhd.

Mobile : **82886302**



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 31 Oct 2017

## Preliminary Advice

Insured Vehicle No	: FBL1735U	Accident Date	: 15/10/2017
TP Vehicle No	: SLS1746H	Assignment Date	: 24/10/2017
Make	: HONDA ODYSSEY	Est. Duration of Repair	: 5.00
Date of Inspection	: 27/10/2017		
Inspection At	: KAH MOTOR CO SDN BHD (UBI) 15 UBI ROAD 4 SINGAPORE 408610		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,743.77
Revised Amount	:S\$	2,203.10
Check Items (Estimated)	:S\$	30.67
Total	:S\$	2,233.77

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

### Remarks

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type	Singapore NRIC
Owner ID	2355H
<b>Vehicle Details</b>	
Vehicle No.	SL51746H
Vehicle to be Exported	No
Intended De-registration Date	31 Oct 2017
Vehicle Make	HONDA
Vehicle Model	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour	Silver
Manufacturing Year	2017
Engine No.	K24W72041217
Chassis No.	JHMRC1890HC203572
Maximum Power Output	129.0 kW (172 bhp)
Open Market Value	\$30,619.00
Original Registration Date	12 Sep 2017
First Registration Date	12 Sep 2017
Transfer Count	0
Actual ARF Paid	\$34,867.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	11 Sep 2027
PARF Rebate Amount	\$26,150.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date	11 Sep 2027
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$50,110.00
COE Rebate Amount	\$49,427.00
<b>Total Rebate Amount</b>	<b>\$75,577.00</b>

The information contained herein is correct as at 31 Oct 2017

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/10/2017 18:00
Date Of Accident	15/10/2017 20:45
Exact Location Of Accident	HUME AVENUE @ EXIT OF HUME PARK 1 CONDOMINIUM
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS1746H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TANG HUIMING JOSEPH
NRIC No	S8332355H
Email Address	JHTANG83@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98265982
Alternative Phone No	OFFICE-98265982
<b>Vehicle Particulars</b>	
Manufacturer	HONDA
Model	ODYSSEY-2.4 EXV-S CVT SR (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MU009328-R00
Cover Note Number	

### Driver

Name of Driver	TANG HUIMING JOSEPH
NRIC No	S8332355H
Date Of Birth	17/10/1983
Occupation	INDOOR
Date Of Driving Pass	22/04/2004
Driving Experience	13 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98265982
Fax Number	
Contact Number	OFFICE-98265982
EEmail Address	JHTANG83@GMAIL.COM

Address  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 5

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO ATTACHMENT

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBL1735U  
 Vehicle Make/Model/Colour YAMAHA YBR125  
 Details Of Properties  
 Name of Driver NATARAJAN PRADEEP KRISHNEN  
 NRIC/Passport Number S9971415H  
 Contact Number 90268530  
 Address BLOCK 111 WHAMPOA ROAD #14-37  
 Postcode 321111  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

#### Details of Witness

Name  
 Phone Number  
 Email Address

Vehicle No SLS1746H

## SKETCH PLAN

Annex D

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


*[Signature]* 16/10/2017  
1500 hrs

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

*[Signature]*  
Witnessed by Reporting Centre Personnel

### Sketch Plan



Please continue to Annex C

Vehicle No SLS 1746H

Annex E

Describe Circumstances of the Accident

At about 2043 hrs on 15/10/2017, my vehicle (SLS 1746H) had just turned left into Hume Avenue from Upper Bukit Timah Road. I approached the entrance of Hume Park I Condominium. ~~As~~ I was passing by the entrance/exit of Hume Park I, (I was proceeding along the main road). The motorcycle (FBL 1735 U) was ~~existing~~ exiting Hume Park I Condo, but did not stop before turning onto the main road, as ~~I~~ I was passing the ~~entrance/exit~~ entrance/exit. The motorcycle knocked into the left side of my car.

You had been advised by the workshop that in the event that you wish to claim against your own policy (OD claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Declaration

We declare the foregoing particulars are true in every respect.

Y. Tang 16/10/2017  
1500hrs  
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

W. Wong  
Witnessed by Reporting Centre Personnel



**KAH MOTOR CO. SDN. BHD.**  
 (A Member of the Oriental Holdings Berhad)  
 Service and Body Repair  
 Tel: +65 6841 3838 Website: www.honda.com.sg  
 For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223  
 Company Ref. No.: S60FC1380G

<b>Customer</b>	: MSIG INSURANCE (SINGAPORE) PTE 16 RAFFLES QUAY HONG LEONG BUILDING SINGAPORE 048581	<b>Document No.</b>	: SQT17004293	<b>Page</b>	1
<b>Registration No</b>	: SLS1746H	<b>Date</b>	: 19. Oct 2017	<b>Customer No.</b>	: WZM003
<b>Chassis No</b>	: JHMRC1890HC203572	<b>Svc Advisor</b>	: PATRICK MOK LI KAY	<b>Engine No</b>	: K24W72041217
<b>Model</b>	: ODYSSEY 2.4 EXV-S 17YM (EURO 6)	<b>Date   Time</b>	: 19. Oct 2017 3:37:28 PM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: TANG HUIMING, JOSEPH	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	: 17-MU009328-R00				
<b>Date of Accident</b>	: 15/10/2017				

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: TANG HUIMING, JOSEPH OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 15/10/2017 SURVEYED BY: DATE: REF NO: TP INSURER: MSIG INSURANCE TP VEH: FBL1735U						
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BKRP02M	PANEL-BEAT/REPAIR LHF DOOR/LHR DOOR	1	1200.00		1200.00	84.00	1284.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	1	1000.00		1000.00	70.00	1070.00
	<b>Sum Labor</b>				<b>2300.00</b>	<b>161.00</b>	<b>2461.00</b>
74165-T6A-000ZG	GARNISH ASSYL.FR.FENDER LOWER	1	40.90	25	30.67	2.15	32.82
75332-T6A-J11ZG	GARNISH ASSYL.FR.DOOR LOWER	1	284.00	25	213.00	14.91	227.91
75333-T6A-J11ZG	GARNISH ASSYL.SLIDE DOOR LWR	1	266.80	25	200.10	14.01	214.11
	<b>Sum Item</b>				<b>443.77</b>	<b>31.07</b>	<b>474.84</b>

Survey By	Tan Jiah 97495749	<b>Total Amount</b>	2,743.77	192.07	2,935.84
Date & Time	27/10/17 01120	<b>Total (Inclusive of GST)</b>			<b>2,935.84</b>
Excess					
Status	WP				
Signature	Resurvey before paint sur@lkhauto.com				

Printed on 24/10/2017 2:55:49 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5480

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Customer: WZM003 / MSIG INSURANCE  
Chassis No: JHMRC1890HC203572  
License No: SLS1746H  
Mileage: 7877  
Engine No: K24W72041217

Document No: SVO17077318  
Printed By: PATRICKMOK  
Order Date: 11. December 2017  
Order Time: 4:02:02 PM  
Service Advisor: PATRICK MOK LIP KAY

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	GST Amt	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: TANG HUIMING, JOSEPH OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 15/10/2017 SURVEYED BY: DATE: REF NO: TP INSURER: MSIG INSURANCE TP VEH: FBL1735U						
75332-T6A-J11ZG	GARNISH ASSYL.FR.DOOR LOWER	1	284.00	25	213.00	14.91	227.91
75333-T6A-J11ZG	GARNISH ASSYL.SLIDE DOOR LWR	1	266.80	25	200.10	14.01	214.11
	SUM PARTS:				413.10	28.92	442.02
BOSUN	0701	1	50.00		50.00	3.50	53.50
	SUNDRIES						
BKRP02M	1466	1	840.00		840.00	58.80	898.80
	PANEL-BEAT/REPAIR LHF DOOR/LHR DOOR ALIGN RR FLOR & RENEW DAMAGE PARTS.						
BP06R	1718	1	900.00		900.00	63.00	963.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS						
	SUM LABOUR:				1,790.00	125.30	1,915.30
	TOTAL SGD				2,203.10	154.22	2,357.32

Total Payable (SGD)

2,357.32

GST Amount is calculated from individual line(s)

5 REPAIR DAYS

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Oct 2017		24 Oct 2017 16:37 <a href="#">Edit Adj Rpt</a>	<b>S\$2,203.10</b> <a href="#">Edit Estimates</a>	<b>S\$2,203.10</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	FAST CLASS SERVICES PTE LTD, Co. Reg. No.: 201323390W, Tel: +6585115032			
Main Claimant:	TANG HUIMING JOSEPH, ID: S8332355H			
Vehicle Reg. No.:	SLS1746H	Date of Loss:	15/10/2017 20:00 - :59	
Claim Type:	TP / MSC/V/17-001621	Policy/Cover Note No.:	MSD/VMT/17-983989-WTT (Third Party Only) Coverage: 04/07/2017 - 03/07/2018	
Vehicle Reg. No. (Insured):	FBL1735U	Policy No. (Claimant):		
		Excess:		
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 23/11/2017]			
Driver/Custodian (Insured):	NATARAJAN PRADEEP KRISHNEN (), NRIC: S9971415H, Tel: +6590268530			

ASSOCIATED MAIL RECEIVED		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.			

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## Claim Documents

**\*SLS1746H (MSC/V/17-001621)**  
**[FBL1735U]**  
**TP**  
**TANG HUIMING JOSEPH**  
**Oct 15 2017 8:00PM**  
**[FAST CLASS SERVICES PTE LTD]**  
**Kah Motor Co Sdn Bhd**

Upload Documents		Upload Photos	Compose New Letter	View <span>View in Browser</span>	
<b>Assessment Reports</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	24/10/17 15:40	<b>Accident Statement</b> From: SC - Reg. No: FBL1735U, Claimant: FAST CLASS SERVICES PTE LTD	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	31/10/17 15:53	<b>Adjuster Immediate Advice</b>	1	Load HTM	
<b>Photos/Images</b>				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/02/18 09:18	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
2	27/02/18 09:18	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
3	27/02/18 09:18	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
4	27/02/18 09:18	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
5	27/02/18 09:18	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
6	27/02/18 09:18	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
7	27/02/18 09:18	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
8	27/02/18 09:18	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
9	27/02/18 09:18	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
10	27/02/18 09:18	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
11	27/02/18 09:18	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
12	27/02/18 09:18	<b>Chassis Number</b>	1	Load JPG	<input checked="" type="checkbox"/>
13	27/02/18 09:18	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
14	27/02/18 09:18	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
15	27/02/18 09:18	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
16	27/02/18 09:18	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
17	27/02/18 09:18	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
18	27/02/18 09:18	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
19	27/02/18 09:18	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
20	27/02/18 09:18	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
21	27/02/18 09:18	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	24/10/17 15:40	<b>ESTIMATE, SLS1746H GIA RPT</b>	1	Load PDF	
2	24/10/17 15:40	<b>SLS1746H GIA RPT</b> From: SC - Reg. No: FBL1735U, Claimant: FAST CLASS SERVICES PTE LTD	1	Load PDF	

## Documents Checklist

**DOCUMENTS CHECKLIST**

Reset

Save

Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17020422/T1QBQ2

Date: 01/03/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/17-983989-WTT
Claimant Vehicle No:	SLS1746H	Insured Vehicle No:	FBL1735U
Date of Loss:	15/10/2017	Nature of Claim:	TP
		Claim No:	MSC/V/17-001621

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLS1746H	Engine No:	K24W72041217
Make & Model:	HONDA ODYSSEY, 2.4 EX-S (A)	Chassis No:	JHMRC1890HC203572
Reg. Date:	12/09/2017 (Man. Year: 2017)	Odometer:	0 km
Colour:	Silver		
Engine Capacity:	2356 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	543.77	463.10	80.67	14.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,740.00	460.00	20.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>2,743.77</b>	<b>2,203.10</b>	<b>540.67</b>	<b>19.71</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>192.06</b>	<b>154.22</b>	<b>37.84</b>	<b>19.70</b>
<b>Nett Amount (\$\$)</b>	<b>2,935.83</b>	<b>2,357.32</b>	<b>578.51</b>	<b>19.71</b>

## INSPECTION

Date of Assignment:	24/10/2017		
Date Inspected:	27/10/2017	Inspected At:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4 Singapore 408610
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 01 Mar 2018)
<b>Parts:</b> M1-MPV	HONDA ODYSSEY 2.4 EX-S (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLS1746H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*GARNISH ASSYL.FR.FENDER LOWER	Not Necessary	30.67 FS	*- FS
3	1		*GARNISH ASSYL.FR.DOOR LOWER	Cut	213.00 FS	*213.00 FS
4	1		*GARNISH ASSYL.SIDE DOOR LWR	Cut	200.10 FS	*200.10 FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (S\$)</b>					<b>543.77</b>	<b>463.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL -BEAT /REPAIR LHF DOOR /LHR DOOR	New	1,200.00	840.00
2	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	1,000.00	900.00
Gross Labour Cost (S\$)			2,200.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >