



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2008 HONDA CIVIC 2.0 (SGK1180R)

Date of Loss

13 October 2017

Time of Loss

13.45

Loss Description

SGK1180R (INSD) C/W SHC8134J (TP)

Comment

Workshop Details

Total Rebate Amount

17600

Nett Loss Amount

\$6,400.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

15/05/2018



Days of work completion *

201



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SGK1180R

Registration State

SINGAPORE

Mileage

146747

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2008

ASSESSMENT INFO...

2008

Purchase Date

dd/mm/yyyy



Registration Date *

05/05/2009



Age of Vehicle

8

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... HONDA

ASSESSMENT INFO...

CATEGORY Model

POLICY INFORMAT... CIVIC 2.0

ASSESSMENT INFO...

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... JHMFD26409S200740

CATEGORY Date of Birth

FNOL INFORMATI...

POST SURVEY INF...



CATEGORY Age

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Driving Experience

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Driver License #

ASSESSMENT INFO... JHMFD26409S200740

CATEGORY Engine No

POLICY INFORMAT... K20Z24500741

ASSESSMENT INFO... K20Z24500741

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1998

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 24000

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

09/11/2017



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

205/55R16

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

205/55R16

Front left side

MAXXIS8mm

Front right side

MAXXIS8mm

Rear left side

MAXXIS8mm

Rear right side

MAXXIS8mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			O/S FRONT DOOR			Damaged	0				0	Reviewing
		2	1			O/S FRONT DOOR BLACK STICKER			Necessary	0				0	Reviewing
		3	1			O/S FRONT DOOR OUTER HANDLE			Serviceable	0	0	0	0	0	Deny
		4	1			O/S FRONT DOOR PROTECTOR			Damaged	0				0	Reviewing
		5	1			O/S FRONT DOOR LOCK			Serviceable	0	0	0	0	0	Deny
		6	1			O/S REAR DOOR			Repair	0	0	0	0	0	Deny
		7	1			O/S REAR DOOR PROTECTOR			Cut	0				0	Reviewing

Labour

Add

Approve

Deny

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOV
		1		TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS	600	0	0	Reviewing		
		2		TO REMOVE DOOR'S FITTINGS	60	0	0	Reviewing		

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAIN	ACTION (LABOUR)	COMMENT	REMOV
		3		TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	1100	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR : 5 DAYS	Reviewing			
	2	PARTS SUPPLIED BY AXAS SUPPLIER \$330.00	Reviewing			

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$1,360.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,760.00	\$1,760.00
Excess	-\$400.00	-\$400.00

Submit for Review