

12/20/2016

ASS: REC BY

REF: CS/FWD17020599 / ALB

Special Instructions

Supervisor  
Mehmen

Admin

ASSIGNMENT (Office)

From (Person): Clara Li

of FWD

Date/Time 27/10/17 @ 12:44pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJJ 2100 K

Insured:

at Workshop m/s

Progressive

Tel:

67415336

of BIK 3022 A Ubi Rd 1, # 01-45/46, 408716

82585595

Policy No: PNPV2017-00001584

Claim No: 1201700007076

Sum Insured:

Excess: \$800.00

Make of Veh:

D.O.A. 24/10/17

(Client's Record)

CA (REV) / REP. / REV 24 HRS

H.O.D. Estimation

Date/Time 27/10/17 @ 2:24pm

Person Contacted Pei Wen

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJJ 2100K-X
31/10-	Revert via mehmeh.
31/10-	authorise by insurance lump sum \$5000/-
31/10-	email authorise repair to wendy

REF:

SJ22100K

ASSIGNMENT

22/07/08

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: DK

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SJ22100K Yr Regn: 2008 July

Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi Lancer C.C. 1584

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JMYSNCS3A8U004757

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/45R16

R: 205/45R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A. \_\_\_\_\_

D.O.I. 27/0/17

Survey held at Progressive (Ubi)

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OP FWD. offer \$4300 Lump Sum.

MV: 11K  
PV: 6.5K  
NET: 4.5K

RECEIVED 30 NOV 2011

Lump Sum \$5000 (Red 5453; 52%)

Date/Time, File Pass to?

: Preli. Report  
 : Final Report

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

250

Transportation:

S + RS, SI

Photos:

Others:

10

TOTAL

Report Format: OD

Lump Sum / I.B.I: (\$) 5000

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FWD SINGAPORE PTE LTD		Ref : CS/FWD17020599/Atb	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4SINGAPORE 038986		Date : 27-10-2017	
		Code : FWD	
1. Policy Particulars :- OWN DAMAGE			
	Insured Veh.	Veh. Inspected	SJJ 2100K
	Policy No. PNPV2017-00001584	Coverage (\$)	0.00
	Claim No. 1201700007076	Excess (\$)	800.00
	Assign From MERIMEN (CLARA LI)	Assign Date	27/10/2017
2. Vehicle Particulars & Condition			
	Make & Model	c.c	0
	Engine No. HIDDEN	Year of Reg.	
	Chassis No.	Colour	
	Odometer -	Steering	
	Brakes	Modification	
	General		
3. Conditions of Tyres			
		Size	Make
	R/H Front Tyre		Balance
	L/H Front Tyre		mm
	R/H Rear Tyre		mm
	L/H Rear Tyre		mm
4. Description of Damages			
5. General Information			
	Accident Date 23/10/2017	Inspection Date	
	Survey held at PROGRESSIVE AUTO PTE LTD NO.1 KAKI BUKIT AVE 6 #02-48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
	A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.		

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Oct 2017 <a href="#">Sendback Est</a>	27 Oct 2017 12:35 <b>S\$10,453.00</b>	27 Oct 2017 12:44 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	<b>KEN OWYONG ZHI XIANG</b> , ID: S8734633A, Tel: +6594517220, Email: XIANG4@GMAIL.COM		
Vehicle Reg. No.:	<b>SJJ2100K</b>	Date of Loss:	24/10/2017 19:00 - :59
Claim Type:	<b>OD / 1201700007076</b>	Policy/Cover Note No.:	PNPV2017-00001584 (Comprehensive)
		Excess:	S\$800.00
Repairer:	<b>Progressive Automotive Pte Ltd (HQ)</b> Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336		
Handling Insurer:	<b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700 ... [Handled by <b>Clara Li Zi Rong</b> ]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [ <b>Final Rpt</b> due 07/11/2017]		
Driver/Custodian:	KEN OWYONG ZHI XIANG (29 / Male), NRIC: S8734633A, Tel: +6594517220		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Clara Li Zi Rong

Date: 31 Oct 2017

**Preliminary Advice**

Vehicle No	: SJJ2100K	Accident Date	: 24/10/2017
Make	: MITSUBISHI LANCER	Policy No.	: PNPV2017-00001584
Assignment Date	: 27/10/2017	Excess	: S\$800.00
Date of Inspection	: 30/10/2017	Est. Duration of Repair	: 7.00
Inspection At	: PROGRESSIVE AUTOMOTIVE PTE LTD (HQ) BLK 3022A UBI ROAD 1, #01-45/46 SINGAPORE 408716		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,453.00
Revised Amount	:S\$	7,176.00
Check Items (Estimated)	:S\$	1,405.00
Total	:S\$	8,581.00

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	11,000.00 - 12,000.00
COE / PARF Rebate	:S\$	6,642.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,358.00 - 5,358.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Repair is asking lump sum \$5000.00

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/10/2017 14:34
Date Of Accident	24/10/2017 19:25
Exact Location Of Accident	PIE ( TUAS )
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJJ2100K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KEN OWYONG ZHI XIANG
NRIC No	S8734633A
Email Address	XIANG4@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94517220
Alternative Phone No	OTHERS-94517220
<b>Vehicle Particulars</b>	
Manufacturer	MITSUBISHI
Model	LANCER-1.6 (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00001584
Cover Note Number	
<b>Driver</b>	
Name of Driver	KEN OWYONG ZHI XIANG
NRIC No	S8734633A
Date Of Birth	03/11/1987
Occupation	INDOOR
Date Of Driving Pass	13/06/2013
Driving Experience	4 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94517220
Fax Number	
Contact Number	OTHERS-94517220
EEmail Address	XIANG4@GMAIL.COM

Address APT BLK 3 JOO CHIAT ROAD # 13-1185  
SINGAPORE

Postcode 420003

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -  
-  
-

Insurance Company of Driver's Own Vehicle -  
-  
-

**General Information of the Accident**

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name TRAFFIC POLICE DIVISION HQ

Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 65470000 - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

**Circumstances of Accident**

REFER ATTACH STATEMENT RECORDED BY JIA MIN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 67415336

**Attachment(s)**

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLH440DD

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver GNANA NAMBI KAMNAN

NRIC/Passport Number S6966037A

Contact Number 93806392

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number

SLG7C

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

PATARA CHEN SI QUN

NRIC/Passport Number

S9509950E

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address

**DETAILS OF INJURED PERSON 1**

Name

KEN OWYONG ZHI XIANG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJJ2100K

Were seat belts worn?

Was injured conveyed to hospital by ambulance? NO

Address

Postcode

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

25/10/17  
1.37pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature


Name:

Jia Min

NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report


- I was travelling at 75 km/h to 80 km/h
- ~~WEDIA~~ MEDIUM TRAFFIC
- I colided 3 to 5 seconds ~~at~~ after they colided. ~~at~~ ~~approximately~~ approximately 40 km/h to 50 km/h.

DECLARATION

I/We declare the foregoing particulars are true in every respect. Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the stipulated timeframe from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature:   
 Date & Time: 25/10/17  
 1:37pm

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:   
 NRIC/FIN No.: JAMIN

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type Singapore NRIC  
Owner ID 4633A

### Vehicle Details

Vehicle No. SJJ2100K  
Vehicle to be Exported Yes  
Intended De-registration Date 25 Oct 2017  
Vehicle Make MITSUBISHI  
Vehicle Model LANCER 1.6 M  
Primary Colour White  
Manufacturing Year 2008  
Engine No. 4G18JR3833  
Chassis No. JMYSNCS3ABU004757  
Maximum Power Output 79.0 kW (105 bhp)  
Open Market Value \$11,163.00  
Original Registration Date 22 Jul 2008  
First Registration Date 22 Jul 2008  
Transfer Count 3  
Actual ARF Paid \$11,163.00

### Intended PARF Rebate Details

PARF Eligibility Yes  
PARF Eligibility Expiry Date 21 Jul 2018  
PARF Rebate Amount \$5,581.00

### Intended COE Rebate Details

COE Expiry Date 21 Jul 2018  
COE Category A - Car (1600cc & below)  
COE Period(Years) 10  
QP Paid \$14,685.00  
COE Rebate Amount \$1,082.00  
**Total Rebate Amount \$6,663.00**

The information contained herein is correct as at 25 Oct 2017

OK

*M.V. Abt .  
\$ 11,000 k .*

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	4633A
Vehicle Details	
Vehicle No.	SJJ2100K
Vehicle to be Exported	Yes
Intended De-registration Date	30 Oct 2017
Vehicle Make	MITSUBISHI
Vehicle Model	LANCER 1.6 M
Primary Colour	White
Manufacturing Year	2008
Engine No.	4G18JR3833
Chassis No.	JMYSNCS3A8U004757
Maximum Power Output	79.0 kW (105 bhp)
Open Market Value	\$11,163.00
Original Registration Date	22 Jul 2008
First Registration Date	22 Jul 2008
Transfer Count	3
Actual ARF Paid	\$11,163.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	21 Jul 2018
PARF Rebate Amount	\$5,581.00
Intended COE Rebate Details	
COE Expiry Date	21 Jul 2018
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$14,685.00
COE Rebate Amount	\$1,061.00
<b>Total Rebate Amount</b>	<b>\$6,642.00</b>

The information contained herein is correct as at 30 Oct 2017

OK



**MYCARFORUM**  
MARKETPLACE  
Buy / Sell Parts & Accessories  
[> click here to visit now!](#)

[» Sign Up New Account](#)  
[» Forgot Password](#)

Price Range  Depreciation  2008  Vehicle Type

[Advanced Search](#)

Used Car Comparison

--- Comparing 3 Vehicles ---

Mitsubishi Lancer 1.6A GLX



[Add to Shortlist](#)

Mitsubishi Lancer 1.6A GLX Sports



[Add to Shortlist](#)

Mitsubishi Lancer 1.6A GLX



[Add to Shortlist](#)



Use search bar above to search to compare.

[Clear All](#)

[Add all to Shortlist](#)

[Back to search result](#)

CAR DETAILS

	Mitsubishi Lancer 1.6A GLX	Mitsubishi Lancer 1.6A GLX Sports	Mitsubishi Lancer 1.6A GLX
Price	\$11,999	\$12,555	\$12,000
Instalment	\$1,071	\$1,120	\$1,221
Registration Date	21-Jul-2008	01-Jul-2008	23-Jun-2008
Manufactured	2008	2008	2008
Mileage	-	110,000 km	-
Transmission	Auto	Auto	Auto
Engine Cap	1,584 cc	1,584 cc	1,584 cc
Road Tax	\$734 /yr	\$734 /yr	\$734 /yr
Power	79.0 kW (105 bhp)	79.0 kW (105 bhp)	79.0 kW (105 bhp)
Curb Weight	1,162 kg	1,130 kg	1,162 kg
Features	-	Full Body Kit With 1 Owner For 8 Years, 16 Rims With Sunroof.	Reluctant Sale. Plan To Renew Coe Therefore Spend Quite A Lot To Do Up The Car But Family Expansion Came Into Pic Suddenly Therefore Needed Bigger Car.
Accessories	-	-	Leather Interior. Double Din Conversion. Pioneer DVD Headunit, Rainbow Component Speaker. Expensive Magnetic Sunshade.
Description	Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only.	New Aircon, Body Kit, 16 Sports Rims, 1 Owner 8 And Half Year. Just Overhaul Engine.	PARF \$6410 Therefore Low Risk And Low Depreciation Vehicle. All Repair Done Up In August. Just Service In August Too With LiquidMoly Engine Oil And Gearbox Oil Changed Zero Oil Leak Assurance And COE Renewal Worthiness. Zero Repair Needed. Definitely, Drive Off To Renew COE Condition. View To Believe.
COE	\$14,590	\$11,009	\$12,001
OMV	\$12,514	\$13,506	\$11,655
ARF	\$12,514	\$13,506	\$12,821
Depreciation	\$7,970 /yr	\$8,710 /yr	\$8,680 /yr
No. of Owners	2	2	2
Type of Vehicle	Sedan	Sedan	Sedan
Category	PARF Car	PARF Car	PARF Car, Direct Owner Sale
Availability	Available	Available	Available

SELLER INFORMATION

## View Received Message

This mail is associated with :

**SJJ2100K (1201700007076)**

OD

Oct 24 2017 7:00PM

[KEN OWYONG ZHI XIANG]  
Progressive Automotive Pte Ltd

Reply

Reply All

Mark as Unread

Print Message

Delete Message

Forward

**From** FWD Singapore Pte. Ltd. (HQ) (FWD\_SG), sent on 31/10/2017 11:56 AM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$5000.00) - SJJ2100K - Claim Handler: Clara Li Zi Rong

Approved:5000.00:Repairer is agreeable to undertake the repair costs (incl. supplementary) not exceeding \$5K on a lump sum basis before excess & GST.

### DOCUMENTS SUMMARY

There are no documents.

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Tuesday, 31 October, 2017 5:05 PM  
**To:** wendy@progauto.com.sg  
**Cc:** peiwen@progauto.com.sg; SUR  
**Subject:** RE: sjj 2100k fwd  
**Attachments:** AUTHORIZATION FOR LUMP SUM REPAIR.PDF

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SJJ 2100K (Excess \$800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Please sign the lump sum letter and return to us

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Monday, 30 October, 2017 4:42 PM  
**To:** 'wendy@progauto.com.sg' <[wendy@progauto.com.sg](mailto:wendy@progauto.com.sg)>  
**Subject:** RE: sjj 2100k fwd

Dear Wendy,

Sorry here is the correct form to sign for lump sum

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Monday, 30 October, 2017 4:34 PM  
**To:** 'wendy@progauto.com.sg' <[wendy@progauto.com.sg](mailto:wendy@progauto.com.sg)>  
**Subject:** sjj 2100k fwd



# PROGRESSIVE AUTOMOTIVE PTE LTD

Bik 3022A Ubi Road 1 #01-45/46 Singapore 408716  
 Tel: 6741 5336 (6 Lines) Fax: 6741 7208  
 E-mail: progauto@progauto.com.sg  
 Reg. No.: 201006949C

We specialise in repairing, panel beating, spray painting of all kinds of Vehicles and also insurance claims. All enquiries are welcome.

INSURER: **FWD Singapore Pte. Ltd. (HQ)**

## PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD 1017-6198
Policy No:	PNPV2017-00001584	Date of Loss:	24/10/2017
Vehicle Reg. No.:	SJJ2100K	Driveable?	
Driver Age/Info:	29 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	KEN OWYONG ZHI XIANG	Contact No:	+6594517220
Driver:	KEN OWYONG ZHI XIANG		
Make/Model:	mitsubishi LANCER, 1.6 (M)	Vehicle Reg. Date:	22/07/2008
Vehicle Colour:	WHITE	Chassis No:	JMYSNCS3AU004757
Engine No:	4G18JR3833		
Odometer:	176044 KM		
Paint Type:			
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	REFER ATTACH STATEMENT RECORDED BY JIA MIN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 67415336		
Remarks:	VEHICLE IS IN WORKSHOP		
Present Location:	PROGRESSIVE AUTOMOTIVE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	7,650.00
Miscellaneous Items	203.00
Labour	1,600.00
Paintwork Labour	1,000.00
Towing	0.00
<b>Gross Total (\$\$)</b>	<b>10,453.00</b>
<b>+ GST 7.00% (\$\$)</b>	<b>731.71</b>
<b>Nett Amount (\$\$)</b>	<b>11,184.71</b>

**This claim is handled by: LILY LIM**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

### REPAIR DETAILS

#### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Oct 2017)  
 Parts: 143 MITSUBISHI LANCER 1.6 (M) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: Progressive Automotive Pte Ltd/SJJ2100K/27/10/2017 12:35  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*BONNET <i>Distorted</i>	0.00	0.00	*450.00 F ✓
2	1	NA	*BONNET RUBBER - INNER <i>from new at</i>	0.00	0.00	*16.00 F + ✓
3	1	NA	*BONNET RUBBER - FRONT <i>from new at</i>	0.00	0.00	*18.00 F ✓
4	1	NA	*BONNET HINGE - LH <i>Best</i>	0.00	0.00	*42.00 F ✓
5	1	NA	*BONNET HINGE - RH	0.00	0.00	*42.00 F ✓
6	1	NA	*BONNET LOCK <i>Distorted</i>	0.00	0.00	*40.00 F ✓
7	1	NA	*BONNET STAND C CLIP <i>from new</i>	0.00	0.00	*4.00 F + ✓
8	1	NA	*BONNET STAND BUSH <i>from new</i>	0.00	0.00	*4.00 F + ✓
9	1	NA	*GRILLE BASE <i>smashed</i>	0.00	0.00	*120.00 F ✓
10	1	NA	*GRILLE - LH <i>smashed</i>	0.00	0.00	*70.00 F ✓
11	1	NA	*GRILLE - RH	0.00	0.00	*70.00 F ✓
12	1	NA	*GRILLE LOGO <i>new</i>	0.00	0.00	*22.00 F ✓
13	4	NA	*GRILLE CLIPS <i>new</i>	0.00	0.00	*6.00 F ✓
14	1	NA	*FRONT BUMPER <i>Distorted</i>	0.00	0.00	*540.00 F ✓
15	10	NA	*FRONT BUMPER CLIPS <i>new</i>	0.00	0.00	*15.00 F ✓
16	1	NA	*FRONT BUMPER SIDE HOLDER - LH <i>from new</i>	0.00	0.00	*30.00 F ✓
17	1	NA	*FRONT BUMPER SIDE HOLDER - RH	0.00	0.00	*30.00 F ✓
18	1	NA	*FRONT BUMPER TOWING COVER - LH <i>from new</i>	0.00	0.00	*25.00 F + ✓
19	1	NA	*FRONT BUMPER TOWING COVER - RH <i>from new</i>	0.00	0.00	*25.00 F + ✓
20	1	NA	*FRONT BUMPER REINFORCEMENT <i>Best</i>	0.00	0.00	*120.00 F ✓
21	1	NA	*FRONT BUMPER CENTRE LOWER MOULDING - LH <i>Deformed</i>	0.00	0.00	*34.00 F ✓
22	1	NA	*FRONT BUMPER CENTRE LOWER MOULDING - RH <i>Deformed</i>	0.00	0.00	*34.00 F ✓
23	1	NA	*FRONT BUMPER LOWER INNER GARNISH <i>Deformed</i>	0.00	0.00	*60.00 F ✓
24	1	NA	*FRONT BUMPER LOWER SPOILER <i>Repair</i>	0.00	0.00	*780.00 F + ✓
25	1	NA	*HEADLAMP UNIT - LH <i>smashed</i>	0.00	0.00	*320.00 F ✓
26	1	NA	*HEADLAMP CLIPS - LH <i>new</i>	0.00	0.00	*6.00 F ✓
27	1	NA	*HEADLAMP UNIT - RH <i>cracked</i>	0.00	0.00	*320.00 F ✓
28	1	NA	*HEADLAMP CLIPS - RH <i>new</i>	0.00	0.00	*6.00 F ✓
29	1	NA	*FRONT FENDER - LH <i>Buckled</i>	0.00	0.00	*320.00 F ✓
30	1	NA	*FRONT FENDER COWLING - LH <i>from new</i>	0.00	0.00	*90.00 F + ✓
31	10	NA	*FRONT FENDER COWLING CLIPS - LH <i>from new</i>	0.00	0.00	*15.00 F + ✓
32	1	NA	*WIPER GARNISH - LH <i>at</i>	0.00	0.00	*45.00 F ✓
33	1	NA	*WIPER GARNISH - RH <i>new</i>	0.00	0.00	*50.00 F + ✓
34	1	NA	*SUPPORT PANEL ASSY <i>Distorted</i>	0.00	0.00	*450.00 F ✓
35	1	NA	*AIR CLEANER BOX ASSY <i>cracked</i>	0.00	0.00	*270.00 F ✓
36	1	NA	*AIR CLEANER AIR DUCT <i>cracked</i>	0.00	0.00	*80.00 F ✓
37	1	NA	*MANIFOLD COVER <i>Distorted</i>	0.00	0.00	*55.00 F ✓
38	1	NA	*FRONT EXHAUST SENSOR <i>from new</i>	0.00	0.00	*380.00 F + ✓
39	1	NA	*FUSE BOX COVER - LH <i>Deformed</i>	0.00	0.00	*20.00 F ✓
40	1	NA	*FUSE BOX ASSY - LH <i>cracked</i>	0.00	0.00	*140.00 F ✓
41	1	NA	*ENGINE MOUNTING - FRONT <i>from new</i>	0.00	0.00	*50.00 F ✓
42	1	NA	*ENGINE MOUNTING - RH <i>from new</i>	0.00	0.00	*120.00 F + ✓
43	1	NA	*GEARBOX MOUNTING - LH <i>from new</i>	0.00	0.00	*110.00 F + ✓
44	1	NA	*GEARBOX MOUNTING BRACKET - LH <i>from new</i>	0.00	0.00	*80.00 F + ✓

Progressive Automotive Pte Ltd/SJJ2100K/27/10/2017 12:35. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
45	1	NA	*ENGINE MOUNTING BRACKET - FRONT <i>Not m</i>	0.00	0.00	*55.00 F ✓
46	1	NA	*RADIATOR <i>Distorted</i>	0.00	0.00	*350.00 F ✓
47	1	NA	*RADIATOR TOP HOSE <i>Twisted</i>	0.00	0.00	*13.00 F ✓
48	1	NA	*RADIATOR BOTTOM HOSE <i>Not m</i>	0.00	0.00	*23.00 F ✓
49	1	NA	*RADIATOR SPARE TANK <i>Distorted</i>	0.00	0.00	*35.00 F ✓
50	2	NA	*RADIATOR TOP BRACKET - RH & LH <i>Best</i>	0.00	0.00	*30.00 F ✓
51	1	NA	*WIPER TANK ASSY <i>Not m</i>	0.00	0.00	*75.00 F ✓
52	1	NA	*RADIATOR FAN MOTOR	0.00	0.00	*150.00 F ✓
53	1	NA	*RADIATOR FAN BLADE <i>Distorted</i>	0.00	0.00	*35.00 F ✓
54	1	NA	*RADIATOR FAN COWLING	0.00	0.00	*95.00 F ✓
55	1	NA	*AIRCON CONDENSER <i>Distorted</i>	0.00	0.00	*300.00 F ✓
56	1	NA	*AIRCON CONDENSER SIDE GARNISH - LH <i>Not m</i>	0.00	0.00	*55.00 F ✓
57	1	NA	*AIRCON CONDENSER SIDE GARNISH - RH <i>Not m</i>	0.00	0.00	*55.00 F ✓
58	1	NA	*AIRCON CONDENSER FAN MOTOR/COWLING & BLADE <i>Distorted</i>	0.00	0.00	*290.00 F ✓
59	1	NA	*AIRCON DISCHARE PIPE <i>Not m</i>	0.00	0.00	*135.00 F ✓
60	1	NA	*AIRCON LIQUID TUBE <i>Not m</i>	0.00	0.00	*130.00 F ✓
61	1	NA	*HORN - LH <i>Not m</i>	0.00	0.00	*65.00 F ✓
62	1	NA	*HORN - RH <i>Not m</i>	0.00	0.00	*65.00 F ✓
63	1	NA	*ENGINE MOUNTING BRACKET - RH <i>Not m</i>	0.00	0.00	*170.00 F ✓
						F=Franchise part.
Total Parts (S\$)						7,650.00

Progressive Automotive Pte Ltd/SJJ2100K/27/10/2017 12:35. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

5073

~~Ad~~

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	BATTERY <i>Replaced</i>	168.00 ✓
2	1	FRONT NUMBER PLATE W/CASING <i>distorted</i>	35.00 ✓
Sub Total (S\$)			<u>203.00</u>

Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Paintwork Labour</b>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	<del>1,000.00</del> 800 ✓
<b>Labour Items</b>			
2	TO KNOCK OUT DENTS; STRAIGHTEN FRONT CHASSIS; CUT/WELD SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	<del>1,000.00</del> 800 ✓
3	TO CHECK WIRING	New	20.00 ✓
4	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New	100.00 ✓
5	TO LIFT UP ENGINE	New	80.00 ✓
6	TO REMOVE; REPLACE FRONT ENGINE MOUNTINGS	New	150.00 ✓
7	TO REMOVE; REPLACE LH FUSE BOX ASSY; AIRCLEANER BOX ASSY AND RELATED PARTS	New	<del>250.00</del> 180 ✓
Gross Labour Cost (S\$)			<u>2,600.00</u>

Progressive Automotive Pte Ltd/SJJ2100K/27/10/2017 12:35. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

Adrian King -  
2/s 27/10/17.  
Not Authorised.  
Excess \$800.

total:  
4/s 5K

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Oct 2017 Sendback Est	27 Oct 2017 12:35 <b>S\$10,453.00</b>	27 Oct 2017 12:44 Edit Adj Rpt	<b>S\$5,000.00</b> Edit Estimates	<b>S\$5,000.00</b> View Rpt		<b>Pending for Survey Report</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS									
<b>Insured:</b>	KEN OWYONG ZHI XIANG, ID: S8734633A, Tel: +6594517220, Email: XIANG4@GMAIL.COM								
<b>Vehicle Reg. No.:</b>	SJJ2100K								
<b>Date of Loss:</b>	24/10/2017 19:00 - :59								
<b>Claim Type:</b>	OD / 1201700007076								
<b>Policy/Cover Note No.:</b>	PNPV2017-00001584 (Comprehensive)								
<b>Excess:</b>	S\$800.00								
<b>Repairer:</b>	Progressive Automotive Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336								
<b>Handling Insurer:</b>	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by <b>Clara Li Zi Rong</b> ]								
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... [Final Rpt due 07/11/2017]								
<b>Driver/Custodian:</b>	KEN OWYONG ZHI XIANG (29 / Male), NRIC: S8734633A, Tel: +6594517220								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float:right">View All   Compose Case Mail</span>									
<ul style="list-style-type: none"> <li>FWD_SG (31/10/2017): Alert - Adj Mandate Approved (S\$5000.00) - SJJ2100K - Claim Handler: Clara Li Zi...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float:right">View All   Search Tasks   Create New Task   Complete</span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

### Claim Documents

**SJJ2100K (1201700007076)**  
**OD**  
**Oct 24 2017 7:00PM**  
**[KEN OWYONG ZHI XIANG]**  
**Progressive Automotive Pte Ltd**

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<b>View</b> <input type="checkbox"/> <b>Use Viewer</b> <input type="checkbox"/>
				1 per page <input type="checkbox"/>
<b>Video</b>				
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	25/10/17 14:47	<b>Video - Accident</b> <small>[Linked Accident Report Documents]</small>	Load AVI	<input type="checkbox"/>
				1 per page <input type="checkbox"/>
<b>Assessment Reports</b>				
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	27/10/17 12:35	<b>Repairer Estimates</b>	Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/10/17 16:44	<b>Adjuster Immediate Advice</b>	Load HTM	<input type="checkbox"/>
2	30/10/17 17:21	<b>Adjuster Immediate Advice</b>	Load HTM	<input type="checkbox"/>
3	31/10/17 11:52	<b>Adjuster Immediate Advice</b>	Load HTM	<input type="checkbox"/>
				3 per page <input type="checkbox"/>
<b>Photos/Images</b>				
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	26/10/17 16:45	<b>1</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
2	26/10/17 16:45	<b>2</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
3	26/10/17 16:45	<b>3</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
4	26/10/17 16:45	<b>4</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
5	26/10/17 16:45	<b>5</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
6	26/10/17 16:45	<b>6</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
7	26/10/17 16:45	<b>7</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
8	26/10/17 16:45	<b>8</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
9	26/10/17 16:45	<b>9</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
10	26/10/17 16:45	<b>10</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
11	26/10/17 16:45	<b>11</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
12	26/10/17 16:45	<b>12</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
13	26/10/17 16:45	<b>13</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
14	26/10/17 16:45	<b>14</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
15	26/10/17 16:45	<b>15</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
16	26/10/17 16:45	<b>16</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
17	26/10/17 16:45	<b>17</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
18	26/10/17 16:45	<b>18</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
19	26/10/17 16:45	<b>19</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
20	26/10/17 16:45	<b>20</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
21	26/10/17 16:45	<b>21</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
22	26/10/17 16:45	<b>22</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
23	26/10/17 16:45	<b>23</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
24	26/10/17 16:45	<b>24</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
25	26/10/17 16:45	<b>25</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
26	26/10/17 16:45	<b>26</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
27	26/10/17 16:45	<b>27</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
28	26/10/17 16:45	<b>28</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
29	26/10/17 16:45	<b>29</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
30	26/10/17 16:45	<b>30</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
31	26/10/17 16:45	<b>31</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
32	26/10/17 16:45	<b>32</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>
33	26/10/17 16:45	<b>33</b>	Load JPG <input type="checkbox"/>	<input checked="" type="checkbox"/>

34	26/10/17 16:45	34		Load JPG	<input checked="" type="checkbox"/>
35	26/10/17 16:45	35		Load JPG	<input checked="" type="checkbox"/>
36	26/10/17 16:45	36		Load JPG	<input checked="" type="checkbox"/>
37	26/10/17 16:45	37		Load JPG	<input checked="" type="checkbox"/>
38	26/10/17 16:45	38		Load JPG	<input checked="" type="checkbox"/>
39	26/10/17 16:45	39		Load JPG	<input checked="" type="checkbox"/>
40	26/10/17 16:45	40		Load JPG	<input checked="" type="checkbox"/>
41	26/10/17 16:45	41		Load JPG	<input checked="" type="checkbox"/>
42	26/10/17 16:45	42		Load JPG	<input checked="" type="checkbox"/>
43	26/10/17 16:45	43		Load JPG	<input checked="" type="checkbox"/>
44	26/10/17 16:45	44		Load JPG	<input checked="" type="checkbox"/>
45	26/10/17 16:45	45		Load JPG	<input checked="" type="checkbox"/>
46	26/10/17 16:45	46		Load JPG	<input checked="" type="checkbox"/>
47	26/10/17 16:45	47		Load JPG	<input checked="" type="checkbox"/>
48	26/10/17 16:45	48		Load JPG	<input checked="" type="checkbox"/>
49	26/10/17 16:45	49		Load JPG	<input checked="" type="checkbox"/>
50	26/10/17 16:45	50		Load JPG	<input checked="" type="checkbox"/>
51	26/10/17 16:45	51		Load JPG	<input checked="" type="checkbox"/>
52	26/10/17 16:45	52		Load JPG	<input checked="" type="checkbox"/>
53	26/10/17 16:45	53		Load JPG	<input checked="" type="checkbox"/>
54	26/10/17 16:45	54		Load JPG	<input checked="" type="checkbox"/>
55	26/10/17 16:45	55		Load JPG	<input checked="" type="checkbox"/>
56	26/10/17 16:45	56		Load JPG	<input checked="" type="checkbox"/>
57	26/10/17 16:45	57		Load JPG	<input checked="" type="checkbox"/>
58	26/10/17 16:45	58		Load JPG	<input checked="" type="checkbox"/>
59	26/10/17 16:45	59		Load JPG	<input checked="" type="checkbox"/>
60	26/10/17 16:45	60		Load JPG	<input checked="" type="checkbox"/>
61	26/10/17 16:45	61		Load JPG	<input checked="" type="checkbox"/>
62	26/10/17 16:45	62		Load JPG	<input checked="" type="checkbox"/>
63	26/10/17 16:45	63		Load JPG	<input checked="" type="checkbox"/>
64	26/10/17 16:45	64		Load JPG	<input checked="" type="checkbox"/>
65	26/10/17 16:45	65		Load JPG	<input checked="" type="checkbox"/>
66	26/10/17 16:45	66		Load JPG	<input checked="" type="checkbox"/>
67	26/10/17 16:45	67		Load JPG	<input checked="" type="checkbox"/>
68	26/10/17 16:45	68		Load JPG	<input checked="" type="checkbox"/>
69	26/10/17 16:45	69		Load JPG	<input checked="" type="checkbox"/>
70	26/10/17 16:45	70		Load JPG	<input checked="" type="checkbox"/>
71	26/10/17 16:45	71		Load JPG	<input checked="" type="checkbox"/>
72	26/10/17 16:45	72		Load JPG	<input checked="" type="checkbox"/>
73	26/10/17 16:45	73		Load JPG	<input checked="" type="checkbox"/>
74	26/10/17 16:45	74		Load JPG	<input checked="" type="checkbox"/>
75	26/10/17 16:45	75		Load JPG	<input checked="" type="checkbox"/>
76	26/10/17 16:45	76		Load JPG	<input checked="" type="checkbox"/>
77	26/10/17 16:45	77		Load JPG	<input checked="" type="checkbox"/>
78	26/10/17 16:45	78		Load JPG	<input checked="" type="checkbox"/>
79	26/10/17 16:45	79		Load JPG	<input checked="" type="checkbox"/>
80	26/10/17 16:45	80		Load JPG	<input checked="" type="checkbox"/>
81	26/10/17 16:45	81		Load JPG	<input checked="" type="checkbox"/>
82	26/10/17 16:45	82		Load JPG	<input checked="" type="checkbox"/>
83	26/10/17 16:45	83		Load JPG	<input checked="" type="checkbox"/>
84	26/10/17 16:45	84		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
2	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>

3	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
4	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
5	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
6	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
7	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
8	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
9	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
10	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
11	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
12	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
13	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
14	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
15	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
16	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
17	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
18	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
19	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
20	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
21	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
22	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
23	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
24	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
25	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
26	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
27	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
28	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
29	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
30	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
31	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
32	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
33	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
34	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
35	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
36	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
37	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
38	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
39	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
40	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
41	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
42	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
43	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
44	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
45	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
46	24/11/17 14:27	General View		Load JPG	<input checked="" type="checkbox"/>
47	24/11/17 14:27	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
48	24/11/17 14:28	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
49	24/11/17 14:28	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
50	24/11/17 14:28	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Automotive Pte Ltd (HQ)		Thumbnail	Print
1	26/10/17 17:06	E-filed GIA report		Load PDF	
2	27/10/17 12:59	COE rebate		Load JPG	<input checked="" type="checkbox"/>

### Linked Accident Report Documents

			View	Use Viewer
<b>Video</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	25/10/17 14:47	Video - Accident	Load AVI	<input checked="" type="checkbox"/>
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	25/10/17 16:53	Accident Statement	Load HTM	<input checked="" type="checkbox"/>
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	25/10/17 16:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	25/10/17 16:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	25/10/17 16:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	25/10/17 16:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	25/10/17 16:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	25/10/17 16:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	25/10/17 16:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	25/10/17 16:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	25/10/17 16:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	25/10/17 16:53	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	25/10/17 16:53	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	25/10/17 16:53	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	25/10/17 16:53	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	25/10/17 16:49	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	25/10/17 16:49	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>
3	25/10/17 16:50	POLICE REPORT PG 1	Load TIF	
4	25/10/17 16:50	POLICE REPORT PG 2	Load TIF	
5	25/10/17 16:50	POLICE REPORT PG 3	Load TIF	
6	25/10/17 16:50	POLICE REPORT PG 4	Load TIF	
7	25/10/17 16:50	DRIVER NRIC & LICENCE	Load TIF	
8	25/10/17 16:50	CI	Load TIF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid gray; height: 40px;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.  
6 Temasek Boulevard, #18-01 Suntec Tower 4  
Singapore 038986

Our File No: CS/FWD17020599/ATBS2

Date: 04/12/2017

## REFERENCE

Insured/Claimant: KEN OWYONG ZHI XIANG Policy No: PNPV2017-00001584  
Date of Loss: 24/10/2017 Nature of Claim: OD Claim No: 1201700007076

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SJJ2100K  
Make & Model: MITSUBISHI LANCER, 1.6 (M) Engine No: 4G18JR3833  
Reg. Date: 22/07/2008 (Man. Year: 2008) Chassis No: JMYSNCS3A8U004757  
Colour: White Odometer: 0 km  
Engine Capacity: 1584 cc  
Market Value/New Car Price: S\$12,000.00  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/45R16 Rear Tyre Size: 205/45R16  
Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm  
Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,650.00	5,073.00	2,577.00	33.69
Miscellaneous Items	203.00	203.00	0.00	0.00
Labour	1,600.00	1,100.00	500.00	31.25
Paintwork Labour	1,000.00	800.00	200.00	20.00
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,453.00</b>	<b>7,176.00</b>	<b>3,277.00</b>	<b>31.35</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,000.00</b>		
<b>- Excess (S\$)</b>	0.00	800.00	-800.00	
<b>(S\$)</b>	10,453.00	4,200.00	6,253.00	59.82
<b>+ GST 7.00/7.00% (S\$)</b>	731.71	294.00	437.71	59.82
<b>Nett Amount (S\$)</b>	<b>11,184.71</b>	<b>4,494.00</b>	<b>6,690.71</b>	<b>59.82</b>

## INSPECTION

Date of Assignment: 27/10/2017 Present Location: Progressive Automotive Pte Ltd (HQ)  
Date Inspected: 27/10/2017 Inspected At: Progressive Automotive Pte Ltd (HQ)  
Blk 3022A Ubi Road 1, #01-45/46  
Singapore 408716

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 04 Dec 2017)	
<b>Parts:</b> 143	MITSUBISHI LANCER 1.6 (M) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SJJ2100K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.		

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BONNET	Distorted	450.00 F	*450.00 F
2	1	NA	*BONNET RUBBER - INNER	Not Necessary	16.00 F	*- F
3	1	NA	*BONNET RUBBER - FRONT	Cut	18.00 F	*18.00 F
4	1	NA	*BONNET HINGE - LH	Bent	42.00 F	*42.00 F
5	1	NA	*BONNET HINGE - RH	Bent	42.00 F	*42.00 F
6	1	NA	*BONNET LOCK	Damaged	40.00 F	*40.00 F
7	1	NA	*BONNET STAND C CLIP	Not Necessary	4.00 F	*- F
8	1	NA	*BONNET STAND BUSH	Not Necessary	4.00 F	*- F
9	1	NA	*GRILLE BASE	Smashed	120.00 F	*120.00 F
10	1	NA	*GRILLE - LH	Smashed	70.00 F	*70.00 F
11	1	NA	*GRILLE - RH	Smashed	70.00 F	*70.00 F
12	1	NA	*GRILLE LOGO	Necessary	22.00 F	*22.00 F
13	4	NA	*GRILLE CLIPS	Necessary	6.00 F	*6.00 F
14	1	NA	*FRONT BUMPER	Distorted	540.00 F	*540.00 F
15	10	NA	*FRONT BUMPER CLIPS	Necessary	15.00 F	*15.00 F
16	1	NA	*FRONT BUMPER SIDE HOLDER - LH	Necessary	30.00 F	*30.00 F
17	1	NA	*FRONT BUMPER SIDE HOLDER - RH	Necessary	30.00 F	*30.00 F
18	1	NA	*FRONT BUMPER TOWING COVER - LH	Not Necessary	25.00 F	*- F
19	1	NA	*FRONT BUMPER TOWING COVER - RH	Not Necessary	25.00 F	*- F
20	1	NA	*FRONT BUMPER REINFORCEMENT	Bent	120.00 F	*120.00 F
21	1	NA	*FRONT BUMPER CENTRE LOWER MOULDING - LH	Deformed	34.00 F	*34.00 F
22	1	NA	*FRONT BUMPER CENTRE LOWER MOULDING - RH	Deformed	34.00 F	*34.00 F
23	1	NA	*FRONT BUMPER LOWER INNER GARNISH	Deformed	60.00 F	*60.00 F
24	1	NA	*FRONT BUMPER LOWER SPOILER	Repair	780.00 F	*- F
25	1	NA	*HEADLAMP UNIT - LH	Smashed	320.00 F	*320.00 F
26	1	NA	*HEADLAMP CLIPS - LH	Necessary	6.00 F	*6.00 F
27	1	NA	*HEADLAMP UNIT - RH	Cracked	320.00 F	*320.00 F
28	1	NA	*HEADLAMP CLIPS - RH	Necessary	6.00 F	*6.00 F
29	1	NA	*FRONT FENDER - LH	Buckled	320.00 F	*320.00 F
30	1	NA	*FRONT FENDER COWLING - LH	Not Necessary	90.00 F	*- F
31	10	NA	*FRONT FENDER COWLING CLIPS - LH	Not Necessary	15.00 F	*- F
32	1	NA	*WIPER GARNISH - LH	Cut	45.00 F	*45.00 F
33	1	NA	*WIPER GARNISH - RH	Not Necessary	50.00 F	*- F
34	1	NA	*SUPPORT PANEL ASSY	Distorted	450.00 F	*450.00 F
35	1	NA	*AIR CLEANER BOX ASSY	Cracked	270.00 F	*270.00 F
36	1	NA	*AIR CLEANER AIR DUCT	Cracked	80.00 F	*80.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
37	1	NA	*MANIFOLD COVER	Dented	55.00 F	*55.00 F	
38	1	NA	*FRONT EXHAUST SENSOR	Not Necessary	380.00 F	*- F	
39	1	NA	*FUSE BOX COVER - LH	Deformed	20.00 F	*20.00 F	
40	1	NA	*FUSE BOX ASSY - LH	Cracked	140.00 F	*140.00 F	
41	1	NA	*ENGINE MOUNTING - FRONT	Not Necessary	50.00 F	*- F	
42	1	NA	*ENGINE MOUNTING - RH	Not Necessary	120.00 F	*- F	
43	1	NA	*GEARBOX MOUNTING - LH	Not Necessary	110.00 F	*- F	
44	1	NA	*GEARBOX MOUNTING BRACKET - LH	Not Necessary	80.00 F	*- F	
45	1	NA	*ENGINE MOUNTING BRACKET - FRONT	Not Necessary	55.00 F	*- F	
46	1	NA	*RADIATOR	Distorted	350.00 F	*350.00 F	
47	1	NA	*RADIATOR TOP HOSE	Twisted	13.00 F	*13.00 F	
48	1	NA	*RADIATOR BOTTOM HOSE	Not Necessary	23.00 F	*- F	
49	1	NA	*RADIATOR SPARE TANK	Distorted	35.00 F	*35.00 F	
50	2	NA	*RADIATOR TOP BRACKET - RH & LH	Bent	30.00 F	*30.00 F	
51	1	NA	*WIPER TANK ASSY	Not Necessary	75.00 F	*- F	
52	1	NA	*RADIATOR FAN MOTOR	Distorted	150.00 F	*150.00 F	
53	1	NA	*RADIATOR FAN BLADE	Distorted	35.00 F	*35.00 F	
54	1	NA	*RADIATOR FAN COWLING	Distorted	95.00 F	*95.00 F	
55	1	NA	*AIRCON CONDENSER	Distorted	300.00 F	*300.00 F	
56	1	NA	*AIRCON CONDENSER SIDE GARNISH - LH	Not Necessary	55.00 F	*- F	
57	1	NA	*AIRCON CONDENSER SIDE GARNISH - RH	Not Necessary	55.00 F	*- F	
58	1	NA	*AIRCON CONDENSER FAN MOTOR/COWLING & BLADE	Distorted	290.00 F	*290.00 F	
59	1	NA	*AIRCON DISCHARE PIPE	Not Necessary	135.00 F	*- F	
60	1	NA	*AIRCON LIQUID TUBE	Not Necessary	130.00 F	*- F	
61	1	NA	*HORN - LH	Not Necessary	65.00 F	*- F	
62	1	NA	*HORN - RH	Not Necessary	65.00 F	*- F	
63	1	NA	*ENGINE MOUNTING BRACKET - RH	Not Necessary	170.00 F	*- F	
					<b>Total Parts (S\$)</b>	<b>7,650.00</b>	<b>5,073.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	BATTERY (DAMAGED)	168.00	168.00
2	1	FRONT NUMBER PLATE W/CASING (DISTORTED)	35.00	35.00
Sub Total (S\$)			<b>203.00</b>	<b>203.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Paintwork Labour</b>				
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,000.00	800.00
<b>Labour Items</b>				
2	TO KNOCK OUT DENTS; STRAIGHTEN FRONT CHASSIS; CUT/WELD SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	1,000.00	800.00
3	TO CHECK WIRING	New	20.00	20.00
4	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New	100.00	100.00
5	TO LIFT UP ENGINE	New	80.00	0.00
6	TO REMOVE; REPLACE FRONT ENGINE MOUNTINGS	New	150.00	0.00
7	TO REMOVE; REPLACE LH FUSE BOX ASSY; AIRCLEANER BOX ASSY AND RELATED PARTS	New	250.00	180.00
Gross Labour Cost (S\$)			<b>2,600.00</b>	<b>1,900.00</b>

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;