

ASSIGNED BY

CS3/MSG17020765/Gb2

Wing

Supervisor

QQ

ASSIGNMENT (OFFICE)

Meimien

Print Name

Lionel Tan

MSG

Task No

31/10/17 @ 10:06am

Estimated Cost

BLK

OD / TP

WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SFY 2809T

Insured

YN 2601H

at Workshop in

Star Automobile

Tel

64821009

at

Blk 5033, # 01-255 AMK Ind Park 2, 569536

Policy No

28631223MKC

Claim No

534735

Sum Insured

Excess

Make of Vehi

(Client's Record)

LOGA

26/10/2017

CA / REV / REP / REV 24 HRS

WPI

Hold Back cost

Date/Time

10:52am @ 31/10/17

Person Connected

ERIC

Vehicle

IN / OUT

Date/Time

Action/Instruction (X) Estimate

SFY 2809T - X

YN 2601H - X

Dismantle Part: 01-11-2017

25/11/17 4:35pm Email to Lionel Tan from Meimien.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG17020765/Gb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 31-10-2017



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	YN 2601H	Veh. Inspected	SFY 2809T
Policy No.	28631223MKC	Coverage (\$)	0.00
Claim No.	534735	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	31/10/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/10/2017	Inspection Date	31/10/2017
Survey held at	STAR AUTOMOBILE SERVICES BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-255 SINGAPORE 569536		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Oct 2017		31 Oct 2017 10:06 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	XING DA FOODSTUFF (S) PTE.LTD., Co. Reg. No.: 200407222D, Tel: +6590689296		
Main Claimant:	ARTLAND DESIGNERS (S) PTE LTD, Co. Reg. No.: 197401437R		
Vehicle Reg. No.:	SFY2809T	Date of Loss:	26/10/2017 14:00 - :59
Claim Type:	TP / 534735	Policy/Cover Note No.:	28631223MKC (Comprehensive) Coverage: 09/11/2016 - 08/11/2017
Vehicle Reg. No. (Insured):	YN2601H	Policy No. (Claimant):	
		Excess:	S\$700.00
Repairer:	Star Automobile Services Pte Ltd (HQ) BLK 5033, #01-255 ANG MO KIO IND PARK 2, 569536 Ang Mo Kio - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/11/2017]		
Driver/Custodian (Insured):	LIU XINGTAO (), NRIC: G6334914W		
Adj Asg. Remarks:	Location - BLK 5033 #01-255 ANG MO KIO INDUSTRIAL PARK 2 S(569536) Please contact the workshop directly @ 6482 1009 to arrange for survey.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (: Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (: Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

--


--

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014



STAR AUTOMOBILE SERVICES PTE LTD
Blk 5033, #0-255,
Ang Mo Kio Industrial Park 2
Singapore 569536
Tel: 64821009
Fax: 64824452
Date : 30/10/2017
Time : 0950

BY FAX & POST

To : MSIG INSURANCE (SINGAPORE) PTE LTD
Fax Number: 66431349
Email: claims@sg.msig-asia.com

Re: Pre Repair Assessment

Dear Sirs

We are instructed by (ARTLAND DESIGNERS (S) PTE LTD) to notify you of a road traffic accident on (26/10/2017) at about (1445) at (ALONG CLEMNTI ROAD) involving our client's vehicle registration number (SFY 2809 T) and vehicle registration number (YN 2601 H) insured by you at the material time. A copy of the Singapore Accident Statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully



STAR AUTOMOBILE SERVICES PTE LTD

Enc

Cc ARTLAND DESIGNERS (S) PTE LTD

Lkk

To : MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way, #21-01, SGX Centre 2
Singapore 068807
Tel: 68277888
Fax Number: 66431349
Email: claims@sg.msig-asia.com

BY FAX & POST
Dated: 30/10/2017
Time: 1810

Dear Ms Iryani Binte Amin (Motor Claim)
Our Ref: SFY2809T
Your Ref: M534735

We write to inform that our client objects to all the motor surveyors proposed by you as outlined in your Reply dated (30 October 2017).

We propose to use Chee Aik Thuan of Automotive Appraiser and Surveying Services to conduct the joint pre-repair survey as a single joint expert.

Please let us know within 2 working days whether you agree to the appointment of the said surveyor as a single joint expert. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Yours faithfully



Eric Tan
Star Automobile Services Pte Ltd

STAR AUTOMOBILE SERVICES PTE LTD
Blk 5033, #0-255,
Ang Mo Kio Industrial Park 2
Singapore 569536
Tel: 64821009
Fax: 64824452
Date : 30/10/2017
Time : 0950

BY FAX & POST

To : MSIG INSURANCE (SINGAPORE) PTE LTD
Fax Number: 66431349
Email: claims@sg.msiga-asia.com

Re: Pre Repair Assessment

Dear Sirs

We are instructed by (ARTLAND DESIGNERS (S) PTE LTD) to notify you of a road traffic accident on (26/10/2017) at about (1445) at (ALONG CLEMNTI ROAD) involving our client's vehicle registration number (SFY 2809 T) and vehicle registration number (YN 2601 H) insured by you at the material time. A copy of the Singapore Accident Statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully

STAR AUTOMOBILE SERVICES PTE LTD

Enc



Cc ARTLAND DESIGNERS (S) PTE LTD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/10/2017 10:54
Date Of Accident	26/10/2017 14:45
Exact Location Of Accident	ALONG CLEMENTI ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFY2809T
Insured/Policyholder	
Name Of Registered Owner	ARTLAND DESIGNERS (S) PTE LTD
Co Reg No	197401437R
Email Address	CHEWKARHOO@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97937554
Alternative Phone No	OFFICE-97937554

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA 1.6
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	17-MC012739-R06
Cover Note Number	20/09/2017 - 19/09/2018

Driver

Name of Driver	CHEW KAR HOO
NRIC No	S2533350J
Date Of Birth	24/12/1941
Occupation	INDOOR
Date Of Driving Pass	12/12/1974
Driving Experience	42 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	CHEWKARHOO@HOTMAIL.COM

Address
 Postcode
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO THE ATTACHED SKETCH PLAN BY DRIVER.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number YN2601H
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver LIU XINGTAO
 NRIC/Passport Number G6334914W
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

Sketch Plan Pg. 1

Date of accident: 26/10/17 Time: 2:45pm Location: along Clementi Rd
 My Vehicle A: SFY2809T Vehicle B: YN2601H Vehicle C: _____
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travel along the Clementi Road
 at 2:45pm on the 2nd lane and
 suddenly the Pick up No. YN2601H came
 behind and hit onto my left rear portion.

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my file accident report to:

My workshop: Qoh Loo Woon

Email address:

& myself:

Email address: shanto28@gmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION
 ARTLAND DESIGNERS (S) PTE LTD
 5001 Beach Road

#06-03 Golden Mile Complex
 Singapore 199888

Tel: 62986822 Fax: 62988169

Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No:

AH LIM MOTOR COMPANY

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

ARTLAND DESIGNERS (S) PTE LTD
5001 Beach Road
#06-03 Golden Mile Complex
Singapore 199598
Tel: 6296 2222 Fax: 6296 8189

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	1437R
Vehicle Details	
Vehicle No.	SFY2809T
Vehicle to be Exported	No
Intended De-registration Date	01 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	COROLLA 1.6
Primary Colour	Gold
Manufacturing Year	2005
Engine No.	3ZZ4504209
Chassis No.	MR053ZEC107097190
Maximum Power Output	81.0 kW (108 bhp)
Open Market Value	\$16,493.00
Original Registration Date	20 Sep 2005
First Registration Date	20 Sep 2005
Transfer Count	0
Actual ARF Paid	\$18,143.00
Intended PARF Rebate Details	
PARF Eligibility	Forfeited
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	19 Sep 2020
COE Category	A - Car (1600cc & below)
COE Period(Years)	5
PQP Paid	\$29,608.00
COE Rebate Amount	\$17,073.00
Total Rebate Amount	\$17,073.00
Message	

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 01 Nov 2017

View Sent Message

This mail is associated with :

***SFY2809T (534735)**
[YN2601H]

TP

ARTLAND DESIGNERS (S) PTE LTD
Oct 26 2017 2:00PM
[XING DA FOODSTUFF (S) PTE.LTD.]
Star Automobile Services Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 25/11/2017 16:35 PM.
To MSIG_LTTP
Subject Pre-repair Inspection

Dear Lionel,

Refer to your assignment on 31.10.2017 at 10.06AM.

Please be informed that we have inspected the vehicle SFY 2809T on 31.10.2017 at 4.30PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,
Catherine Chong | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Oct 2017		31 Oct 2017 10:06 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	XING DA FOODSTUFF (S) PTE.LTD., Co. Reg. No.: 200407222D, Tel: +6590689296	
Main Claimant:	ARTLAND DESIGNERS (S) PTE LTD, Co. Reg. No.: 197401437R	
Vehicle Reg. No.:	SFY2809T	Date of Loss: 26/10/2017 14:00 - :59
Claim Type:	TP / 534735	Policy/Cover Note No.: 28631223MKC (Comprehensive) Coverage: 09/11/2016 - 08/11/2017
Vehicle Reg. No. (Insured):	YN2601H	Policy No. (Claimant):
		Excess: S\$700.00
Repairer:	Star Automobile Services Pte Ltd (HQ) BLK 5033, #01-255 ANG MO KIO IND PARK 2, 569536 Ang Mo Kio - Tel:	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 01/11/2017]	
Driver/Custodian (Insured):	LIU XINGTAO (), NRIC: G6334914W	
Adj Asg. Remarks:	Location - BLK 5033 #01-255 ANG MO KIO INDUSTRIAL PARK 2 S(569536) Please contact the workshop directly @ 6482 1009 to arrange for survey.	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> MSIG_LTTP (27/11/2017): Upload final report - SFY2809T 		

ALL ASSOCIATED TASKS [□]									
						View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SFY2809T (534735)**
[YN2601H]
TP
ARTLAND DESIGNERS (S) PTE LTD
Oct 26 2017 2:00PM
[XING DA FOODSTUFF (S) PTE.LTD.]
Star Automobile Services Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Letters/Correspondences							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	30/10/17 14:45	Non Reporting Letter to OI						Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
2	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
3	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
4	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
5	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
6	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
7	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
8	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
9	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
10	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
11	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
12	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
13	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
14	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
15	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
16	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
17	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
18	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
19	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
20	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
21	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
22	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
23	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
24	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
25	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
26	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
27	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
28	19/01/18 14:11	General View						Load JPG	<input checked="" type="checkbox"/>	
29	19/01/18 14:11	Odometer Reading						Load JPG	<input checked="" type="checkbox"/>	
30	19/01/18 14:11	Chassis Number						Load JPG	<input checked="" type="checkbox"/>	
31	19/01/18 14:11	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
32	19/01/18 14:11	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	

33	19/01/18 14:11	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
34	19/01/18 14:11	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
35	19/01/18 14:11	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
Documentation					
			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	30/10/17 14:44	TPD SFY2809T - PRI & GIA REPORT	1	Load PDF	
2	27/11/17 11:04	Letter of Demand from Third Party	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div> <div style="text-align: right;"> ^ v </div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17020765/GBE2

Date: 19/01/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28631223MKC

Claimant Vehicle No : SFY2809T

Insured Vehicle No : YN2601H

Date of Loss: 26/10/2017

Nature of Claim: TP

Claim No: 534735

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFY2809T

Make & Model: TOYOTA COROLLA, 1.6 (A)

Engine No: 3ZZ4504209

Reg. Date: 20/09/2005 (Man. Year: 2005)

Chassis No: MR053ZEC107097190

Colour: Gold

Odometer: 152791 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14

Rear Tyre Size: 185/70 R14

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 31/10/2017

Date Inspected: 31/10/2017 Inspected At:

Star Automobile Services Pte Ltd (HQ)
BLK 5033,#01-255 ANG MO KIO IND
PARK 2
Singapore 569536

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 - \$3,500.00

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 19 Jan 2018)
Parts: 143 TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SFY2809T)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >