

22/03/2002

ASS. REC. BY:

REF:

CS/ACCU7020769/Rigby

Special Instruction:

Surveyor: Rosul**ASSIGNMENT (Office)**From (Person): Rachel Tun

of

AGI

Date/Time:

31/10/2017 9:14am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SJN 142G

Insured:

SKR 5045T

at Workshop m/s

Sing Ah Tee

Tel:

6268 6183

of

516 3 Pioneer Rd North #01-18

Policy No:

Claim No:

C100021091/JM

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13.10.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS '08'

H.O.D. Endorsement:

Date/Time:

31-10-1712:08pm

Person Contacted:

SamanthaVehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SJN 142G - xSKR 5045T - CCS / AXA 16001447 / Rug392SKR 05041608/11/18 @2:35pm Confirmed with Sharon - LS & 400, 7 days by email.
(Ref & 1920.50, 32%).

REF:

388213

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJN 1426at Workshop m/s SNA AH TEE

of _____

Insured: AGI / mp

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJN 1426 Yr Regn: 2009 JanType: M.C. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA ULOS E 9 cc 1497Colour: BLUE A.C. Insured / Std / Nil / NASp. Reading: 135846 T Radio Insured / Std / Nil / NA

Eng No: _____

C.No: MRO53 H49 8050 99937Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / Rim / STD A/Rim orTyre Size: F: 185/60R15R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 13/10/17 D.O.I. 31/10/17Survey held at SNA AH TEEDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 12/11/2017

Date/Time File Pass to?

☐

Preli. Report

11/08/15 typist☐

Final Report

Date/Time File Return to?

2

Days Of Repair: 7Resurvey No. of Trip: 1

Survey Fee:

Transportation

1.33 + 35.00

Photos

Other

Report Format: 7pLump Sum / I.B. / S 4100Add Fee: ☐ Site Insp / S☐ Interview / S☐ Tech. Insp. / S☐ Weekend / S

TOTAL

290



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI17020769/R1qb

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 31-10-2017



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKQ 5045T	Veh. Inspected	SJN 142G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	RACHEL TAN	Assign Date	31/10/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/10/2017	Inspection Date	31/10/2017
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Catherine Chong (LKK Auto)

From: Rachel Tan <rachel.tan@budgetdirect.com.sg>
Sent: Tuesday, 31 October, 2017 9:14 AM
To: SAMANTHA TAN
Cc: assignments@lkkauto.com
Subject: RE: ACCIDENT INVOLVING OUR CLEINT'S VEHICLE SJN142G & YOUR INSURED SKQ5045T ON 13/10/2017
Attachments: img-X30150121.pdf

Hi LKK

Kindly assist on Direct Survey.
Attached is Third party estimates.

Rachel Tan
Executive, Claims

T +65 6540 2181 (Direct Line)
F +65 6725 0853 (Claims)
E rachel.tan@budgetdirect.com.sg

From: SAMANTHA TAN [mailto:sam@sngahtee.com]
Sent: Monday, 30 October, 2017 3:07 PM
To: Rachel Tan <rachel.tan@budgetdirect.com.sg>
Subject: RE: ACCIDENT INVOLVING OUR CLEINT'S VEHICLE SJN142G & YOUR INSURED SKQ5045T ON 13/10/2017

Hi Rachel,

Enclose herewith the attached Estimate repair cost for your reference.

As spoken, you had arrange LKK for survey the above vehicle for tomorrow 31/10/2017.

Thank you.

Best Regards

Samantha Tan | sam@sngahtee.com

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



From: Rachel Tan [mailto:rachel.tan@budgetdirect.com.sg]
Sent: Friday, 20 October 2017 5:28 PM
To: sam@sngahtee.com
Subject: RE: ACCIDENT INVOLVING OUR CLEINT'S VEHICLE SJN142G & YOUR INSURED SKQ5045T ON 13/10/2017

Hi Samantha

Has the surveyor surveyed the car?
Noticed that I have not confirmed assignment to the surveyor.
Shall I proceed to arrange PRI?

Our insured is liable for accident.

Rachel Tan
Executive, Claims

T +65 6540 2181 (Direct Line)
F +65 6725 0853 (Claims)
E rachel.tan@budgetdirect.com.sg

From: Rachel Tan
Sent: Monday, 16 October, 2017 5:09 PM
To: 'sam@sngahtee.com' <sam@sngahtee.com>
Subject: RE: ACCIDENT INVOLVING OUR CLEINT'S VEHICLE SJN142G & YOUR INSURED SKQ5045T ON 13/10/2017

Hi Samantha

Liability is clear.

Rachel Tan
Executive, Claims

T +65 6540 2181 (Direct Line)
F +65 6725 0853 (Claims)
E rachel.tan@budgetdirect.com.sg

From: Albert Hong
Sent: Monday, 16 October, 2017 5:02 PM
To: Rachel Tan <rachel.tan@budgetdirect.com.sg>
Cc: Lincoln Yeo <lincoln.yeo@budgetdirect.com.sg>
Subject: FW: ACCIDENT INVOLVING OUR CLEINT'S VEHICLE SJN142G & YOUR INSURED SKQ5045T ON 13/10/2017

Hi Rachel,

FYA.

This is the new case you are doing now.

Regards,

Albert Hong
Senior Executive, Claims

T +65 6540 2182
F +65 6725 0853
E albert.hong@budgetdirect.com.sg

Shiau Chan (LKKAuto)

From: Julie Mangubat <julie.m@budgetdirect.com.sg>
Sent: Tuesday, 8 May 2018 3:52 PM
To: Shiau Chan (LKKAuto); SUR
Cc: assignments
Subject: RE: ACCIDENT INVOLVING OUR CLEINT'S VEHICLE SJN142G & YOUR INSURED SKQ5045T ON 13/10/2017 |

Hi Shiau Chan

Rachel is no longer with Budget Direct.

I will be taking over this case and the reference: C10001091/JM

Thank you,
-Julie

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Tuesday, 8 May, 2018 2:39 PM
To: Rachel Tan <rachel.tan@budgetdirect.com.sg>; SUR <sur@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>
Subject: RE: ACCIDENT INVOLVING OUR CLEINT'S VEHICLE SJN142G & YOUR INSURED SKQ5045T ON 13/10/2017

Dear Rachel,

Kindly provide us the claim no.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 31 October 2017 12:08 PM
To: 'Rachel Tan' <rachel.tan@budgetdirect.com.sg>; SUR <sur@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>
Subject: RE: ACCIDENT INVOLVING OUR CLEINT'S VEHICLE SJN142G & YOUR INSURED SKQ5045T ON 13/10/2017

Dear Rachel,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Rachel Tan [<mailto:rachel.tan@budgetdirect.com.sg>]
Sent: Tuesday, 31 October, 2017 9:14 AM

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 8 May 2018 2:35 PM
To: 'Sharon Sng'; SUR; Rasul (LKKAUTO)
Subject: RE: SJN142G - FINALISE

Dear Rasul,

Confirm Lump Sum \$4,100.00 before GST and 7 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Sng [<mailto:sharon@sngahtee.com>]
Sent: Tuesday, 8 May 2018 11:53 AM
To: SUR <sur@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>
Subject: FW: SJN142G - FINALISE

Hi

Please assist in finalise.
Insured chase us on this case.
Thanks.

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



From: Sharon Sng [<mailto:sharon@sngahtee.com>]
Sent: Tuesday, April 24, 2018 3:10 PM
To: 'Rasul (LKKAUTO)'
Subject: FW: SJN142G - FINALISE

From: Sharon Sng [<mailto:sharon@sngahtee.com>]
Sent: Tuesday, April 24, 2018 3:00 PM
To: 'Rasul (LKKAUTO)'
Subject: SJN142G - FINALISE

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	3382B

Vehicle Details

Vehicle No.	SJN142G
Vehicle to be Exported	No
Intended De-registration Date	31 Oct 2017
Vehicle Make	TOYOTA
Vehicle Model	VIOS E AUTO
Primary Colour	Blue
Manufacturing Year	2008
Engine No.	1NZX865183
Chassis No.	MR053HY9305099937
Maximum Power Output	80.0 kW (107 bhp)
Open Market Value	\$11,900.00
Original Registration Date	<u>23 Jan 2009</u>
First Registration Date	23 Jan 2009
Transfer Count	0
Actual ARF Paid	\$11,900.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	22 Jan 2019
PARF Rebate Amount	\$6,545.00

Intended COE Rebate Details

COE Expiry Date	<u>22 Jan 2019</u>
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$2,693.00
COE Rebate Amount	\$330.00
Total Rebate Amount	\$6,875.00

The information contained herein is correct as at 16 Oct 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/10/2017 09:08
Date Of Accident	13/10/2017 18:40
Exact Location Of Accident	COMMONWEALTH AVEJUNCTION TO QUEENSWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN142G
Insured/Policyholder	
Name Of Registered Owner	SONG HAOCHUN
NRIC No	S7263382B
Email Address	SHC0969@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98253196
Alternative Phone No	HOME-68530981

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 A (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100116767
Cover Note Number	

Driver

Name of Driver	SONG HAOCHUN
NRIC No	S7263382B
Date Of Birth	30/01/1972
Occupation	INDOOR
Date Of Driving Pass	27/11/2008
Driving Experience	8 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98253196
Fax Number	
Contact Number	HOME-68530981
EMail Address	SHC0969@GMAIL.COM

Address	BLK 485 JURONG WEST AVENUE 1 #09-69
Postcode	640485
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKQ5045T
Vehicle Make/Model/Colour	MIT GRANDIS/RED
Details Of Properties	
Name of Driver	WONG YU WING
NRIC/Passport Number	S7870832H
Contact Number	90189265
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT PORTION
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please fill in correctly the details of the accident to speed up the claims process.
2. This Report must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or willful hiding of material facts may allow insurance companies to **repudiate policy liability**.
4. Completion and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance company.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Road Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for future be made available upon application by interested parties.
7. By the signing of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copying of the report being made available afterwards.
8. **Consent under the Personal Data Protection Act (PDPA)**
- I, the undersigned, acknowledge and consent to request that:
- (a) My Officer may work along with the General Insurance Association of Singapore (GIA) Insurance personnel to collect, store, process and use my personal data, including information relating to the accident, for the purpose of processing, handling and dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
- (b) My Officer may use my personal data for the purpose of:
- (i) processing, handling and dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) processing my claims dealing with my instructions or responding to any enquiries by me;
- (iii) processing my claims including the mailing of correspondence, statements, invoices, reports or letters to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope/mail package; and/or
- (iv) working with applicable law in administering, processing, handling and/or dealing with my claims collectively the "Purposes";
- (b) all the terms who have been involved in the accident and the insurance company/ies involved in the accident;
- (c) all the information about me may be disclosed to any of the insurance company/ies involved in the accident;
- (d) my Personal Information may be collected and used for the purpose of settling the claims and for the purpose of the insurance management, assessment and all future claims;
- (e) my information may be disclosed under all circumstances to any party;
- (f) I shall assume liability for any other third parties that arise from the accident, including any third party, legal, civil, law enforcement and government agencies or authorities required for the purposes mentioned;
- (g) I shall comply with regulations to identify myself with all laws or regulations.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name
NRIC/ID No.:

Sketch Plan #2

SKETCH PLAN



A SJN 1426
B SJN 1426

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

2007年10月30(四) 6:40pm 我駕駛 SJN 1426 行經 Commonwealth Ave 並因大石轉進入 Queensway 時，交通燈由綠轉紅，我停在停車綫，遭到 SJN 1426 的 (A) 在 (B) 大石前位置，不斷按喇叭，我等了幾分鐘，因是下課繁忙交通時間，我平常太忙，路已很繁忙，出于安全考量，我在車輛後方停左肩停回停車綫，處理緊急事宜。

DECLARATION

I, the undersigned, being the driver of the vehicle, hereby declare that the information provided is true and correct.

Signature of Driver

Date & Time

Signature of Driver

If driver is not the policyholder, Date & Time

Signature of Reporting Centre

Name of Reporting Centre & Signature of Reporting Centre

孫亞弟汽車燒焊私人有限公司

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB Reg / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003242

AUTO & GENERAL INSURANCE(SINGAPORE) PTE LTD

190 CLEMENCEAU AVE
#03-01 S'PORE SHOPPING CENTRE
(S) 239924

ATTENTION :

CONTACT : -

FAX NO: 67250853

DATE 30/10/2017

ACCIDENT DATE : 13/10/2017

VEHICLE NO : SJN142G

CHASSIS/ENG.NO :

VEHICLE MODEL : TOYOTA VIOS

CLAIM NO :

POLICY NO :

REMARK 142AUTO TP AGST
SKQ5045T

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER	371.45	25	278.59	278.59
2	2	PC	REAR BUMPER SIDE RETAINER	132.25	25	99.19	198.38
3	10	PC	REAR BUMPER CLIPS	12.90	25	9.68	96.80
4	2	PC	REAR BUMPER REFLECTOR	141.45	25	106.09	212.18
5	1	PC	REAR BOOT LID	781.90	25	586.42	586.42
6	2	PC	REAR BOOT LID HINGE	172.25	25	129.19	258.38
7	1	PC	REAR BOOT LID EMBLEM	43.75	25	32.81	32.81
8	1	PC	REAR BOOT LID VIOS LOGO	43.10	25	32.33	32.33
9	1	PC	REAR BOOT E LOGO	43.50	25	32.63	32.63
10	2	PC	REAR TAILLAMP	374.80	25	281.10	562.20
11	4	PC	REAR TAILLAMP CLIPS	12.90	25	9.68	38.72
12	1	PC	REAR END PANEL	781.90	25	586.42	586.42
13	1	PC	REAR BOOT WEATHERSTRIPE	178.10	25	133.57	133.57
14	1	PC	REAR END PANEL GARNISH	274.45	25	205.84	205.84
15	1	PC	REAR SPARE TYRE TRIMBOARD	371.85	25	278.89	278.89
16	1	PC	REAR BOOT LID LOCK	172.45	25	129.34	129.34
SUB-TOTAL:							3,663.50
** NETT PRICE **							
1	1	PC	REAR REVERSE SENSOR	380.00	10	342.00	342.00
SUB-TOTAL							342.00
** SPECIAL NETT PRICE **							
1	1	PC	REAR NUMBER PLATE	35.00		35.00	35.00
SUB-TOTAL							35.00

SAM

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003242

AUTO & GENERAL INSURANCE(SINGAPORE) PTE LTD

190 CLEMENCEAU AVE
#03-01 S'PORE SHOPPING CENTRE
(S) 239924

ATTENTION :

CONTACT : -

FAX NO: 67250853

DATE : 30/10/2017
ACCIDENT DATE : 13/10/2017
VEHICLE NO : SJN142G
CHASSIS/ENG.NO :
VEHICLE MODEL : TOYOTA VIOS
CLAIM NO :
POLICY NO :
REMARK : 142AUTO TP AGST
SKQ5045T

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** WORK LABOUR **							
			TO CHECK WIRING	30.00			30.00
			TO APPLY ANTI RUST COATING	150.00	80		150.00
			TO REMOVE & REFIX TRIMS	100.00	80		100.00
			TO KNOCK, WELD, REMOVE & FIX ON ABOVE PARTS	800.00	70		800.00
			TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	900.00	80		900.00
				SUB-TOTAL			1,980.00

Rate
HP 90010068

7 days

4/5

31/10/17 @ 1730

Re-survey after repair

31/11/17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

SAM

PAGE: 2 of 2

41
SUB-TOTAL : S\$ 6,020.80

ADD 7% GST. S\$ 421.44

GRAND TOTAL : S\$ 6,441.94

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O.E

孫亞弟汽車燒焊私人有限公司

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003242

AUTO & GENERAL INSURANCE(SINGAPORE) PTE LTD

DATE 30/10/2017

ACCIDENT DATE : 13/10/2017

VEHICLE NO : SJN142G

CHASSIS/ENG.NO :

VEHICLE MODEL : TOYOTA VIOS

CLAIM NO :

POLICY NO :

REMARK 142AUTO TP AGST
SKQ5045T

190 CLEMENCEAU AVE

#03-01 S'PORE SHOPPING CENTRE

(S) 239924

ATTENTION :

CONTACT : -

FAX NO: 67250853

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER	371.45	25	278.59	DE 278.59 ✓
2	2	PC	REAR BUMPER SIDE RETAINER	132.25	25	99.19	NE 198.38 ✓
3	10	PC	REAR BUMPER CLIPS	12.90	25	9.68	NE 96.80 ✓
4	2	PC	REAR BUMPER REFLECTOR	141.45	25	106.09	? 212.18 ✓
5	1	PC	REAR BOOT LID	781.90	25	586.42	TH 586.42 ✓
6	2	PC	REAR BOOT LID HINGE	172.25	25	129.19	X 258.38 ✓
7	1	PC	REAR BOOT LID EMBLEM	43.75	25	32.81	NE 32.81 ✓
8	1	PC	REAR BOOT LID VIOS LOGO	43.10	25	32.33	NE 32.33 ✓
9	1	PC	REAR BOOT E LOGO	43.50	25	32.63	NE 32.63 ✓
10	2	PC	REAR TAILLAMP	374.80	25	281.10	CRA 562.20 ✓
11	4	PC	REAR TAILLAMP CLIPS	12.90	25	9.68	NE 38.72 ✓
12	1	PC	REAR END PANEL	781.90	25	586.42	PT 586.42 ✓
13	1	PC	REAR BOOT WEATHERSTRIPE	178.10	25	133.57	NE 133.57 ✓
14	1	PC	REAR END PANEL GARNISH	274.45	25	205.84	CRA 205.84 ✓
15	1	PC	REAR SPARE TYRE TRIMBOARD	371.85	25	278.89	NE 278.89 ✓
16	1	PC	REAR BOOT LID LOCK	172.45	25	129.34	TH 129.34 ✓
				SUB-TOTAL: 3,663.50 \$3192.94 NE 220			
** NETT PRICE **							
1	1	PC	REAR REVERSE SENSOR	380.00	10	342.00	342.00 ✓
				SUB-TOTAL 342.00 \$7701			
** SPECIAL NETT PRICE **							
1	1	PC	REAR NUMBER PLATE	35.00		35.00	SEA 35.00 ✓
				SUB-TOTAL 35.00			

SAM

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O E

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003242

AUTO & GENERAL INSURANCE(SINGAPORE) PTE LTD

190 CLEMENCEAU AVE

#03-01 S'PORE SHOPPING CENTRE

(S) 239924

ATTENTION :

CONTACT : -

FAX NO: 67250853

DATE 30/10/2017

ACCIDENT DATE : 13/10/2017

VEHICLE NO : SJN142G

CHASSIS/ENG.NO :

VEHICLE MODEL : TOYOTA VIOS

CLAIM NO :

POLICY NO :

REMARK : 142AUTO TP AGST
SKQ5045T

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
------	-----	------	-------------	-------	--------	-------------	-----------

** WORK LABOUR **

TO CHECK WIRING				30.00			30.00
TO APPLY ANTI RUST COATING				150.00	80		150.00
TO REMOVE & REFIX TRIMS				100.00	80		100.00
TO KNOCK, WELD, REMOVE & FIX ON ABOVE PARTS				800.00	70		800.00
TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS				900.00	80		900.00
				SUB-TOTAL			1,980.00

\$1690.00

Rate
HP 90010068

7 days

4/5

31/10/17 @ 1730

Repairing after repair

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total \$5137.94
less 20% = \$4110.35
Net \$4100.7 - Lumpsum
OK? 16 PERCENT. SHANN
24/11/17

SAM

PAGE: 2 of 2

SUB-TOTAL : S\$ 6,020.50

ADD 7% GST. S\$ 421.44

GRAND TOTAL : S\$ 6,441.94

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O E



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL			Ref : CS/AGI17020769/R1qbe2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date : 11-05-2018	
			Code : AGI	
1. Policy Particulars - THIRD PARTY CLAIM				
Insured Veh.	SKQ 5045T	Veh. Inspected	SJN 142G	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10001091/JM	Excess (\$)	0.00	
Assign From	RACHEL TAN	Assign Date	31/10/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS E A	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053HY9305099937	Colour	BLUE	
Odometer	139846	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/10/2017	Inspection Date	31/10/2017	
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 142G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	371.45	371.45
2	REAR BUMPER SIDE RETAINER @\$132.25	NECESSARY	264.50	264.50
10	REAR BUMPER CLIPS @\$12.90	NECESSARY	129.00	129.00
2	REAR BUMPER REFLECTOR @\$141.45	SERVICEABLE	282.90	-
1	REAR BOOT LID	BENT	781.90	781.90
2	REAR BOOT LID HINGE @\$172.25	SERVICEABLE	344.50	-
1	REAR BOOT LID EMBLEM	NECESSARY	43.75	43.75
1	REAR BOOT LID VIOS LOGO	NECESSARY	43.10	43.10
1	REAR BOOT E LOGO	NECESSARY	43.50	43.50
2	REAR TAILLAMP @\$374.80	CRACKED	749.60	749.60
4	REAR TAILLAMP CLIPS @\$12.90	NECESSARY	51.60	51.60
1	REAR END PANEL	BENT	781.90	781.90
1	REAR BOOT WEATHERSTRIPE	NECESSARY	178.10	178.10
1	REAR END PANEL GARNISH	CRACKED	274.45	274.45
1	REAR SPARE TYRE TRIMBOARD	DEFORMED	371.85	371.85
1	REAR BOOT LID LOCK	BENT	172.45	172.45
	LESS 25% DISCOUNT		-1,221.14	-1,064.29
			3,663.41	3,192.86
1	REAR REVERSE SENSOR (N)	NOT WORKING	380.00	220.00
	LESS 10% DISCOUNT		-38.00	-
			342.00	220.00
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	SCRATCHED	35.00	35.00
			35.00	35.00
LABOUR				
	TO CHECK WIRING.		30.00	30.00
	TO APPLY ANTI RUST COATING.		150.00	80.00
	TO REMOVE & REFIX TRIMS.		100.00	80.00
	TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS.		800.00	700.00
	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS.		900.00	800.00
			1,980.00	1,690.00

Report Ref No. CS/AGI17020769/R1qbe2



GRAND TOTAL		6,020.41	5,137.86
RECOMMENDED COST OF LUMP SUM REPAIR (TO ITS PRE-ACCIDENT CONDITION)			4,100.00

Report Ref No. CS/AGI17020769/R1qbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.