

REF:

CS/TP17020772/Arbnz

Sinzur

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBG7184X

Yr Regn:

2012, Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Zongshen ZS125

c.c

124

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

50896

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

LZSXCJLR185200105

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 80/80 R17 - Dunlop

R: 80/90 R17 - Michelin

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

31/10/17

Survey held at

Hua Meng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP INC Independent -

FBG7184X - X

Confirm L/S \$3500, 5 days
Red: \$2771, 44%

RECEIVED 25 NOV 2018

Date/Time, File Pass to?



Preli. Report



Final Report

1)

typist

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

145

50

50

110

80

435

Report Format:

TP - Independent

Lump Sum / +B.I.: (\$ 3500)

78150



Post FREE Ad

What are you looking for?

West

Cars & Vehicles

Motorcycles, Scooters & Motorbikes in Boon Lay / Jurong / Tuas

ad 211972244

motorbike zongshen 150cc coe till 2022**\$4,900****Post an ad like this for FREE!**

Date Listed	05/10/2017	Model	Other
Location	Boon Lay / Jurong / Tuas, West	Year	2012
		Kilometers	5400
For Sale By	Owner		
Make	Other		

90%all new parts original change.for parts got guarantee 5month by agent guan hoe chong.bike fully paid.coe renewal.have parts receipt I change and pictures.

Look 8/10

Engine 9/10

Class 2B

Gumtree User

(More ads from this seller)

User since Jul 2017

935*** [Show phone number](#)**Email poster**

Message

☐ I'm interested. Please contact me.

☐ When and where can I see it?

Name

Email

Phone (optional)

☐ Send a copy to my email
Send

By clicking "Send" you accept the Terms of Use and Privacy Notice and agree to receive newsletters and promo offers

..... US.

Add to Watchlist

Safety Tips - Your safety is important to us and we believe that you can stay safe. Learn More

Report this ad

You might be interested in these similar ads

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	7815D
Vehicle Details	
Vehicle No.	FBG7184X
Vehicle to be Exported	Yes
Intended De-registration Date	31 Oct 2017
Vehicle Make	ZONGSHEN
Vehicle Model	ZS125-47 MANUAL
Primary Colour	Black
Manufacturing Year	2011
Engine No.	ZS154FMI35BA00833
Chassis No.	LZSXCJLR1B5200105
Maximum Power Output	-
Open Market Value	\$670.00
Original Registration Date	24 Oct 2012
First Registration Date	24 Oct 2012
Transfer Count	1
Actual ARF Paid	\$101.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	23 Oct 2022
COE Category	D - Motorcycle
COE Period(Years)	10
QP Paid	\$1,801.00
COE Rebate Amount	\$903.00
Total Rebate Amount	\$903.00

The information contained herein is correct as at 31 Oct 2017

OK

MSME7132347 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 06/10/2017 09:09

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 06/10/2017 09:19

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/10/2017 09:09
Date Of Accident	03/10/2017 11:30
Exact Location Of Accident	SLE TWDS YIO CHU KANG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBG7184X
Insured/Policyholder	
Name Of Registered Owner	TAN KIM CHUAN
NRIC No	S0157815D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96934973
Alternative Phone No	OFFICE-96934973

Vehicle Particulars

Manufacturer	ZONGSHEN
Model	ZS125-47-124CC (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5062165794-03
Cover Note Number	

Driver

Name of Driver	TAN KIM CHUAN
NRIC No	S0157815D
Date Of Birth	21/06/1950
Occupation	INDOOR
Date Of Driving Pass	08/05/1975
Driving Experience	42 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96934973
Fax Number	
Contact Number	OFFICE-96934973
Email Address	NOEMAIL

Address BLK 868 YISHUN ST 81 #04-91
 Postcode 760868
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name TRAFFIC POLICE DIVISION HQ
 Police Station Address ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 65470000 - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT: T/20171004/2029.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number UNKNOWN
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name TAN KIM CHUAN

Approximate Age

Injuries Sustain

Injured person in which vehicle? FBG7184X

Were seat belts worn?

Was injured conveyed to hospital by ambulance? YES

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of the report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) my insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers;
 - (b) all insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"; the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages; and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (c) all insurers (who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms) may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (d) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

SEE COMMENTS Y.O. 10/10/17

Vehicle FBS-104 X

Vehicle 10/10/17

10/10/17

10/10/17

HUA MING

Sketch Plan #2 Pg. 1


Describe Circumstances of the Accident

Please refer the police report ① : 7/20171004/2029
② : 7/20171004/2048

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date &
Time


Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

Sketch Plan #3 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20171004/2029

1 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20171004/2029

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 04/10/2017 10:32	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: TAN KIM CHUAN			Address: 868 YISHUN ST 81 HDB-YISHUN SINGAPORE 760868	
ID Type / ID No.: NRIC NO / S0157815D			Contact No.: Home/Office:	Mobile: 96934973
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 67	Date of Birth: 21/06/1950	Type of Informant: Rider	
Race: Chinese			Language: English	Institution / School Name:
Occupation: ST TECHNICIAN			Driving Licence Information: Class: 2B Date of Expiry:	

General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 03/10/2017 11:30	Type of Location: Straight Road
Location: SELETAR EXPRESSWAY SLE TOWARD YIO CHU KANG				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBG7184X (Not Accurate)	Motorcycle	ZONGSHEN	ZS125-47 MANUAL	Black	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBG7184X (Not Accurate)	NTUC Income Insurance Co-Operative Limited	5062165794-03	24/10/2016	23/10/2017

Sketch Plan #4 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20171004/2029

2 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20171004/2029

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	TAN KIM CHUAN	ID No.	S0157815D
Related Vehicle	FBG7184X (Motorcycle)	Contact No.	96934973
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	03/10/2017	Date Discharge	03/10/2017
No. of Days granted Medical Leave	04	Degree of Injury	Slight

Brief Details.

ON THE ABOVE MENTIONED DATE, TIME AND LOCATION

I(FBG7184X) WAS TRAVELLING ALONG SLE TOWARDS YIO CHU KANG. I WAS HEADING TOWARDS YIO CHU KANG THEREFORE I RIDE TOWARDS THE EXIT OF YIO CHU KANG, HOWEVER WHEN I WAS AT THE LANE THAT WAS LEADING TO THE EXIT OF YIO CHU KANG, SUDDENLY TO UNKNOWN REASON A CAR BANGED ONTO THE REAR OF MY BIKE. AFTER THAT I THEN FELL DOWN AND SUFFERED INJURIES, SHORTLY AFTER THE AMBULANCE THEN ARRIVED, I WAS THEN CONVEYED TO THE HOSPITAL BY THE AMBULANCE. THAT'S ALL.

Sketch Plan #5 Pg. 1

**SINGAPORE
POLICE FORCE**

T/20171004/2029

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000

3 of 3

Report No. T/20171004/2029

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

TP /

KEVAN ANG ZI SHENG

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

04/10/2017 10:32

Officer In Charge Of Case:

TP / GIT /

Sgt 3 RASHIDAH BINTE AZMAN

Contact No.: 65476216

Classification Of Case:

SINGAPORE
POLICE FORCE

Authentication Stamp

NP168

Sketch Plan #6 Pg. 1



SINGAPORE
POLICE FORCE



F/20171004/2048

1 of 2

POLICE REPORT (NP322)

Report No. F/20171004/2048

Police Station Of Origin
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

Date/Time Report Made 04/10/2017 13:48	Video Report No.	Station Diary No. 43
Name Of Informant TAN KIM CHUAN	Address APT BLK 868 YISHUN STREET 81 #04-91 SINGAPORE 760868	
ID Type / ID No. NRIC NO / S0157815D	Contact No. Home/Office	Mobile 96934973
Nationality SINGAPORE CITIZEN	Email Address	
Occupation MAINTANCE TECHNICIAN	Sex Male	Age 67
Institution/School Name	Date of Birth 21/06/1950	Race Chinese
Date/Time Of Incident 03/10/2017 16:55 - 03/10/2017 16:55	Location Of Incident 90 YISHUN CENTRAL KHOO TECK PUAT HOSPITAL SINGAPORE 768828 Khoo Teck Puat Hospital	

Brief details.

On 03/09/2017 at about 1655hrs, while I was at Khoo Teck Puat Hospital, I discovered that the below mentioned items are missing. I had made a search but to no avail. I am lodging this report for record purpose.

Property Information

Signature Of Officer Recording The Report:

F / Sgt 2 ISAAC LEE YU JIN

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
F / Yishun South N.P.C /
Sr Staff Sgt ONG KAH KIAT
Contact No.: 68522999

Signature Of Informant:

Date/Time:
04/10/2017 13:48

Classification Of Case:

Authentication Stamp



FUPO hotline number: 68429645

Accident Sketch Plan Pg. 1



SINGAPORE
POLICE FORCE



F/20171004/2048

2 of 2

POLICE REPORT (NP322)

CONTINUATION OF REPORT

Report No. F/20171004/2048

S/N	Item	Type	Brand/ Account/ Property/ Security- Type	Make/ Model/ Bank/ Address/ Counter	Serial No./ IMEI/ Acct No	Quantity	Value	Description
1	General property	Lost			80301659	1		One ST Aerospace staff pass belonging to Tan Kim Chuan
2	Licence	Lost	Qualified Driving Licence			1		One driving licence belonging to Tan Kim Chuan

Signature Of Officer Recording The Report:

F / Sgt 2 ISAAC LEE YU JIN

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

F / Yishun South N.P.C /
Sr Staff Sgt ONG KAH KIAT
Contact No.: 68522999

Authentication Stamp



Signature Of Informant:

Date/Time:

04/10/2017 13:48

Classification Of Case:

FUPO hotline number: 68429645

FBG7184X 2012 Oct.
Zhangzhen ZS125 124 CC
LZSXCJLR1BS200105

Front Number Plate	Bent	25(SN) 15(SN)
Front Basket	Dented	120(SN) 80(SN)
Front Wheel Fender	Cut	95 ✓
Front Wheel Rim	Not New	280(SN) ✗
Front Brake Disc	Warped.	165 ✓
Front Fork Assy	Bent	425 ✓
Front Fork Oil	2 New	30(SN) ✓
Front Fork Oil Seal.		55(SN) ✓
Front Fork Bracket	Bent	138 ✓
Steering Core and Bearing	2 New	78 ✓
Steering Stem		125 ✓
Front Centre Cowling.	Cracked	68 ✓
Front Side Cowling x 02	Cracked	$145 \times 2 = 290$ ✓
Headlamp	Cracked.	165 ✓
Headlamp Cowling.	Cut	82 ✓
ERP Unit.	ut	160(SN) ✓
Handle Grip x 02	Not New	$26 \times 2 = 52$ ✗
Handle Balancer x 02	RH ut	$20 \times 2 = 40$ 20
Front Mirror x 02	RH Missing	$35 \times 2 = 70$ 35
Speedometer	Not New	350 ✗
Front Inner Centre Garnish	Cracked	75 ✓
Front Brake Lever.	Cut	28 ✓

FBG7184X

Front Foot Rest Bracket Best 68 ✓
 Front Foot Rest Rubber x 02 RH ut 25 x 2 = 50 25.
 Rear Foot Rest Bracket RH x 1 ut 48 x
 Rear Foot Rest Rubber RH. ut 25 ✓
 Rear Side Cowling x 02 Cracked 118 x 2 = 236 ✓

Rear Exhaust Pipe Best 325 ✓
 Rear Exhaust Heat Shield. Best 58 ✓

Tail lamp Smashed 135 ✓

Rear Wheel Cowling. Cracked 132 ✓
 Rear Shock Absorber x 02 135 x 2 = 270 x.

Rear Box ut 280 (SN) ✓

Rear Box lower Holder ut 68 ✓

Rear Box Bracket Best 185 ✓

Stickers Hw 100 (SN) 80 (SN)

Rear Number Plate Missing 25 (SN) 15 (SN)

Helmet. ut 100 (SN) 60 (SN)

Panel Bending. 400 300

Spray Painting. 400 300

To straighten chassis frame 400 200

Towing Fees. 50 ✓
 6271

LKR
 the following:
 • To be before/after spray painting
 • To be damaged parts during the repair
 • Parts prices are subject to confirmation
 • Third party survey is on a 'Wipe out' basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

hist 3046
 um 10/ 27440
 SN: 785
 Labours: 850.
 total: 4366.40.
 1/5: 3.5k.
 05 days.

351C
 0507

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HUA MENG SPRAY PAINTING WORKSHOP		Ref : CS/TP17020772/Arbn2	
1 KAKI BUKIT AVE 6 #01-61 AUTOBAYSINGAPORE 417883 ON BEHALF OF TAN KIM CHUAN		Date : 26-03-2018	
		Code : TP127	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	Veh. Inspected		FBG 7184X
Policy No.	Coverage (\$)		0.00
Claim No.	Excess (\$)		0.00
Assign From	Assign Date		31/10/2017
2. Vehicle Particulars & Condition			
Make & Model	ZONGSHEN ZS125	c.c	124
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	LZSXCJLR1B5200105	Colour	BLACK
Odometer	50896	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	80/80 R17	DUNLOP	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90 R17	MICHELIN	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/10/2017	Inspection Date	31/10/2017
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 7184X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT WHEEL FENDER	CUT	95.00	95.00
1	FRONT BRAKE DISC	WARPED	165.00	165.00
1	FRONT FORK ASSY	BENT	425.00	425.00
1	FRONT FORK BRACKET	BENT	138.00	138.00
1	STEERING CONE AND BEARING	NECESSARY	78.00	78.00
1	STEERING STEM	NECESSARY	125.00	125.00
1	FRONT CENTRE COWLING	CRACKED	68.00	68.00
2	FRONT SIDE COWLING @\$145.00	CRACKED	290.00	290.00
1	HEADLAMP	CRACKED	165.00	165.00
1	HEADLAMP COWLING	CUT	82.00	82.00
2	HANDLE GRIP @\$26.00	NOT NECESSARY	52.00	-
2	HANDLE BALANCER @\$20.00	O/S CUT	40.00	20.00
2	FRONT MIRROR @\$35.00	O/S MISSING	70.00	35.00
1	SPEEDOMETER	NOT NECESSARY	350.00	-
1	FRONT INNER CENTRE GARNISH	CRACKED	75.00	75.00
1	FRONT BRAKE LEVER	CUT	28.00	28.00
1	FRONT FOOT REST BRACKET	BENT	68.00	68.00
2	FRONT FOOT REST RUBBER @\$25.00	O/S CUT	50.00	25.00
1	REAR FOOT REST BRACKET RH	NOT NECESSARY	48.00	-
1	REAR FOOT REST RUBBER RH	CUT	25.00	25.00
2	REAR SIDE COWLING @\$118.00	CRACKED	236.00	236.00
1	REAR EXHAUST PIPE	BENT	325.00	325.00
1	REAR EXHAUST HEAT SHIELD	BENT	58.00	58.00
1	TAILLAMP	SMASHED	135.00	135.00
1	REAR WHEEL COWLING	CRACKED	132.00	132.00
2	REAR SHOCK ABSORBER @\$135.00	NOT NECESSARY	270.00	-
1	REAR BOX LOWER HOLDER	CUT	68.00	68.00
1	REAR BOX BRACKET	BENT	185.00	185.00
	LESS 10% DISCOUNT		-	-304.60
			3,846.00	2,741.40
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	BENT	25.00	15.00
1	FRONT BASKET (SN)	DENTED	120.00	80.00

Report Ref No. CS/TP17020772/Arbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT WHEEL RIM (SN)	NOT NECESSARY	280.00	-
1	FRONT FORK OIL (SN)	NECESSARY	30.00	30.00
1	FRONT FORK OIL SEAL (SN)	NECESSARY	55.00	55.00
1	ERP UNIT (SN)	CUT	160.00	160.00
1	REAR BOX (SN)	CUT	280.00	280.00
1	STICKERS (SN)	NECESSARY	100.00	80.00
1	REAR NUMBER PLATE (SN)	MISSING	25.00	15.00
1	HELMET (SN)	CUT	100.00	60.00
			1,175.00	775.00
	LABOUR			
	PANEL BEATING.		400.00	300.00
	SPRAY PAINTING.		400.00	300.00
	TO STRAIGHTEN CHASSIS FRAME.		400.00	200.00
	TOWING FEES.		50.00	50.00
			1,250.00	850.00
GRAND TOTAL			6,271.00	4,366.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,500.00

Report Ref No. CS/TP17020772/Arbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.